

ASS. REC. BY:

REP:

CS/CT118010307/T1sd3⁷²

Special Instruction:

Surveyor
Maimun

Taufik

ASSIGNMENT (Office)

From (Person):

Chong Boon den

of

CTI

Date/Time: 06/06/18 @ 2.21pm

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLM 2193C

Insured:

GBD 6864P

at Workshop m/s

Pegasus Engineering

Tel:

6513 7748

of

74 Kian Teck Rd

Policy No:

DMCVSN 3015231802

Claim No:

SNM18D02818C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

05/06/2018

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

3.47pm @ 6/6/18

Person Contacted:

Alvin

Vehicle

IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLM 2193C-X

GBD 6864P-X

02/10/18

Confirmed P/P \$ 3,268.62 @ 6 days with Taufik.
(\$ 7,076.16 Red - 68%)

Handwritten signature

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s: _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: *SLM 2193C* Yr Regn: *2017* *March*
 Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: *Toyota Vios* C.C: *1426*
 Colour: *Silver* A/C: Insured / Std / NI / NA
 Sp. Reading: *90998* T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: *MHF B29F3802* *no. 9143*
 Gen. Cond: *Good* / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: *195/50R16*
 R: *195/50R16*
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or *Wastlake*
 Front: _____ Rear: _____
 R/Bal: *6* mm R/Bal: *6* mm
 L/Bal: *6* mm L/Bal: *6* mm
 D.O.A. _____ D.O.I. *6/6/18 @ 1730*
 Survey held at *Pegasus Urban Tech.*
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Frt o/s, 4/c.
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 22 OCT 2018

Date/Time, File Pass to?
22/10/18
 Ty: *Typist*
 Date/Time, File Return to?

☐ : Preli. Report
☒ : Final Report

Days Of Repair: *6*
 Resurvey No. of Trip: *2*

Survey Fee: _____
 Transportation: _____
) \$ + R5. _____
) Photos _____
) Other _____

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Report Format :

Lump Sum / I.B.I: (\$) *3,268.62 p/r*

TOTAL

220



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18010307/T1sd3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 06-06-2018

Code : CTI



Policy Particulars :- THIRD PARTY CLAIM

1.

Insured Veh.	GBD 6864P	Veh. Inspected	SLM 2193C
Policy No.	DMCVSN3015231802	Coverage (\$)	0.00
Claim No.	SNM18D02818C02	Excess (\$)	0.00
Assign From	MERIMEN (CHONG BOON SEN)	Assign Date	06/06/2018

Vehicle Particulars & Condition

2.

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer		Steering
Brakes		Modification
General		

Conditions of Tyres

3.

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

Description of Damages

4.

--	--

General Information

5.

Accident Date	05/06/2018	Inspection Date	06/06/2018
Survey held at	74 KIAN TECK ROAD		
Repairer	PEGASUS ENGINEERING & TRADING PTE LTD		

Remarks

5a.

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Jun 2018		06 Jun 2018 14:21 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	HONG LAM MARINE PTE LTD		
Main Claimant:	GRAB RENTALS PTE LTD		
Vehicle Reg. No.:	SLM2193C	Date of Loss:	05/06/2018 14:00 - :59
Claim Type:	TP / SNM18D02818C02	Policy/Cover Note No.:	DMCVSN3015231802
Vehicle Reg. No. (Insured):	GBD6864P	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Pegasus Engineering & Trading Pte Ltd - Kian Teck Road (HQ) 74 KIAN TECK ROAD, 628800 Pioneer - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 18/06/2018]		
Adj Asg. Remarks:	Appoint Marcus Chua as SJE.		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	7200G
Vehicle Details	
Vehicle No.:	SLM2193C
Vehicle to be Exported:	Yes
Intended De-registration Date:	05 Jun 2018
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS 1.5E CVT
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	2NRX141114
Chassis No.:	MHFB29F3802009143
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$12,946.00
Original Registration Date:	24 Mar 2017
First Registration Date:	24 Mar 2017
Transfer Count:	0
Actual ARF Paid:	\$7,946.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Mar 2027
PARF Rebate Amount:	\$5,959.00
Intended COE Rebate Details	
COE Expiry Date:	23 Mar 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,101.00
COE Rebate Amount:	\$40,080.00
Total Rebate Amount:	\$46,039.00

The information contained herein is correct as at 05 Jun 2018

OK

Shirley Hiew (LKK Auto)

From: lionelchua@pegasusengrg.com.sg
Sent: Monday, 22 October 2018 12:12 PM
To: Shirley Hiew (LKK Auto); 'Pegasus Engineering'
Cc: Admin-D (LKKAuto); Admin A; lionelchua@pegasusengrg.com.sg
Subject: RE: SLM2193C TP-China Taiping (DOA-05/06/2018) Finalised on a Without Prejudice basis

Dear Shirley,

On a Without Prejudice Basis,

Finalisation for SLM 2193C confirmed.

Cost of Repairs based on Part by Part - \$3,268.62 (before GST)
Number of Repair Days - 06 Days.

Thanks & Regards,

Lionel Chua
Pegasus Engineering & Trading Pte Ltd
74 Kian Teck Road
Singapore 628800

Tel : 6513 7749
Fax : 6251 3161

Email : lionelchua@pegasusengrg.com.sg

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 2 October 2018 4:42 PM
To: 'Pegasus Engineering' <ar_claims@pegasusengrg.com.sg>
Cc: 'Admin-D (LKKAuto)' <admin-d@lkkauto.com>; 'Admin A' <admin-a@lkkauto.com>;
lionelchua@pegasusengrg.com.sg
Subject: RE: SLM2193C TP-China Taiping (DOA-05/06/2018) Finalised on a Without Prejudice basis

Hi Lionel,

Please Confirm final fig of \$3,268.62 (part by part) @ 6 days of repairs before GST.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Pegasus Engineering [mailto:ar_claims@pegasusengrg.com.sg]
Sent: Monday, 24 September 2018 5:02 PM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Cc: Admin-D (LKKAuto) <admin-d@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Lionel Chua <lionelchua@pegasusengrg.com.sg> <lionelchua@pegasusengrg.com.sg>
Subject: Re: SLM2193C TP-China Taiping (DOA-05/06/2018) Finalised on a Without Prejudice basis

Hi Shirley,

Enclosed with before paint photos.

Thank You

Best Regards,

Pegasus Engineering & Trading Pte Ltd
74 Kian Teck Road S628800
Office: 65137748
Fax: 62513161

On Mon, Sep 24, 2018 at 4:38 PM Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com> wrote:

Hi Lionel,

Kindly send us the resurvey before paint photo.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Pegasus Engineering <ar_claims@pegasusengrg.com.sg>
Sent: Monday, 24 September 2018 3:20 PM

To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>; Pegasus Engineering <ar_claims@pegasusengrg.com.sg>; Lionel Chua <lionelchua@pegasusengrg.com.sg> <lionelchua@pegasusengrg.com.sg>
Subject: SLM2193C TP-China Taiping (DOA-05/06/2018) Finalised on a Without Prejudice basis

Dear Taufikh,

Please find the calculation for your confirmation.

Part by Part repair \$3,418.62 and 8 days repair.

The attached copies of the documents for your attention.

Thank You

Best Regards,

Lionel Chua

Pegasus Engineering & Trading Pte Ltd

74 Kian Teck Road S628800

Office: 65137748

Fax: 62513161



Virus-free. www.avast.com

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GlA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/06/2018 16:57
Date Of Accident	05/06/2018 14:10
Exact Location Of Accident	ALONG TUAS ROUNDABOUT EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLM2193C
Insured/Policyholder	
Name Of Registered Owner	GRAB RENTALS PTE LTD
Co Reg No	201617200G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66550005

Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS 1.5E CVT
Exact Purpose for which vehicle was being used at time of accident	HIRE & REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	A29069766MKF
Cover Note Number	N.A

Driver

Name of Driver	RICKY TEO CHOON PENG
NRIC No	S8007918D
Date Of Birth	19/03/1980
Occupation	OUTDOOR
Date Of Driving Pass	20/06/2012
Driving Experience	5 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81008308
Fax Number	
Contact Number	
Email Address	FATTYRICZ@GMAIL.COM

Address	HDB BENDEMEER LIGHT, 10B BENDEMEER ROAD #12-121
Postcode	332010
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - ROUNDABOUT
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : BERNARD LIM
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I SLM2193C was driving along AYE Tuas wanted to go to Kian Teck road, while driving along the round about wanted to exit to pioneer rd North. As I miss the exit I make one more turn at the 2nd lane, suddenly the other 3rd party GBD6864P from the 1st lane cut onto my lane with a high speed to make an exit to JLN Ahmad Ibrahim. As the other party cut onto my lane the other party rear left tail had a contact onto my right front bumper and pull my vehicle to the side. The other party did not stop at that point of time until I sound a horn for a quite long time, so he stopped at JLN AHAMED IBRAHIM side road. I ask him for his IC and licences to exchange our particular when he went back to his lorry he start his lorry and run. We did not manage to exchange our particular, but I had a video clip on my vehicle when incident happened. No injuries as for now.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	YES - RETRIEVING
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBD6864P
Vehicle Make/Model/Colour	KIA K2500 6M/T / BLU
Details Of Properties	NIL
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

Sketch Plan

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers to the Insurers of the GIA Reports Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of the report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available as stated.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


VERIFIED BY AJAX MARS
REPORTING OFFICER
MUHAMMAD SUMARDI BIN
MOHD AFFANDI

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
Personnel

Sketch Plan



ACCIDENT STATEMENT (2000 characters)

I SLM2193C was driving along aye Tuas wanted to go to Kian Teck road, while driving along the round about wanted to exit to pioneer rd North .As I miss the exit I make one more turn at the 2nd lane, suddenly the other 3rd party GBD6864P from the 1st lane cut onto my lane with a high speed to make an exit to JLN Ahmad Ibrahim. As the other party cut onto my lane the other party rear left tail had a contact onto my right front bumper and pull my vehicle to the side. The other party did not stop at that point of time until I sound a horn for a quite long time, so he stopped at JLN AHAMED Ibrahim side road. I ask him for his IC and licences to exchange our particular when he went back to his lorry he start his lorry and run. We did not manage to exchange our particular, but I had a video clip on my vehicle when incident happened. No injuries as for now.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MUHAMMAD SUMARDI BIN MOHD AFFANDI

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

5 June 2018 4:42 pm

Date/Time:

5 June 2018 4:42 pm

PEGASUS **ENGINEERING & TRADING PTE LTD**

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : ALVIN LOW WAI LUN Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :
---	---

Quotation No : QO18/06-1050	Quotation Date : 06/06/2018	Terms : 30 DAYS
Vehicle No : SLM2193C	Chassis No : MHFB29F3802009143	Third Party Insurer :
Model : VIOS	Date of Accident :	
Remarks : TP INSURER: CHINA TAIPING, INSURED'S VEHICLE NO: GBD6864P, DATE OF ACCIDENT: 05.06.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	FRONT BUMPER	1	427.9000	de 427.90
2	O/S FRONT BUMPER SIDE RETAINER	1	65.7000	ner 65.70
3	O/S FRONT BUMPER SPOT LAMP GARNISH	1	56.6000	? 56.60 xnn
4	O/S FRONT BUMPER LOWER SPLASHIELD COVER	1	209.1000	de 209.10
5	O/S FRONT FENDER	1	612.7000	bt 612.70
6	FRONT FENDER INNER COWLING	1	288.0000	de 288.00
7	FRONT FENDER INNER COWLING CLIPS	4	4.3000	ner 17.20
8	O/S FRONT FENDER 1/4 GARNISH TOP	1	30.7000	? 30.70 xnn
9	FRONT FENDER INSULATION FOAM	1	38.0000	ner 38.00
10	O/S HEAD LAMP	1	588.1000	cut 588.10
11	O/S FRONT SHOCK ABSORBER	1	378.7000	? 378.70
12	O/S FRONT SHOCK TOP MOUNT	1	82.3000	? 82.30
13	O/S FRONT WHEEL KNUKLE	1	549.6000	? 549.60
14	FRONT WHEEL BEARING WITH HUB	1	492.8000	? 492.80
15	FRONT LOWER ARM	1	1,012.9000	? 1,012.90
16	STEERING RACK AND PINION	1	1,620.7000	X 1,620.70
17	O/S DRIVE SHAFT	1	1,295.7000	X 1,295.70
18	DRIVE SHAFT OIL SEAL	1	21.1000	X 21.10
19	FRONT ANTI ROLL BAR	1	413.0000	X 413.00
20	FRONT ANTI ROLL BAR LINK	2	27.5000	X 55.00
21	FRONT ANTI ROLL BAR BUSHING	1	27.0000	X 27.00
22	FRONT SUPPORT PANEL	1	494.8000	Rx 494.80
23	BONNET	1	757.3000	Rx 757.30

C/F 0.00

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : ALVIN LOW WAI LUN Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :
---	---

Quotation No : QO18/06-1050	Quotation Date : 06/06/2018	Terms : 30 DAYS
Vehicle No : SLM2193C	Chassis No : MHFB29F3802009143	Third Party Insurer :
Model : VIOS	Date of Accident :	
Remarks : TP INSURER: CHINA TAIPING, INSURED'S VEHICLE NO: GBD6864P, DATE OF ACCIDENT: 05.06.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
24	LESS 25% ITEM (1-23)	1	-2,383.7250	-2,383.72
25	O/S FRONT WHEEL RIM	1	323.6000	323.60
26	O/S FRONT WHEEL TYRE	1	220.0000	220.00
27	TO CHECK ELECTRICAL LIGHTING CONCERNED.	1	60.0000	60.00
28	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	1	150.0000	150.00
29	TO DROP FRONT SUSPENSION UNDERCARRIAGE PARTS, REMOVE AND RENEWAL OF THE NECESSARY PARTS, TO PERFORM FINAL CHECKING AND TESTING.	1	450.0000	450.00
30	TO RUST-PROOFING OF THE AFFECTED AREAS.	1	80.0000	80.00
31	TO TRANSFER OF TYRE, RIM AND ON WHEEL BALANCING.	1	30.0000	30.00
32	TO DISMANTLE AIR-CON ASSY, REMOVE AND RENEWAL OF PARTS, VACUUM AND CHARGE-IN GAS.	1	180.0000	180.00
33	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	1	800.0000	800.00
34	PUTTY AND SPARY PAINTING OF THE AFFECTED PORTION.	1	900.0000	900.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Please conduct the survey at
Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216

Signature:
Date:

Tan Lim 97495349

6/6/18 @ 1730

6 days

Resurvey before/after paint

sure lkkauto.com

To check p/p / 4/5 repair

Sub Total 10,344.78
GST(7.00%) 724.13
Total (SGD) 11,068.91

[Handwritten Signature]
12/6/18

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18010307/T1SD3N2
Date: 22/10/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3015231802
Claimant Vehicle No :	SLM2193C	Insured Vehicle No :	GBD6864P
Date of Loss:	05/06/2018	Nature of Claim:	TP
		Claim No:	SNM18D02818C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLM2193C	Engine No:	2NRX141114
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Chassis No:	MHFB29F3802009143
Reg. Date:	24/03/2017 (Man. Year: 2017)	Odometer:	90998 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/50 R16	Rear Tyre Size:	195/50 R16
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,694.77	2,008.62	5,686.15	73.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,650.00	1,260.00	1,390.00	52.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,344.77	3,268.62	7,076.15	68.40
+ GST 7.00/7.00% (S\$)	724.13	228.80	495.33	68.40
Nett Amount (S\$)	11,068.90	3,497.42	7,571.48	68.40

INSPECTION

Date of Assignment:	06/06/2018	
Date Inspected:	06/06/2018	Inspected At: Pegasus Engineering & Trading Pte Ltd (Kian Teck) 74 Kian Teck Road Singapore 628800

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 22 Oct 2018)
Parts: 143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLM2193C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Deformed	427.90 FL	*427.90 FL
2	1	*O/S FRONT BUMPER SIDE RETAINER	Necessary	65.70 FL	*65.70 FL
3	1	*O/S FRONT BUMPER SPOT LAMP GARNISH	Not Necessary	56.60 FL	*- FL
4	1	*O/S FRONT BUMPER LOWER SPLASHIELD COVER	Deformed	209.10 FL	*209.10 FL
5	1	*O/S FRONT FENDER	Bent	612.70 FL	*612.70 FL
6	1	*FRONT FENDER INNER COWLING	Deformed	288.00 FL	*288.00 FL
7	4	*FRONT FENDER INNER COWLING CLIPS	Necessary	17.20 FL	*17.20 FL
8	1	*O/S FRONT FENDER 1/4 GARNISH TOP	Not Necessary	30.70 FL	*- FL
9	1	*FRONT FENDER INSULATION FOAM	Necessary	38.00 FL	*38.00 FL
10	1	*O/S HEAD LAMP	Cracked	588.10 FL	*588.10 FL
11	1	*O/S FRONT SHOCK ABSORBER	Not Necessary	378.70 FL	*- FL
12	1	*O/S FRONT SHOCK TOP MOUNT	Not Necessary	82.30 FL	*- FL
13	1	*O/S FRONT WHEEL KNUCKLE	Not Necessary	549.60 FL	*- FL
14	1	*FRONT WHEEL BEARING WITH HUB	Not Necessary	492.80 FL	*- FL
15	1	*FRONT LOWER ARM	Not Necessary	1,012.90 FL	*- FL
16	1	*STEERING RACK AND PINION	Not Necessary	1,620.70 FL	*- FL
17	1	*O/S DRIVE SHAFT	Not Necessary	1,295.70 FL	*- FL
18	1	*DRIVE SHAFT OIL SEAL	Not Necessary	21.10 FL	*- FL
19	1	*FRONT ANTI ROLL BAR	Not Necessary	413.00 FL	*- FL
20	2	*FRONT ANTI ROLL BAR LINK	Not Necessary	55.00 FL	*- FL
21	1	*FRONT ANTI ROLL BAR BUSHING	Not Necessary	27.00 FL	*- FL
22	1	*FRONT SUPPORT PANEL	Repair	494.80 FL	*- FL
23	1	*BONNET	Repair	757.30 FL	*- FL
24	1	*O/S FRONT WHEEL RIM	Cut	323.60 FS	*323.60 FS
25	1	*O/S FRONT WHEEL TYRE	Not Necessary	220.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,078.50	2,570.30
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,383.73	561.68
Total Parts (\$\$)	7,694.77	2,008.62

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	60.00	30.00
2	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	150.00	80.00
3	TO DROP FRONT SUSPENSION UNDERCARRIAGE PARTS,REMOVE AND RENEWAL OF THE NECESSARY PARTS,TO PERFORM FINAL CHECKING AND TESTING	New	450.00	-
4	TO RUST-PROOFING OF THE AFFECTED AREAS	New	80.00	30.00
5	TO TRANSFER OF TYRE,RIM AND ON WHEEL BALANCING	New	30.00	20.00
6	TO DISMANTLE AIR-CON ASSY,REMOVE AND RENEWAL OF PARTS,VACUUM AND CHARGE-IN GAS	New	180.00	-
7	PANEL BEATING,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	800.00	500.00
8	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	900.00	600.00
Gross Labour Cost (\$\$)			2,650.00	1,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >