

ASS. REC. BY:

REF:

CS/CTI18010319/ A9d36

Special Instruction:

Surveyor
Maximen

Adrian

ASSIGNMENT (Office)

From (Person):

Elaine cheong

of

CTI

Date/Time:

06/06/18 @ 10:46am

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLB 51664

Insured:

SLM 215L

at Workshop m/s

Borneo Motors

Tel:

9847 6209

of

17 Ubi Road 4

Policy No:

DMPCSN1719331801

Claim No:

SNM18D02812C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

04/06/2018

CA / REV / REP. / REV 24 HRS ^(up)

H.O.D. Endorsement:

Date/Time:

2/6pm @ 6/6/18

Person Contacted:

Sam

Vehicle IN ☒ OUT

Date/Time	Action/Instruction (✓) Estimate
	SLB 51664 - X
	SLM 215L - X
19/6/18 @ 3:03pm	confirmed with Sam final fig \$1308.12, 7 days. (Red. to 5285.40, 29%)

REF: CT1

ASSIGNMENT

From: Date: 11-06-2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLB 5166U

at Workshop m/s Borneo Motor

of 17 Ubi Rd 4

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh: Sam

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 07 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLB 5166U

Yr Regn: 2016 April

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Wish

C.C.

1788

Colour: White

A/C: Insured / Std / NI / NA

Sp. Reading: 39032

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JTDG620W30J003978

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

F:

195/65R15

R:

195/65R15.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

11/06/18

Survey held at

Borneo (Ubi)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Chuan.

RECEIVED 19 SEP 2018

Date/Time, File Pass to?



Preli. Report

1) 19/09/2018



Final Report

Date/Time, File Return to?

2)

Days Of Repair: 7

Resurvey No. of Trip: 1

Survey Fee

220

Transportation

) S + RS SI

) Photos

) Others

TOTAL

220

Add Fee:



Site Insp (\$



Interview (\$



Tech Invs (\$



Weekend (\$

Report Format: MER-TP

Lump Sum / I.B.I: (\$ 1308.12)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18010319/Aqd3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 06-06-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLM 215L	Veh. Inspected	SLB 5166U
Policy No.	DMPCSN1719331801	Coverage (\$)	0.00
Claim No.	SNM18D02812C02	Excess (\$)	0.00
Assign From	MERIMEN (ELAINE CHEONG)	Assign Date	06/06/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	04/06/2018	Inspection Date
Survey held at	BORNEO MOTORS (S) PTE LTD 17 UBI ROAD 4 SINGAPORE 408611	

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Jun 2018		06 Jun 2018 10:46 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	SIM YEOW KIM DENNIS, ID: S7518014D		
Vehicle Reg. No.:	SLB5166U	Date of Loss:	04/06/2018 08:00 - :59
Claim Type:	TP / SNM18D02812C02	Policy/Cover Note No.:	DMPCSN1719331801
Vehicle Reg. No. (Insured):	SLM215L	Policy No. (Claimant):	VPA/P2069808
		Excess:	\$750.00
Repairer:	Borneo Motors (S) Pte Ltd (Ubi) 17 Ubi Road 4, 408611 Ubi - Tel: 6631 1868		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 18/06/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 19 September 2018 3:03 PM
To: 'Sam San Joi UBI'; SUR
Subject: RE: photos SLB5166U

Dear Sam,

WITHOUT PREJUDICE

Confirm final fig \$13,108.12 before GST and 7 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sam San Joi UBI <SanJoi.Sam@borneomotors.com.sg>
Sent: Monday, 17 September 2018 8:01 AM
To: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: photos SLB5166U

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/06/2018 11:11
Date Of Accident	04/06/2018 08:05
Exact Location Of Accident	UBI ENTERING KPE TUNNEL
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLB5166U
Insured/Policyholder	
Name Of Registered Owner	SIM YEOW KIM DENNIS
NRIC No	S7518014D
Email Address	DS1MYK@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97930140
Alternative Phone No	OFFICE-97930140

Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VPA/P2069808
Cover Note Number	

Driver

Name of Driver	SIM YEOW KIM DENNIS
NRIC No	S7518014D
Date Of Birth	17/06/1975
Occupation	INDOOR
Date Of Driving Pass	21/06/1997
Driving Experience	20 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97930140
Fax Number	
Contact Number	OFFICE-97930140
EMail Address	DS1MYK@GMAIL.COM

Address	27 YIO CHU KANG RD
Postcode	545542
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER AS ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLM215L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TAN LEE LEE
NRIC/Passport Number	S7220556A
Contact Number	98255688
Address	14 PARKSTONE RD
Postcode	437659
Insurance Company Name	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

TYPE OF CLAIM: ☐ OD ☐ OD/UL ☒ DS

MCA: Sam

MOTOR ACCIDENT REPORT

Date Of Report: 4/6/2018 Time: Date Of Accident: 4/6/2018 Time: 0802H.

Exact Location Of Accident: UBI entering KPE tunnel.

Country/State of Loss: Singapore ☐ / Wilayah Persekutuan ☐ / Selangor Darul Ehsan ☐ / Negeri Sembilan ☐ / Melaka ☐ / Pahang ☐ / Johor ☐ / Perak ☐ / Kedah ☐ / Kelantan ☐ / Terengganu ☐ / Pulau Pinang ☐ / Perlis ☐ / Thailand ☐

OWN VEHICLE DETAILS (INSURED/POLICY HOLDER)

Vehicle Registration Number: SLB 5166U Co. Reg. No(for Co. Vehicle)/NRIC/PP/FIN No:

Name Of Registered Owner: SIM YEOW KIM, DENNIS

Mobile Number: 97930140 Alternative No: Email Address: ds1myk@gmail.com.

Manufacturer: Toyota ☒ Lexus ☐ Suzuki ☐ Hino ☐ Model: WISHExact Purpose for which vehicle was being used at time of accident: Normal Usage ☒ Other ☐ (please specify):Are you claiming under your own insurance policy for repair to your vehicle? Yes ☐ Reporting Only ☐ Third Party ☒Vehicle Category: Private Car ☒ Commercial Vehicle ☐ Others ☐

Name of Insurance Company: AXA

Type Of Coverage: Comprehensive ☒ Third Party ☐ Third Party Fire and/or Theft ☐Fleet Policy: Yes ☐ No ☒ Policy / Cover Note No: VPA/P2069808

DRIVER DETAILS AT POINT OF ACCIDENT

Name of Driver: SIM YEOW KIM DENNIS NRIC/Passport / FIN No: S7518014D

Date Of Birth: 17/6/1975 Occupation: Indoor ☒ Outdoor ☐Date Of Driving Pass: 21/6/1997 Gender: Male ☒ Female ☐

Mobile Number: 97930140 Fax No: Alternative No:

Address: 27 YIO CHU KANG ROAD Postal Code: 545542

Email Address: ds1myk@gmail.com.

Was driver an employee of the Insured's Company? Yes ☐ No ☒ State relationship of the driver with the insured:

Vehicle Registration Number of Driver's Own Vehicle (if applicable):

Insurance Company of Driver's Own Vehicle (if applicable):

GENERAL INFORMATION OF THE ACCIDENT

Type Of Accident: Rear End Collision

Number of Passengers in the above vehicle (including Driver): 1 / If more than 2 Pax Please fill ANNEX B

PASSENGER 1

Name: Gender: Male ☐ Female ☐Weather Conditions: Clear ☐ Raining ☐ Others ☐ (If others, please state condition):Road Surface: Wet ☐ Dry ☒ Others ☐ (If others, please state condition):Was any body injured in the Accident? No ☒ Yes ☐Was any injured conveyed to hospital by ambulance? No ☐ Yes ☐Was any foreign vehicle involved in this accident? No ☐ Yes ☐ Vehicle No: Vehicle type:

Number of vehicles involved in the accident: 2

Was there any witness? No ☒ Yes ☐Was there any other vehicle or property damaged? No ☐ Yes ☐Was there any video captured by Car Camera? No ☐ Yes ☐ Are accident scene photos available for attachment? No ☐ Yes ☒Was the accident reported to the police? No ☒ Yes ☐ (If yes, please state which Police Station):Was notice of intended Prosecution given? No ☐ Yes ☐ (If yes, please state against whom):I have been approached by unknown person(s) soliciting/offering accident claims assistance. No ☒ Yes ☐

DETAILS OF OTHER VEHICLE PROPERTY 1 (Please fill Annex A if more vehicles involved)

Vehicle Registration Number: SLM 215L Vehicle Make/Model/Colour:

Details Of Properties Damage In Accident:

Vehicle Category:

Name of Driver: TAN LEE LEE

NRIC/Passport/FIN Number: S7220556A Contact Number: 98255688

Address: 14 PARKSTONE ROAD SINGAPORE 437659. Postal Code: 437659.

Insurance Company Name:

Nature Of Damage: No. Of Passenger (including Driver):

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;


(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.


(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time

4/6/2018



Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

To KPE Tunnel . Down slope .

→




Describe Circumstances of the Accident


Was entering the KPE tunnel at UPI entrance.
Slow moving as heavy traffic entering.
Vehicle behind bang into my back of the car. w

Declaration

We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date & Time
4/6/2018

Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

AXA INSURANCE PTE LTD
8 Shenton Way, #24-01
AXA Tower, Singapore 068811
Customer Service Centre #B1-01
Tel:(65)63387288 Fax:(65)63382522
Website:www.axa.com.sg
GST Registration Number: 199903512M
customer.service@axa.com.sg



CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act. (Chapter 189) Motor Vehicles (Third-Party Risks and Compensation) Rules. 1960 Road Transport Act. 1987 (Malaysia) Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

CERTIFICATE NO. : VPA/P2069808 Account No. : 14888
Coverage : Comprehensive (SmartDrive Toyota Prestige)
Sum Insured : Market Value At The Time Of Loss
Name of Policy Holder : SIM YEOW KIM
Vehicle Registration No. : SLB5166U
Period of Insurance : From 12/04/2018 To 11/04/2020 (Both Dates Inclusive)

PERSONS OR CLASSES OF PERSONS ENTITLED TO DRIVE*

(a) The Policyholder

The Policyholder may also drive a Motor Car not belonging to or not hired (under a hire purchase agreement or otherwise) to him or his employer or his partner

(b) Any other person who is driving on the Policyholder's order or with his permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

LIMITATIONS AS TO USE*

Use only for social, domestic and pleasure purposes and for the Policyholder's business. The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speedtesting, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

(01)

Basic Own Damage Excess : SGD 500.00

An Additional Excess is applicable as follows:

S\$2,500.00 for Young or Inexperienced Driver.

Young or Inexperienced Driver is defined as any driver whom is aged below 23 years old and/or less than one year of driving experience.

(Please refer to your policy on the terms & conditions)* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA INSURANCE PTE LTD


Authorized Signature

Issued by - SGOAGPH on 13/02/2018

IMPORTANT :

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation Act (Cap. 189). The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, covernote and endorsement etc.

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: **S7518014D**

Name:

**SIM YEOW KIM DENNIS
(SHEN YAOJIN DENNIS)**

Birth Date: **17 Jun 1975**

Issue Date: **14 Apr 2003**



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S7518014D**



Name

**SIM YEOW KIM DENNIS
(SHEN YAOJIN DENNIS)**

沈 耀 金

Race

CHINESE

Date of birth

17-06-1975

Sex

M

Country of birth

SINGAPORE

S7518014D


YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3

Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE

21 Jun 1997



Licence No: **S7518014D**

NP 428A

3729188



HRIC No. **S7518014D**



Date of issue

17-06-2005

**27 YIO CHU KANG ROAD #04-03
SINGAPORE 545542**

S7518014D

26/01/2014



Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sgCo Reg No : 196700086Z
GST Reg No : MR-8500000-9**ESTIMATE**Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!Toyota Bodycare Centre
17 Ubi Road 4,
Singapore 409611
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1 Document No 0 Document Date 07/06/2018	Mr Sim Yeow Kim 27 Yio Chu Kang Road #04-03 Singapore 545542 Mobile: 97930140

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	HPXNP	S6	ZGE20R	12/04/2016	SLB5166U	36087	16567 67/DS/SLB5166U
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTDGG20W30J003978	2ZR1753397	60	Sam San Joi	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY TP INS:CHINA TAIPENG INSURANCE TP VEH: SLM215L DATE OF ACC: 04.06.2018 NO.OF REPAIR: SURVEY BY:				✓ 50.00
2	S	BP-SUBLET SUPPLY JOINT PANEL SEALANT (NETT)				160 200.00 ✓
3	S	BP-SUBLET DRILL HOLE AND INSTALL REVERSE SENSOR (NETT)				✓ 169.50
4	S	BP-SUBLET REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR (NETT)				✓ 678.00
5	S	BP-SUBLET CHECK WIRING AND CONDUCT WATER TEST (NETT)				✓ 169.50
6	S	BP-SUBLET REPLACE TAILGATE GLASS (NETT)				✓ 496.00
7	S	BP-SUBLET REMOVE AND TRANSFER TAILGATE COMPONENTS ONTO NEW TAILGATE (NETT)				✓ 339.00
8	S	BP-SUBLET R/I REAR REVERSE CAMERA TO FAC REPAIR (NETT)				✓ 339.00
9	S	BP-SUBLET R/I TAILGATE SPOILER TO FAC REPAIR (NETT)				✓ 127.12

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3691522

TO SECURITY GUARD

3691522

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 07/06/2018
TIME 16:28

VEHICLE NO

SLB5166U

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**



Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sgCo Reg No : 196700086Z
GST Reg No : MR-8500000-9**ESTIMATE**Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no: 6631-1188

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	Mr Sim Yeow Kim 27 Yio Chu Kang Road #04-03 Singapore 545542 Mobile: 97930140
	Document No 0	
	Document Date 07/06/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	HPXNP	S6	ZGE20R	12/04/2016	SLB5166U	36087	16567 67/DS/SLB5166U
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTDGG20W30J003978	2ZR1753397	60	Sam San Joi	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
10	S	BP-SUBLET REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS				1695 3390.00
11	S	BP-SUBLET RESPRAY ACC AFFECTED AREAS				1668 3336.00
12	B	BP-ECU TO RESET ECU AND REPROGRAMME (NETT)				✓ 678.00
13	L	BP-LPO SUPPLY REGN PLATE (PO#) (NETT) Bent				✓ 80.00
14	L	BP-LPO SUPPLY 3M SOLAR FILM (NETT)				✓ 480.00
15	1	T52159-68907 REAR BUMPER COVER, Replaced	1.00	574.90		✓ 574.90
16	2	S52161-0K040 CLIPS	10.00	3.90		✓ 39.00
17	3	T52156-68030 L/RR BUMPER SUPPORT, Replaced	1.00	93.90		X 93.90 X
18	4	T52576-68020 L/R SIDE BPR RETAINER, Replaced	1.00	44.40		✓ 44.40
19	5	T52155-68030 R/RR BUMPER SUPPORT, Replaced	1.00	93.90		X 93.90 X
20	6	T52575-68020 R/R SIDE BPR RETAINER, Replaced	1.00	44.40		✓ 44.40
21	7	T81910-13022 R/REAR BPR REFLECTOR, Replaced	1.00	58.00		✓ 58.00
22	8	T81920-13022 L/R BUMPER REFLECTOR, Replaced	1.00	58.00		✓ 58.00
23	9	T58307-68031 REAR LOWER FLR PANEL, Bent	1.00	520.00		✓ 520.00
24	0	T52181-68010 ARM, RR BUMPER, Replaced	1.00	52.10		X 52.10 X
25	1	T52181-68010 ARM, RR BUMPER, Replaced	1.00	52.10		X 52.10 X
26	2	T67935-68020 B0 PLATE BACK DOOR, Replaced	1.00	288.70		✓ 288.70
27	3	T58410-68020 B1 REAR DECK BOARD ASSY, Replaced	1.00	602.10		✓ 602.10

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3691523

TO SECURITY GUARD

3691523

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 07/06/2018
TIME 16:28

VEHICLE NO SLB5166U

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**

Co Reg No : 196700086Z
GS Reg No : MR-8500000-9**ESTIMATE**Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1 Document No 0 Document Date 07/06/2018	Mr Sim Yeow Kim 27 Yio Chu Kang Road #04-03 Singapore 545542 Mobile: 97930140

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	HPXNP	S6	ZGE20R	12/04/2016	SLB5166U	36087	16567 67/DS/SLB5166U
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
JTDGG20W30J003978	2ZR1753397	60	Sam San Joi	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
28	4	T58412-68020 B0 REAR BOARD DECK NO 2, <i>3 new</i>	1.00	93.30		+ 93.30
29	5	T58411-68020 B0 REAR BOARD DECK NO 1, <i>3 new</i>	1.00	93.30		+ 93.30
30	6	T67005-68041 PANEL ASSY, BACK DOOR <i>Painted</i>	1.00	1428.40		✓ 1428.40
31	7	T67881-68030 WEATHERSTRIP, BACK <i>new</i>	1.00	325.80		✓ 325.80
32	8	T68105-68071 REAR BACK DOOR GLASS, <i>new</i>	1.00	1009.20		✓ 1009.20
33	9	T69350-28151 LOCK ASSY, BACK DOOR <i>new</i>	1.00	399.60		x 399.60
34	0	T08826-08609 SUPER FAST URETHANE BLACK <i>3 new</i>	1.00	108.00		✓ 108.00
35	1	T08826-08682 SINGLE STEP PRIMER	1.00	200.00		✓ 200.00
36	2	T90975-02086 FRONT BONNET EMBLEM, <i>new</i>	1.00	72.20		✓ 72.20
37	3	T75444-68010 PLATE, LUGGAGE COMPT (VALVE MATI <i>new</i>	1.00	39.70		✓ 39.70
38	4	T81551-68062 LENS & BODY, RR <i>3 new</i>	1.00	344.00		+ 344.00
39	5	T81561-68062 LENS, RR COMB LH <i>3 new</i>	1.00	344.00		+ 344.00
40	6	T81581-68020 LENS & BODY, RR <i>3 new</i>	1.00	285.10		+ 285.10
41	7	T81591-68020 LENS & BODY, RR <i>3 new</i>	1.00	285.10		+ 285.10
42	8	T89997-30070 ELECTRICAL ANTENNA, <i>3 new</i>	1.00	160.60		? 160.60
43	9	SP2061-12010 16 070 SENSOR <i>3 new</i>	1.00	151.60		? 151.60

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 7,861.40 Labour 728.00 Materials 9,804.12 Lubrication/Fluid 0.00 Others 0.00	18,393.52 GST 7.00% 1,287.55 Less 0.00 Amount Due 19,681.07

PLEASE TEAR ALONG PERFORATED LINE.

3691524

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 07/06/2018
TIME 16:28Adrian Lj
P/P 06-08 Rys. 11/06/18
3691524

VEHICLE NO

SLB5166U

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Borneo Motors

TAX INVOICE

Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no.: 6631 1188

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909
Attn: Motor Claims Dept

S1000003/ICCI1

39006886

11/07/2018

Mr Sim Yeow Kim
27 Yio Chu Kang Road
#04-03
Singapore 545542
Mobile: 97930140

16 HPXNP S6 ZGE20R 12/04/2016 SLB5166U 39032 16567 67/DS/SLB5166U

JTDGG20W30J003978 2ZR1753397 60 Sam San Joi 04/06/2018 10.17 18/06/2018 14.23

1	Z	BP-SUNDRY	TP INS:CHINA TAIPENG INSURANCE		50.00
			TP VEH: SLM215L		
			DATE OF ACC: 04.06.2018		
			NO.OF REPAIR:8 DAYS		
			SURVEY BY:ADRIAN(LKK)		
2	S	BP-SUBLET	SUPPLY JOINT PANEL SEALANT (NETT)	A45	160.00
3	S	BP-SUBLET	DRILL HOLE AND INSTALL REVERSE SENSOR (N	A45	169.50
			ETT)		
4	S	BP-SUBLET	REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR	A45	678.00
			(NETT)		
5	S	BP-SUBLET	CHECK WIRING AND CONDUCT WATER TEST (NET	A45	169.50
			T)		
6	S	BP-SUBLET	REPLACE TAILGATE GLASS (NETT)	A45	496.00
7	S	BP-SUBLET	REMOVE AND TRANSFER TAILGATE COMPONENTS	A45	339.00
			ONTO NEW TAILGATE (NETT)		
8	S	BP-SUBLET	R/I REAR REVERSE CAMERA TO FAC REPAIR (N	A45	339.00
			ETT)		
9	S	BP-SUBLET	R/I TAILGATE SPOILER TO FAC REPAIR (NETT	A45	127.12
)		

11/07/2018
16:48

SLB5166U

TAX INVOICE

Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no.: 6631 1188

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909
Attn: Motor Claims Dept

S1000003 /ICCI1

39006886

11/07/2018

Mr Sim Yeow Kim
27 Yio Chu Kang Road
#04-03
Singapore 545542
Mobile: 97930140

16 HPXNP S6 ZGE20R 12/04/2016 SLB5166U 39032 16567 67/DS/SLB5166U

JTDGG20W30J003978 2ZR1753397 60 Sam San Joi 04/06/2018 10.17 18/06/2018 14.23

10	S	BP-SUBLET	REPLACE ACC DAMAGED PARTS	A45			2712.00
			AND STRAIGHTEN/REALIGN				
			ACC AFFECTED AREAS				
11	S	BP-SUBLET	RESPRAY ACC AFFECTED AREAS	A45			2224.00
12	B	BP-ECU	TO RESET ECU AND REPROGRAMME (NETT)	18			678.00
13	L	BP-LPO	SUPPLY REGN PLATE (PO#) (NETT)	E33			80.00
14	L	BP-LPO	SUPPLY 3M SOLAR FILM (NETT)	M30			480.00
15	1	T52159-68907	COVER RR BUMPER	1.00	574.90		574.90
16	2	S52161-0K040	PIECE,RR BUMPER	10.00	3.90		39.00
17	3	T52576-68020	RETAINER RR BUMPER	1.00	44.40		44.40
18	4	T52575-68020	RETAINER RR BUMPER	1.00	44.40		44.40
19	5	T67005-68041	PANEL ASSY,BACK DOOR	1.00	1428.40		1428.40
20	6	T67881-68030	WEATHERSTRIP, BACK	1.00	325.80		325.80
21	7	T08826-08609	SUPER FAST URETHANE BLACK	1.00	108.00		108.00
22	8	T08826-08682	SINGLE STEP PRIMER	1.00	200.00		200.00
23	9	T90975-02086	EMBLEM,SYMBOL	1.00	72.20		72.20
24	0	T75444-68010	PLATE, LUGGAGE COMPT	1.00	39.70		39.70
25	1	T68105-68071	GLASS BACK DOOR	1.00	1009.20		1009.20
26	2	T58307-68031	PANEL LAMP LOWER	1.00	520.00		520.00

13,108.12

4,406.00 GST 7.00% 917.57

728.00 0.00

7,974.12 0.00

0.00

0.00

14,025.69

PLEASE MAIL YOUR CHEQUE TO 2 PANDAN CRESCENT, LEVEL 10 INCHCAPE CENTRE, SINGAPORE 128462

11/07/2018

16:48

SLB5166U

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Jun 2018		06 Jun 2018 10:46 Edit Adj Rpt	S\$13,108.12 Edit Estimates	S\$13,108.12 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	-, Co. Reg. No.: -								
Main Claimant:	SIM YEOW KIM DENNIS , ID: S7518014D								
Vehicle Reg. No.:	SLB5166U	Date of Loss:	04/06/2018 08:00 - :59 [25 Months and 23 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D02812C02	Policy/Cover Note No.:	DMPCSN1719331801						
Vehicle Reg. No. (Insured):	SLM215L	Policy No. (Claimant):	VPA/P2069808						
		Excess:	S\$750.00						
Repairer:	Borneo Motors (S) Pte Ltd (Ubi) 17 Ubi Road 4, 408611 Ubi - Tel: 6631 1868								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 18/06/2018]								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/>		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									




















Claim Documents

***SLB5166U (SNM18D02812C02)**
[SLM215L]
TP
SIM YEOW KIM DENNIS
Jun 4 2018 8:00AM
[-]
Borneo Motors (S) Pte Ltd

Upload Documents Upload Photos Compose New Letter			View <input type="button" value="View in Browser"/>	
Photos/Images			3 per page <input type="button" value="3"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/09/18 13:51	General View	Load JPG	<input checked="" type="checkbox"/>
2	18/09/18 13:51	General View	Load JPG	<input checked="" type="checkbox"/>
3	18/09/18 13:51	General View	Load JPG	<input checked="" type="checkbox"/>
4	18/09/18 13:51	General View	Load JPG	<input checked="" type="checkbox"/>
5	18/09/18 13:51	General View	Load JPG	<input checked="" type="checkbox"/>
6	18/09/18 13:51	General View	Load JPG	<input checked="" type="checkbox"/>
7	18/09/18 13:51	General View	Load JPG	<input checked="" type="checkbox"/>
8	18/09/18 13:51	General View	Load JPG	<input checked="" type="checkbox"/>
9	18/09/18 13:51	General View	Load JPG	<input checked="" type="checkbox"/>
10	18/09/18 13:51	General View	Load JPG	<input checked="" type="checkbox"/>
11	18/09/18 13:51	General View	Load JPG	<input checked="" type="checkbox"/>
12	18/09/18 13:51	General View	Load JPG	<input checked="" type="checkbox"/>
13	18/09/18 13:51	General View	Load JPG	<input checked="" type="checkbox"/>
14	18/09/18 13:51	General View	Load JPG	<input checked="" type="checkbox"/>
15	18/09/18 13:51	General View	Load JPG	<input checked="" type="checkbox"/>
16	18/09/18 13:51	General View	Load JPG	<input checked="" type="checkbox"/>
17	18/09/18 13:51	General View	Load JPG	<input checked="" type="checkbox"/>
18	18/09/18 13:51	General View	Load JPG	<input checked="" type="checkbox"/>
19	18/09/18 13:51	General View	Load JPG	<input checked="" type="checkbox"/>
20	18/09/18 13:51	General View	Load JPG	<input checked="" type="checkbox"/>
21	18/09/18 13:51	General View	Load JPG	<input checked="" type="checkbox"/>
22	18/09/18 13:51	General View	Load JPG	<input checked="" type="checkbox"/>
23	18/09/18 13:51	General View	Load JPG	<input checked="" type="checkbox"/>
24	18/09/18 13:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
25	18/09/18 13:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
26	18/09/18 13:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
27	18/09/18 13:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
28	18/09/18 13:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
29	18/09/18 13:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
30	18/09/18 13:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
31	18/09/18 13:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Borneo Motors (S) Pte Ltd (Ubi)	Thumbnail	Print
1	04/06/18 11:16	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Borneo Motors (S) Pte Ltd (Ubi)	Thumbnail	Print
1	04/06/18 11:16	Accident Scene Photo	 Load JPG	<input checked="" type="checkbox"/>
2	04/06/18 11:16	Accident Scene Photo	 Load JPG	<input checked="" type="checkbox"/>
3	04/06/18 11:16	Accident Scene Photo	 Load JPG	<input checked="" type="checkbox"/>
4	04/06/18 11:16	Accident Scene Photo	 Load JPG	<input checked="" type="checkbox"/>
5	04/06/18 11:16	TP IC	 Load JPG	<input checked="" type="checkbox"/>
6	04/06/18 11:16	TP IC	 Load JPG	<input checked="" type="checkbox"/>
7	04/06/18 11:16	Accident Scene Photo	 Load JPG	<input checked="" type="checkbox"/>
8	04/06/18 11:16	Accident Scene Photo	 Load JPG	<input checked="" type="checkbox"/>
9	04/06/18 11:16	Accident Scene Photo	 Load JPG	<input checked="" type="checkbox"/>
10	04/06/18 11:16	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	04/06/18 11:16	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	04/06/18 11:16	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	04/06/18 11:16	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
14	04/06/18 11:16	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Borneo Motors (S) Pte Ltd (Ubi)	Thumbnail	Print
1	04/06/18 11:16	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	04/06/18 11:16	Accident Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
3	04/06/18 11:16	CI	 Load JPG	<input checked="" type="checkbox"/>
4	04/06/18 11:16	IC	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118010319/AQD3E2

Date: 20/09/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN1719331801

Claimant Vehicle
No: SLB5166UInsured Vehicle
No: SLM215L

Date of Loss: 04/06/2018

Nature of Claim: TP

Claim
No: SNM18D02812C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLB5166U

Make & Model: TOYOTA WISH, 1.8 (A)

Engine No: 2ZR1753397

Reg. Date: 12/04/2016 (Man. Year: 2016)

Chassis No: JTDGG20W30J003978

Colour: White

Odometer: 39032 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Goodyear 6 mm

Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,471.40	5,016.00	3,455.40	40.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,922.12	8,092.12	1,830.00	18.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	18,393.52	13,108.12	5,285.40	28.74
+ GST 7.00/7.00% (S\$)	1,287.55	917.57	369.98	28.74
Nett Amount (S\$)	19,681.07	14,025.69	5,655.38	28.74

INSPECTION

Date of Assignment: 06/06/2018

Date Inspected: 11/06/2018 Inspected At:

Borneo Motors (S) Pte Ltd (Ubi)
17 Ubi Road 4
Singapore 408611

Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Sep 2018)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLB5166U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRY	Necessary	50.00 FS	*50.00 FS
2	1		*REGN PLATE (PO#)	Bent	80.00 FS	*80.00 FS
3	1		*3M SOLAR FILM	Necessary	480.00 FS	*480.00 FS
4	1		*REAR BUMPER COVER	Deformed	574.90 FS	*574.90 FS
5	10		*CLIPS	Necessary	39.00 FS	*39.00 FS
6	1		*L/RR BUMPER SUPPORT	Not Necessary	93.90 FS	*- FS
7	1		*L/R SIDE BPR RETAINER	Necessary	44.40 FS	*44.40 FS
8	1		*R/RR BUMPER SUPPORT	Not Necessary	93.90 FS	*- FS
9	1		*R/R SIDE BPR RETAINER	Necessary	44.40 FS	*44.40 FS
10	1		*R/REAR BPR REFLECTOR	Not Necessary	58.00 FS	*- FS
11	1		*L/R BUMPER REFLECTOR	Not Necessary	58.00 FS	*- FS
12	1		*REAR LOWER FLR PANEL	Dented	520.00 FS	*520.00 FS
13	1		*ARM, RR BUMPER	Not Necessary	52.10 FS	*- FS
14	1		*ARM, RR BUMPER	Not Necessary	52.10 FS	*- FS
15	1		*PLATE BACK DOOR	Not Necessary	288.70 FS	*- FS
16	1		*REAR DECK BOARD ASSY	Not Necessary	602.10 FS	*- FS
17	1		*REAR BOARD DECK NO 2	Not Necessary	93.30 FS	*- FS
18	1		*REAR BOARD DECK NO 1	Not Necessary	93.30 FS	*- FS
19	1		*PANEL ASSY, BACK DOOR	Dented	1,428.40 FS	*1,428.40 FS
20	1		*WEATHERSTRIP, BACK	Necessary	325.80 FS	*325.80 FS
21	1		*REAR BACK DOOR GLASS	Necessary	1,009.20 FS	*1,009.20 FS
22	1		*LOCK ASSY, BACK DOOR	Not Necessary	399.60 FS	*- FS
23	1		*SUPER FAST URETHANE BLACK	Necessary	108.00 FS	*108.00 FS
24	1		*SINGLE STEP PRIMER	Necessary	200.00 FS	*200.00 FS
25	1		*FRONT BONNET EMBLEM	Necessary	72.20 FS	*72.20 FS
26	1		*PLATE, LUGGAGE COMPT (VALVE MATI	Necessary	39.70 FS	*39.70 FS
27	1		*LENS & BODY, RR	Not Necessary	344.00 FS	*- FS
28	1		*LENS, RR COMB LH	Not Necessary	344.00 FS	*- FS
29	1		*LENS & BODY, RR	Not Necessary	285.10 FS	*- FS
30	1		*LENS & BODY, RR	Not Necessary	285.10 FS	*- FS
31	1		*ELECTRICAL ANTENNA	Not Necessary	160.60 FS	*- FS
32	1		*070 SENSOR	Not Necessary	151.60 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	8,471.40	5,016.00
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	DRILL HOLE AND INSTALL REVERSE SENSOR	New	169.50	169.50
2	REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR	New	678.00	678.00
3	CHECK WIRING AND CONDUCT WATER TEST	New	169.50	169.50
4	REPLACE TAILGATE GLASS	New	496.00	496.00
5	REMOVE AND TRANSFER TAILGATE COMPONENT ONTO NEW TAILGATE	New	339.00	339.00
6	R/I REAR REVERSE CAMERA TO FAC REPAIR	New	339.00	339.00
7	R/I TAILGATE SPOILER TO FAC REPAIR	New	127.12	127.12
8	REPLACE ACC DAMAGED PARTS AND STRAIGHTEN / REALIGN ACC AFFECTED AREAS	New	3,390.00	2,712.00
9	RESPRAY ACC AFFECTED AREAS	New	3,336.00	2,224.00
10	TO RESET ECU AND REPROGRAMME	New	678.00	678.00
11	SUPPLY JOINT PANEL SEALANT	New	200.00	160.00
Gross Labour Cost (S\$)			9,922.12	8,092.12

Report was unsubmitted during this print-out.

< END OF ESTIMATES >