

22/03/2002

ASS. REC. BY:

REF: CS/MSG18010355/Ard361 Special Instruction:

Surveyor:
Menmen

Adrian

ASSIGNMENT (Office)

From (Person):

Jasmine Lok

of

MSG

Date/Time:

7/6/18 @ 9:34am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLN 3864M

Insured:

SGC 154R

at Workshop m/s

Siang Hui Motor

Tel:

67444605

of

3006 Ubi Rd T # 01-338

Policy No:

A28650187QMX

Claim No:

560210

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

30/05/2018

CA / REV / REP. / REV 24 HRS

1up

H.O.D. Endorsement:

Date/Time:

10:50am @ 7/6/18

Person Contacted:

Siang hui

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLN 3864M - X
	SGC 154R - X.
12/6/18	sent pending est from repairer email.
	confirm LIS 84600 @ 4 days (Ref: 83905.70 4k1.)

REF:

ASS. REC. BY: Adrian Ling**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLN3864M Yr Regn: 2017 / MayType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Opel Amokka c.c. 1598Colour: Brown A/C: Insured / Std / NI / NASp. Reading: 57040 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WOLJDTEC3HB17927Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/55R18R: 215/55R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Comfoses

Front

Rear

R/Bal. 06 mmR/Bal. 06 mmL/Bal. 06 mmL/Bal. 06 mm

D.O.A. _____

D.O.I. 07/06/18

Survey held at

Siam TreeDes. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop orFront r/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP mslg.

Date/Time, File Pass to?

☐

: Preli. Report

1) typist☒

: Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 4Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

15010160Report Format: TPLump Sum / LE: (\$ 4600)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18010355/Ard3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 07-06-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGC 154R	Veh. Inspected	SLN 3864M
Policy No.	A28650187QMX	Coverage (\$)	0.00
Claim No.	560210	Excess (\$)	0.00
Assign From	MERIMEN (JASMINE LOK)	Assign Date	07/06/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	30/05/2018	Inspection Date	07/06/2018
Survey held at	SIANG HUI MOTOR WORKS BLK 3006 UBI ROAD 1 #01-338 SINGAPORE 408700		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Jun 2018		07 Jun 2018 09:34 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	JUGINDER PALL JAIN, ID: S2195953G		
Main Claimant:	NATIONAL CAR RENTALS (PTE) LTD, Co. Reg. No.: 19100157E		
Vehicle Reg. No.:	SLN3864M	Date of Loss:	30/05/2018 10:00 - :59 [12 Months and 28 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 560210	Policy/Cover Note No.:	A28650187QMX(COMP) (Comprehensive) Coverage: 05/01/2018 - 04/01/2019
Vehicle Reg. No. (Insured):	SGC154R	Policy No. (Claimant):	
		Excess:	
Repairer:	Siang Hui Motor Works (HQ) 3006 Ubi Road 1, #01-338, 408700 Ubi - Tel: 67444605		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 08/06/2018]		
Driver/Custodian (Insured):	AMIT JAIN (), NRIC: S8005788A, Tel: +6596483544		
Adj Asg. Remarks:	on WP. Third Party Pre-Repair Survey. TP nominated LKK (Mr Adrian Ling) to survey. Liability - 100%		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

560210

REG/CS/PAY/FA

05 JUN 2018

BONNIE KWOK LLC*Advocates & Solicitors*

101A Upper Cross Street
#08-12 People's Park Centre
Singapore 058358

Tel: (65) 6536 6026
Fax: (65) 6536 2279
(Not for service of court documents)
GST Reg. No. 2012035472

Your Vehicle: SGC 154R (3rd Party Vehicle)

Our Vehicle: SLN 3864M

Date: 5 June 2018

M/s MSIG Insurance (Singapore) Pte Ltd
16 Raffles Quay
#24-01 Hong Leong Building
Singapore 048581

By Fax 6827 7800 Only

Dear Sir,

ACCIDENT INVOLVING SLN 3864M & SGC 154R ON 30/5/18

We refer to the above matter.

I hereby give you 2 days' notice to conduct a pre-repair inspection of vehicle SLN 3864M at
M/s Siang Hui Motor Works, Block 3006 Ubi Road 1 #01-338 Singapore 568047. Contact number
67444605.

Your faithfully



Print Sent Message

This mail is associated with :

***SLN3864M (560210)**
[SGC154R]

TP
NATIONAL CAR RENTALS (PTE) LTD
May 30 2018 10:00AM
[JUGINDER PALL JAIN]
Siang Hui Motor Works

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 12/06/2018 14:17 PM.
To jasmine_lok@sg.msgig-asia.com
Subject SLN3864M (560210)

Dear Jasmine,

Please be informed that we have inspected the vehicle **SKT 1397M** on 04/06/2018.

We are still pending estimate from repairer.

Thank you.

Regards,
Jannice

Your NCD will be affected due to late reporting
Actual e-Filing Submission Date & Time: 01/06/2018 17:26

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the CIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available at request.

ACCIDENT STATEMENT	
Date Of Report	01/06/2018 17:12
Date Of Accident	30/05/2018 10:30
Exact Location Of Accident	8 BIOMEDICAL GROVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLN3864M

Insured/Policyholder	
Name Of Registered Owner	NATIONAL CAR RENTALS (PRIVATE) LIMITED
Co Reg No	19100157E
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-94871051

Vehicle Particulars	
Manufacturer	OPEL
Model	MOKKA-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5089517881
Cover Note Number	

Driver	
Name of Driver	TEO SIEW CHOO ALICE
NRIC No	S1695644I
Date Of Birth	22/10/1965
Occupation	INDOOR
Date Of Driving Pass	27/04/1984
Driving Experience	34 YEARS AND 1 MONTH
Gender	FEMALE
Mobile Number	(LOCAL) +65-94871051
Fax Number	
Contact Number	
E/Mail Address	NOEMAIL

Address 390A HAVELOCK RD #01-07 WATERFRONT PLAZA S 169664
Postcode
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - OPENING DOOR OF VEHICLE
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance?
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHED REPORT

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SGC154R
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver AMIT JAIN
NRIC/Passport Number
Contact Number 96483544

Address NA
Postcode NA
Insurance Company Name NA
Nature Of Damage
No. Of Passenger (Including Driver)

SKETCH PLAN

SKETCH PLAN

SAC
1960

SIN 360um

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Driver of car SEC 15VR AMIT JAIN opened his car door without seeing my car approaching and his car door hit my car front left head lamp side

/We declare the foregoing particulars are true in every respect.



Abuse

祥輝汽車修理 SIANG HUI MOTOR WORKS

Blk 3006, Ubi Road 1 #01-338, Singapore 408700.
Tel: 67444605 Fax: 67440726
REG. No. 322208/00M

TP MS16.

Janice.

Date, 06-06-18

VEHICLE NO: SLN 3864 M

OPREL MOKKA

1	IPC Headlamp (LH) canld	✓ \$	2635.00
2	IPC Front fender (LH) Buckd	✓ \$ ⁵⁸⁴	835.00
3	IPC Front fender garnish at	✓ \$	295.00
4	IPC Front bumper (TOP) Relnd	\$ ¹³⁶²	1890.00
5	IPC Front bumper (Lower) Lt ✓	\$ ⁷⁴⁸	1420.00
6	IPC Front bumper side retrainer (LH) ✓	\$	38.00
7	IPC Fog light Cover (LH) ?	+ \$	136.00
8	IPC Fog light (LH) {m	+ \$	389.00
9	IPC Front Sensor (LH) m	+ \$	235.00

Total:

\$ 7873.00

Less 10%

\$ 787.30

\$ 7085.70

Labour charges:-

730

1	To replace repair straighten + realign all damaged parts.	\$ 680.00 300.
2	To spray paint on all affected areas	\$ 680.00 400
3	To check wiring	\$ 60.00 30

Adrian Lij

15.5.18 07/06/18

04244

Grand Total:

\$ 8505.70

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Jun 2018		07 Jun 2018 09:34 Edit Adj Rpt	S\$4,600.00 Edit Estimates	S\$4,600.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	JUGINDER PALL JAIN, ID: S2195953G	
Main Claimant:	NATIONAL CAR RENTALS (PTE) LTD, Co. Reg. No.: 19100157E	
Vehicle Reg. No.:	SLN3864M	Date of Loss: 30/05/2018 10:00 - :59 [12 Months and 28 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 560210	Policy/Cover Note No.: A28650187QMX(COMP) (Comprehensive) Coverage: 05/01/2018 - 04/01/2019
Vehicle Reg. No. (Insured):	SGC154R	Policy No. (Claimant): Excess:
Repairer:	Siang Hui Motor Works (HQ) 3006 Ubi Road 1, #01-338, 408700 Ubi - Tel: 67444605	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Imm.Advice due 08/06/2018]	
Driver/Custodian (Insured):	AMIT JAIN (), NRIC: S8005788A, Tel: +6596483544	
Adj Asg. Remarks:	on WP. Third Party Pre-Repair Survey. TP nominated LKK (Mr Adrian Ling) to survey. Liability - 100%	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	
No results.										

Claim Documents

***SLN3864M (560210)**
[SGC154R]

TP

NATIONAL CAR RENTALS (PTE) LTD

May 30 2018 10:00AM

[JUGINDER PALL JAIN]

Siang Hui Motor Works

Upload Documents		Upload Photos	Compose New Letter	View Use Viewer ▼	
Photos/Images				3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	25/07/18 15:27	General View		Load JPG	☒
2	25/07/18 15:27	General View		Load JPG	☒
3	25/07/18 15:27	General View		Load JPG	☒
4	25/07/18 15:27	General View		Load JPG	☒
5	25/07/18 15:27	General View		Load JPG	☒
6	25/07/18 15:27	General View		Load JPG	☒
7	25/07/18 15:27	General View		Load JPG	☒
8	25/07/18 15:27	General View		Load JPG	☒
9	25/07/18 15:27	General View		Load JPG	☒
10	25/07/18 15:27	General View		Load JPG	☒
11	25/07/18 15:27	General View		Load JPG	☒
12	25/07/18 15:27	General View		Load JPG	☒
13	25/07/18 15:27	General View		Load JPG	☒
14	25/07/18 15:27	General View		Load JPG	☒
15	25/07/18 15:27	General View		Load JPG	☒
16	25/07/18 15:27	Reinspection Photo		Load JPG	☒
17	25/07/18 15:27	Reinspection Photo		Load JPG	☒
18	25/07/18 15:27	Reinspection Photo		Load JPG	☒
19	25/07/18 15:27	Reinspection Photo		Load JPG	☒
20	25/07/18 15:27	Reinspection Photo		Load JPG	☒
21	25/07/18 15:27	Reinspection Photo		Load JPG	☒
22	25/07/18 15:27	Reinspection Photo		Load JPG	☒
Documentation				1 per page ▼	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	05/06/18 16:53	TP PRI		Load PDF	
2	05/06/18 16:54	E-FILE REPORT (SLN3864M)		Load PDF	
3	06/06/18 15:12	TP NOMINATED LKK TO BE OUR SJE		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18010355/ARD3E2

Date: 16/08/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A28650187QMX (COMP)		
Claimant Vehicle No :	SLN3864M	Insured Vehicle No :	SGC154R		
Date of Loss:	30/05/2018	Nature of Claim:	TP	Claim No:	560210

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN3864M	Engine No:	A2170045GU7X0404
Make & Model:	OPEL MOKKA X, 1.6 CDTI 6AT (LED) (A)	Chassis No:	W0LJD7EC3HB179427
Reg. Date:	02/05/2017 (Man. Year: 2017)	Odometer:	57040 km
Colour:	Brown		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R18	Rear Tyre Size:	215/55 R18
Front Left Side:	Comforser 6 mm	Rear Left Side:	Comforser 6 mm
Front Right Side:	Comforser 6 mm	Rear Right Side:	Comforser 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	7,085.70	5,095.80	1,989.90	28.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,420.00	730.00	690.00	48.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,505.70	5,825.80	2,679.90	31.51
Approved Total (Overridden) (\$\$)		4,600.00		
Nett Amount (\$\$)	8,505.70	4,600.00	3,905.70	45.92

INSPECTION

Date of Assignment:	07/06/2018		
Date Inspected:	07/06/2018	Inspected At:	Siang Hui Motor Works (HQ) 3006 Ubi Road 1, #01-338 Singapore 408700
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Aug 2018)
Parts:	143	OPEL MOKKA X 1.6 CDTI 6AT (LED) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLN3864M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP (LH)	Cracked	2,635.00 FL	*2,635.00 FL
2	1		*FRONT FENDER (LH)	Buckled	835.00 FL	*584.00 FL
3	1		*FRONT FENDER GARNISH	Cut	295.00 FL	*295.00 FL
4	1		*FRONT BUMPER (TOP)	Deformed	1,890.00 FL	*1,362.00 FL
5	1		*FRONT BUMPER (LOWER)	Cut	1,420.00 FL	*748.00 FL
6	1		*FRONT BUMPER SIDE RETAINER (LH)	Necessary	38.00 FL	*38.00 FL
7	1		*FOG LIGHT COVER (LH)	Not Necessary	136.00 FL	*- FL
8	1		*FOG LIGHT (LH)	Not Necessary	389.00 FL	*- FL
9	1		*FRONT SENSOR (LH)	Not Necessary	235.00 FL	*- FL
					Sub Total (\$\$)	7,873.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	787.30
					Total Parts (\$\$)	7,085.70
						5,095.80

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REPAIR STRAIGHTEN & REALIGN ALL DAMAGED PARTS	New	680.00	300.00
2	TO SPRAY PAINT ON AFFECTED AREAS	New	680.00	400.00
3	TO CHECK WIRING	New	60.00	30.00
Gross Labour Cost (\$\$)			1,420.00	730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >