

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2541Z
Vehicle Details	
Vehicle No.:	SLH4393E
Vehicle to be Exported:	No
Intended De-registration Date:	09 Jun 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA AXIO HYBRID 1.5G CVT D/AIRBAG
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	1NZR413535
Chassis No.:	NKE1657135375
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$24,263.00
Original Registration Date:	02 Nov 2016
First Registration Date:	02 Nov 2016
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Nov 2026
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	01 Nov 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,991.00
COE Rebate Amount:	\$42,808.00
Total Rebate Amount:	\$46,558.00

The information contained herein is correct as at 09 Jun 2018

OK

Allswell Motor Traders

25 Defu Lane 9, Singapore 539266

Tel : +65 6679 1146

email: ben@allswellmotor.com.sg

4 Days.
part by part.
before paint photos.
Guo Qianl.
07/6/18

(3rd party claim against MS First Capital insured 8HA3309R)

Estimate repair

Vehicle No. : SUH4393E
Make & Model : Toyota AXIO
Chassis No. : Hybrid 1.5G
Date of survey : _____

Submitted by
COE expiry
Engine No.

[Signature]
12/6/18

Bun
01-11-2026

S/No	Part Description	Qty	Unit Price	Price	Disposition by
01	RH rear door X part	01	#1049		X repair 1249
02	RH rear fender X repair	01	#721.0		* repair
					259: 786.7
	<u>Labour description</u>				
01	Dismantle / Assembly of RH rear door / RH fender elements	01	#260.0	100	150 200
02	Panel beating of rear fender area	01	#460.0	200	250
03	Spray painting including putty / grind and polish with anti-rust paint	01	#660.00	600	700 600
				700	
				1050	
	4 Day.				
	Link Auto Consultants hence notify the Repairer of the following: - To reserves before after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____				

Note: If any of the quoted parts are recommended to be repaired, then an additional labour cost will be charged accordingly under supplementary.

2,350

1686.75

2,807.50



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 4393E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	RH REAR DOOR	TO REPAIR SEE LABOUR	1,049.00	-
1	RH REAR FENDER	TO REPAIR SEE LABOUR	721.00	-
			1,770.00	-
	<u>LABOUR</u>			
	DISMANTLE / ASSEMBLY OF RH REAR DOOR / RH FENDER ELEMENTS.		360.00	200.00
	PANEL BEATING OF REAR FENDER AREA. INCLUSIVE OF THE REPAIR OF RH REAR DOOR AND RH REAR FENDER.		460.00	250.00
	SPRAY PAINTING INCLUDING PUTTY / GRIND AND POLISH WITH ANTI-RUST PAINT.		660.00	600.00
			1,480.00	1,050.00
GRAND TOTAL			3,250.00	1,050.00
RECOMMENDED COST OF REPAIRS				1,050.00

Report Ref No. CS/FCI18010356/Gsd3e2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.