

22/03/2002

ASS. REC. BY:

REF: es/FCI18010362/ Kvd3ⁿ² Special Instruction:

Surveyor:

CWS

Kenneth

ASSIGNMENT (Office)

From (Person):

81thura

of

Tel

Date/Time: 7/6/18 @ 11:26am

Estimated Cost:

Bill to:

OD/TP WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SCM 8034X

Insured:

SHC 7292S

at Workshop m/s

cheng hua motor

Tel:

67556142

of

Blk 1019 Yishun Ind. Park A #01-374

Policy No:

Claim No:

D18004555MFST

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 06/06/2018

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

12:39pm @ 7/6/18

Person Contacted:

e fe da

Vehicle ☒ IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SCM 8034X - NA/INC09015974/C2

DOA: 16/7/2009

SHC 7292S - CC4/ICS17005981/M1ea3

DOA: 22/03/2017

Sent preli thru email.

27/8

11 Sep @ 77502 Confirm Efects (Recd 4043.73, 34/8)

ASS. REC. BY:

REF:

F021

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

8/6

File pass to Cashier

RECEIVED 20 AUG 2018

Veh No:

SCM 8034X

Yr Regn:

11, 12

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Estima

c.c

2362

Colour:

M.P. White

A/C:

Insured / Std / NI / NA

Sp. Reading

136911

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

AIR 20 - 7064710

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

225/55R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

6/6/18

D.O.I.

7/6/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 28/8 - typist

Days Of Repair:

8

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format:

CWS

Lump Sum / I.B.I. (\$

7750 p

170 + 15
50
50 + 50
37
372



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18010362/Krd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 07-06-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7292S	Veh. Inspected	SCM 8034X	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18004555MFSH	Excess (\$)	0.00	
Assign From	CWS (SITHARA)	Assign Date	07/06/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	06/06/2018	Inspection Date	07/06/2018	
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18004555MFSH

Our Ref: CS/FCI18010362/Krd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SCM 8034X

Please be informed that we had conducted the inspection of the above mentioned vehicle on 07.06.2018 at the premises of M/s CHENG HOE MOTOR PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ <u>11,265.98</u>
Revised Estimate Amount	: S\$ <u>8,791.55</u>
"Check" Items Amount	: S\$ <u>2,028.05</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages
at rear portion.



Yours faithfully
KENNETH
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	06-06-2018	Our Ref No. D18004555MFSH
Accident Date	06-06-2018	Claim Type. Third Party
Insured Vehicle	SHC7292S	Third Party Vehicle. SCM8034X
Survey Location	BLK 1019 YISHUN IND. PARK A #01-374	
Contact Person.	JUNE	
Contact No.	67556142/ 0	Fax No. 67557719
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHENG HOE MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/241218)



PRI Documents



Close



PRI Header Details

Claim No	D18004555MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & CHENG H
Workshop Name	CHENG HOE MOTOR PTE LTD (Contact Person : JUNE)	Survey Location & Contact Details	BLK 1019 YISHUN IND. PARK A #01-374 Mobile: 0 , Phone: 67556142 , Fax: 67557719 EmailId: CHMOTOR@SINGNET.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHC7292S	TP Vehicle No	SCM8034X
PRI Recieved Date	06-06-2018 10:23:14 PM	Surveyor Appointed Date	07-06-2018 11:25:00 AM	Surveyor Accept Date	07-06-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	07-06-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	0276E

Vehicle Details

Vehicle No.:	SCM8034X
Vehicle to be Exported:	No
Intended De-registration Date:	06 Jun 2018
Vehicle Make:	TOYOTA
Vehicle Model:	ESTIMA AERAS HYBRID 2.4 A
Primary Colour:	White
Manufacturing Year:	2012
Engine No.:	2AZH890640
Chassis No.:	AHR207064710
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$54,266.00
Original Registration Date:	14 Nov 2012
First Registration Date:	14 Nov 2012
Transfer Count:	1
Actual ARF Paid:	\$32,560.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Nov 2022
PARF Rebate Amount:	\$22,792.00

Intended COE Rebate Details

COE Expiry Date:	13 Nov 2022
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$95,034.00
COE Rebate Amount:	\$41,922.00
Total Rebate Amount:	\$64,714.00

The information contained herein is correct as at 06 Jun 2018

OK

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SCM 8034X
 TP/FC

M/S : MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD
 #16-01 CITY HOUSE
 SINGAPORE 068877

TEL: 65073848

FAX: 65073849

ATTN: Motor Claim Department

WS Ref: TP/FC/YS

Claim Type: Third Party

Accident Date: 06/06/2018

TP Veh Reg No: SHC7292S

Estimate No: ES1890626/YISHUN

Date: 07 Jun 2018

Policy No: 5059034762-05

Veh Reg No: SCM8034X

Make/Model: TOYOTA ESTIMA
 AERAS HYBRID 2.4 A

Chassis No: AHR207064710

Engine No: 2AZH890640

Reg. Date: 14/11/2012

Estimate Repair Cost to Vehicle No :SCM8034X

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 REAR BUMPER	1,388.50	1 PC	1,388.50	✓
2 REAR BUMPER LH TOW COVER	56.10	1 PC	56.10	✓
3 REAR BUMPER LH REFLECTOR	59.40	1 PC	59.40	✓
4 REAR BUMPER SIDE RETAINER	62.70	1 PC	62.70	✓
5 REAR BUMPER LH INNER SPONGE	61.50	1 PC	61.50	✓
6 REAR BUMPER CLIPS	3.50	6 PCS	21.00	✓
7 REAR TAILGATE	1,669.70	1 PC	1,669.70	✓
8 TAILGATE LOGO	59.10	1 PC	59.10	✓
9 TAILGATE EMBLEM 'ESTIMA'	62.10	1 PC	62.10	✓
10 TAILGATE EMBLEM 'HYBRID'	49.90	1 PC	49.90	✓
11 TAILGATE EMBLEM 'AERAS'	69.50	1 PC	69.50	✓
12 TAILGATE EMBLEM 'E-FOUR'	52.70	1 PC	52.70	✓
13 TAILGATE EMBLEM 'HYBRID SYNERGY'	59.80	1 PC	59.80	✓
14 TAILGATE INNER LOCK	432.70	1 PC	432.70	✓
15 TAILGATE INNER RUBBER	324.10	1 PC	324.10	✓
16 TAILGATE INNER LOCK AUTO SWITCH	124.01	1 PC	124.01	✓
17 TAILGATE INNER TRIM BOARD	529.10	1 PC	529.10	✓
18 TAILGATE INNER SIDE FRAME SEAL	69.80	1 PC	69.80	✓
19 TAILGATE DAMPERS	361.00	2 PCS	722.00	✓
20 REAR WINDSCREEN GLASS MOULDING	247.10	1 PC	247.10	✓
21 REAR PANEL	729.50	1 PC	729.50	✓
22 REAR PANEL INNER TOP GARNISH	397.10	1 PC	397.10	✓
23 REAR PANEL INNER TOP GARNISH CLIPS	4.50	6 PCS	27.00	✓
24 REAR LH FENDER INNER GARNISH	794.10	1 PC	794.10	✓
25 REAR RH FENDER INNER GARNISH	794.10	1 PC	794.10	✓
26 REAR LOCK ANTENNA SENSOR	159.40	1 PC	159.40	✓
27 LH TAILLAMP	385.10	1 PC	385.10	✓
28 REAR FLOOR BOARD TOP CUSHION	1,090.00	1 PC	1,090.00	✓
29 REAR PANEL INNER LOWER GARNISH	298.20	1 PC	298.20	✓
30 REAR PANEL INNER LOWER GARNISH CLIPS	6.50	4 PCS	26.00	✓
			10,821.31	
		Less 25%	2,705.33	8,115.98

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

TEL: 65073848

FAX: 65073849

ATTN: Motor Claim Department

WS Ref: TP/FC/YS

Claim Type: Third Party

Accident Date: 06/06/2018

TP Veh Reg No: SHC7292S

Estimate No: ES1890626/YISHUN

Date: 07 Jun 2018

Policy No: 5059034762-05

Veh Reg No: SCM8034X

Make/Model: TOYOTA ESTIMA
AERAS HYBRID 2.4 A

Chassis No: AHR207064710

Engine No: 2AZH890640

Reg. Date: 14/11/2012

Estimate Repair Cost to Vehicle No :SCM8034X

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Special Net				
31 REAR WINDSCREEN GLASS GUM	40.00	1 PC	40.00	✓
32 REAR SPARE TYRE PANEL TOP COAT	80.00	1 PC	80.00	60.00
			120.00	120.00
Labour				
33 REMOVE AND REFIX REAR WINDSCREEN GLASS	100.00	1 LA	100.00	✓
34 REMOVE & REFIX REAR BUMPER ASSY, TAILGATE, SPOILER, REFLECTORS, REAR WIPER ASSY, LOCK ASSY, THIRD BRAKE, CUT, WELD & RENEW REAR PANEL, TO STRAIGHTEN, KNOCK & REPAIR REAR LH FENDER, REAR SPARE TYRE COMPARTMENT & REALIGN THE SAME	1,300.00	1 LA	1,300.00	1200
35 REMOVE & REFIX REVERSE CAMERA & RESET SYSTEM	50.00	1 LA	50.00	✓
36 REMOVE & REFIX REAR SEAT, CARPET, GARNISH, SAFETY BELT, ETC	120.00	1 LA	120.00	✓
37 REMOVE & REFIX BATTERY & RESET SYSTEM	100.00	1 LA	100.00	✓
38 PUTTY & RESPRAY ON REAR LH FENDER, FLOOR BOARD PANEL, REAR RH FENDER, REAR PANEL, TAILGATE, REAR BUMPER & REAR AFFECTED AREAS (PEARL WHITE)	1,300.00	1 LA	1,300.00	1200
39 RUSTPROOFING	60.00	1 LA	60.00	✓
			3,030.00	3,030.00
			Total	S\$ 11,265.98
			Add GST @ 7%	788.62
			Total Amount Payable	S\$ 12,054.60

11,793.73

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (VIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SCM 8034X
SUPP 2

M/S : MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

TEL: 65073848

FAX: 65073849

ATTN: Motor Claim Department

WS Ref: TP/FC/YS

Claim Type: Third Party

Accident Date: 06/06/2018

TP Veh Reg No: SHC7292S

Estimate No: ES1890626/YISHUN

Date: 22 Jun 2018

Policy No: 5059034762-05

Veh Reg No: SCM8034X

Make/Model: TOYOTA ESTIMA
AERAS HYBRID 2.4 A

Chassis No: AHR207064710

Engine No: 2AZH890640

Reg. Date: 14/11/2012

Estimate Repair Cost to Vehicle No :SCM8034X

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Supplementary 2				
Special Net				
1 REVERSE CAMERA	Short 380.00	1 SET	380.00	350.00
			380.00	380.00
			Total	S\$ 380.00
			GST Amount	S\$ 26.60
			Total Amount Payable	S\$ 406.60

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SCM 8034x
SUPP 1

M/S : MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

TEL: 65073848

FAX: 65073849

ATTN: Motor Claim Department

WS Ref: TP/FC/YS

Claim Type: Third Party

Accident Date: 06/06/2018

TP Veh Reg No: SHC7292S

Estimate No: ES1890626/YISHUN

Date: 13 Jun 2018

Policy No: 5059034762-05

Veh Reg No: SCM8034X

Make/Model: TOYOTA ESTIMA
AERAS HYBRID 2.4 A

Chassis No: AHR207064710

Engine No: 2AZH890640

Reg. Date: 14/11/2012

Estimate Repair Cost to Vehicle No :SCM8034X

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Supplementary 1				
List Price				
1 REAR PANEL INNER GARNISH LOWER	197.00	1 PC	197.00	
			197.00	
		Less 25%	49.25	147.75
Total				S\$ 147.75
GST Amount				S\$ 10.34
Total Amount Payable				S\$ 158.09

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18010362/Kvd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 29-08-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 7292S	Veh. Inspected	SCM 8034X	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18004555MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	07/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ESTIMA (A)	c.c	2362	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	AHR207064710	Colour	METALLIC PEARL WHITE	
Odometer	136911	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55 R17	DUNLOP	6 mm	
L/H Front Tyre	225/55 R17	DUNLOP	6 mm	
R/H Rear Tyre	225/55 R17	DUNLOP	6 mm	
L/H Rear Tyre	225/55 R17	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/06/2018	Inspection Date	07/06/2018	
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCM 8034X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	BENT	1,388.50	1,388.50
1	REAR BUMPER LH TOW COVER	MISSING	56.10	56.10
1	REAR BUMPER LH REFLECTOR	CRACKED	59.40	59.40
1	REAR BUMPER SIDE RETAINER	DISTORTED	62.70	62.70
1	REAR BUMPER LH INNER SPONGE	CRACKED	61.50	61.50
6	REAR BUMPER CLIPS @\$3.50	NECESSARY	21.00	21.00
1	REAR TAILGATE	BENT	1,669.70	1,669.70
1	TAILGATE LOGO	NECESSARY	59.10	59.10
1	TAILGATE EMBLEM "ESTIMA"	NECESSARY	62.10	62.10
1	TAILGATE EMBLEM "HYBRID"	NECESSARY	49.90	49.90
1	TAILGATE EMBLEM "AERAS"	NECESSARY	69.50	69.50
1	TAILGATE EMBLEM "E-FOUR"	NECESSARY	52.70	52.70
1	TAILGATE EMBLEM "HYBRID SYNERGY"	NECESSARY	59.80	59.80
1	TAILGATE INNER LOCK	DENTED	432.70	432.70
1	TAILGATE INNER LOCK AUTO SWITCH	SERVICEABLE	124.01	-
1	TAILGATE INNER TRIM BOARD	BUCKLED	529.10	529.10
1	TAILGATE INNER SIDE FRAME SEAL	NECESSARY	69.80	69.80
2	TAILGATE DAMPERS @\$361.00	SERVICEABLE	722.00	-
1	REAR WINDSCREEN GLASS MOULDING	NECESSARY	247.10	247.10
1	REAR PANEL	BENT	729.50	729.50
1	REAR PANEL INNER TOP GARNISH	BUCKLED	397.10	397.10
6	REAR PANEL INNER TOP GARNISH CLIPS @\$4.50	NECESSARY	27.00	27.00
1	REAR LH FENDER INNER GARNISH	BUCKLED	794.10	794.10
1	REAR RH FENDER INNER GARNISH	BUCKLED	794.10	794.10
1	REAR LOCK ANTENNA SENSOR	DISTORTED / CRACKED	159.40	159.40
1	LH TAILLAMP	SERVICEABLE	385.10	-
1	REAR FLOOR BOARD TOP CUSHION	SERVICEABLE	1,090.00	-
1	REAR PANEL INNER LOWER GARNISH	BUCKLED	298.20	298.20
4	REAR PANEL INNER LOWER GARNISH CLIPS @\$6.50	NECESSARY	26.00	26.00
1	REAR PANEL INNER GARNISH LOWER (ADDITIONAL)	BUCKLED	197.00	197.00

Report Ref No. CS/FCI18010362/Kvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 25% DISCOUNT		-2,673.55	-2,093.27
			8,020.66	6,279.83
1	TAILGATE INNER RUBBER (50%)(SN)	DISTORTED / DENTED	324.10	162.05
	LESS 25% DISCOUNT		-81.03	-
			243.07	162.05
	SPECIAL NETT ITEMS			
1	REAR WINDSCREEN GLASS GUM (SN)	NECESSARY	40.00	40.00
1	REAR SPARE TYRE PANEL TOP COAT (SN)	NECESSARY	80.00	60.00
1	SET REVERSE CAMERA (SN)(ADDITIONAL)	SHORTED	380.00	350.00
			500.00	450.00
	LABOUR			
	REMOVE AND REFIX REAR WINDSCREEN GLASS.		100.00	100.00
	REMOVE & REFIX REAR BUMPER ASSY, TAILGATE, SPOILER, REFLECTORS, REAR WIPER ASSY, LOCK ASSY, THIRD BRAKE, CUT, WELD & RENEW REAR PANEL, TO STRAIGHTEN, KNOCK & REPAIR REAR LH FENDER, REAR SPARE TYRE COMPARTMENT & REALIGN THE SAME.		1,300.00	1,200.00
	REMOVE & REFIX REVERSE CAMERA & RESET SYSTEM.		50.00	50.00
	REMOVE & REFIX REAR SEAT, CARPET, GARNISH, SAFETY BELT, ETC.		120.00	120.00
	REMOVE & REFIX BATTERY & RESET SYSTEM.		100.00	100.00
	PUTTY & RESPRAY ON REAR LH FENDER, FLOOR BOARD PANEL, REAR RH FENDER, REAR PANEL, TAILGATE, REAR BUMPER & REAR AFFECTED AREAS (PEARL WHITE).		1,300.00	1,200.00
	RUSTPROOFING.		60.00	60.00
	-		-	-
	-		-	-
	-		-	-
			3,030.00	2,830.00
	GRAND TOTAL		11,793.73	9,721.88

Report Ref No. CS/FCI18010362/Kvd3n2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,750.00
---	--	--	----------

Report Ref No. CS/FCI18010362/Kvd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.