Surveyor Taufilds	ASS	SIGNMEN	I (Office)			
From (Person): Joe Tur	of	AX	A	Date/Ti	me: 07	062018 11-26am
Estimated Cost:		В	ill to:			
OD THES ! O To Inspect Vehicle No:	D RES / EVA / INV	IMVICS		Insured:	Public	liability
at Workshop m/s	Cycle &	e Comage		Tel:		7
of		andan hard	lon			
Policy No:			Claim No:	SBCOOHFK		
Sum Insured:			Excess:			
Make of Veh: (Client's Record)				D.O.A.	05	V51018
CA / REV / REP. / REV Date/Time: 0706 2018		ontacted;	Jian Ye	H.O.D Vehicle	. Endorsem	ent:
Date/Time Action/Instru	action (V) E	stimate				
Z/X 1/1/8	59 - X					
Public Lia	x - phlic					
08/06/18 @ 15:5: 12/06/13 vehicle 12/06/18 Submit	2 em Clar	al PA	+0 2	Se l'a	2mail	1
	P	20 111	10		7	

guirdus J.	authos REF:	SIGNMENT
	2430	
From:	Date:	Veh No. SLX 4485P Yr Regn: 2011, V
Estimated Cost:		Type: M.Ca/ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD (TP) WS / TP RE	S / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No	d .	Make: 169 Cerub Forte 113 0.0 159
at Workshop m/s		Colour White . A/C: Insured / Std / N
of		Sp.Reading 2/42 T/Radio: Insured / Std / N
Insured:		Eng/No:
Policy No.		C/No: KNA FJ414 J5756390
Claims No.		Gen. Cond. Good / Fair / Poor / Burnt
Sum Insured:	Excess:	Steering: Ingroger / Jammed / Leaked / Burnt or
(Client's Record)		Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:		Modi: Nil /SIRim / STD A/Rim or
		Tyre Size: F: 195/6516/5
(Policy Condition)		R: 2
Remark: The veh had	d commenced its	4
	e time of inspection.	TOYO/YOKO or Nexten.
5.1		Front Rear
Bal. or Market Value:	Consistent? : Yes or No	R/Bal. 6 mm R/Bal. 6
IDAC Accident Rport:	Consistent? : Yes or No	L/Bal. / mm L/Bal.
GIA / PR Seen:	Consistent r , res or No	
	Post Vos or No	DOL 316//0
Est. Repairs:	days Res.: Yes or No	D.O.A. D.O.I. 7/6//8
Est. Repairs:	% 3 Val.: Yes or No	Survey held at Carpada Gah
Lum Sum:	% 3 Val.: Yes or No W P'	Survey held at Des. of Damages: Fit Rear 6)\$ MS U/C Rooflop or
Lum Sum: CA / REV / REF	% 3 Val.: Yes or No W P' Vehicle: IN/OU	Des. of Damages: Fit Rear 6/5 MS U/C Rooffop or
Lum Sum: CA / REV / REP Date:	% 3 Val.: Yes or No W / ' P. / 24 HRS Vehicle: IN / OL Person Contacted:	Survey held at Des. of Damages: Fit Rear 6)\$ MS U/C Rooflop or
Lum Sum: CA / REV / REP Date:	% 3 Val.: Yes or No W P' Vehicle: IN/OU	Des. of Damages: Fit Rear 6/5 MS U/C Rooffop or
Lum Sum: CA / REV / REP Date:	% 3 Val.: Yes or No W / ' P. / 24 HRS Vehicle: IN / OL Person Contacted:	Des. of Damages: Fit Rear 6/5 MS U/C Rooffop or
Lum Sum: CA / REV / REP Date:	% 3 Val.: Yes or No W P' P. / 24 HRS Vehicle: IN / OU Siton / Instruction	Survey held at Des. of Damages: Fit Rear Olds Wis U/C Rooftop or The U/C Chassis frame Body Structure affected due to o
Lum Sum: CA / REV / REP Date:	% 3 Val.: Yes or No W P' P. / 24 HRS Vehicle: IN / OU Siton / Instruction	Des. of Damages: Fit Rear 6/5 MS U/C Rooffop or
Lum Sum: CA / REV / REP Date:	% 3 Val.: Yes or No W P' P. / 24 HRS Vehicle: IN / OU Siton / Instruction	Survey held at Des. of Damages: Fit Rear Olds Wis U/C Rooftop or The U/C Chassis frame Body Structure affected due to o
Lum Sum: CA / REV / REP Date:	% 3 Val.: Yes or No W P' P. / 24 HRS Vehicle: IN / OU Siton / Instruction	Survey held at Des. of Damages: Fit Rear Olds Wis U/C Rooftop or The U/C Chassis frame Body Structure affected due to o
Lum Sum: CA / REV / REP Date:	% 3 Val.: Yes or No W P' P. / 24 HRS Vehicle: IN / OU Siton / Instruction	Survey held at Des. of Damages: Fit Rear Olds Wis U/C Rooftop or The U/C Chassis frame Body Structure affected due to o
Lum Sum: CA / REV / REF Date: Date / Time Ac	% 3 Val.: Yes or No W P' P. 1 24 HRS Person Contacted: Vehicle: IN 1 OU Six Y RECEIV	Survey held at Des. of Damages: Fit Rear Obs Mis U/C Rooffop or The U/C Chassis frame Body Structure affected due to constant of the constant
Lum Sum: CA / REV / REP Date:	% 3 Val.: Yes or No W P' P. / 24 HRS Vehicle: IN / OU Sit of RECEIV : Preli. Report	Survey held at Des. of Damages: Fit Rear Obs Mis U/C Rooffop or The U/C Chassis frame Body Structure affected due to constant of the constant
Date/Time, File Pass to?	% 3 Val.: Yes or No W P' P. / 24 HRS Vehicle: IN / OU Six Six Stion / Instruction RECEIV : Preli. Report : Final Report	Survey held at Des. of Damages: Fit Rear Obs MS U/C Rooflop or The U/C Chassis frame Body Structure affected due to co
Date/Time, File Pass to? 12/06/18 1) Type: Date/Time, File Return to?	% 3 Val.: Yes or No W P' P. / 24 HRS Person Contacted: Vehicle: IN / OU Six Y Sition / Instruction RECEIV : Preli. Report : Final Report	Survey held at Des. of Damages: Fit Rear Obs MS U/C Rooffop or The U/C Chassis frame Body Structure affected due to constitution ED 2 JUN 2018 Days Of Repair: Survey Fee: 2 Transportation Transportation 2
Date/Time, File Pass to?	% 3 Val.: Yes or No W P' P. / 24 HRS Vehicle: IN / OU Six Six Stion / Instruction RECEIV : Preli. Report : Final Report	Survey held at Des. of Damages: Fit Rear Obs MS U/C Rooflop or The U/C Chassis frame Body Structure affected due to compare the structure of the structure affected due to compare the structure of the structure o
Date/Time, File Pass to? 12/06/18 1) Type: Date/Time, File Return to?	% 3 Val.: Yes or No W P' P. / 24 HRS Person Contacted: Vehicle: IN / OU Six Y Sition / Instruction RECEIV : Preli. Report : Final Report	Survey held at Des. of Damages: Fit Rear Obs MS U/C Rooffop or The U/C Chassis frame Body Structure affected due to constitution ED 2 JUN 2018 Days Of Repair: Survey Fee: 2 Transportation Transportation 2

Shirley Hiew (LKK Auto)

From:

Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Sent:

Friday, 8 June 2018 3:52 PM

To:

'TAN Joe'

Cc:

Subject:

'Catherine Chong (LKK Auto)'; assignments@lkkauto.com; sur@lkkauto.com RE: (AXA REF: S8C00HFK) Public Liability - Tree fell onto car and traffic light on 05

May 2018 at Shelton College International Pte Ltd

Attachments:

SLX 4485P - Preli Advise.pdf

Dear Joe,

Enclosed herewith preliminary advice of SLX 4485P.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>Sur@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]

Sent: Thursday, 7 June 2018 1:08 PM

To: 'TAN Joe' <joe.tansq@axa.com.sg>; assignments@lkkauto.com; sur@lkkauto.com

Cc: 'Ang Eugene' <angeugene@toplis.com.sg>; victorfong@toplis.com.sg

Subject: RE: (AXA REF: S8C00HFK) Public Liability - Tree fell onto car and traffic light on 05 May 2018 at Shelton

College International Pte Ltd

Dear Mr Joe,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: TAN Joe [mailto:joe.tansq@axa.com.sg]

Sent: Thursday, 7 June, 2018 11:26 AM

To: assignments@lkkauto.com; sur@lkkauto.com

Cc: 'Ang Eugene' <angeugene@toplis.com.sg>; victorfong@toplis.com.sg

Subject: (AXA REF: S8C00HFK) Public Liability - Tree fell onto car and traffic light on 05 May 2018 at Shelton College

International Pte Ltd Importance: High

New Motor Survey

Dear Catherine,

Please assist us to survey the motor vehicle, SLX4485P – Kia K3 at the third party's motor repairer Cycle & Carriage Kia Pte Ltd.

*Catherine Chong (LKK Auto)

From:

TAN Joe <joe.tansq@axa.com.sg>

Sent:

Thursday, 7 June, 2018 11:26 AM

To:

assignments@lkkauto.com; sur@lkkauto.com

Cc: Subject: 'Ang Eugene'; victorfong@toplis.com.sg

(AXA REF: S8C00HFK) Public Liability - Tree fell onto car and traffic light on 05 May

2018 at Shelton College International Pte Ltd

Attachments:

quotation.pdf; SAS2402084.PDF

Importance:

High

New Motor Survey

Dear Catherine,

Please assist us to survey the motor vehicle, SLX4485P – Kia K3 at the third party's motor repairer Cycle & Carriage Kia Pte Ltd.

We attached the repair quotation and SAS report for your attention.

Kindly also keep our loss adjuster in the email loop. (Toplis Ref : S826308)

Thank you.

Best Regards

Joe Tan

Specialist - P&C Claims

AXA Insurance Pte Ltd | 8 Shenton Way, #24-01 AXA Tower, Singapore 068811 | www.axa.com.sg

Email: joe.tanSQ@axa.com.sg





Please consider the environment before printing this message

This message is confidential. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

----Disclaimer----

This message may contain confidential information intended solely for the use of the named addressee. If you are not the intended recipient, you should not read, use, disclose or reproduce the content of this message. If you have received this message by mistake, please notify the sender immediately. Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of AXA Insurance Pte Ltd or any other entity of the AXA Group, unless otherwise stated by the sender and duly authorized by the said companies.



Auto Consultants Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: S8C00HFK

Date: 08 June 2018

Our Ref: CS/AXA18010366/T1sb

The Motor Claims Department
M/s AXA Insurance Singapore Pte Ltd

Without Prejudice

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO SLX 4485P


We thank you for the instruction on <u>07/06/2018</u>.

Please be informed that we had conducted the inspection of the abovementioned vehicle on <u>07/06/2018 @16.10 pm</u> at the premises of M/s <u>Cycle & Carriage Kia Pte Ltd</u> and have the following to report:-

Workshop Estimate Amount	: <u>S</u> \$	14,120.00	
Revised Estimate Amount	: S\$	10,371.00	
"Check" Items Amount	: S\$	2,311.00	
Market Value	: <u>S</u> \$		
LTA Reimbursement Value	: <u>S</u> \$		
Nett Value	: <u>S</u> \$		

Description of Damage:

The vehicle sustained damages at the front, o/s, n/s and rooftop portion.



Comments/ Present Status:

Damages Consistent. Repair days: 11 Days

Yours faithfully, Mohamad Taufikh Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Driving Experience

Mobile Number
Fax Number
Contact Number

EMail Address

Gender

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate</u> as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

aforesaid.	
THE STATE OF STATE OF THE STATE OF	ACCIDENT STATEMENT
Date Of Report	07/05/2018 13:42
Date Of Accident	05/05/2018 14:00
Exact Location Of Accident	TELOK BLANGAH WAY TURNING TO TELOK BLANGAH RISE
Country/State of Loss	SINGAPORE
And the second of the second o	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SLX4485P
Insured/Policyholder	
Name Of Registered Owner	LIM JUN RONG
NRIC No	S9226118B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92266125
Alternative Phone No	OTHERS-92266125
Vehicle Particulars	
Manufacturer	KIA
Model	CERATO FORTE-1.6 EX (A)
Exact Purpose for which vehicle was being used at time of accident	PERSONAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800030837
Cover Note Number	
Driver	
Name of Driver	LIM CHUN LIAN
NRIC No	S8300034A
Date Of Birth	04/01/1983
Occupation	INDOOR
Date Of Driving Pass	13/06/2003

14 YEARS AND 10 MONTHS

(LOCAL) +65-92266125

JUNELIM32@GMAIL.COM

FEMALE

Address

BLK 817A KEAT HONG LINK #10-79

Postcode

681817

Was driver an employee of the Insured's Company NO

SIBLING

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

HIT BY FALLEN TREE / OTHER OBJECTS

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance?

NO

Was any other material or property damaged? I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

5

Passenger 1

NAME:

: CHO SIEW KEN

GENDER:

: FEMALE

Passenger 2

NAME:

: LIM JUNRONG

GENDER:

: FEMALE

Passenger 3

NAME:

: LIM CHUN LIAN

GENDER:

: FEMALE

Passenger 4

NAME:

: TAN LIANG

GENDER:

: MALE

Details of Police Action

Was the accident reported to the police? If Yes, Please state which Police Station

YES

Police Station Name

BUKIT MERAH WEST NPC

Police Station Address

ROAD: 500 BUKIT MERAH VIEW #01-01, POSTCODE: 159682,

COUNTRY: SINGAPORE

Police Station Contact

TEL NO: - FAX NO:

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material
 facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Ane

Policyholder's Signature

Date & Time:

07 May 2018

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Sketch Plan #2

			-	40.00
SK	ЕΤ	CH	PI	AN

Telot Blongen	haffic Can			
Har -	南			
	(3)			

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 05/05/18 at around 1400, I was waiting for the trafight along Telok Blangah way of the left lane. Suddenly, a tree branch dropped on top of my car (5LX 4485	On	05	105/18	at arou	nd 1400	, (was	Waitin	a for	the tests
	ght a	along tree	Te lok branch	Blangah dvoppe	way of	the lop of	left	lane	Sudd (SL	enly, X 4485 F

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 07. 05 - 2016

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240

ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K	LOTIMATE	GST Reg No : MR-8500111-X
Invoice Name & Address		Owner Name & Vehicle Info
LIM JUN RONG	Cust No/Name	LCV05106/MR LIM JUN RONG
LIM JON KONG	Reg No/Reg Date	SLX4485P / 28/03/201
BLK 20 TELOK BLANGAH CRES	Date In/Mileage	/ 0
#02-70	Chassis No	KNAFJ411MJ5756390
SINGAPORE 090020	Engine No	G4FGHH688310
Contact No	Make/Model	KIA/FORTE K3 1.6 A L 189
	Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK

E PNT88000 TO RENEW ROOF PANEL,HOOD, REPAIR BOTH A & B PILLAR, FRT BUMPER, FRT BOTH FENDER, FRT BOTH DOOR E PNT98000 PAINT WORK SPRAY FRT BUMPER. HOOD, FRT BOTH FENDER, FRT BOTH DOOR, FRT BOTH A & B PILLAR, ROOF PANEL E PNT88000 TO REMOVE AND REFIT ROOF PANEL TRIM A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST M SUNDRY TO APPLY WINDSCREEN SEALANT E PNT88000 TO RENEW FRT WINDSCREEN M SUNDRY TO APPLY BODY SEALANT M SUNDRY TO APPLY BODY SEALANT M SUNDRY POLISHING THE WHOLE CAR S SPECIALISTJOB WO: T147549 ACCIDENT TOWING FROM TELOK BANGAH WAY TO PG CNC NOTE: 55 MIN WAITING M SUNDRY TO SUPPLY SOLAR FIRM FOR FRT WINDSCREEN M PANEL-ROOF M MOULDING-WINDSHIELD GLASS 1.00 62.00 00.00 M HINGE ASSY-HOOD,LH 1.00 34.00 00.00 ANAL REPLANCE 22/00 30 25/01	Account No	Terms	Date/Time Pri	inted	CSE	Operator			WIP No	and the	
E PNT88000 TO RENEW ROOF PANEL,HOOD, REPAIR BOTH A & B PILLAR, FRT BUMPER, FRT BOTH FENDER, FRT BOTH DOOR E PNT98000 PAINT WORK SPRAY FRT BUMPER. HOOD, FRT BOTH FENDER, FRT BOTH DOOR, FRT BOTH A & B PILLAR, ROOF PANEL E PNT88000 TO REMOVE AND REFIT ROOF PANEL TRIM A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PROTEST M SUNDRY TO APPLY WINDSCREEN SEALANT E PNT88000 TO RENEW FRT WINDSCREEN M SUNDRY TO APPLY BODY SEALANT M SUNDRY POLISHING THE WHOLE CAR S SPECIALISTJOB WO: T147549 ACCIDENT TOWING FROM TELOK BANGAH WAY TO PG CNC NOTE: 55 MIN WAITING M SUNDRY TO SUPPLY SOLAR FIRM FOR FRT WINDSCREEN M PANEL-ROOF M PANEL-ROOF M MOULDING-WINDSHIELD GLASS 1.00 62.00 00.00 M GLASS-WINDSHIELD 1.00 821.00 00.00 AVAILABLE ASSY-HOOD,H HINGE ASSY-HOOD,H HINGE ASSY-HOOD,RH 1.00 34.00 00.00 AVAILABLE ASSY-HOOD,RH 34.00	LCV05106	CRDVCH	05/06/2018/	16:03		465 / Ta	ıy Jian Ye		28104		
TO RENEW ROOF PANEL, HOOD, REPAIR BOTH A & B PILLAR, FRT BUMPER, FRT BOTH FENDER, FRT BOTH DOOR FAIRT WORK SPRAY FRT BUMPER. HOOD, FRT BOTH FENDER, FRT BOTH DOOR, FRT BOTH A & B PILLAR, ROOF PANEL E PNT8BOOD TO REMOVE AND REFIT ROOF PANEL TRIM A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST WINDRY TO APPLY WINDSCREEN SEALANT E PNT8BOOD TO RENEW FRT WINDSCREEN M SUNDRY TO APPLY BODY SEALANT M SUNDRY TO SUPPLY SOLAR FIRM FOR FRT WINDSCREEN M PANEL-ROOF M PANEL-ROOF M GLASS-WINDSHIELD M GLASS-WINDSHIELD M HINGE ASSY-HOOD, H HINGE ASSY-HOOD, H HINGE ASSY-HOOD, H A PANEL ASSY-HOOD M PANEL ASSY-HOOD M PANEL ASSY-HOOD M PANEL ASSY-HOOD M PANEL ASSY-HOOD M 1.00			Description	of Goods	/ Services	- Si sit - /		Qty	Unit Price	Disc%	
BUMPER, FRT BOTH FENDER, FRT BOTH DOOR E PNT98000 PAINT WORK SPRAY FRT BUMPER. HOOD, FRT BOTH FENDER, FRT BOTH DOOR, FRT BOTH A & B PILLAR, ROOF PANEL E PNT88000 TO REMOVE AND REFIT ROOF PANEL TRIM 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST M SUNDRY TO APPLY WINDSCREEN SEALANT E PNT88000 TO RENEW FRT WINDSCREEN M SUNDRY TO APPLY BODY SEALANT M SUNDRY POLISHING THE WHOLE CAR S SPECIALISTJOB WO: T147549 ACCIDENT TOWING FROM TELOK BANGAH WAY TO PG CNC NOTE: 55 MIN WAITING M SUNDRY TO SUPPLY SOLAR FIRM FOR FRT WINDSCREEN M PANEL-ROOF M MOULDING-WINDSHIELD GLASS M GLASS-WINDSHIELD M HINGE ASSY-HOOD,HH HINGE ASSY-HOOD,H M HINGE ASSY-HOOD,RH M PANEL ASSY-HOOD M PANEL ASSY-HOOD D TO REMEW FRT BOTH DOOR, FRT BOTH BOTH FENDER, FRT BOTH DOOR, FRT BOTH A & B PILLAR 250 250 250 250 250 250 260 260		ROOF PAN	NEL HOOD REI	PAIR ROTH	I A & R PTII	AR FRT					2750 3200.00
E PNT98000 PAINT WORK SPRAY FRT BUMPER. HOOD, FRT BOTH FENDER, FRT BOTH DOOR, FRT BOTH A & B PILLAR, ROOF PANEL E PNT88000 TO REMOVE AND REFIT ROOF PANEL TRIM A 5490099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST WISING HI-SCAN PRO TEST M SUNDRY TO APPLY WINDSCREEN SEALANT E PNT88000 TO RENEW FRT WINDSCREEN M SUNDRY TO APPLY BODY SEALANT M SUNDRY TO APPLY BODY SEALANT M SUNDRY TO APPLY BODY SEALANT M SUNDRY TO SUPPLY SOLAR FIRM FOR FRT WINDSCREEN M PANEL-ROOF M PANEL-ROOF M PANEL-ROOF M MOULDING-WINDSHIELD GLASS M GLASS-WINDSHIELD M HINGE ASSY-HOOD,LH M HINGE ASSY-HOOD,LH 1.00 34.00 00.00 M PANEL ASSY-HOOD,RH M PANEL ASSY-HOOD,RH M PANEL ASSY-HOOD,RH M PANEL ASSY-HOOD, RI M PANEL ASSY-HOOD, RI M PANEL ASSY-HOOD, RI M 1.00 1224.00 00.00 AT 1224.00 M PANEL ASSY-HOOD, RI M 1.00 1224.00 M 1.00 1224.00 M 1.00 M 1.00 1224.00 M 1.00 M 1.00 M 1.00 1224.00 M 1.00 M 1.00 M 1.00 M 1.00 1224.00 M 1.00 M						LAN, THI					
PAINT WORK SPRAY FRI BUMPER. HOOD, FRI BOTH FENDER, FRI BOTH DOOR, FRI BOTH A & B PILLAR, ROOF PANEL E PNT88000 TO REMOVE AND REFIT ROOF PANEL TRIM A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST WISING HI-SCAN PRO TEST M SUNDRY TO APPLY WINDSCREEN SEALANT E PNT88000 TO RENEW FRI WINDSCREEN M SUNDRY TO APPLY BODY SEALANT M SUNDRY POLISHING THE WHOLE CAR S SPECIALISTJOB WO: T147549 ACCIDENT TOWING FROM TELOK BANGAH WAY TO PG CNC NOTE: 55 MIN WAITING M SUNDRY TO SUPPLY SOLAR FIRM FOR FRT WINDSCREEN M PANEL-ROOF M MOULDING-WINDSHIELD GLASS 1.00 62.00 00.00 M GLASS-WINDSHIELD 1.00 34.00 00.00 M HINGE ASSY-HOOD,LH 1.00 34.00 00.00 M PANEL ASSY-HOOD,RH 1.00 34.00 00.00 M PANEL ASSY-HOOD,RH 1.00 34.00 00.00 M PANEL ASSY-HOOD, RH 1.00 1224.00 00.00 M PANEL ASSY-HOOD 1.00 1224.00 00.00				/			Fot LH				2100 3000.00
FRT BOTH A & B PILLAR , ROOF PANEL / E PNT88000 TO REMOVE AND REFIT ROOF PANEL TRIM A 5490099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM A 10028901 TO CARRY OUT DIAGNOSTIC CHECKLUSING HE-SCAN PROTEST WISING HI-SCAN PRO TEST M SUNDRY TO APPLY WINDSCREEN SEALANT E PNT88000 TO RENEW FRT WINDSCREEN M SUNDRY TO APPLY BODY SEALANT M SUNDRY POLISHING THE WHOLE CAR SPECIALISTJOB WO: T147549 ACCIDENT TOWING FROM TELOK BANGAH WAY TO PG CNC NOTE: 55 MIN WAITING M SUNDRY TO SUPPLY SOLAR FIRM FOR FRT WINDSCREEN M PANEL-ROOF M MOULDING-WINDSHIELD GLASS 1.00 62.00 00.00 M GLASS-WINDSHIELD 1.00 34.00 00.00 M HINGE ASSY-HOOD, LH 1.00 34.00 00.00 M PANEL ASSY-HOOD, RH 1.00 1224.00 00.00		RK SPRAY		HOOD, FRT	BOTH FENDE	ER , FRT	BOTH DOOR,				23 544 5 444 5 444 5 444 5 444 5 444 5 444 5
E PNT88000 TO REMOVE AND REFIT ROOF PANEL TRIM A 5490099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST WISING HI-SCAN PRO TEST M SUNDRY TO APPLY WINDSCREEN SEALANT E PNT88000 TO RENEW FRT WINDSCREEN M SUNDRY TO APPLY BODY SEALANT M SUNDRY TO APPLY BODY SEALANT M SUNDRY POLISHING THE WHOLE CAR S SPECIALISTJOB WO: T147549 ACCIDENT TOWING FROM TELOK BANGAH WAY TO PG CNC NOTE: 55 MIN WAITING M SUNDRY TO SUPPLY SOLAR FIRM FOR FRT WINDSCREEN M PANEL-ROOF M MOULDING-WINDSHIELD GLASS 1.00 62.00 00.00 M GLASS-WINDSHIELD 1.00 34.00 00.00 M HINGE ASSY-HOOD, LH 1.00 34.00 00.00 M PANEL ASSY-HOOD, RH 1.00 34.00 00.00 M PANEL ASSY-HOOD 1.00 1224.00 00.00	FRT BOTH	A & B PI	LLAR , ROOF I	PANEL /							950
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PROTEST USING HI-SCAN PRO TEST M SUNDRY TO APPLY WINDSCREEN SEALANT E PNT88000 TO RENEW FRT WINDSCREEN M SUNDRY TO APPLY BODY SEALANT M SUNDRY TO APPLY BODY SEALANT M SUNDRY POLISHING THE WHOLE CAR S SPECIALISTJOB WO: T147549 ACCIDENT TOWING FROM TELOK BANGAH WAY TO PG CNC NOTE: 55 MIN WAITING M SUNDRY TO SUPPLY SOLAR FIRM FOR FRT WINDSCREEN M PANEL-ROOF M MOULDING-WINDSHIELD GLASS 1.00 792.00 00.00 M MOULDING-WINDSHIELD 1.00 821.00 00.00 M HINGE ASSY-HOOD,LH 1.00 34.00 00.00 M HINGE ASSY-HOOD,RH 1.00 34.00 00.00 M PANEL ASSY-HOOD,RH 1.00 34.00 00.00 M PANEL ASSY-HOOD, CH	E PNT88000		,								300.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST WISING HI-SCAN PRO TEST M SUNDRY TO APPLY WINDSCREEN SEALANT E PNT88000 TO RENEW FRT WINDSCREEN M SUNDRY TO APPLY BODY SEALANT M SUNDRY POLISHING THE WHOLE CAR S SPECIALISTJOB WO: T147549 ACCIDENT TOWING FROM TELOK BANGAH WAY TO PG CNC NOTE: 55 MIN WAITING M SUNDRY TO SUPPLY SOLAR FIRM FOR FRT WINDSCREEN M PANEL-ROOF M MOULDING-WINDSHIELD GLASS M GLASS-WINDSHIELD M HINGE ASSY-HOOD,LH M HINGE ASSY-HOOD,RH M PANEL ASSY-HOOD,RH M PANEL ASSY-HOOD,RH M PANEL ASSY-HOOD M PANEL ASSY-HOOD M 1.00 1224.00 00.00 M 1100 1224.00 00.00 M 1100 1224.00 00.00 M 1100 1224.00 00.00 M 1100 1224.00 00.00	TO REMOVE	E AND REF	IT ROOF PANE	L TRIM							. /
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST M SUNDRY TO APPLY WINDSCREEN SEALANT E PNT88000 TO RENEW FRT WINDSCREEN M SUNDRY TO APPLY BODY SEALANT M SUNDRY POLISHING THE WHOLE CAR S SPECIALISTJOB WO: T147549 ACCIDENT TOWING FROM TELOK BANGAH WAY TO PG CNC NOTE: 55 MIN WAITING M SUNDRY TO SUPPLY SOLAR FIRM FOR FRT WINDSCREEN M PANEL-ROOF M MOULDING-WINDSHIELD GLASS 1.00 62.00 00.00 M MOULDING-WINDSHIELD GLASS 1.00 62.00 00.00 M HINGE ASSY-HOOD,LH 1.00 34.00 00.00 M HINGE ASSY-HOOD,RH 1.00 34.00 00.00 M PANEL ASSY-HOOD,RH 1.00 34.00 00.00 M PANEL ASSY-HOOD,RH 1.00 34.00 00.00 M PANEL ASSY-HOOD											30.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST M SUNDRY TO APPLY WINDSCREEN SEALANT E PNT88000 TO RENEW FRT WINDSCREEN M SUNDRY TO APPLY BODY SEALANT M SUNDRY POLISHING THE WHOLE CAR S SPECIALISTJOB WO: T147549 ACCIDENT TOWING FROM TELOK BANGAH WAY TO PG CNC NOTE: 55 MIN WAITING M SUNDRY TO SUPPLY SOLAR FIRM FOR FRT WINDSCREEN M PANEL-ROOF M MOULDING-WINDSHIELD GLASS M GLASS-WINDSHIELD GLASS M I.00 62.00 00.00 M HINGE ASSY-HOOD,LH I.00 34.00 00.00 M HINGE ASSY-HOOD,RH I.00 34.00 00.00 M PANEL ASSY-HOOD,RH I.00 34.00 00.00 M PANEL ASSY-HOOD		RING AND	CHASSIS ELEC	TRICAL SY	STEM						/
TO APPLY WINDSCREEN SEALANT E PNT88000 TO RENEW FRT WINDSCREEN M SUNDRY TO APPLY BODY SEALANT M SUNDRY POLISHING THE WHOLE CAR S SPECIALISTJOB WO: T147549 ACCIDENT TOWING FROM TELOK BANGAH WAY TO PG CNC NOTE: 55 MIN WAITING M SUNDRY TO SUPPLY SOLAR FIRM FOR FRT WINDSCREEN M PANEL-ROOF M MOULDING-WINDSHIELD GLASS M GLASS-WINDSHIELD M HINGE ASSY-HOOD,LH HINGE ASSY-HOOD,RH D AND AND AND AND ON								1			200.00
TO APPLY WINDSCREEN SEALANT E PNT88000 TO RENEW FRT WINDSCREEN M SUNDRY TO APPLY BODY SEALANT M SUNDRY POLISHING THE WHOLE CAR S SPECIALISTJOB WO: T147549 ACCIDENT TOWING FROM TELOK BANGAH WAY TO PG CNC NOTE: 55 MIN WAITING M SUNDRY TO SUPPLY SOLAR FIRM FOR FRT WINDSCREEN M PANEL-ROOF M MOULDING-WINDSHIELD GLASS M GLASS-WINDSHIELD M HINGE ASSY-HOOD,LH HINGE ASSY-HOOD,RH D AND AND AND AND ON				OSTING HT	-SCAN PRO	IEST	1) 6017	1(0)			
TO APPLY WINDSCREEN SEALANT E PNT88000 TO RENEW FRT WINDSCREEN M SUNDRY TO APPLY BODY SEALANT M SUNDRY POLISHING THE WHOLE CAR S SPECIALISTJOB WO: T147549 ACCIDENT TOWING FROM TELOK BANGAH WAY TO PG CNC NOTE: 55 MIN WAITING M SUNDRY TO SUPPLY SOLAR FIRM FOR FRT WINDSCREEN M PANEL-ROOF M MOULDING-WINDSHIELD GLASS M GLASS-WINDSHIELD M HINGE ASSY-HOOD,LH HINGE ASSY-HOOD,RH D AND AND AND AND ON		-SCAN PRO) IESI		2)		101		l.		80.00
E PNT88000 TO RENEW FRT WINDSCREEN M SUNDRY TO APPLY BODY SEALANT M SUNDRY POLISHING THE WHOLE CAR S SPECIALISTJOB WO: T147549 ACCIDENT TOWING FROM TELOK BANGAH WAY TO PG CNC NOTE: 55 MIN WAITING M SUNDRY TO SUPPLY SOLAR FIRM FOR FRT WINDSCREEN M PANEL-ROOF M MOULDING-WINDSHIELD GLASS 1.00 62.00 00.00 M GLASS-WINDSHIELD 1.00 34.00 00.00 M HINGE ASSY-HOOD,LH 1.00 34.00 00.00 M PANEL ASSY-HOOD,RH 1.00 34.00 00.00 M PANEL ASSY-HOOD M PANEL ASSY-HOOD M PANEL ASSY-HOOD M PANEL ASSY-HOOD M 1.00 1224.00 00.00		MINDSCRE	EN SEALANT								80.00
TO RENEW FRT WINDSCREEN M SUNDRY TO APPLY BODY SEALANT M SUNDRY POLISHING THE WHOLE CAR S SPECIALISTJOB WO: T147549 ACCIDENT TOWING FROM TELOK BANGAH WAY TO PG CNC NOTE: 55 MIN WAITING M SUNDRY TO SUPPLY SOLAR FIRM FOR FRT WINDSCREEN M PANEL-ROOF M MOULDING-WINDSHIELD GLASS 1.00 62.00 00.00 M GLASS-WINDSHIELD 1.00 34.00 00.00 M HINGE ASSY-HOOD,LH 1.00 34.00 00.00 M PANEL ASSY-HOOD,RH 1.00 34.00 00.00 M PANEL ASSY-HOOD M PANEL ASSY-HOOD M PANEL ASSY-HOOD M PANEL ASSY-HOOD M 1.00 1224.00 00.00		WINDSCRE	LII SEALAITI								√ 240.00
M SUNDRY TO APPLY BODY SEALANT M SUNDRY POLISHING THE WHOLE CAR S SPECIALISTJOB WO: T147549 ACCIDENT TOWING FROM TELOK BANGAH WAY TO PG CNC NOTE: 55 MIN WAITING M SUNDRY TO SUPPLY SOLAR FIRM FOR FRT WINDSCREEN M PANEL-ROOF M MOULDING-WINDSHIELD GLASS M GLASS-WINDSHIELD M HINGE ASSY-HOOD,LH HINGE ASSY-HOOD,RH PANEL ASSY-HOOD M PANEL ASSY-HOOD M PANEL ASSY-HOOD M PANEL ASSY-HOOD M 1.00 M		FRT WIND	SCREEN								
M SUNDRY POLISHING THE WHOLE CAR S SPECIALISTJOB W0: T147549 ACCIDENT TOWING FROM TELOK BANGAH WAY TO PG CNC NOTE: 55 MIN WAITING M SUNDRY TO SUPPLY SOLAR FIRM FOR FRT WINDSCREEN M PANEL-ROOF M MOULDING-WINDSHIELD GLASS M GLASS-WINDSHIELD M HINGE ASSY-HOOD,LH M HINGE ASSY-HOOD,RH M PANEL ASSY-HOOD M PANEL ASSY-HOOD M PANEL ASSY-HOOD M PANEL ASSY-HOOD M 1.00											150.00
POLISHING THE WHOLE CAR S SPECIALISTJOB WO: T147549 ACCIDENT TOWING FROM TELOK BANGAH WAY TO PG CNC NOTE: 55 MIN WAITING M SUNDRY TO SUPPLY SOLAR FIRM FOR FRT WINDSCREEN M PANEL-ROOF M MOULDING-WINDSHIELD GLASS 1.00 62.00 00.00 M HINGE ASSY-HOOD, LH HINGE ASSY-HOOD, RH PANEL ASSY-HOOD M 1.00 1224.00 00.00 M 1.00 1224.00 00.00	TO APPLY	BODY SEA	ALANT								,
S SPECIALISTJOB WO: T147549 ACCIDENT TOWING FROM TELOK BANGAH WAY TO PG CNC NOTE: 55 MIN WAITING M SUNDRY TO SUPPLY SOLAR FIRM FOR FRT WINDSCREEN M PANEL-ROOF M MOULDING-WINDSHIELD GLASS 1.00 62.00 00.00 M GLASS-WINDSHIELD 1.00 821.00 00.00 M HINGE ASSY-HOOD,LH HINGE ASSY-HOOD,RH PANEL ASSY-HOOD M PANEL ASSY-HOOD 1.00 1224.00 00.00 M 1224.00 00.00	M SUNDRY										√ 350.00
WO: T147549 ACCIDENT TOWING FROM TELOK BANGAH WAY TO PG CNC NOTE: 55 MIN WAITING M SUNDRY TO SUPPLY SOLAR FIRM FOR FRT WINDSCREEN M PANEL-ROOF M MOULDING-WINDSHIELD GLASS 1.00 62.00 00.00 M GLASS-WINDSHIELD 1.00 821.00 00.00 M HINGE ASSY-HOOD,LH HINGE ASSY-HOOD,RH PANEL ASSY-HOOD M PANEL ASSY-HOOD 1.00 1224.00 00.00 M 1.00 1224.00 00.00	POLISHING	G THE WHO	LE CAR								./
NOTE: 55 MIN WAITING M SUNDRY TO SUPPLY SOLAR FIRM FOR FRT WINDSCREEN M PANEL-ROOF M MOULDING-WINDSHIELD GLASS M GLASS-WINDSHIELD M HINGE ASSY-HOOD,LH M HINGE ASSY-HOOD,RH M PANEL ASSY-HOOD M PANEL ASSY-HOOD M PANEL ASSY-HOOD M 1.00 M	S SPECIALIST	TJOB									100.00
M SUNDRY				ROM TELOK	BANGAH WAY	Y TO PG (CNC				
TO SUPPLY SOLAR FIRM FOR FRT WINDSCREEN M PANEL-ROOF M MOULDING-WINDSHIELD GLASS M GLASS-WINDSHIELD M HINGE ASSY-HOOD,LH M HINGE ASSY-HOOD,RH M PANEL ASSY-HOOD M PANEL ASSY-HOOD M PANEL ASSY-HOOD M PANEL ASSY-HOOD M 1.00 M 1.00		MIN WAIT	ING								/
M PANEL-ROOF 1.00 792.00 00.00 792.00 00.00 792.00 00.00 792.00 00.00 792.00 00.00 792.00 00.00 792.00 00.00 792.00 00.00 792.00 00.00 792.00		/ COLAD E	TOM FOR FRE	ITNIDCODER	· NI						220.00
M MOULDING-WINDSHIELD GLASS 1.00 62.00 00.00 common 8 M GLASS-WINDSHIELD 1.00 821.00 00.00 common 8 M HINGE ASSY-HOOD, LH 1.00 34.00 00.00 common 8 M HINGE ASSY-HOOD, RH 1.00 34.00 00.00 common 8 M PANEL ASSY-HOOD 1.00 1224.00 00.00 common 8			TRM FUR FRI	MINDSCREE	.N			1 00	702 00	00 00	b4 792.00
M GLASS-WINDSHIELD 1.00 821.00 00.0			1 D GL ASS								
M HINGE ASSY-HOOD, LH M HINGE ASSY-HOOD, RH M PANEL ASSY-HOOD 1.00 34.00 00.00 7 1.00 34.00 00.00 7 1.00 1.00 1.00 1.00 1.00 1.0			LD GLASS								
M HINGE ASSY-HOOD, RH M PANEL ASSY-HOOD 1.00 34.00 00.00 ht 12			Н								7 34.00
M PANEL ASSY-HOOD 1.00 1224.00 00.00 ht 12											? 34.00
M LAMP ASSY-HEAD, LH 1.00 810.00 00.00 of 8		F									1 1
	M LAMP ASSY	Y-HEAD, LH	1					1.00	810.00	00.00	at 810.00
Confirm & accepted by	* * *	100 100						1.00	810.00	00.00	00/ 2010.0
	Authorized	signatorv	and company	stamp	_						
Authorized signatory and company stamp			a is 14 days fro			C C			and the same of the same of		

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info
LIM JUN RONG	Cust No/Name	LCV05106/MR LIM JUN RONG
LIN OUN KONG	Reg No/Reg Date	SLX4485P / 28/03/201
BLK 20 TELOK BLANGAH CRES	Date In/Mileage	/ 0
#02-70	Chassis No	KNAFJ411MJ5756390
SINGAPORE 090020	Engine No	G4FGHH688310
Contact No	Make/Model	KIA/FORTE K3 1.6 A L 189
	Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time	Printed	CSE	Operator		WIP No	the since	
CV05106	CRDVCH	05/06/2018	/ 16:03		465 / Tay Jia	n Ye	28104		
	SEP CONTRACTOR	Descriptio	n of Goods	/ Services		Qty l	Init Price	Disc%	Amount
M GRILLE AS M ORNAMENT M MIRROR AS M MIRROR AS M W/STRIP	RADIATOR SSY-RADIA -KIA NO.1 SSY-OUTS3 SSY-OUTS3 ASSY-FR [ASSY-FR [SY-FRONT SY-FRONT	GRILLE, UPR ATOR 115 IDE RR VIEW IDE RR VIEW OR BELT O/S OR BELT O/S DOOR, LH	LH RH RH LH		lma	1.00 1.00 1.00 1.00 1.00 1.00 1.00 1.00	810.00 38.00 160.00 32.00 419.00 419.00 58.00 207.00 207.00 65.00	00.00 00.00 00.00 00.00 00.00 00.00 00.00 00.00 00.00	7 810.00 38.00 160.00 32.00 7 419.00 7 58.00 7 58.00 7 207.00 7 65.00
					11100	grysry Jugar 610 Wf Jove point			
			the Repairer To resurvey b	onsultants hen of the following efore/after spray	ce notify ng: painting	Journ			-
Confirm & a	ccepted b	ру	 Parts prices a Third party so No illegal mo Supplementa 	dification(s) is allo ry item(s) must be	irmation out Prejudice" basis wed	7% GST on	Net 14120.0		14,120.0 988.4

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



5b.

ESTIMATED NORMAL PERIOD FOR REPAIR:

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

AXA IN	NSURANCE PTE	LTD	Ref : CS/AXA180103	366/T1sbe2
	NTON WAY #24 OWERSINGAPO		Date: 12-06-2018 Code: AXA2	
1.		Policy Particula	ars :- THIRD PARTY CLA	IM
I	Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SLX 4485P
ı	Policy No.		Coverage (\$)	0.00
	Claim No.	S8C00HFK	Excess (\$)	0.00
/	Assign From	JOE TAN	Assign Date	07/06/2018
2.		Vehicle Pa	articulars & Condition	
r	Make & Model	KIA CERATO FORTE K3	c.c	1591
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	KNAFJ411MJ5756390	Colour	WHITE
	Odometer	2142	Steering	IN ORDER
F	Brakes	IN ORDER	Modification	SPORTS RIM
(General	GOOD	0	
3.		Con	ditions of Tyres	
		Size	Make	Balance
F	R/H Front Tyre	195/65 R15	NEXEN	6 mm
!	L/H Front Tyre	195/65 R15	NEXEN	6 mm
-	R/H Rear Tyre	195/65 R15	NEXEN	6 mm
	L/H Rear Tyre	195/65 R15	NEXEN	6 mm
4.			iption of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE	O/S, N/S BODY , FRONT AN	ND ROOFTOP PORTION.
	DAMAGES SEE D			
5.		The second second second second second	eral Information	
-	Accident Date	05/05/2018	Inspection Date	07/06/2018
	Survey held at	CYCLE & CARRIAGE KIA P	IE LTD	
		209 PANDAN GARDENS SINGAPORE 609339		
5a.			Remarks	

Estimate Days of Repair

11 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLX 4485P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	PANEL-ROOF (SN)	BENT	792.00	792.00
1	MOULDING-WINDSHIELD GLASS (SN)	NECESSARY	62.00	62.00
1	GLASS-WINDSHIELD (SN)	CRACKED	821.00	821.00
1	HINGE ASSY-HOOD, LH (SN)	* CHECK	34.00	-
1	HINGE ASSY-HOOD, RH (SN)	* CHECK	34.00	-
1	PANEL ASSY-HOOD (SN)	BENT	1,224.00	1,224.00
1	LAMP ASSY-HEAD, LH (SN)	CUT	810.00	810.00
1	LAMP ASSY-HEAD, RH (SN)	* CHECK	810.00	-
1	GARNISH-RADIATOR GRILLE, UPR (SN)	TO REPAIR SEE LABOUR	38.00	-
1	GRILLE ASSY-RADIATOR (SN)	сит	160.00	160.00
1	ORNAMENT-KIA NO.115 (SN)	сит	32.00	32.00
1	MIRROR ASSY-OUTSIDE RR VIEW, LH (SN)	* CHECK	419.00	-
1	MIRROR ASSY-OUTSIDE RR VIEW, RH (SN)	* CHECK	419.00	-
1	W/STRIP ASSY-FR DR BELT O/S RH (SN)	* CHECK	58.00	-
1	W/STRIP ASSY-FR DR BELT O/S LH (SN)	* CHECK	58.00	-
1	GLASS ASSY-FRONT DOOR, LH (SN)	* CHECK	207.00	-
1	GLASS ASSY-FRONT DOOR, RH (SN)	* CHECK	207.00	-
1	LATCH ASSY-HOOD (SN)	* CHECK	65.00	-
			6,250.00	3,901.00
	LABOUR			
	TO RENEW ROOF PANEL, HOOD, REPAIR BOTH A & B PILLAR, FRT BUMPER, FRT BOTH FENDER, FRT BOTH DOOR. INCLUSIVE OF THE REPAIR OF GARNISH-RADIATOR GRILLE, UPR.		3,200.00	2,750.00
	PAINT WORK SPRAY FRT BUMPER, HOOD, FRT BOTH FENDER, FRT BOTH DOOR, FRT BOTH A & B PILLAR, ROOF PANEL.		3,000.00	2,100.00
	TO REMOVE AND REFIT ROOF PANEL TRIM.		300.00	250.00
	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM.		30.00	30.00
	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST.		200.00	200.00
	TO APPLY WINDSCREEN SEALANT.		80.00	80.00
	TO RENEW FRT WINDSCREEN.		240.00	240.00
	TO APPLY BODY SEALANT.		150.00	150.00
	POLISHING THE WHOLE CAR.		350.00	350.00

Report Ref No. CS/AXA18010366/T1sbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	WO: T147549 ACCIDENT TOWING FROM TELOK BANGAH WAY TO PG CNC NOTE: 55 MIN WAITING.		100.00	100.00
	TO SUPPLY SOLAR FILM FOR FRT WINDSCREEN.		220.00	220.00
			7,870.00	6,470.00
	GRAND TOTAL		14,120.00	10,371.00

RECOMMENDED COST OF REPAIRS	10,371.00
(REPAIR COST NOT CONCLUDE)	
(EXCLUDE CHECK ITEMS S\$2,311.00 NETT)	

Report Ref No. CS/AXA18010366/T1sbe2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.