

REF:

NS/WC 18010368 / Stbn2

SCHEDULE

From:

Date:

Estimated Cost:

UD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop no:

of:

Insured

Policy No:

Claims No:

Sum Insured

Excess

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res:

Yes or No

Lump Sum:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

SHF 130 G

Vr Regn:

1/11/17

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius 4.

C.G. 1798

Colour:

Maroon.

A/C:

Insured / Std / NI / NA

Sp Reading:

75394

T-Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB3FH 60 3575451

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size

F: 195/65R15

R:

"

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

6

mm

R/Bal:

6

mm

L/Bal:

6

mm

L/Bal:

6

mm

D.O.A.

23/5/18.

D.O.I.

20/5/18.

Survey held at

SMART.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

TA X/05/18/2119

Lick

NTUC.

SLH 6218R

Partby part \$561.25  
(Red. 2447.15 : 81%)

RECEIVED 6 JUL 2018

Date/Time File Pass to?



Preli. Report



Final Report

67 Typist

Date/Time File Return to?

Days Of Repair:

2

Resurvey No. of Trip:

1

Survey Fee

Transportation

Add Fee:



Site Insp. 1\$



Intercept 1\$



Tech. Visit 1\$



Workshop 1\$

Report Format:

Tp

Lump Sum:

561.25

160  
35

195



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18010368/Stb

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 07-06-2018

189556



Code: INC4

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLH 6218R	Veh. Inspected	SHF 130G
Policy No.	5086742382-01	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	30/05/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	27/05/2018	Inspection Date	30/05/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

eBaoTech

General Claim

Hello, NAC\_PAYA\_UBI\_800601

• Change Language

• Change Password

• Log Out

My Desktop

Notice of Loss

## Policy Query

Policy No.	<input type="text"/>	Date of Accident	<input type="text" value="27/05/2018 13:45"/>						
Vehicle No. (For Motor)	<input type="text" value="SLH6218R"/>								
<input type="button" value="Search"/>									
Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5086742382-01	KHOO CHUAN CHUEN	S8919137H	GPC	drive PREMIUM	SLH6218R	SLH6218R	26/12/2017	25/12/2018
<input type="button" value="Continue"/>									

## Denise Tay (LKKAUTO)

---

**From:** mtreg <mtreg@income.com.sg>  
**Sent:** Friday, 6 July 2018 3:42 PM  
**To:** Denise Tay (LKKAUTO)  
**Subject:** FW: REQUEST CLAIM NUMBER

Hi,

Claim created

With Regards

Samsia  
Senior Admin Assistant, Motor Insurance  
[www.income.com.sg](http://www.income.com.sg)



---

**From:** Denise Tay (LKKAUTO) [mailto:denisetay@lkkauto.com]  
**Sent:** Friday, July 06, 2018 2:16 PM  
**To:** mtreg <mtreg@income.com.sg>  
**Subject:** REQUEST CLAIM NUMBER

Dear Sir,

### TP Claims against NTUC Income: Follow-Through Survey

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Dc
1	MT/0999341-003	SMRT TAXIS PTE LTD	SHF 130G	SLH 6218R	

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	28/05/2018 12:26
Date Of Accident	27/05/2018 11:25
Exact Location Of Accident	RIVER VALLEY ROAD TOWARDS ALEXANDRA ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHF130G
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-800000000

### Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	

### Driver

Name of Driver	LEAN CHEONG SOON
NRIC No	S1560961C
Date Of Birth	26/01/1962
Occupation	OUTDOOR
Date Of Driving Pass	30/05/1994
Driving Experience	23 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	12-56
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN
	GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

I WAS STATIONARY ALONG RIVER VALLEY ROAD TOWARDS ALEXANDRA ROAD WITH ONE PASSENGER (MALE CHINESE) ON BOARD AS IT WAS THE RED TRAFFIC LIGHT. SUDDENLY I FELT AN IMPACT AT THE REAR OF MY TAXI. A VEHICLE SLH6218H HAD COLLIDED ONTO THE REAR OF MY TAXI.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLH6218R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	KHOO CHUAN CHEN
NRIC/Passport Number	S8919137H
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

B-SLH6218R



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date &amp; Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name: \_\_\_\_\_

NRIC/FIN No. \_\_\_\_\_



SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	5369K
<b>Vehicle Details</b>	
Vehicle No.:	SHF130G
Vehicle to be Exported:	No
Intended De-registration Date:	07 Jun 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	2ZRS100824
Chassis No.:	JTDKB3FU603573451
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	01 Nov 2017
First Registration Date:	01 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	31 Oct 2025
PARF Rebate Amount:	\$3,750.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	31 Oct 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$33,596.00
COE Rebate Amount:	\$31,067.00
<b>Total Rebate Amount:</b>	<b>\$34,817.00</b>
<b>Message</b>	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 07 Jun 2018

OK

## SMRT Accident Vehicle Repair Estimates

NTHC CIP

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHF130G  
 Ref. No : TAX/05/18/2119  
 Reg. Date : 01/11/2017  
 Vehicle Type : TAXI  
 Make : TOYOTA PRIUS  
 Model : PRIUS4  
 Name of Driver : LEAN CHEONG SOON  
 Type of Accident : HEAD TO REAR  
 Date / Time of Accident : 27/05/2018 11:26:00 AM  
 Accident Reported Date / Time : 28/05/2018 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by :  
 Vehicle is Towed Back? : No  
 Towed Back Date/Time :  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No : 000024096310  
 Special Instruction to ARC, if any :  
 SLH6218H  
 Prepared Date : 28/05/2018 12:36:21 PM



Sebastian.  
 30/5/18.

- Part by part repair.
- Question Mark Item Photo.
- Photo Before Paint

*[Signature]*  
 8/6/18

L K Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : JTDKB3FU603573451

Mileage :

0

Work Shop :

Repair Completed Date / Time :

**Summary of Repair Estimates**

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 338.00	0.00
Total Spray Painting Charges	: 558.00	0.00
Total Material Charges	: 1,504.78	1,504.78
Other Charges	: 260.00	0.00
<b>TOTAL</b>	<b>: 2,660.78</b>	<b>0.00</b>
<b>Lum Sum Total</b>	<b>: 0.00</b>	<b>0.00</b>
No. of Repair Days	: 3.00	0.00
Prepared / Adjusted By	:	2 days
Arc / Surveyor Sing Off Date	: 28/05/2018 02:20:25 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 28/05/2018 02:20:21 PM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount : 0.00	Prepared Date : 5/28/2018 2:21:58 PM

**Section D - Details of Repair Estimates****Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	338.00 ✓	0.00 200
<b>Total Labour</b>	<b>338.00</b>	<b>0.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00 ✓	0.00 200
TO RESPRAY BUMPER BEAM	180.00 ✗	0.00 ?
<b>Total Spray Painting &amp; Panel Beating</b>	<b>558.00</b>	<b>0.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00 ✗	0.00 ✗
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 30
TO WASH AND VACUUM	60.00 ✗	0.00 ✗
<b>Total Other Costs</b>	<b>260.00</b>	<b>0.00</b>

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52159479 13			COVER, RR BUMPER ASSY	1	423.90	25.00	317.92	Replace	Replace	No <input checked="" type="checkbox"/>
52161160 10			CLIPS PIECE, FRT & RR BUMPER	10	1.50	25.00	11.25	Replace	Replace	No <input checked="" type="checkbox"/>
52462470 30			PAD, RR BUMPER, RH & LH, 1	2	3.80	25.00	5.70	Replace	Replace	No <input checked="" type="checkbox"/>
52462470 20			PAD, RR BUMPER, RH & LH, 2	2	3.80	25.00	5.70	Replace	Replace	No <input checked="" type="checkbox"/>
52462470 10			PAD, RR BUMPER, RH & LH, 3	2	3.80	25.00	5.70	Replace	Replace	No <input checked="" type="checkbox"/>
52191470 30			SEAL, RR BUMPER ARM, RH & LH	2	11.00	25.00	16.50	Replace	Replace	No <input checked="" type="checkbox"/>
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No <input checked="" type="checkbox"/>
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No <input checked="" type="checkbox"/>
52576470 40			RETAINER, RR BUMPER, LH	1	111.50	25.00	83.62	Replace	Replace	No <input checked="" type="checkbox"/>
52575470 40			RETAINER, RR BUMPER, RH	1	112.70	25.00	84.52	Replace	Replace	No <input checked="" type="checkbox"/>
52023470 30			REAR BUMPER REINFORCEMENT	1	318.80	25.00	239.10	Replace	Replace	No <input checked="" type="checkbox"/>
52453470 10			GUARD, RR BUMPER, LOWER	1	558.30	25.00	418.72	Replace	Replace	No <input checked="" type="checkbox"/>
52169470 20			COVER, GUARD RR BUMPER LOWER	1	14.80	25.00	11.10	Replace	Replace	No <input checked="" type="checkbox"/>
52461470 10			PAD, RR BUMPER, CTR	3	2.20	25.00	4.95	Replace	Replace	No <input checked="" type="checkbox"/>
<b>TOTAL MATERIALS</b>								<b>1,504.80</b>	<b>1,504.78</b>	
<b>TOTAL MATERIALS(Discounted)</b>							<b>1,504.78</b>	<b>1,504.78</b>		

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
<b>TOTAL SUPPLEMENTARY MATERIALS</b>									

# SMRT Accident Vehicle Repair Estimates

## Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHF130G  
Ref. No : TAX/05/18/2119  
Reg. Date : 01/11/2017  
Vehicle Type : TAXI  
Make : TOYOTA PRIUS  
Model : PRIUS4  
Name of Driver : LEAN CHEONG SOON  
Type of Accident : HEAD TO REAR  
Date / Time of Accident : 27/05/2018 11:26:00 AM  
Accident Reported Date / Time : 28/05/2018 12:00:00 AM  
Surveyor is Required? : Yes  
Survey by : Sebastian  
Vehicle is Towed Back? : No  
Towed Back Date/Time :  
Replacement Vehicle issued? : No  
Accident Repair Job Card No : 000024096310  
Special Instruction to ARC, if any :

SLH6218H NTUC P/P

BEFORE PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL SURVEYOR SEBASTIAN (LKK)  
& Email : sebastianyeang @lkkauto.com HP:90036121

Prepared Date : 28/05/2018 12:36:21 PM

12:06  
1:05  
1-6-18 - reject sensor reverse faulty.  
pass.

Recording Camera

☐ ☒

Radio Antenna

☐ ☒

1<sup>st</sup> witness

Date 30-5-18


2<sup>nd</sup> witness

Date

E 1/2 F  
KM 75393

01/06/18 12:06 Q/L Rejet

sensor Reverse Faulty



Vehicle to Waga Date In: 30/5  
Time In: 16:32 Driver: TM  
Waga Job No: 05/0338  
Vehicle sent to SMRT Date In: 1-6-2018  
Time In: 11:30 Driver:  
Insured by (SMRT):

**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : JTDKB3FU603573451

Mileage : 0

Work Shop :

Repair Completed Date / Time :

**Summary of Repair Estimates**

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 338.00	200.00
Total Spray Painting Charges	: 558.00	200.00
Total Material Charges	: 588.90	131.25
Other Charges	: 260.00	30.00
<b>TOTAL</b>	<b>: 1,744.90</b>	<b>561.25</b>
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 3.00	2.00
Prepared / Adjusted By	:	SEBASTIAN (LKK)
Arc / Surveyor Sing Off Date	: 28/05/2018 02:20:25 PM	30/05/2018 02:14:23 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 28/05/2018 02:20:21 PM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No : QN-1806-051

Invoice No :

Quotation Date : 7/6

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 5/28/2018 2:21:58 PM



Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	338.00 ✓	200.00
<b>Total Labour</b>	<b>338.00</b>	<b>200.00</b>

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00 ✓	200.00
TO RESPRAY BUMPER BEAM	180.00 X	0.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>558.00</b>	<b>200.00</b>

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30.00
TO WASH AND VACUUM	60.00	0.00
<b>Total Other Costs</b>	<b>260.00</b>	<b>30.00</b>

# Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
5215947913			COVER, RR BUMPER ASSY	R 1	423.90	100.00	0.00	Replace	Repair R	No R
5216116010			CLIPS PIECE, FRT & RR BUMPER	L 10	1.50 15	25.00	11.25	Replace	Replace nec	No nec
5246247030			PAD, RR BUMPER, RH & LH, 1	X 2	3.80 7.6	25.00	5.70	Replace	Check nm	No X
5246247020			PAD, RR BUMPER, RH & LH, 2	X 2	3.80 7.6	25.00	5.70	Replace	Check nm	No X
5246247010			PAD, RR BUMPER, RH & LH, 3	X 2	3.80 7.6	25.00	5.70	Replace	Check nm	No X
5219147030			SEAL, RR BUMPER ARM, RH & LH	X 2	11.00 22	25.00	16.50	Replace	Check nm	No X
			SENSOR REVERSE	X 1	180.00	0.00	180.00	Replace	Check nm	No X
			PIXEL STICKER	L 2	60.00	0.00	120.00	Replace	Replace nec	No L
5257647040			RETAINER, RR BUMPER, LH	X 0	111.50	25.00	0.00	Replace	Not given nm	No X
5257547040			RETAINER, RR BUMPER, RH	X 0	112.70	25.00	0.00	Replace	Not given nm	No X
5202347030			REAR BUMPER REINFORCEMENT	X 1	318.80	25.00	239.10	Replace	Check nm	No Y
5245347010			GUARD, RR BUMPER, LOWER	R 1	558.30	100.00	0.00	Replace	Repair R	No R
5216947020			COVER, GUARD RR BUMPER LOWER	X 0	14.80	25.00	0.00	Replace	Not given nm	No X
5246147010			PAD, RR BUMPER, CTR	X 3	2.20 6.6	25.00	4.95	Replace	Check nm	No Y
TOTAL MATERIALS							588.90	131.25		
TOTAL MATERIALS(Discounted)							588.90	131.25		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

131.25  
+ 200.00  
+ 230.00  


---

561.25

3062.40



Thatcham escribe

## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18010368/Stbn2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE

189556

Date: 09-07-2018



Code: INC4

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLH 6218R	Veh. Inspected	SHF 130G
Policy No.	5086742382-01	Coverage (\$)	0.00
Claim No.	MT/0999341-003	Excess (\$)	0.00
Assign From		Assign Date	30/05/2018

### 2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS 4	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU603573451	Colour	MAROON
Odometer	75394	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	YOKOHAMA	6 mm
L/H Front Tyre	195/65 R15	YOKOHAMA	6 mm
R/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm
L/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

### 5. General Information

Accident Date	27/05/2018	Inspection Date	30/05/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 130G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
10	CLIPS PIECE,FRT & RR BUMPER @\$1.50 (DISC 25%)	NECESSARY	15.00	11.25
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
2	PAD,RR BUMPER,RH & LH,1 @\$3.80	NOT NECESSARY	7.60	-
2	PAD,RR BUMPER,RH & LH,2 @\$3.80	NOT NECESSARY	7.60	-
2	PAD,RR BUMPER,RH & LH,3 @\$3.80	NOT NECESSARY	7.60	-
2	SEAL,RR BUMPER ARM,RH & LH @\$11.00	NOT NECESSARY	22.00	-
1	SENSOR REVERSE	NOT NECESSARY	180.00	-
1	RETAINER,RR BUMPER,LH	NOT NECESSARY	111.50	-
1	RETAINER,RR BUMPER,RH	NOT NECESSARY	112.70	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	318.80	-
1	COVER,GUARD RR BUMPER LOWER	NOT NECESSARY	14.80	-
3	PAD,RR BUMPER,CTR @\$2.20	NOT NECESSARY	6.60	-
1	COVER,RR BUMPER ASSY	TO REPAIR	423.90	-
1	GUARD,RR BUMPER,LOWER	TO REPAIR	558.30	-
			1,906.40	131.25
<b>LABOUR</b>				
	THATCHAM STANDARD REPAIR TIME ON BODY WORKS.		538.00	230.00
	THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.		558.00	200.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			1,156.00	430.00
<b>GRAND TOTAL</b>			<b>3,062.40</b>	<b>561.25</b>
<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>				<b>561.25</b>

Report Ref No. NS/INC18010368/Stbn2

YEANG WAI KEEN

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.