



Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

CHOW FOOK HENG
BLK 339 CLEMENTI AVE 5 #09-244
SINGAPORE 120339

Attention : THE OWNER
Contact : 93398745

Estimate : ES006370

Date : 07/06/2018
Vehicle Num. : SJW6938R
Make/Model : TOYOTA ALTIS 1.6-2010
Chassis/Eng# : MR053ZEE106173256/3ZZ4992925
Accident Date : 03/06/2018
Claim No. :
Reference :
Policy No. :

NOT AUTHORIZED
U/Lng & ?
Rehove After Paint

2 days

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	LIST ITEMS :		
2.	1	FRONT BUMPER	581.90	✓
3.	1	FRONT BUMPER SPONGE	112.00	?
4.	1	FRONT BUMPER REINFORCEMENT	383.80	?
5.	6	FRONT BUMPER SIDE RETAINER R/H	57.20	✓
6.	1	FRONT BUMPER CLIP	8.50	na
7.	1	FRONT BUMPER FOG LAMP GARNISH R/H	51.00	✓
8.	2	FRONT BUMPER FOG LAMP R/H	84.20	?
9.	1	FRONT BUMPER BRACKET	184.20	?
10.	3	FRONT FENDER SPLASH SHIELD R/H	57.30	na
11.	1	FRONT FENDER SPLASH SHIELD CLIP	114.60	X
		HEADLAMP R/H	8.50	na
			25.50	X
			664.50	?

List TotalS\$:
25.00% Discount S\$:

2,414.90
603.73
1,811.17

LABOUR :
CHANGE HEAD LAMP & DO WIRING & LIGHT BEAM LEVEL CHECKS
RUST PROOFING TREATMENT
SPRAY PAINT DAMAGED AREA AFFECTED
TO KNOCK AND STRAIGHTEN FRONT SUPPORT PANEL, FRONT
CHASSIS FRAME, AND CHANGE ALL NECESSARY PARTS

200
na 45.00
220 80.00 X
250 500.00
250 600.00
1,225.00

Labour Total S\$:

SingDollars : Three Thousand Thirty-Six & Cents Seventeen Only

Total S\$: 3,036.17

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: