

REF:

CC3/Alt 13010390 / Arb₂₂

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured

Policy No. 1800052828

Claims No. 801673378 356

Sum Insured:

Excess:

8600

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

158K

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs: 24 days

Res: Yes or No

Lum Sutr:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SL26844M

Yr Regn:

2018 / May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A4 Sedan

cc 1984

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading:

1418

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WAAU22F4XJA092657

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / Rim or

Tyre Size:

F: 245/40R18

R: 245/40R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

06/06/18

Survey held at

Premium

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

OP AIG

7/6/18 Report

8/6/18 Authorise repair

11/6/18 Inform repairer authorise

14/9/18 seek mandate for supplementary

5/10/18 mandate approve

28/10/18 Confirm \$48,365.48 @ 24 days

Red: \$40897.52, 46%

RECEIVED 25 OCT 2018

Date/Time, File Pass to/



Prel. Report

typist



Final Report

Date/Time, File Return to/

3

Add Fee:



Site Insp \$



Interview \$



Tech. Insp \$



Weekend \$

Report Format:

07

Lump Sum / L.B.k / \$

48,365.48

Days Of Repair:

24

Resurvey No. of Trip:

1

Survey Fee:

200

Transportation:

B + RG \$

Photos:

Video:

10

TOTAL

210

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 07 Jun 2018

Preliminary Advice

Vehicle No	: SLZ6844M	Accident Date	: 05/06/2018
Make	: AUDI A4	Policy No.	: 1800052828
Assignment Date	: 07/06/2018	Excess	: S\$0.00
Date of Inspection	: 06/06/2018	Est. Duration of Repair	: 21.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front and rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	88,593.00
Revised Amount	:S\$	47,886.00
Check Items (Estimated)	:S\$	11,149.00
Total	:S\$	59,035.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	158,000.00
COE / PARF Rebate	:S\$	59,664.00
Salvage Value	:S\$	
Margin for Repair	:S\$	98,336.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Print Received Message

This mail is associated with :

***SLZ6844M (8016733783SG)**
OD
Jun 5 2018 8:00AM
[KONG KOK CHEE]
Premium Automobiles Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 08/06/2018 15:24 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$59035.00) - SLZ6844M - Claim Handler: Tr, Tinesh

Approved:59035.00:To commence work, all check and supplementary items to be backed with clear damaged photographs

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Monday, June 11, 2018 12:42 PM
To: 'claims@premiumauto.com.sg'
Cc: SUR
Subject: SLZ 6844M AIG OD

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SLZ 6844M (excess \$600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Tr, Tinesh

Date: 19 Sep 2018

Preliminary Advice

Vehicle No	: SLZ6844M	Accident Date	: 05/06/2018
Make	: AUDI A4	Policy No.	: 1800052828
Assignment Date	: 07/06/2018	Excess	: S\$600.00
Date of Inspection	: 06/06/2018	Est. Duration of Repair	: 21.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front and rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	89,263.00	(Include supplementary \$670.00)
Revised Amount	:S\$	48,365.48	(Include supplementary + check item)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	48,365.48	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	158,000.00
COE / PARF Rebate	:S\$	59,664.00
Salvage Value	:S\$	
Margin for Repair	:S\$	98,336.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Print Received Message

This mail is associated with :

*SLZ6844M (8016733783SG)

OD

Jun 5 2018 8:00AM

[KONG KOK CHEE]

Premium Automobiles Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 15/10/2018 12:01 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$48365.48) - SLZ6844M - Claim Handler: Tr, Tinesh

Approved:48365.48.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Information	
Owner ID Type:	Singapore NRIC
Owner ID:	5786D
Vehicle Details	
Vehicle No.:	SLZ6844M
Vehicle to be Exported:	Yes
Intended De-registration Date:	07 Jun 2018
Vehicle Make:	AUDI
Vehicle Model:	A4 SEDAN 2.0 TFSI S TRONIC
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	CVK052819
Chassis No.:	WAUZZZF4XJA092657
Maximum Power Output:	140.0 kW (187 bhp)
Open Market Value:	\$33,204.00
Original Registration Date:	15 May 2018
First Registration Date:	15 May 2018
Transfer Count:	0
Actual ARF Paid:	\$38,486.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 May 2028
PARF Rebate Amount:	\$28,864.00
Intended COE Rebate Details	
COE Expiry Date:	14 May 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$38,501.00
COE Rebate Amount:	\$30,800.00
Total Rebate Amount:	\$59,664.00

The information contained herein is correct as at 07 Jun 2018

OK



CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)

▶ **SEARCH** to [Advanced Search](#)

[Home](#) > [New Cars](#) > [Audi A4 Search Results](#)▶ **Audi A4 Search Results (2 vehicles)**Sort by

15 results/page

Car Model	Price	Dealer	Built in	User Rating
Audi A4				
	☐ 2.0 TFSI S tronic (A) NEW VARIANT \$176,980 \$13,300 /yr (2)	Premium Automobiles • 19.2km/l 188bhp 7-speed (A) S tronic	Germany	★★★★☆ 17 User Reviews Promotion Editor's Review
	☐ 2.0 TFSI quattro S tronic Design (A) NEW VARIANT \$253,080 \$22,400 /yr (2)	• 16.1km/l 252bhp 7-speed (A) S tronic		
Audi A4 Avant				
	☐ 2.0 TFSI S tronic (A) NEW VARIANT \$186,480 \$13,300 /yr (2)	Premium Automobiles • 18.5km/l 188bhp 7-speed (A) S tronic	Germany	★★★★☆ 1 User Review
	☐ 2.0 TFSI quattro S tronic Design (A) NEW VARIANT \$262,680 \$23,700 /yr (2)	• 15.4km/l 252bhp 7-speed (A) S tronic		

Car Model	Price	Dealer	Built in	User Rating
-----------	-------	--------	----------	-------------

15 results/page

7 result(s) for **Audi A4** models no longer being sold by local distributors.
[View all past Audi A4 cars](#)

Audi A4 Avant
(2013-2016)Audi A4
(2008-2016)Audi A4 Allroad
(2011-2014)Audi A4 Avant
(2008-2014)Audi A4 Cabriolet
(2006-2009)
[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car site for buying Singapore cars, including new cars, parallel import cars & used cars. View all new cars, such as Toyota, Honda, Nissan, Volkswagen, Mitsubishi & BMW. We have new car dealers comprising parallel importers, authorised car distributors, and used car dealers. Find new car price lists, new car launches, new car promotions, new car reviews, latest car news & car advice. Also join our car discussion and forum discussion for car reviews, motoring news & motoring guides. Visit our partner sites who have job openings for Singapore jobs, Singapore classifieds, motor and real estate properties for sale.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow [sgCarMart.com](#)
[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2018 sgCarMart. All rights reserved.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/06/2018 12:22
Date Of Accident	05/06/2018 08:15
Exact Location Of Accident	ENTRANCE OF KPE FROM TPE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLZ6844M
Insured/Policyholder	
Name Of Registered Owner	KONG KOK CHEE
NRIC No	S7135786D
Email Address	KONG.KC@PORTEK.COM
Mobile Phone No	(LOCAL) +65-97455659
Alternative Phone No	OTHERS-97455659

Vehicle Particulars

Manufacturer	AUDI
Model	A4 SEDAN 2.0 TFSI 8W
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800052828
Cover Note Number	

Driver

Name of Driver	KONG KOK CHEE
NRIC No	S7135786D
Date Of Birth	12/10/1971
Occupation	INDOOR
Date Of Driving Pass	05/07/1989
Driving Experience	28 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97455659
Fax Number	
Contact Number	OTHERS-97455659
Email Address	KONG.KC@PORTEK.COM

Address	BLK 318B ANCHORVALE LINK #15-263
Postcode	542318
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : LAU SUET YEE GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 5 JUN 2018 AT ABOUT 0815 HRS, WHILE ENTERING KPE TUNNEL ENTRANCE VIA TPE, VEHICLE NUMBER SJX1034B (WHITE SUZUKI SWIFT), DRIVEN BY FERNANDEZ COLIN BENEDICT (S8537767A) DID AN EMERGENCY BRAKE. I MANAGED TO STOP IN TIME WITHOUT CONTACT BUT VEHICLE NUMBER SJK896E (BLUE TOYOTA ISIS) DRIVEN BY RICHARD TOH KOK SAN (S7827330E), HIT MY CAR FROM BEHIND, RESULTING IN THE DAMAGE. IN TURN, MY CAR MOVED FORWARD DUE TO THE IMPACT AND HIT SJX1034B. MY CAR IS IN THE MIDDLE OF THE CHAIN ACCIDENT. AFTER THE ACCIDENT, MY WIFE FELT PAIN ON HER LEFT SHOULDER AND I WILL BE SEEKING ADVICE FROM THE DOCTOR. LIKEWISE, I WILL ALSO SEEK MEDICAL ADVICE FOR A PAIN ON LEFT SHOULDER AS WELL.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJK896E
Vehicle Make/Model/Colour	TOYOTA / ISIS / BLUE
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	RICHARD TOH KOK SAN
NRIC/Passport Number	S7827330E
Contact Number	98719276

Address

BLK 448A, SENGKANG WEST
#20-203

Postcode

791448

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SJX1034B

Vehicle Make/Model/Colour

SUZUKI/ SWIFT / WHITE

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

FERNANDEZ COLIN BENEDICT

NRIC/Passport Number

S8537767A

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

Approximate Age

Injuries Sustain

SHOULDER PAIN

Injured person in which vehicle?

SLZ6844M

Were seat belts worn?

Was this injured conveyed to hospital by
ambulance?

NO

Address

Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 5/6/18

@ 1030h

Driver's Signature

(If driver is not the policyholder)

Date & Time:




Reporting Centre Personnel's Signature

Name: Tan Fong

NRIC/VIN No.: 429131471

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 5 Jun'18 @ about 0815 hrs, while ~~entering~~ KPE tunnel entrance via TPE, vehicle number SJK 103HB (White Suzuki Swift) driven by Fernandez Colin Benedict (S853767A) ~~did~~ an emergency brake. I managed to stop in time without contact but vehicle number SJK 896E (Blue Toyota Isis) driven by Richard Teh Kek San (S7827330E) hits my car from behind, resulting in the damage. In turn, my car moved forward due to the impact and hit SJK 103HB. My car is in the middle of the chain accident.

After the accident, my wife felt pain on her left shoulder and will be seeking advice from doctor. Likewise, I will also seek ~~my~~ medical advice for a pain on left shoulder as well.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 5/6/18

@ 1010 hrs

Driver's Signature

(If driver is not the policyholder)

Date & Time:



Reporting Centre Personnel's Signature

Name: Tay Fong

NRIC/FIN No.: 62001971

Accident Photo





CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : KONG KOK CHEE (GONG GUOZHI)
Period of Insurance : 15 May 2018 To 14 May 2019
Engine No. : CVK052819
Chassis No. : WAUZZZF4XJA092657

Vehicle No. : SLZ6844M
Policy No. : 1800052828
Endorsement No. : 000000000201327
Issued Date : 17 May 2018

ABOUT THE COVER

Make/Model : AUDI A4 Sedan 2.0 TFSI S tronic
Engine Capacity/Tonnage : 1,984.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2018
Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive*

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use: 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$1600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

KONG KOK CHEE (GONG GUOZHI) - \$1600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125201

PREMIUM LEASING - DL

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

SSCSAN

What can the 24-hour AIG Auto Emergency Hotline provide for you?

- Immediate assistance after an accident
- Emergency breakdown service
- Towing service (accident or non-accident related)
- Advice on Motor Claims procedures
- Medical Referral Assistance

If no one is injured in the accident:

- You are not required to make any police report.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s).
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the police, providing full details of the circumstances of the accident.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s), if applicable.
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

What should I do in the event of an accident?

- Keep calm and move your car to a safe place
- Do not admit or discuss fault or blame with the other party(ies).
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.
- Submit Writ/Summons/Correspondences from third party(ies) to AIG immediately

LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number **(65) 6419-3000** for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

Steps to activate Loss of Use Car Replacement Benefit and Important Information

1. To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
2. Your rental car will be made available within **5** working hours of activation with the Rental Car Company.
3. At the time of collection of the Rental Car, the **original** insurance policy and schedule issued by AIG, a copy of the Accident Report from **Audi Customer Service Centre** must be produced.
4. The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
5. Rental cars are strictly for use in Singapore only.
6. Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
7. Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.

Rental Car Company: Popular Rent A Car Pte. Ltd.

Activation Hotline: 67428888

501 Guillemard Road Singapore 399840

Operation Hours: Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 4pm

*The Rental Car Company's Terms & Conditions apply (i.e., refundable security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc).

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is **IMPORTANT** and **MUST** be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number: **S7135786D**

Name: **KONG KOK CHEE**
(GONG GUOZHI)

Birth Date: **12 Oct 1971**

Issue Date: **03 Jun 2003**

000529089




REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S79858911**

Name: **LAU SUET YEE**
劉雪儀

Race: **CHINESE**

Date of birth: **02-08-1979** Sex: **F**

Country of birth: **HONG KONG**

S79858911






YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE: **05 Jul 1989**

License No: **S7135786D**

HP 425A



NRIC No: **S79858911**

Nationality: **CHINESE**

Date of issue: **28-09-2007**

APT BLK 318B ANCHORVALE LINK #15-263
SINGAPORE 542318

NRIC No: **S79858911** Date: **11/04/2009** No: **8194218**




Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0659/2018/GW
Date	:	6-Jun-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Kong Kok Chee
Address	:	Blk 318 B Anchorvale link #15-263 Singapore 542318
Telephone	:	(HP) 97455659
Type of Claim	:	Own Damage Claims
Policy No.	:	1800052828
Vehicle No	:	SLZ 6844 M
Model Code	:	Audi A4 Sedan 2.0 TFSI
Model / Year	:	May-18
Engine No	:	CVK 052819
Chassis No	:	WAUZZZF4XJA092657
Mileage	:	
Date In	:	5-Jun-18
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	5-Jun-18
Place of Accident	:	Entrance Of KPE from TPE

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6843 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLZ 6844 M.

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N 5: 360.00 ✓
2	To dismantle and renew front bumper, both headlights and bonnet. Re-organise front crash management components. Reinstall all parts removed.	\$ 2,400.00 1252 ✓
3	To respray front bumper and bonnet.	\$ 1,500.00 7100 ✓
TOTAL LABOUR CHARGES - FRONT		\$ 4,260.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1163

Telefax

Material List for Accident Vehicle Regn No. SLZ 6844 M.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Rehnd</i>	\$ 1,849.00	✓ 1979.20
2	RADIATOR GRILLE <i>Crashed</i>	\$ 972.00	✓ 777.20
3	FRONT BUMPER FIXING PART <i>Green</i>	\$ 245.00	X
4	FRONT BUMPER GRILLE-CENTRE	\$ 171.00	X
5	FRONT BUMPER AIR GUIDE GRILLE-LH/RH <i>Not new</i>	\$ 236.00	X
6	FOAM FILLER PIECE <i>Not new</i>	\$ 107.00	X
7	FRONT BUMPER CARRIER <i>Not new</i>	\$ 702.00	X
8	FRONT BUMPER SUPPORT-LH/RH <i>Not new</i>	2 \$ 48.00	X
9	FRONT BUMPER BRACKET LOCK CARRIER <i>Crashed</i>	\$ 118.00	✓ 94.00
10	FRONT BUMPER COVER <i>Not new</i>	\$ 109.00	X
11	SIGN "CAUTION" <i>Not new</i>	\$ 12.00	X
12	AIR CONDITIONER STICKER <i>Not new</i>	\$ 7.00	X
13	RELEASE LEVER <i>Not new</i>	\$ 12.00	X
14	BOWDEN CABLE	\$ 50.00	X
15	LED HEADLIGHTS-LH/RH <i>Lit</i>	2 \$ 2390.00 6973	✓ 5575.40
16	BONNET <i>Crashed</i>	\$ 2,163.00	✓ 1760.40
17	BONNET ATTACHMENT PARTS <i>Not new</i>	\$ 105.00	X
18	BONNET IMPACT PROTECTION-LH/RH <i>Not new</i>	2 \$ 48.00	✓ 37.70
19	BONNET IMPACT PROTECTION-CENTER	\$ 24.00	✓ 18.89
20	FRONT NO. PLATE <i>Bit</i>	S/N \$ 23.00	✓ 25.00
TOTAL SPARE PARTS CHARGES - FRONT		\$ 20,949.00	
TOTAL LABOUR CHARGES - FRONT		\$ 4,260.00	
GRAND TOTAL - FRONT		\$ 25,209.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Some parts are Special Item

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLZ 6844 M.

S/N	Nature of Jobs	Estimated Charges
1	To remove and renew rear parking aid and rear lid kick sensor assy.	S/N \$ 360.00 ✓ 360
2	To dislodge and reinstall rear wire harness, audio equipment, control units, relay and fuse trays, end panelling, spare wheel housing and rear lid harness.	S/N \$ 1,800.00 ✓ 1800
3	To remove and reinstall rear seats, back rest, carpets, ABCD pillar trims, disengage air bag system.	S/N \$ 1,800.00 ✓ 1800
4	To remove and and renew center and rear exhaust silencers. Align to position.	S/N \$ 480.00 ? 480
5	To renew lhs rear 1/4 glass and rear windscreen.	S/N \$ 600.00 X X
6	To remove and install rear suspension assy to facillitate cellette bench repairs. Inspect for damages.	S/N \$ 2,800.00 ✓ 2800
SUB-TOTAL LABOUR CHARGES - (REAR)		: \$ 7,840.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLZ 6844 M

S/N	Nature of Jobs	Estimated Charges
7	To remove and reinstall petrol tank.	S/N \$ 480.00 ✓ 480
8	To set up and place vehicle on car-o-liner.	S/N \$ 2,400.00 ✓ 2400
9	To dismantle rear bumper and rear lid. Cut out and weld rear end panels, spare wheel housing, cross members and lhs rear fender. Repair and align whole rear substructure to specification of origin. Renew rear bumper and rear lid. Reinstall all parts removed.	\$ 12,000.00 5000.5000 Not inclusive of rear fender
10	To carry out stonechip primer work on rear panelling and spare wheel housing.	S/N \$ 800.00 ✓ 800
11	To spray paint on rear bumper, rear lid, spare wheel housing, boot floor, end panelling, both rear fenders, lhs sill panel, drain panel, roof channel. To carry out joint sealer works, cavity preservation and stone chip treatment.	\$ 6,500.00 3850 3850
12	To carry out wheel alignment.	S/N \$ 240.00 ✓ 240
SUB-TOTAL LABOUR CHARGES - (REAR)		: \$ 30,260.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLZ 6844 M.

		Damage Parts & Prices	
S/N	Parts Description	S/NETT	REMARKS
1	REAR BUMPER <i>Dislnd</i>	S	1,907.00 - 1525.60
2	REAR BUMPER FIXING PARTS <i>Dislnd</i>	S	63.00 - X
3	REAR BUMPER SPOILER	S	216.00 - 172.80
4	REAR BUMPER SECURING STRIP <i>Dislnd</i>	S	191.00 - 152.80
5	REAR LIGHT REFLECTOR-LH/RH <i>RH embled</i>	S	20.00 - 35 27.76
6	REAR SENSOR <i>Dislnd</i>	4 S	842.00 - 673.60
7	REAR SENSOR SEAL RING <i>rec</i>	S	14.00 - 10.38
8	REAR BUMPER WIRING <i>Not Nec</i>	S	598.00 - ? X
9	CABLE HOLDER <i>Dislnd</i>	S	8.00 - 6.24
10	OPENING BOOT LID CONTROL UNIT <i>Not a DM</i>	S	362.00 - 389.60 X
11	RETAINER CONTROL UNIT <i>rec</i>	S	7.00 - X
12	TAILGATE OPENING SENSOR LINE <i>Dislnd</i>	S	184.00 - 147.20
13	REAR BUMPER CARRIER <i>Best</i>	S	786.00 - 629.40
14	REAR BUMPR SEAL <i>rec</i>	2 S	24.00 - 18.86
15	REAR BUMPER GUDIE SECTION-LH/RH <i>rec</i>	2 S	75.00 - X
16	REAR BUMPER UPPER GUDIE SECTION-LH/RH <i>rec</i>	2 S DM	38.00 - 29.76 X
17	REAR LID <i>Dislnd</i>	S	2,362.00 - 1859.60
18	REAR LID ATTACHMENT PARTS <i>rec</i>	S	125.00 - 93.60
19	REAR LID HINGE-LH/RH <i>Not Nec</i>	2 S	400.00 - X
20	REAR LID LOCK <i>Not Nec</i>	S	202.00 - X
SUB-TOTAL SPARE PARTS - REAR		S	8,474.00

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLZ 6844 M.

		Damage Parts & Prices	
S/N	Parts Description	S/NETT	REMARKS
21	REAR LID PUSH BUTTON <i>Not in</i>	S	475.00 +
22	REAR LOCK STRIKER <i>2</i>	S	29.00 +
23	REAR STOP BUFFER <i>Not in</i>	2 S	28.00 +
24	REAR GASKET FLAP <i>Not in</i>	S	176.00 +
25	ADHESIVE PACKING <i>2</i>	S	15.00 ✓ 11.60
26	AUDI EMBLEM <i>Not in</i>	S	108.00 ✓ 82.00
27	REAR INSCRIPTION "A4" <i>Not in</i>	S	83.00 ✓ 66.16
28	REAR INSCRIPTION "TFSI" <i>Not in</i>	S	83.00 ✓ 66.16
29	LED TAIL LIGHTS-LH/RH <i>2</i>	2 S	1,830.00 +
30	TAIL LIGHTS TRIM-LH/RH <i>Not in</i>	2 S	52.00 +
31	LED OUTER TAIL LIGHTS-LH/RH <i>Not in</i>	2 S	1,632.00 +
32	OUTER TRIM TAIL LIGHTS-LH/RH <i>Not in</i>	2 S	52.00 +
33	REAR CROSS PANEL <i>Distorted</i>	S	230.00 ✓ 188.60
34	REAR CROSS PANEL REINFORCEMENT <i>Distorted</i>	S	445.00 ✓ 356.00
35	REAR SIDE PANEL REINFORCEMENT-LH/RH <i>Distorted</i>	2 S	360.00 ✓ 287.20
36	SPARE WHEEL WELL <i>Distorted</i>	S	1,938.00 ✓ 1550.40
37	SPARE WHEEL MOUNTING <i>Not in</i>	S	117.00 ? X
38	BATTERY CLAMPING STRIP <i>Not in</i>	S	11.00 ? 8.50
39	CROSS MEMBER <i>Not in</i>	S	1,263.00 ? X
40	REAR SILENCER HEAT SHIELD-LH/RH <i>Not in</i>	2 S	266.00 133 X
SUB-TOTAL SPARE PARTS - REAR			\$ 9,193.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLZ 6844 M.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
41	SIDE PANEL SECTIONAL PART-LH <i>Regr</i>	\$	2,347.00 X
42	SIDE WINDOW	\$	541.00 X
43	REAR WINDOW	\$	1,014.00 X
44	PRIMER	2 \$	37.00 X
45	SILENCER-CENTRE <i>Best.</i>	\$	801.00 ? 640.00
46	REAR SILENCER-LH/RH <i>Best</i>	2 \$	1,578.00 ? 1262.40
47	DUAL CLIP <i>new</i>	2 \$	85.00 ? 68.00
48	EXHAUST SILENCER BRACKET <i>Damaged.</i>	2 \$	73.00 ? 58.00
49	REAR NO.PLATE <i>Revised</i>	S/N \$	25.00 ✓ 25.00
50	ACRYLIC SEALER ?	S/N \$	360.00 ✓ 360.00
51	CAVITY WAX <i>new</i>	S/N \$	280.00 ✓ 280.00
52	STONE CHIP	S/N \$	360.00 ✓ 360.00
53	METAL FILLER POWDER <i>new</i>	S/N \$	280.00 ✓ 280.00
54	WINDSCREEN SEALANT <i>new</i>	S/N \$	200.00 X
55	1/4 GLASS SEALANT <i>new</i>	S/N \$	100.00 X
56	CENTRAL PROTECTION <i>Activated.</i>	\$	470.00 ? 376.00
57	THREE POINT AUTOMATIC SEAT BELT-LH/RH <i>Activated</i>	2 \$	1,912.00 ✓ 1529.60
58	SEAT BELT HEIGHT ADJUSTER <i>new Broken</i>	2 \$	306.00 X 244.80
59	AIRBAG CONTROL UNIT <i>new Activated</i>	\$	1,870.00 ? 1496.00
60	AIRBAG CRASH SENSOR <i>new</i>	3 \$	818.00 ? X
61	SUNDRIES <i>new</i>	\$	2,000.00 ? 30.28
TOTAL SPARE PARTS - REAR		:	\$ 33,124.00
TOTAL LABOUR CHARGES - REAR		:	\$ 30,260.00
GRAND TOTAL - REAR		:	\$ 63,384.00
GRAND TOTAL - FRONT/REAR		:	\$ 88,593.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 06/06/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 21 Days

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LOK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary work(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0659/2018/GW
21-Jul-18
CHANG
1 of 1
SLZ 6844 M
Audi A4 SEDAN 2.0 TFSI

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	LOCK CARRIER AIR GUIDE - LH/RH UPPER <i>2 ang d.</i>	\$ 20.00	\$ 15.36 ✓
2	REAR SILENCER HEAT SHIELD - LH/RH <i>crumpled.</i>	\$ 266.00	\$ 212.00 ✓
TOTAL PARTS :		\$ 286.00	\$ 227.36
<u>labour</u>			
1	TO CARRY OUT DIAGNOSTIC SN	\$ 384.00	\$ 384.00 ✓
GRAND TOTAL :		\$ 670.00	\$ 611.36

For Premium Automobiles Pte Ltd

Adrian Ling
SLS

Authorised Signature

Janice Lee (LKKAUTO)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Wednesday, September 05, 2018 3:30 PM
To: Adrian Ling (LKKAUTO); Janice Lee (LKKAUTO); SUR; Carrine Leong;
jiayee.yap@premiumauto.com.sg; Chang Chee Sing
Subject: AMENDED REVISION - SLZ6844M - OD AIG - SURVEYED 6 JUN 18
Attachments: PA06592018 - SLZ 6844 M- A4 Sedan 2.0 TFSI - FRONT + REAR (AIG) + SUPP.xls

Hi Adrian and all,

Amended revised estimate is attached.

Please confirm repair cost of \$48,365.44 @ 25 days of repairs exclude 1 PH and 3 Sundays.

Your early closure is well appreciated.

Best regards - jb

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0659/2018/GW
Date	:	06-Jun-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adnan

We took 25 days exclude 1 PH

3 Sundays - jo 4th Sept 18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Kong Kok Chee
Address	:	Blk 318 B Anchorvale link #15-263 Singapore 542318
Telephone	:	(HP) 97455659
Type of Claim	:	Own Damage Claims
Policy No.	:	1800052828
Vehicle No	:	SLZ 6844 M
Model Code	:	Audi A4 Sedan 2.0 TFSI
Model / Year	:	May-18
Engine No	:	CVK 052819
Chassis No	:	WAUZZZF4XJA092657
Mileage	:	
Date In	:	05-Jun-18
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	05-Jun-18
Place of Accident	:	Entrance Of KPE from TPE

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLZ 6844 M.

S/N	Nature of Jobs	Estimated Charges			
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N	\$ 360.00	\$	360.00
2	To dismantle and renew front bumper, both headlights and bonnet. Re-organise front crash management components. Reinstall all parts removed.	\$	2,400.00	\$	1,250.00
3	To respray front bumper and bonnet.	\$	1,500.00	\$	1,100.00
TOTAL LABOUR CHARGES - FRONT		:	\$ 4,260.00	\$	2,710.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLZ 6844 M.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 1,849.00	\$ 1,479.20
2	RADIATOR GRILLE	\$ 972.00	\$ 777.20
3	FRONT BUMPER FIXING PARST	\$ 245.00	
4	FRONT BUMPER GRILLE-CENTRE	\$ 171.00	
5	FRONT BUMPER AIR GUIDE GRILE-LH/RH	\$ 236.00	
6	FOAM FILLER PIECE	\$ 107.00	
7	FRONT BUMPER CARRIER	\$ 702.00	
8	FRONT BUMPER SUPPORT-LH/RH	2 \$ 48.00	
9	FRONT BUMPER BRACKET LOCK CARRIER	\$ 118.00	\$ 94.00
10	FRONT BUMPER COVER	\$ 109.00	
11	SIGN 'CAUTION'	\$ 12.00	
12	AIR CONDITIONER STICKER	\$ 7.00	
13	RELEASE LEVER	\$ 12.00	
14	BOWDEN CABLE	\$ 50.00	
15	LED HEADLIGHTS-LH/RH	2 \$ 13,946.00	\$ 5,578.40
16	BONNET	\$ 2,163.00	\$ 1,730.40
17	BONNET ATTACHMENT PARTS	\$ 105.00	
18	BONNET IMPACT PROTECTION-LH/RH	2 \$ 48.00	\$ 37.76
19	BONNET IMPACT PROTECTION-CENTER	\$ 24.00	\$ 18.88
20	FRONT NO.PLATE	S/N \$ 25.00	\$ 25.00
TOTAL SPARE PARTS CHARGES - FRONT		\$ 20,949.00	\$ 9,740.84
TOTAL LABOUR CHARGES - FRONT		\$ 4,260.00	\$ 2,710.00
GRAND TOTAL - FRONT		\$ 25,209.00	\$ 12,450.84

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLZ 6844 M.

S/N	Nature of Jobs	Estimated Charges	
	<i>Labour front c/f</i>	\$	2,710.00
1	To remove and renew rear parking aid and rear lid kick sensor assy.	S/N \$ 360.00	\$ 360.00
2	To dislodge and reinstall rear wire harness, audio equipment, control units, relay and fuse trays, end panelling, spare wheel housing and rear lid harness.	S/N \$ 1,800.00	\$ 1,800.00
3	To remove and reinstall rear seats, back rest, carpets, ABCD pillar trims, disengage air bag system.	S/N \$ 1,800.00	\$ 1,800.00
4	To remove and and renew center and rear exhaust silencers. Align to position.	S/N \$ 480.00	\$ 480.00
5	To renew lhs rear 1/4 glass and rear windscreen.	S/N \$ 600.00	
6	To remove and install rear suspension assy to facillitate cellette bench repairs. Inspect for damages.	S/N \$ 2,800.00	\$ 2,800.00
SUB-TOTAL LABOUR CHARGES - (REAR)		: \$ 7,840.00	\$ 9,950.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLZ 6844 M

S/N	Nature of Jobs		Estimated Charges		
		<i>c/f</i>		\$	9,950.00
7	To remove and reinstall petrol tank.	S/N	\$ 480.00	\$	480.00
8	To set up and place vehicle on car-o-liner.	S/N	\$ 2,400.00	\$	2,400.00
9	To dismantle rear bumper and rear lid. Cut out and weld rear end panels, spare wheel housing, cross members and lhs rear fender. Repair and align whole rear substructure to specification of origin. Renew rear bumper and rear lid. Reinstall all parts removed.		\$ 12,000.00	\$	5,000.00
10	To carry out stonechip primer work on rear panelling and spare wheel housing.	S/N	\$ 800.00	\$	800.00
11	To spray paint on rear bumper, rear lid, spare wheel housing, boot floor, end panelling, both rear fenders, lhs sill panel, drain panel, roof channel. To carry out joint sealer works, cavity preservation and stone chip treatment.		\$ 6,500.00	\$	3,850.00
11A	Added labour charges - diagnostic - see attached	S/N	\$ 384.00	\$	384.00
12	To carry out wheel alignment.	S/N	\$ 240.00	\$	240.00
SUB-TOTAL LABOUR CHARGES - (REAR)		:	\$ 30,644.00	\$	23,104.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLZ 6844 M.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
	<i>Materials frt c/f</i>		\$ 9,740.84
1	REAR BUMPER	\$ 1,907.00	\$ 1,525.60
2	REAR BUMPER FIXING PARTS	\$ 63.00	
3	REAR BUMPER SPOILER	\$ 216.00	\$ 172.80
4	REAR BUMPER SECURING STRIP	\$ 191.00	\$ 152.80
5	REAR LIGHT REFLECTOR-LH/RH	\$ 70.00	\$ 27.76
6	REAR SENSOR	4 \$ 842.00	\$ 673.60
7	REAR SENSOR SEAL RING	\$ 14.00	\$ 10.88
8	REAR BUMPER WIRING	\$ 598.00	
9	CABLE HOLDER	\$ 8.00	\$ 6.24
10	OPENING BOOT LID CONTROL UNTI	\$ 362.00	\$ 289.60
11	RETAINER CONTROL UNIT	\$ 7.00	
12	TAILGATE OPNENING SENSOR LINE	\$ 184.00	\$ 147.20
13	REAR BUMPER CARRIER	\$ 786.00	\$ 628.40
14	REAR BUMPR SEAL	2 \$ 24.00	\$ 18.56
15	REAR BUMPER GUDIE SECTION-LH/RH	2 \$ 75.00	
16	REAR BUMPER UPPER GUDIE SECTION-LH/RH	2 \$ 38.00	\$ 29.76
17	REAR LID	\$ 2,362.00	\$ 1,889.60
18	REAR LID ATTACHMENT PARTS	\$ 125.00	\$ 93.60
19	REAR LID HINGE-LH/RH	2 \$ 400.00	
20	REAR LID LOCK	\$ 202.00	
SUB-TOTAL SPARE PARTS - REAR		\$ 8,474.00	\$ 15,407.24

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Material List for Accident Vehicle Regn No.SLZ 6844 M.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLZ 6844 M.

S/N	Parts Description	Damage Parts & Prices		
		S/NETT	REMARKS	
		c/f	\$	18,023.12
41	SIDE PANEL SECTIONAL PART-LH	\$	2,347.00	
42	SIDE WINDOW	\$	541.00	
43	REAR WINDOW	\$	1,014.00	
44	PRIMER	2 \$	37.00	
45	SILENCER-CENTRE	\$	801.00	\$ 640.80
46	REAR SILENCER-LH/RH	2 \$	1,578.00	\$ 1,262.40
47	DUAL CLIP	2 \$	85.00	\$ 68.00
48	EXHAUST SILENCER BRACKET	2 \$	73.00	\$ 58.08
49	REAR NO.PLATE	S/N \$	25.00	\$ 25.00
50	ACRYLIC SEALER	S/N \$	360.00	\$ 360.00
51	CAVITY WAX	S/N \$	280.00	\$ 280.00
52	STONE CHIP	S/N \$	360.00	\$ 360.00
53	METAL FILLER POWDER	S/N \$	280.00	\$ 280.00
54	WINDSCREEN SEALANT	S/N \$	200.00	
55	1/4 GLASS SEALANT	S/N \$	100.00	
56	CENTRAL PROTECTION	\$	470.00	\$ 376.00
57	THREE POINT AUTOMATIC SEAT BELT-LH/RH	2 \$	1,912.00	\$ 1,529.60
58	SEAT BELT HEIGHT ADJUSTER	2 \$	306.00	\$ 244.80
59	AIRBAG CONTROL UNIT	\$	1,870.00	\$ 1,496.00
60	AIRBAG CRASH SENSOR	3 \$	818.00	
61	SUPPLEMENTARY	\$	286.00	\$ 227.36
62	SUNDRIES	\$	2,000.00	\$ 30.28
Total parts		:	\$ 33,410.00	\$ 25,261.44
Total labour		:	\$ 30,644.00	\$ 23,104.00
GRAND TOTAL - frt/rr		:	\$ 64,054.00	\$ 48,365.44

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLZ 6844 M

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0659/2018/MAS

23 Oct 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

total pages

RE: INSURANCE CLAIM FOR SLZ 6844 M, Audi A4 Sedan 2.0 TFSI

With reference to the above-mentioned vehicle, no **SLZ 6844 M**, claimant, **Mr. Kong Kok Chee**, please find the related document per attached.

1. A copy of the Original invoice no. 85013028 – S\$51,109.06
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLZ 6844 M

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119938
Main Telephone 6384 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 119938
Telephone 6384 2223
Telefax 6475 1033

Ubi Service Centre
55 Ubi Road 1
Singapore 408654
Telephone 6385 1233
Telefax 6385 1233

Customer Service
Service Appointment
Four Breakdown Service
Email
6384 2523
6478 1233
customer.care@premiumaudi.com.sg

Page 1 14:00

INS TAX INVOICE

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD	Invoice: 85013028	Account: 00006 (T 0)
MOTOR CLAIM DEPT	Date : 18/10/2018	AIG ASIA PACIFIC INSURANCE PTE LTD
AIG BUILDING	Order : SLZ6844M	MOTOR CLAIM DEPT
78 SHENTON WAY	Term : 30	AIG BUILDING
#07-16		78 SHENTON WAY
SINGAPORE 079120 079120		#07-16
		SINGAPORE 079120

Regn No.: SLZ6844M (V 36451)	Regn Date: 15/05/2018	Mileage: 430	WIP No.: 12656
Model: A4 SEDAN 2.0 TFSI 8M2R0G	Chassis: WAUZZZF4XJA092657	Engine: CVK 052819	Dept: U
VSB No.:			
You have been assisted by :- UA-Jiayee (33)			

		Details	Qty	Unit Price	Amount
S	SUBLET	N: TO SUPPLY VEHICLE NUMBER PLATE (FRONT AND REAR)	50.00	1.00	50.00
D	EXC	N: 8888 Insurance Excess/Liability	-600.00	1.00	-600.00
S	BODYWORK	N: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	360.00	1.00	360.00
S	BODYWORK	N: TO DISMANTLE AND RENEW FRONT BUMPER, BOTH HEADLIGHTS AND BONNET. REORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	1250.00	1.00	1,250.00
S	BODYWORK	N: TO RESPRAY FRONT BUMPER AND BONNET	1100.00	1.00	1,100.00
S	BODYWORK	N: TO REMOVE AND RENEW REAR PARKING AID AND	360.00	1.00	360.00

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Add Centre Singapore
281 Alexandra Road
Singapore 119938
Main Telephone: 6344 2223
Main Telefax: 6471 2733
Page 2 14:00

Alexandra Service Centre
281 Alexandra Road
Singapore 119938
Telephone: 6344 2223
Telefax: 6471 1033

UBi Service Centre
95 Ubi Road 1
Singapore 408623
Telephone: 6744 2283
Telefax: 6741 1122

Customer Service
Service Appointment:
Hour Breakdown Service
Email: customer.care@premiumauto.com.sg
6344 2323
6828 1234

INS TAX INVOICE

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013028 Date : 18/10/2018 Order : SL76844M Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SL76844M (V 36451) Regn Date: 15/05/2018 Mileage: 430 WIP No.: 12656
Model: A4 SEDAN 2.0 TFSI 8M2AD6 Chassis: WAUZZZF4XJA092657 Engine: CVK 052819 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
S	BODYWORK	REAR LID KICK SENSOR ASSY. N:	1800.00	1.00	1,800.00
S	BODYWORK	TO DISLODGE AND REINSTALL REAR WIRE HARNESS, AUDIO EQUIPMENT, CONTROL UNIT, RELAY AND FUSE TRAYS, END PANELLING, SPARE WHEEL HOUSING AND REAR LID HARNESS N:	1800.00	1.00	1,800.00
S	BODYWORK	TO REMOVE AND REINSTALL REAR SEATS, BACK REST, CARPETS, ABCD PILLAR TRIMS, DISENGAGE AIR BAG SYSTEM N:	400.00	1.00	400.00
S	BODYWORK	TO REMOVE AND RENEW CENTRE AND REAR EXHAUST SILENCER, ALIGN TO POSITION N:	2800.00	1.00	2,800.00
S	BODYWORK	TO REMOVE AND INSTALL REAR SUSPENSION ASSY TO FACILITATE CELLETTE BENCH REPAIR. INSPECT FOR DAMAGES N:	400.00	1.00	400.00

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6884 2222
Main Telefax: 6471 3733
Page 3 14:00

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6888 2222
Telefax: 6475 1033

UBi Service Centre
55 Ubi Road 1
Singapore 408722
Telephone: 6365 3222
Telefax: 6341 7122

Customer Service
Service Appointment:
6864 2323
6828 1233
Email: customer.care@premiumcars.com.sg

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013028 Date : 18/10/2018 Order : SLZ6844M Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLZ6844M (V 36451) Regn Date: 15/05/2018 Mileage: 430 WIP No.: 12656
Model: A4 SEDAN 2.0 TFSI 8M2ADG Chassis: WAUZZZF4XJA092657 Engine: CVK 052819 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
S	BODYWORK	TO REMOVE AND REINSTALL PETROL TANK M:	2400.00	1.00	2,400.00
S	BODYWORK	TO SET UP AND PLACE VEHICLE ON CAR O LINER M:	5000.00	1.00	5,000.00
S	BODYWORK	TO DISMANTLE REAR BUMPER AND RAR LID, CUT OUT AND WELD REAR END PANEL, SPARE WHEEL HOUSING, CROSS MEMBERS AND LHS REAR FENDER. REPAIR AND ALIGN WHOLE REAR SUBSTRUCTURE TO SPECIFICATION OF ORIGIN, RENEW REAR BUMPER AND REAR LID, REINSTALL ALL PARTS REMOVED M:	600.00	1.00	600.00
S	BODYWORK	TO CARRY OUT STONE CHIP PRIMER WORK ON REAR PANNELLING AND SPARE WHEEL HOUSING M:	3850.00	1.00	3,850.00
		TO SPRAY PAINT ON REAR BUMPER, REAR LID, SPARE WHEEL HOUSING, BOOT FLOOR, END PANNELLING AND BOTH REAR FENDERS, TO CARRY OUT JOINT SEALER WORKS, CAVITY PRESERVATION AND STONE CHIP			
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Add Centre Singapore
281 Alexandra Road
Singapore 159958
Main Telephone: 6384 2222
Main Telefax: 6471 3733
Page 4 14:00

Alexandra Service Centre
281 Alexandra Road
Singapore 159958
Telephone: 6384 2222
Telefax: 6475 1033

Ubi Service Centre
55 Ubi Road 1
Singapore 408688
Telephone: 6384 2222
Telefax: 6341 1127

Customer Service
Service Appointment
Door Breakdown Service
Email: customer.care@premiumauto.com.sg
6384 2323
6326 1233

INS TAX INVOICE

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Invoice: 85013028
Date : 18/10/2018
Order : SLZ6844M
Term : 30

Account: A0006 (T 0)
AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No.: SLZ6844M (V 36451) Regn Date: 15/05/2018 Mileage: 430 WIP No.: 12656
Model: A4 SEDAN 2.0 TFSI 8W2906 Chassis: WAUZZZF4XJA092657 Engine: CVK 052819 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
S	BODYWORK	TREATMENT M:	240.00	1.00	240.00
S	BODYWORK	TO CARRY OUT WHEEL ALIGNMENT M:	384.00	1.00	384.00
S	BODYWORK	TO CARRY OUT DIAGNOSTIC CHECK M:	1280.00	1.00	1,280.00
		TO SUPPLY ACRYLIC SEALER, CAVITY WAX, STONE CHIP AND METAL FILLER POWDER,			
X	ABW0802088C	WHEEL WELL (SK) (A) Less 020%	1.00	1938.00	1,550.40
X	ABW0802715C	MOUNTING (Ger) (V) Less 020%	1.00	117.00	93.60
X	ABW0803123	STRIP (SK) (A) Less 020%	1.00	11.00	8.80
X	ABW0857705 W04	SEAT BELT (SK) (A) Less 020%	1.00	956.00	764.80
X	ABW0857706 W04	SEAT BELT (Ger) (A) Less 020%	1.00	956.00	764.80
X	ABW5253609A	SILENCER (V) (G) Less 020%	1.00	789.00	631.20
X	ABW5253610A	SILENCER (V) (G) Less 020%	1.00	789.00	631.20
X	ABW5253409	MUFFLER (V) (G) Less 020%	1.00	801.00	640.80
X	ABW0804172	PLATE Less 020%	1.00	132.50	106.00
X	ABW0853651 3F2	GRILLE Less 020%	1.00	971.50	777.20
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Addl Centre Singapore
281 Alexandra Road
Singapore 159958
Main Telephone: 6386 2222
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159958
Telephone: 6386 2222
Telefax: 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408623
Telephone: 6386 2222
Telefax: 6475 1023

Customer Service
Service Appointment
Hour Breakdown Service
(Email)

6386 2222
9628 1233

customer.care@premiumauto.com.sg

INS TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Page 5 14:00

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013028 Date : 18/10/2018 Order : SLZ6844M Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLZ6844M (V 36451) Regn Date: 15/05/2018 Mileage: 430 WIP No.: 12656

Model: A4 SEDAN 2.0 TFSI 8W2ADG Chassis: WAUZZZF4XJA092657 Engine: CVK 052B19 Dept: U

VSB No.:

You have been assisted by :- UB-Jiayee (33)

		Details		Qty	Unit Price	Amount
X	ABW0941773A	HEADLIGHT	Less 020%	1.00	6973.00	5,578.40
X	ABW5827025J	LID (SK) (A)	Less 020%	1.00	2362.00	1,889.60
X	ABW0807521A 989	SPOILER (Ger) (V)	Less 020%	1.00	216.00	172.80
X	ABW5813331TA	REINFORCE	Less 020%	1.00	445.00	356.00
X	ABW0807309	BRACKET	Less 020%	1.00	785.50	628.40
X	ABW5813307A	REAR APRON	Less 020%	1.00	229.50	183.60
X	ABW0823029A	HOOD	Less 020%	1.00	2163.00	1,730.40
X	ABW0807065C GRU	COVER	Less 020%	1.00	1849.00	1,479.20
X	ABW5807067A GRU	COVER	Less 020%	1.00	1907.00	1,525.60
X	ABW5807889	GUIDE	Less 020%	1.00	18.60	14.88
X	ABW0853741 222	INSCRIPTION 'A4'	Less 020%	1.00	82.70	66.16
X	ABW5853742 222	AUDI SIGN	Less 020%	1.00	107.50	86.00
X	ABW0853737A 222	INSCRIPTION 'TFSI'	Less 020%	1.00	82.70	66.16
X	ABW5807890	GUIDE	Less 020%	1.00	18.60	14.88
X	ABW5810613	REINFORCEM (Ger) (V)	Less 020%	1.00	179.50	143.60
X	ABW5810614	REINFORCEM	Less 020%	1.00	179.50	143.60
X	ABW0807900	STRIP	Less 020%	1.00	191.00	152.80
X	ABW0121673A	AIR DUCT	Less 020%	1.00	9.60	7.68

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Add Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6834 2222
Fax: 6471 3733
Page 6 14:00

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6888 2222
Telefax: 6475 1023

UBI Service Centre
95 Ubi Road 1
Singapore 408623
Telephone: 6754 2222
Fax: 6754 1222

Customer Service
Service Appointment
24-hour Breakdown Service
Email: customer.care@premiumauto.com.sg
6384 2323
6828 1233

INS TAX INVOICE

Company No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Invoice: 85013828
Date: 18/10/2018
Order: SLZ6844M
Term: 30

Account: A0006 (T 0)
AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No.: SLZ6844M (V 36451)

Regn Date: 15/05/2018

Mileage: 430

WIP No.: 12656

Model: A4 SEDAN 2.0 TFSI 8M2906

Chassis: WAUZZZF4XJA093657

Engine: CVK 052819

Dept: U

USB No.:

You have been assisted by :- UB-Jiayee

(33)

		Details		Qty	Unit Price	Amount
X	ABW0121674A	AIR DUCT	Less 820%	1.00	3.60	7.68
X	A4M0857819	Adjuster (SK) (A)	Less 820%	2.00	153.00	244.80
X	ABW0807669	GASKET	Less 820%	2.00	11.60	18.56
X	ABD0853419F	PACKING	Less 820%	1.00	14.50	11.60
X	ABW0823125	PROTECTION (SK) (A)	Less 820%	1.00	23.60	18.88
X	ABW0823126	PROTECTION	Less 820%	1.00	23.60	18.88
X	ABW0253141C	CLAMP	Less 820%	2.00	42.50	68.00
X	A4M0253144E	BRACKET	Less 820%	2.00	35.30	58.08
X	ABT0827310A	CLIP	Less 820%	2.00	6.92	11.08
X	A3A962243H	CONTR. UNIT	Less 820%	1.00	362.00	289.60
X	ABW0962239	SENSORLINE	Less 820%	1.00	184.00	147.20
X	ABW0945106C	REFLECTOR	Less 820%	1.00	34.70	27.76
X	A4H0971741	HOLDER (Ber) (V)	Less 820%	1.00	7.80	6.24
X	ASD0919275B GRU	SENSOR	Less 820%	4.00	210.50	673.60
X	ASD0919133 704	WASHER	Less 820%	4.00	3.40	10.88
X	ABW0010515A	STICKER	Less 820%	1.00	7.35	5.88
X	ABK0010520A	PLATE	Less 820%	1.00	11.65	9.32
X	ABW0959655F	MODULE (SK) (A)	Less 820%	1.00	1870.00	1,496.00
Sub-Total						
7% GST						
Grand Total						



Premium Automobiles Pte Ltd

Add Centre Singapore
281 Alexandra Road
Singapore 159958
Main Telephone: 6388 2222
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159958
Telephone: 6388 2222
Telefax: 6475 1023

UBI Service Centre
15 Ubi Road 1
Singapore 408711
Telephone: 6388 2222

Customer Service
Service Appointment
Hour Breakdown Service
Email: customer.care@premiumautos.com.sg

6388 2222
6426 1233

Page 7 14:00

INS TAX INVOICE

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013028 Date : 18/10/2018 Order : SLZ6844M Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLZ6844M (V 36451) Regn Date: 15/05/2018 Mileage: 430 WTP No.: 12656

Model: A4 SEDAN 2.0 TFSI 8W2ADG Chassis: WAUZZZF4XJA002657 Engine: CVK 052B19 Dept: U

VSB No.:

You have been assisted by :- UB-Jiayee (33)

		Details		Qty	Unit Price	Amount
X	ABW0804171	PLATE (SK) (R)	Less 020%	1.00	132.50	132.50
X	ABW0807771	BRACKET	Less 020%	1.00	117.50	115.50
X	ABW0915459E	FUSE UNIT (Ger) (V)	Less 020%	1.00	470.00	460.00
X	AN 0195307	BOLT	Less 020%	2.00	2.50	5.00
X	ABW0823124	PROTECTION	Less 020%	1.00	23.60	23.18

Parts	23,931.48	Sub-Total	47,765.48
Labour	0.00		
Sublet	24,434.00	7% GST	3,343.58
Menus	0.00		
Lubricant	0.00	Grand Total	51,109.06



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer

Premium Automobiles

Telefax

to AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLZ 6844 M

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0659/20/G/KS
10TH July 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1

total pages

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A4 SEDAN 2.0 TFSI
Vehicle Chassis No. : WAUZZZ4XJA092657
Vehicle Regn No. : SLZ 6844 M
Vehicle Mileage : 420 KM
Vehicle Owner : Mr. Kong Kok Chee
Certificate No : 1800052828
Policy Excess : S\$642.00 (inclusive 7% GST)
Accident Date : 5th June 2018
Place : Entrance of KPE from TPE
Repair Cost : \$51,109.06
WIP No. : 12656
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :

Time :

Date :


1505 km
12 JUL '18

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Jun 2018 17:50		07 Jun 2018 15:41 Edit Adj Rpt	S\$48,365.48 Edit Estimates	S\$48,365.48 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	KONG KOK CHEE, ID: S7135786D, Tel: +6597455659, Email: KONG.KC@PORTEK.COM								
Vehicle Reg. No.:	SLZ6844M	Date of Loss:	05/06/2018 08:00 - :59 [21 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 8016733783SG	Policy/Cover Note No.:	1800052828 (Comprehensive)						
		Excess:	S\$600.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Tr, Tinesh] Tinesh.Tr@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 19/06/2018]								
Driver/Custodian:	KONG KOK CHEE (46 / Male), NRIC: S7135786D, Tel: +6597455659								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (15/10/2018): Alert - Adj Mandate Approved (S\$48365.48) - SLZ6844M - Claim Handler: Tr, Tinesh - AIG_SG (08/06/2018): Alert - Adj Mandate Approved (S\$59035.00) - SLZ6844M - Claim Handler: Tr, Tinesh - AIG_SG (08/06/2018): SLZ6844M / OD / 05/06/2018 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLZ6844M (8016733783SG)
OD
Jun 5 2018 8:00AM
[KONG KOK CHEE]
Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Video															1 per page		☒	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (5G)												Thumbnail		Print		
1	11/06/18 15:23	Video - Other													Load MP4			
Assessment Reports															1 per page		☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print		
1	07/06/18 17:58	Adjuster Immediate Advice													Load HTM			
2	19/09/18 12:35	Adjuster Immediate Advice													Load HTM			
Photos/Images															3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print		
1	08/06/18 10:04	General View													Load JPG	☒		
2	08/06/18 10:04	General View													Load JPG	☒		
3	08/06/18 10:04	General View													Load JPG	☒		
4	08/06/18 10:04	General View													Load JPG	☒		
5	08/06/18 10:04	General View													Load JPG	☒		
6	08/06/18 10:04	General View													Load JPG	☒		
7	08/06/18 10:04	General View													Load JPG	☒		
8	08/06/18 10:04	General View													Load JPG	☒		
9	08/06/18 10:04	General View													Load JPG	☒		
10	08/06/18 10:04	General View													Load JPG	☒		
11	08/06/18 10:04	General View													Load JPG	☒		
12	08/06/18 10:04	General View													Load JPG	☒		
13	08/06/18 10:04	General View													Load JPG	☒		
14	08/06/18 10:04	General View													Load JPG	☒		
15	08/06/18 10:04	General View													Load JPG	☒		
16	08/06/18 10:04	General View													Load JPG	☒		
17	08/06/18 10:04	General View													Load JPG	☒		
18	08/06/18 10:04	General View													Load JPG	☒		
19	08/06/18 10:04	General View													Load JPG	☒		
20	08/06/18 10:04	General View													Load JPG	☒		
21	08/06/18 10:04	General View													Load JPG	☒		
22	08/06/18 10:04	General View													Load JPG	☒		
23	08/06/18 10:04	General View													Load JPG	☒		
24	08/06/18 10:04	General View													Load JPG	☒		
25	08/06/18 10:04	General View													Load JPG	☒		
26	08/06/18 10:04	General View													Load JPG	☒		
27	08/06/18 10:04	General View													Load JPG	☒		
28	08/06/18 10:04	General View													Load JPG	☒		
29	08/06/18 10:04	General View													Load JPG	☒		
30	08/06/18 10:04	General View													Load JPG	☒		
31	08/06/18 10:04	General View													Load JPG	☒		

Video			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
32	08/06/18 10:04	General View	 Load JPG	☒
33	08/06/18 10:04	General View	 Load JPG	☒
34	08/06/18 10:04	General View	 Load JPG	☒
35	08/06/18 10:04	General View	 Load JPG	☒
36	08/06/18 10:04	General View	 Load JPG	☒
37	08/06/18 10:04	General View	 Load JPG	☒
38	08/06/18 10:04	General View	 Load JPG	☒
39	08/06/18 10:04	General View	 Load JPG	☒
40	08/06/18 10:04	General View	 Load JPG	☒
41	08/06/18 10:04	General View	 Load JPG	☒
42	08/06/18 10:04	General View	 Load JPG	☒
43	08/06/18 10:04	General View	 Load JPG	☒
44	08/06/18 10:04	General View	 Load JPG	☒
45	08/06/18 10:04	General View	 Load JPG	☒
46	08/06/18 10:04	General View	 Load JPG	☒
47	08/06/18 10:04	General View	 Load JPG	☒
48	08/06/18 10:04	General View	 Load JPG	☒
49	08/06/18 10:04	General View	 Load JPG	☒
50	08/06/18 10:04	General View	 Load JPG	☒
51	08/06/18 10:04	General View	 Load JPG	☒
52	08/06/18 10:04	General View	 Load JPG	☒
53	08/06/18 10:04	General View	 Load JPG	☒
54	08/06/18 10:04	General View	 Load JPG	☒
55	08/06/18 10:04	General View	 Load JPG	☒
56	08/06/18 10:04	General View	 Load JPG	☒
57	08/06/18 10:04	General View	 Load JPG	☒
58	08/06/18 10:04	General View	 Load JPG	☒
59	08/06/18 10:04	General View	 Load JPG	☒
60	08/06/18 10:04	General View	 Load JPG	☒
61	08/06/18 10:04	General View	 Load JPG	☒
62	08/06/18 10:04	General View	 Load JPG	☒
63	08/06/18 10:04	General View	 Load JPG	☒
64	08/06/18 10:04	General View	 Load JPG	☒
65	08/06/18 10:04	General View	 Load JPG	☒
66	08/06/18 10:04	General View	 Load JPG	☒
67	08/06/18 10:04	General View	 Load JPG	☒
68	08/06/18 10:04	General View	 Load JPG	☒
69	08/06/18 10:04	General View	 Load JPG	☒
70	08/06/18 10:04	General View	 Load JPG	☒
71	08/06/18 10:04	General View	 Load JPG	☒
72	11/09/18 17:23	Reinspection Photo	 Load JPG	☒
73	11/09/18 17:23	Reinspection Photo	 Load JPG	☒
74	11/09/18 17:23	Reinspection Photo	 Load JPG	☒
75	11/09/18 17:23	Reinspection Photo	 Load JPG	☒
76	11/09/18 17:23	Reinspection Photo	 Load JPG	☒
77	11/09/18 17:23	Reinspection Photo	 Load JPG	☒
78	11/09/18 17:23	Reinspection Photo	 Load JPG	☒
79	11/09/18 17:23	Reinspection Photo	 Load JPG	☒
80	11/09/18 17:23	Reinspection Photo	 Load JPG	☒
81	11/09/18 17:23	Reinspection Photo	 Load JPG	☒

Video			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
82	11/09/18 17:23	Reinspection Photo	Load JPG	☒
83	11/09/18 17:23	Reinspection Photo	Load JPG	☒
84	11/09/18 17:23	Reinspection Photo	Load JPG	☒
85	11/09/18 17:23	Reinspection Photo	Load JPG	☒
86	11/09/18 17:23	Reinspection Photo	Load JPG	☒
87	11/09/18 17:23	Reinspection Photo	Load JPG	☒
88	11/09/18 17:23	Reinspection Photo	Load JPG	☒
89	11/09/18 17:23	Reinspection Photo	Load JPG	☒
90	11/09/18 17:23	Reinspection Photo	Load JPG	☒
91	11/09/18 17:23	Reinspection Photo	Load JPG	☒
92	11/09/18 17:23	Reinspection Photo	Load JPG	☒
93	11/09/18 17:23	Reinspection Photo	Load JPG	☒
94	11/09/18 17:23	Reinspection Photo	Load JPG	☒
95	11/09/18 17:23	Reinspection Photo	Load JPG	☒
96	11/09/18 17:23	Reinspection Photo	Load JPG	☒
97	11/09/18 17:23	Reinspection Photo	Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/06/18 09:51	Singapore Accident Statement	Load PDF	
2	08/06/18 10:02	SLZ 6844M ESTIMATE	Load PDF	
3	08/06/18 10:02	Certificate of Insurance	Load PDF	
4	08/06/18 13:59	SLZ 6844M DL AND NRIC	Load PDF	
5	19/09/18 12:40	SLZ 6844M FINALIZE ADJUSTMENT + SUPPLEMENTARY EST	Load PDF	
6	19/09/18 12:40	SLZ 6844M SUPPLEMENTARY EST	Load PDF	

Linked Accident Report Documents

Assessment Reports			View View in Browser	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	05/06/18 13:11	Accident Statement	Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	05/06/18 12:58	Accident Photo	Load JPG	☒
2	05/06/18 12:58	Accident Photo	Load JPG	☒
3	05/06/18 12:58	Accident Photo	Load JPG	☒
4	05/06/18 12:58	Accident Photo	Load JPG	☒
5	05/06/18 12:58	Accident Photo	Load JPG	☒
6	05/06/18 12:58	Accident Photo	Load JPG	☒
7	05/06/18 12:58	Accident Photo	Load JPG	☒
8	05/06/18 12:58	Accident Photo	Load JPG	☒
9	05/06/18 12:58	Accident Photo	Load JPG	☒
10	05/06/18 12:58	Accident Photo	Load JPG	☒
11	05/06/18 12:58	Accident Photo	Load JPG	☒
12	05/06/18 12:58	Accident Photo	Load JPG	☒
13	05/06/18 12:58	Accident Photo	Load JPG	☒
14	05/06/18 12:58	Accident Photo	Load JPG	☒
15	05/06/18 12:58	Accident Photo	Load JPG	☒
Documentation			1 per page	☒

Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	05/06/18 12:52	Sketch Plan	 Load JPG	☒
2	05/06/18 12:52	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG18010390/ARBE2

Date: 12/11/2018

REFERENCE

Insured/Claimant: KONG KOK CHEE Policy No: 1800052828
Date of Loss: 05/06/2018 Nature of Claim: OD Claim No: 8016733783SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLZ6844M**
Make & Model: AUDI A4, 2.0 (A) Engine No: CVK052819
Reg. Date: 15/05/2018 (Man. Year: 2017) Chassis No: WAUZZZF4XJA092657
Colour: Grey Odometer: 418 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$158,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R18 Rear Tyre Size: 245/40 R18
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	54,300.36	25,261.48	29,038.88	53.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	34,904.00	23,104.00	11,800.00	33.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	89,204.36	48,365.48	40,838.88	45.78
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	88,604.36	47,765.48	40,838.88	46.09
+ GST 7.00/7.00% (S\$)	6,202.31	3,343.58	2,858.73	46.09
Nett Amount (S\$)	94,806.67	51,109.06	43,697.61	46.09

INSPECTION

Date of Assignment: 07/06/2018
Date Inspected: 06/06/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 24.0 days

Adjuster: ADRIAN LING

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,849.00 FS	*1,479.20 FS
2	1		*RADIATOR GRILLE	Cracked	972.00 FS	*777.20 FS
3	1		*FRONT BUMPER FIXING PARTS	Not Necessary	245.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTRE	Not Necessary	171.00 FS	*- FS
5	2		*FRONT BUMPER AIR GUIDE GRILLE - LH/RH	Not Necessary	236.00 FS	*- FS
6	1		*FOAM FILLER PIECE	Not Necessary	107.00 FS	*- FS
7	1		*FRONT BUMPER CARRIER	Not Necessary	702.00 FS	*- FS
8	2		*FRONT BUMPER SUPPORT - LH/RH	Not Necessary	48.00 FS	*- FS
9	1		*FRONT BUMPER BRACKET LOCK CARRIER	Cracked	118.00 FS	*94.00 FS
10	1		*FRONT BUMPER COVER	Not Necessary	109.00 FS	*- FS
11	1		*SIGN CAUTION	Not Necessary	12.00 FS	*- FS
12	1		*AIR CONDITIONER STICKER	Not Necessary	7.00 FS	*- FS
13	1		*RELEASE LEVER	Not Necessary	12.00 FS	*- FS
14	1		*BOWDEN CABLE	Not Necessary	50.00 FS	*- FS
15	2		*LED HEADLIGHTS - LH/RH	N/S Cut	13,946.00 FS	*5,578.40 FS
16	1		*BONNET	Buckled	2,163.00 FS	*1,730.40 FS
17	1		*BONNET ATTACHMENT PARTS	Not Necessary	105.00 FS	*- FS
18	2		*BONNET IMPACT PROTECTION - LH/RH	Necessary	48.00 FS	*37.76 FS
19	1		*BONNET IMPACT PROTECTION - CENTER	Necessary	24.00 FS	*18.88 FS
20	1		*FRONT NO.PLATE	Bent	25.00 FS	*25.00 FS
21	1		*REAR BUMPER	Distorted	1,907.00 FS	*1,525.60 FS
22	1		*REAR BUMPER FIXING PARTS	Not Necessary	63.00 FS	*- FS
23	1		*REAR BUMPER SPOILER	Distorted	216.00 FS	*172.80 FS
24	1		*REAR BUMPER SECURING STRIP	Distorted	191.00 FS	*152.80 FS
25	1		*REAR LIGHT REFLECTOR - LH/RH	O/S Cracked	70.00 FS	*27.76 FS
26	4		*REAR SENSOR	Damaged	842.00 FS	*673.60 FS
27	1		*REAR SENSON SEAL RING	Necessary	14.00 FS	*10.88 FS
28	1		*REAR BUMPER WIRING	Not Necessary	598.00 FS	*- FS
29	1		*CABLE HOLDER	Damaged	8.00 FS	*6.24 FS
30	1		*OPENING BOOT LID CONTROL UNIT	Damaged	362.00 FS	*289.60 FS
31	1		*RETAINER CONTROL UNIT	Not Necessary	7.00 FS	*- FS
32	1		*TAILGATE OPENING SENSOR LINE	Damaged	184.00 FS	*147.20 FS
33	1		*REAR BUMPER CARRIER	Bent	786.00 FS	*628.40 FS
34	2		*REAR BUMPER SEAL	Necessary	24.00 FS	*18.56 FS
35	2		*REAR BUMPER GUIDE SECTION - LH/RH	Not Necessary	75.00 FS	*- FS
36	2		*REAR BUMPER UPPER GUIDE SECTION - LH/RH	Damaged	38.00 FS	*29.76 FS
37	1		*REAR LID	Dented	2,362.00 FS	*1,889.60 FS
38	1		*REAR LID ATTACHMENT PARTS	Necessary	125.00 FS	*93.60 FS
39	2		*REAR LID HINGE - LH/RH	Not Necessary	400.00 FS	*- FS
40	1		*REAR LID LOCK	Not Necessary	202.00 FS	*- FS
41	1		*REAR LID PUSH BUTTON	Not Necessary	475.00 FS	*- FS
42	1		*REAR LOCK STRIKER	Not Necessary	29.00 FS	*- FS
43	2		*REAR STOP BUFFER	Not Necessary	28.00 FS	*- FS
44	1		*REAR GASKET FLAP	Not Necessary	176.00 FS	*- FS
45	1		*ADHESIVE PACKING	Necessary	15.00 FS	*11.60 FS
46	1		*AUDI EMBLEM	Necessary	108.00 FS	*86.00 FS
47	1		*REAR INSCRIPTION A4	Necessary	83.00 FS	*66.16 FS
48	1		*REAR INSCRIPTION TFSI	Necessary	83.00 FS	*66.16 FS
49	2		*LED TAIL LIGHTS - LH/RH	Not Necessary	1,830.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	2		*TAIL LIGHTS TRIM - LH/RH	Not Necessary	52.00 FS	*- FS
51	2		*LED OUTER TAIL LIGHT - LH/RH	Not Necessary	1,632.00 FS	*- FS
52	2		*OUTER TRIM TAIL LIGHTS - LH/RH	Not Necessary	52.00 FS	*- FS
53	1		*REAR CROSS PANEL	Distorted	230.00 FS	*183.60 FS
54	1		*REAR CROSS PANEL REINFORCEMENT	Distorted	445.00 FS	*358.00 FS
55	2		*REAR SIDE PANEL REINFORCEMENT - LH/RH	Distorted	360.00 FS	*287.20 FS
56	1		*SPARE WHEEL WELL	Distorted	1,938.00 FS	*1,550.40 FS
57	1		*SPARE WHEEL MOUNTING	Not Necessary	117.00 FS	*- FS
58	1		*BATTERY CLAMPING STRIP	Necessary	11.00 FS	*8.80 FS
59	1		*CROSS MEMBER	Not Necessary	1,263.00 FS	*- FS
60	2		*REAR SILENCER HEAT SHIELD - LH/RH	Not Necessary	266.00 FS	*- FS
61	1		*SIDE PANEL SECTIONAL PART - LH	Repair	2,347.00 FS	*- FS
62	1		*SIDE WINDOW	Not Necessary	541.00 FS	*- FS
63	1		*REAR WINDOW	Not Necessary	1,014.00 FS	*- FS
64	2		*PRIMER	Not Necessary	37.00 FS	*- FS
65	1		*SILENCER - CENTRE	Bent	801.00 FS	*640.80 FS
66	2		*REAR SILENCER - LH/RH	Bent	1,578.00 FS	*1,262.40 FS
67	2		*DUAL CLIP	Necessary	85.00 FS	*68.00 FS
68	2		*EXHAUST SILENCER BRACKET	Damaged	73.00 FS	*58.08 FS
69	1		*REAR NO. PLATE	Dented	25.00 FS	*25.00 FS
70	1		*ACRYLIC SEALER	Necessary	360.00 FS	*360.00 FS
71	1		*CAVITY WAX	Necessary	280.00 FS	*280.00 FS
72	1		*STONE CHIP	Necessary	360.00 FS	*360.00 FS
73	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
74	1		*WINDSCREEN SEALANT	Not Necessary	200.00 FS	*- FS
75	1		*1/4 GLASS SEALANT	Not Necessary	100.00 FS	*- FS
76	1		*CENTRAL PROTECTION	Activated	470.00 FS	*376.00 FS
77	2		*THREE POINT AUTOMATIC SEAT BELT - LH/RH	Activated	1,912.00 FS	*1,529.60 FS
78	2		*SEAT BELT HEIGHT ADJUSTER	Broken	306.00 FS	*244.80 FS
79	1		*AIRBAG CONTROL UNIT	Activated	1,870.00 FS	*1,496.00 FS
80	3		*AIRBAG CRASH SENSOR	Not Necessary	818.00 FS	*- FS
81	1		*SUNDRIES	Necessary	2,000.00 FS	*30.28 FS
82	2		*LOCK CARRIER AIR GUIDE - LH/RH UPPER	Damaged	15.36 FS	*15.36 FS
83	2		*REAR SILENCER HEAT SHIELD - LH/RH	Crumpled	212.00 FS	*212.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	54,300.36	25,261.48
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH HEADLIGHTS AND BONNET. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,400.00	1,250.00
3	TO RESPRAY FRONT BUMPER AND BONNET	New	1,500.00	1,100.00
4	TO REMOVE AND RENEW REAR PARKING AID AND REAR LID KICK SENSOR ASSY	New	360.00	360.00
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS, AUDIO EQUIPMENT, CONTROL UNITS, RELAY AND FUSE TRAYS, END PANELLING, SPARE WHEEL HOUSING AND REAR LID HARNESS	New	1,800.00	1,800.00
6	TO REMOVE AND REINSTALL REAR SEATS, BACK REST, CARPETS, ABCD PILLAR TRIMS, DISENGAGE AIR BAG SYSTEM	New	1,800.00	1,800.00
7	TO REMOVE AND RENEW CENTER AND REAR EXHAUST SILENCERS. ALIGN TO POSITION	New	480.00	480.00
8	TO RENEW LHS REAR 1/4 GLASS AND REAR WINDSCREEN	New	600.00	0.00
9	TO REMOVE AND INSTALL REAR SUSPENSION ASSY TO FACILITATE CELLETTE BENCH REPAIRS. INSPECT FOR DAMAGES	New	2,800.00	2,800.00
10	TO REMOVE AND REINSTALL PETROL TANK	New	480.00	480.00
11	TO SET UP AND PLACE VEHICLE ON CAR-O-LINER	New	2,400.00	2,400.00
12	TO DISMANTLE REAR BUMPER AND REAR LID. CUT OUT AND WELD REAR END PANELS, SPARE WHEEL HOUSING, CROSS MEMBERS AND LHS REAR FENDER. REPAIR AND ALIGN WHOLE REAR SUBSTRUCTURE TO SPECIFICATION OF ORIGIN. RENEW REAR BUMPER AND REAR LID. REINSTALL ALL PARTS REMOVED	New	12,000.00	5,000.00
13	TO CARRY OUT STONECHIP PRIMER WORK ON REAR PANELLING AND SPARE WHEEL HOUSING	New	800.00	800.00
14	TO SPRAY PAINT ON REAR BUMPER, REAR LID, SPARE WHEEL HOUSING, BOOT FLOOR, END PANELLING, BOTH REAR FENDERS, LHS SILL PANEL, DRAIN PANEL, ROOF CHANNEL TO CARRY OUT JOINT SEALER WORKS, CAVITY PRESERVATION AND STONE CHIP TREATMENT	New	6,500.00	3,850.00
15	TO CARRY OUT WHEEL ALIGNMENT	New	240.00	240.00
16	TO CARRY OUT DIAGNOSTIC	New	384.00	384.00
Gross Labour Cost (S\$)			34,904.00	23,104.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >