

CITYCAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 731M

DATE 6/5/2018 15:31

MAKE :

MODEL : HYUNDAI i40

LKK/Katun H/Sam
Like QBE

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Door (RH) <i>X repair</i>			\$ 1,351.10
	Front Door (RH) <i>-</i>			\$ 1,403.05
	Rocker Panel Outer Garnish (RH) <i>-</i>			\$ 483.60
	Rear Wheel Hup-Cap (RH) <i>-</i>			\$ 150.70
	SUB TOTAL			\$ 3,388.45
	LESS 20% <i>25%</i>			\$ 677.69
	DISCOUNTED TOTAL			\$ 2,710.76
	Rear Bumper Advertisement Logo <i>-</i>			\$ 50.00 Nett
	Rear Bumper Rubber Mat <i>X</i>			\$ 50.00 Nett
	Rear Fender Advertisement Logo (RH) <i>-</i>			\$ 100.00 Nett
	Rear Door Advertisement Logo (RH) <i>-</i>			\$ 100.00 Nett
	Rear Door Tel No. Sticker (RH) <i>-</i>			\$ 10.00 Nett
	Rear Door Comfortdelgro & Apps Sticker (RH) <i>-</i>			\$ 80.00 Nett
	Front Door Coloured Comfort Logo (RH) <i>-</i>			\$ 75.00 Nett
	Front Door Advertisement Logo (RH) <i>-</i>			\$ 100.00 Nett
				\$ 565.00
	Labour Charge			
	Panel Beating			\$ 350.00 <i>300</i>
	Spray Painting Charge			\$ 1,000.00 <i>800</i>
	Wiring Charge			\$ 30.00 <i>X</i>
	Tuff Kote			\$ 50.00 <i>20</i>
	Remove/Refix Reverse Sensor			\$ 120.00 <i>X</i>
	Transfer of Door			\$ 120.00 <i>50</i>
	Rear Wheel Alignment			\$ 80.00 <i>X</i>
	TOTAL LABOUR			\$ 1,750.00
	ESTIMATE TOTAL			\$ 5,025.76

Katun 11/11/18
6/6/18 1050 hrs
3 Pgs
45
After Repair Lho

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- Display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Complementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: