

ASS. REC. BY:

REF:

CS/EG118010404/8vd3m

Special Instruction:

Surveyor: Sebastian

ASSIGNMENT (Office)

From (Person):

Yue pei Li

of

EGI

Date/Time:

7/6/18 @ 2:37pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 4698A

Insured:

GBH 1891 Y

at Workshop m/s

SMRT

Tel:

6866 2672

of

60 Woodlands Ind. Park E4

Policy No:

Claim No:

GBH1891Y/RH/p

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

06/06/2018

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

3:41pm @ 7/6/18

Person Contacted:

shanti

Vehicle

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SHC 4698A - NS/INC/8003821/Svbe 2

D.O.A: 21/02/2018

GBH 1891 Y - X

8/6/18

Email preli revised to Pei Li

20/6/18

LS \$4350 confirmed by email (Ref 8517.10, 66b)

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No.:

at Workshop m/s:

of:

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No. SHC 4698 A Yr Regn: Sept 2014Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi Prime Mover /

Truck / Trailer or

Make: Toyota PriusC.C. 1798Colour: Maroon

A/C Insured / Std / NI / NA

Sp. Reading: 423965

T/Radio: Insured / Std / NI / NA

Eng/No: 2ZR6177416C/No: JTDKN36U005751088Gen. Cond: Good / Fair / Poor / BurntSteering: Order / Jammed / Leaked / Burnt orBrake: Order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65 R15R: 195/65 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 6/6/2018D.O.I. 7/6/2018Survey held at SMARTDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TAX/06/18/2021

RECEIVED 20 JUN 2018

Ergo

- GBH 1891 Y

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 4

1)

☐ : Final ReportResurvey No. of Trip: 1

Date/Time, File Return to?

Survey Fee:

2) 2016 - typistAdd Fee: ☐ Site Insp (\$)

Transportation:

☐ Interview (\$)

) S + R3: \$

☐ Tech. Insp (\$)

) Photos

Report Format :

) Others:

Form 100 (1/1/10)

TP
LS \$4350/-

350



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI18010404/Svd3

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 07-06-2018



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBH 1891Y	Veh. Inspected	SHC 4698A
Policy No.		Coverage (\$)	0.00
Claim No.	GBH1891Y/RH/pl	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	07/06/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	06/06/2018	Inspection Date	07/06/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Your Ref: GBH1891Y/RH/pl

Our Ref: CS/EGI18010404/Svd3

Date: 8/6/2018

The Motor Claims Department
M/s: ERGO INSURANCE PTE LTD

Without Prejudice

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. SHC 4698A


We thank you for your instruction on 7/6/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 7/6/2018 at the premises of M/s SMRT AUTOMOTIVE SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$12,904.10
Revised Estimate Amount	: S\$5,015.38
"Check" Items Amount	: S\$683.01
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

YEANG WAI KEEN

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Thursday, 7 June 2018 2:37 PM
To: 'admin-d@lkkauto.com'
Subject: OI : GBH1891Y / TP : SHC4698A/LKK / DOA : 06/06/2018
Attachments: GBH1891Y - SAS.pdf; SHC4698A - SAS.pdf; SHC4698A - ESTIMATE.pdf; SHC4698A - PRS FORM.pdf; RE: SHC4698A - Survey (Ergo) (1.18 MB)

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **SMRT AUTOMOTIVE SERVICES PTE LTD**,

ADDRESS : WOODLANDS SMRT DEPOT
60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705

PERSON TO CONTACT : SHANTI @ 6866 2671/2

ERGO OFFICER-IN-CHARGE : ROHAINI

Note: To survey on without prejudice basis. Please note that our insured/insured driver has yet to e-file their SAS for this accident and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimate and third party's SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

ERGO

Date: 07.06.2018
Our Reference: GBH 1891Y/RH/pl
Your Reference: SHC 4698A

Sent via Fax

or

Email

BThaiyalN@smrt.com.sg

To: **SMRT AUTOMOTIVE SERVICES PTE LTD**

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SHC 4698A
Insured's Vehicle: GBH 1891Y
Date Of Accident: 06.06.2018

We acknowledge receipt of your request for PRS on: 07.06.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* **LKK**

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

☐	Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
☐	Your request for inspection does not have your client's GIA report, kindly forward a copy.
☐	We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
☐	Our Insured's driver has not reported the accident to us todate.
☒	Others: <u>OFFICER-IN-CHARGE - ROHAINI</u>

Prepared by:		Pei Li	6829 9194	claims@ergo.com.sg
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 8 June 2018 9:40 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: SUR; 'Yee Pei Li'
Subject: RE: GBH1891Y / TP : SHC4698A/LKK / DOA : 06/06/2018
Attachments: SHC 4698A PRELI REVISED.pdf

Dear Pei Li,

Enclosed preliminary revised of vehicle SHC 4698A
Date of survey: 7/6/2018
Number of days:4 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 7 June 2018 3:46 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; 'Yee Pei Li' <peili.yee@ergo.com.sg>
Subject: RE: GBH1891Y / TP : SHC4698A/LKK / DOA : 06/06/2018

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]
Sent: Thursday, 7 June 2018 2:37 PM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Subject: OI : GBH1891Y / TP : SHC4698A/LKK / DOA : 06/06/2018

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **SMRT AUTOMOTIVE SERVICES PTE LTD**.

ADDRESS : WOODLANDS SMRT DEPOT
60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705

PERSON TO CONTACT : SHANTI @ 6866 2671/2

ERGO OFFICER-IN-CHARGE : ROHAINI

Note: To survey on without prejudice basis. Please note that our insured/insured driver has yet to e-file their SAS for this accident and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimate and third party's SAS (**note: reports not to be released to any Third Party**).

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

> [Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details

Vehicle No. :	SHC4698A		
Vehicle Type :	H10 - Public Transport Taxi (Motor Car)		
Vehicle Attachment 1 :	Air-Con (Taxi)		
Vehicle Scheme :	Taxi (Company)		
Vehicle Make :	TOYOTA		
Vehicle Model :	PRIUS TAXI (SMRT)		
Chassis No. :	JTDKN36U005751088		
Propellant :	Petrol-Electric		
Engine No. :	2ZR6177416		
Motor No. :	3JM6177416		
Engine Capacity :	1798 cc		
Power Rating :	60.0 kW		
Maximum Power Output :	100.0 kW (134 bhp)		
Maximum Laden Weight :	1805 kg		
Unladen Weight :	1370 kg		
Year Of Manufacture :	2014		
Original Registration Date :	24 Sep 2014		
Lifespan Expiry Date :	23 Sep 2022		
COE Category :	A - Car up to 1600cc & 97kW (130bhp)		
PQP Paid :	\$50,704.00		
COE Expiry Date :	23 Sep 2022		
Road Tax Expiry Date :	23 Sep 2018		
PARF Eligibility Expiry Date :	23 Sep 2022		
Inspection Due Date :	23 Sep 2018		
Intended Transfer Date :	07 Jun 2018		
CO2 Emission :	92.00 (g/km)		
CEV/VES Rebate Utilised Amount :	\$30,000.00		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00
Message			
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.			

You may print this page for reference.

OK

Print

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4698A
 Ref. No : TAX/06/18/2021
 Reg. Date : 24/09/2014
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : QUAH PENG ENG
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 06/06/2018 10:10:00 AM
 Accident Reported Date / Time : 06/06/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024096460
 Special Instruction to ARC, if any :
 GBH1891Y
 Prepared Date : 06/06/2018 02:10:13 PM



Sathya Sai

7/6/2018

sebastianyeang@lkkauto.com

- Lump Sum Repair
- Question mark item photo
- Photo after paint.

Signature
8/6/18

4 days

LKK Auto Consultants hence notify the Reparer of the following:
 • To resurvey before/after spray painting
 • To display damaged parts during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company
 Acknowledged by Reparer
 Signature:
 Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U005751088

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates**Quotation from ARC****Adjusted by Surveyor, if applicable**

Total Labour Charges	:	1,183.00		0.00
Total Spray Painting Charges	:	1,674.00		0.00
Total Material Charges	:	5,453.93		5,453.93
Other Charges	:	1,305.00		0.00
TOTAL	:	9,615.93		0.00
Lum Sum Total	:	9,600.00	12,904.10	0.00
No. of Repair Days	:	7.00		0.00 4 days
Prepared / Adjusted By	:			
Arc / Surveyor Sign Off Date	:	06/06/2018 06:47:02 PM		01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 06/06/2018 06:47:02 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,183.00	0.00 600
Total Labour	1,183.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY REAR PANEL	180.00	0.00 ?
TO RESPRAY TAIL GATE	378.00	0.00 200
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0.00 100
TO RESPRAY SPOILER	180.00	0.00 100
TO RESPRAY REAR FENDER LH	378.00	0.00 x
Total Spray Painting & Panel Beating	1,674.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 40
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 50
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 40
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00 60
TO REMOVE AND REFIX REAR WINDSCREEN	120.00	0.00 60
TO REMOVE / REFIT SEAT	120.00	0.00 x
TO REMOVE & REFIT REAR QUARTER GLASS LH	120.00	0.00 x
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	0.00 x
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00 60
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 60
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 x
Total Other Costs	1,305.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR ✓ DMG	1	458.60	25.00	343.95	Replace	Replace	No
52023-12240		6505547	BUMPER REINFORCEMENT REAR ✓ DT	1	205.70	25.00	154.27	Replace	Replace	No
52016-47030			ARM SUB-ASSY, RR BUMPER LH ✓ DT	1	139.60	25.00	104.70	Replace	Replace	No
52015-47050			ARM SUB-ASSY, RR BUMPER RH ✓ DT	1	139.60	25.00	104.70	Replace	Replace	No
			SENSOR REVERSE ✓ DMG	1	180.00	0.00	180.00	Replace	Replace	No
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH ✓ CRK	1	94.80	25.00	71.10	Replace	Replace	No
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH ?	1	94.80	25.00	71.10	Replace	Replace	No
76088-47020		6505617	BUMPER LIP COVER RR/LH ✓ CRK	1	72.20	25.00	54.15	Replace	Replace	No
76087-47020		6505618	BUMPER LIP COVER RR/RH ✓ CRK	1	118.10	25.00	88.57	Replace	Replace	No
76891-47020		6505619	BUMPER LIP REAR ✓ CRK	1	228.90	25.00	171.67	Replace	Replace	No
			PIXEL STICKER ✓ NEC	2	60.00 120	0.00	120.00	Replace	Replace	No
58308-47011			UNDER COVER SUB-ASSY, RR FLOOR ?	1	514.50	25.00	385.87	Replace	Replace	No
58307-47060		6505522	END PANEL R	1	602.10	25.00	451.57	Replace	Replace	No
	COMMON	4006314	SEALANT SIKAFLEX X NN	1	37.00	0.00	37.00	Replace	Replace	No
67005-47241			TAILGATE ASY R	1	1,007.90	25.00	755.92	Replace	Replace	No
76801-47070-B0			TAILGATE OUTSIDE GARNISH ✓ CUT	1	504.90	25.00	378.67	Replace	Replace	No
75374-47051			NAME PLATE (HYBRID) ✓ CRK	1	51.90	25.00	38.92	Replace	Replace	No
75442-47030			NAME PLATE (PRIUS) ✓ NEC	1	60.80	25.00	45.60	Replace	Replace	No
75443-47030			NAME PLATE (TOYOTA) ✓ NEC	1	51.90	25.00	38.92	Replace	Replace	No
75310-47020		6505639	EMBLEM REAR ✓ NEC	1	60.30	25.00	45.22	Replace	Replace	No
	COMMON		SMRT LOGO ✓ NEC	1	7.80	0.00	7.80	Replace	Replace	No
			STICKER DECAL 6555 8888 ✓ NEC	1	21.60	0.00	21.60	Replace	Replace	No
75574-47020			TAIL GATE DOOR GLASS MOULDING, LH X NN	1	29.40	25.00	22.05	Replace	Replace	No
75573-47080			TAIL GATE DOOR GLASS MOULDING, RH X NN	1	29.40	25.00	22.05	Replace	Replace	No
	COMMON		SEALANT W/SCREEN X NN	2	37.00 74	0.00	74.00	Replace	Replace	No
75575 - 47030			MOULDING BACK WINDOW, LOWER NO.1 X NN	1	29.40	25.00	22.05	Replace	Replace	No
	COMMON		SEALANT W/SCREEN X NN	1	37.00	0.00	37.00	Replace	Replace	No
64718-47031B0			END PANEL COVER, DECK TRIM HOLE ✓ CRK	1	46.10	25.00	34.57	Replace	Replace	No

50/830

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
64716-47031B0			END PANEL COVER, DECK TRIM, RR ✓CRK	1	121.10	25.00	90.82	Replace	Replace	No
89997-30070			ANTENNA, ELECTRICAL LOWER REAR ✓BR	1	157.40	10.00	141.66	Replace	Replace	No
67881-47022			TAILGATE DOOR WEATHER STRIP ✓CUT	1	353.40	25.00	265.05	Replace	Replace	No
64740-47031B2			PANEL ASSY, DECK LH X NN	1	307.00	25.00	230.25	Replace	Replace	No
64730-47031B2			PANEL ASSY, DECK RH X NN	1	307.00	25.00	230.25	Replace	Replace	No
76085-47910		6505620	SPOILER REAR ✓CRK	1	953.70	25.00	715.27	Replace	Replace	No
81006-47011		6505464	3RD BRAKE LAMP ✓BR	1	231.30	10.00	208.17	Replace	Replace	No
52563-47010			TAIL LAMP BRACKET, LH ?	1	30.70	25.00	23.02	Replace	Replace	No
52562-47010			TAIL LAMP BRACKET, RH ?	1	30.70	25.00	23.02	Replace	Replace	No
61602-47091		6505476	FENDER RR/LH X NN	1	766.80	25.00	575.10	Replace	Replace	No
	COMMON		SMRT LOGO X NN	1	7.80	0.00	7.80	Replace	Replace	No
			STICKER DECAL 6555 8888 X NN	1	21.60	0.00	21.60	Replace	Replace	No
62720-47031			QUARTER GLASS RR/LH X NN	1	168.10	25.00	126.07	Replace	Replace	No
	COMMON		SEALANT W/SCREEN X NN	1	37.00	0.00	37.00	Replace	Replace	No
65638-47021		6505477	FENDER LINER RR/LH X NN	1	141.30	25.00	105.97	Replace	Replace	No
52592-47021			BUMPER SEAL, RR LH X SVC	1	88.90	25.00	66.67	Replace	Replace	No
TOTAL MATERIALS					3723.80		6,750.83	6,750.74		
TOTAL MATERIALS(Discounted)							5,453.93	5,453.93		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

3425.38
 - 20%

 2740.304
 + 600.00
 + 600.00
 + 390.00

 4330.304

L/S : \$ 4350

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4698A
 Ref. No : TAX/06/18/2021
 Reg. Date : 24/09/2014
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : QUAH PENG ENG
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 06/06/2018 10:10:00 AM
 Accident Reported Date / Time : 06/06/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : Sebastian
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024096460
 Special Instruction to ARC, if any :
 GBH1891Y - ERGO
 BEFORE PAINT PHOTO AND AFTER PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL SURVEYOR SEBASTIAN (LKK) & Email : sebastianyeang @lkkauto.com HP: 90036121
 Prepared Date : 06/06/2018 02:10:13 PM



Recording Camera

☐ ☒

Radio Antenna

☐ ☒

1st witness Date 7-6-18

2nd witness Date

E 1/2 F
 KM 123.86

Vehicle to Wega Date In: <u>8/6</u>	Towing: <u> </u>
Time In: <u>1400</u>	Driver: <u> </u>
Wega Job No: <u>86/0865</u>	
Vehicle sent to SMRT Date In: <u>12.6/18</u>	Towing: <u> </u>
Time In: <u>11:00</u>	Driver: <u> </u>
Received by (SMRT): <u> </u>	

12/6/18 13.44 QC Reject

Name plate Toyota van 14.25 PASS

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U005751088

Mileage


0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,183.00	600.00
Total Spray Painting Charges	: 1,674.00	600.00
Total Material Charges	: 3,142.72	2,740.30
Other Charges	: 1,305.00	390.00
TOTAL	: 7,304.72 12,867.10	4,330.30
Lum Sum Total	: 7,300.00	4,350.00
No. of Repair Days	: 7.00	4.00 ✓
Prepared / Adjusted By	:	SEBASTIAN (LKK)
Arc / Surveyor Sing Off Date	: 06/06/2018 06:47:02 PM	07/06/2018 03:58:28 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 06/06/2018 06:47:02 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1806-0323 Invoice No :
Quotation Date : Invoice Date :
Invoice Amount : 1216. Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,183.00 ✓	600.00 ✓
Total Labour	1,183.00	600.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00 ✓	200.00 ✓
TO RESPRAY REAR PANEL	180.00 ✗	0.00
TO RESPRAY TAIL GATE	378.00 ✓	200.00 ✓
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00 ✓	100.00 ✓
TO RESPRAY SPOILER	180.00 ✓	100.00 ✓
TO RESPRAY REAR FENDER LH	378.00 ✗	0.00
Total Spray Painting & Panel Beating	1,674.00	600.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	40.00 ✓
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	50.00 ✓
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	40.00 ✓
TO TRANSFER REAR TAILGATE MECHANISM	120.00	60.00 ✓
TO REMOVE AND REFIX REAR WINDSCREEN	120.00	60.00 ✓
TO REMOVE / REFIT SEAT	120.00	0.00
TO REMOVE & REFIT REAR QUARTER GLASS LH	120.00	0.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	0.00 NA
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	60.00 ✓
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	60.00 ✓
TO REPLACE SUNDRY PARTS	100.00	20.00 ✓
TO WASH AND VACUUM	60.00	0.00
Total Other Costs	1,305.00	390.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached	
52159-47905		6505548	BUMPER REAR	✓ 1	458.60	25.00	343.95	Replace	Replace	No ✓	DMG
52023-12240		6505547	BUMPER REINFORCEMENT REAR	✓ 1	205.70	25.00	154.27	Replace	Replace	No ✓	DT
52016-47030			ARM SUB-ASSY, RR BUMPER LH	✓ 1	139.60	25.00	104.70	Replace	Replace	No ✓	DT
52015-47050			ARM SUB-ASSY, RR BUMPER RH	✓ 1	139.60	25.00	104.70	Replace	Replace	No ✓	DT
			SENSOR REVERSE	✓ 1	180.00	0.00	180.00	Replace	Replace	No ✓	DMG
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	✓ 1	94.80	25.00	71.10	Replace	Replace	No ✓	CRK
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	X 1	94.80	25.00	71.10	Replace	Check	No X	NN
76088-47020		6505617	BUMPER LIP COVER RR/LH	✓ 1	72.20	25.00	54.15	Replace	Replace	No ✓	CRK
76087-47020		6505618	BUMPER LIP COVER RR/RH	✓ 1	118.10	25.00	88.57	Replace	Replace	No ✓	CRK
76891-47020		6505619	BUMPER LIP REAR	✓ 1	228.90	25.00	171.67	Replace	Replace	No ✓	CRK
			PIXEL STICKER	✓ 2	60.00 ¹²⁰	0.00	120.00	Replace	Replace	No ✓	NEC
58308-47011			UNDER COVER SUB-ASSY, RR FLOOR	X 1	514.50	25.00	385.88	Replace	Check	No X	NN
58307-47060		6505522	END PANEL	R 1	602.10	100.00	0.00	Replace	Repair	No R	
	COMMON	4006314	SEALANT SIKAFLEX	X 0	37.00	0.00	0.00	Replace	Not given	No X	NN
7005-17241			TAILGATE ASY	R 1	1,007.90	100.00	0.00	Replace	Repair	No R	
76801-17070-B0			TAILGATE OUTSIDE GARNISH	✓ 1	504.90	25.00	378.67	Replace	Replace	No ✓	CRK
5374-7051			NAME PLATE (HYBRID)	✓ 1	51.90	25.00	38.92	Replace	Replace	No ✓	CRK
5442-7030			NAME PLATE (PRIUS)	✓ 1	60.80	25.00	45.60	Replace	Replace	No ✓	NEC
5443-7030			NAME PLATE (TOYOTA)	✓ 1	51.90	25.00	38.92	Replace	Replace	No ✓	
5310-7020		6505639	EMBLEM REAR	✓ 1	60.30	25.00	45.22	Replace	Replace	No ✓	
	COMMON		SMRT LOGO	✓ 1	7.80	0.00	7.80	Replace	Replace	No ✓	NN
			STICKER DECAL 6555 8888	✓ 1	21.60	0.00	21.60	Replace	Replace	No ✓	
5574-7020			TAIL GATE DOOR GLASS MOULDING, LH	X 0	29.40	25.00	0.00	Replace	Not given	No X	
5573-7080			TAIL GATE DOOR GLASS MOULDING, RH	X 0	29.40	25.00	0.00	Replace	Not given	No X	NN
	COMMON		SEALANT W/SCREEN	X 0	37.00	0.00	0.00	Replace	Not given	No X	
5575-7030			MOULDING BACK WINDOW, LOWER NO.1	X 0	29.40	25.00	0.00	Replace	Not given	No X	
	COMMON		SEALANT W/SCREEN	X 0	37.00	0.00	0.00	Replace	Not given	No X	CRK
4718-7031B0			END PANEL COVER, DECK TRIM HOLE	✓ 1	46.10	25.00	34.57	Replace	Replace	No ✓	

4981.30

Part Number	Portion	Stock ID	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached	
64716-47031B0			END PANEL COVER, DECK TRIM, RR	✓ 1	121.10	25.00	90.82	Replace	Replace	No ✓	CRK
89997-30070			ANTENNA, ELECTRICAL LOWER REAR	1	157.40	10.00	141.66	Replace	Replace	No ✓	BR
37881-47022			TAILGATE DOOR WEATHER STRIP	1	353.40	25.00	265.05	Replace	Replace	No ✓	CUT
34740-47031B2			PANEL ASSY, DECK LH	0	307.00	25.00	0.00	Replace	Not given	No X	} NN
34730-47031B2			PANEL ASSY, DECK RH	0	307.00	25.00	0.00	Replace	Not given	No X	
76085-47910		6505620	SPOILER REAR	1	953.70	25.00	715.27	Replace	Replace	No ✓	CRK
31006-47011		6505464	3RD BRAKE LAMP	1	231.30	10.00	208.17	Replace	Replace	No ✓	BR
52563-47010			TAIL LAMP BRACKET, LH	1	30.70	25.00	23.03	Replace	Check	No X	}
52562-47010			TAIL LAMP BRACKET, RH	1	30.70	25.00	23.03	Replace	Check	No X	
31602-47091		6505476	FENDER RR/LH	0	766.80	25.00	0.00	Replace	Not given	No X	} NN
	COMMON		SMRT LOGO	0	7.80	0.00	0.00	Replace	Not given	No X	
			STICKER DECAL 6555 8888	0	21.60	0.00	0.00	Replace	Not given	No X	}
42720-7031			QUARTER GLASS RR/LH	0	168.10	25.00	0.00	Replace	Not given	No X	
	COMMON		SEALANT W/SCREEN	0	37.00	0.00	0.00	Replace	Not given	No X	}
5638-7021		6505477	FENDER LINER RR/LH	0	141.30	25.00	0.00	Replace	Not given	No X	
2592-7021			BUMPER SEAL, RR LH	0	88.90	25.00	0.00	Replace	Not given	No X	SVC
TOTAL MATERIALS					3723.80			3,928.46	3,425.38		
TOTAL MATERIALS(Discounted)								3,142.72	2,740.30		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

$$\begin{array}{r}
 3475.38 \\
 - 20\% \\
 \hline
 2740.30 \\
 + 600 \\
 + 990 \\
 \hline
 4330.30
 \end{array}$$

$$45 = \$4350$$

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 20 June 2018 11:18 AM
To: Sathya Sai (LKK Auto); Yeo Poh Suan(Auto Svcs/Maint Ops/ARC)
Cc: SUR
Subject: RE: SHC4698A-DOA: 6/6/2018

Dear Poh Sun,

WITHOUT PREJUDICE

Confirmed amount of \$4,350 @ 4 working days under lump sum repair.

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Veron Chen (LKKAuto)
Sent: Wednesday, 20 June 2018 7:57 AM
To: Sathya Sai (LKK Auto) <SathyaSai@lkkauto.com>
Subject: FW: SHC4698A

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25
| S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) [mailto:YeoPohsuan@smrt.com.sg]
Sent: Tuesday, 19 June 2018 4:31 PM
To: SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Subject: SHC4698A

Hi SUR & CS-A Team,

Attached herewith the repair estimate of SHC 4698A having Case No: TAX/06/18/2021.

There is no change to the approved amount of \$4,350 @ 4 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards

Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)

Sent: Tuesday, 19 June 2018 4:32 PM

To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)

Subject: Scan Data from FX-D421D6



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EG18010404/Vvd3n2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 21-06-2018		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBH 1891Y	Veh. Inspected	SHC 4698A	
Policy No.		Coverage (\$)	0.00	
Claim No.	GBH1891Y/RH/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	07/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	JTDKN36U005751088	Colour	MAROON	
Odometer	423965	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	FALKEN	6 mm	
L/H Front Tyre	195/65 R15	FALKEN	6 mm	
R/H Rear Tyre	195/65 R15	FALKEN	6 mm	
L/H Rear Tyre	195/65 R15	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/06/2018	Inspection Date	07/06/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4698A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER REAR (DISC 25%)	DAMAGED	458.60	343.95
1	BUMPER REINFORCEMENT REAR (DISC 25%)	DENTED	205.70	154.27
1	ARM SUB-ASSY,RR BUMPER LH (DISC 25%)	DENTED	139.60	104.70
1	ARM SUB-ASSY,RR BUMPER RH (DISC 25%)	DENTED	139.60	104.70
1	BUMPER SIDE RETAINER RR/LH (DISC 25%)	CRACKED	94.80	71.10
1	BUMPER LIP COVER RR/LH (DISC 25%)	CRACKED	72.20	54.15
1	BUMPER LIP COVER RR/RH (DISC 25%)	CRACKED	118.10	88.57
1	BUMPER LIP REAR (DISC 25%)	CRACKED	228.90	171.67
1	TAILGATE OUTSIDE GARNISH (DISC 25%)	CUT	504.90	378.67
1	NAME PLATE (HYBRID) (DISC 25%)	CRACKED	51.90	38.92
1	NAME PLATE (PRIUS) (DISC 25%)	NECESSARY	60.80	45.60
1	NAME PLATE (TOYOTA) (DISC 25%)	NECESSARY	51.90	38.92
1	EMBLEM REAR (DISC 25%)	NECESSARY	60.30	45.22
1	END PANEL COVER,DECK TRIM HOLE(DISC 25%)	CRACKED	46.10	34.57
1	END PANEL COVER,DECK TRIM,RR(DISC 25%)	CRACKED	121.10	90.82
1	TAILGATE DOOR WEATHER STRIP (DISC 25%)	CUT	353.40	265.05
1	SPOILER REAR (DISC 25%)	CRACKED	953.70	715.27
1	ANTENNA,ELECTRICAL LOWER REAR (DISC 10%)	BROKEN	157.40	141.66
1	3RD BRAKE LAMP (DISC 10%)	BROKEN	231.30	208.17
1	SENSOR REVERSE (SN)	DAMAGED	180.00	180.00
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 65558888 (SN)	NECESSARY	21.60	21.60
1	BUMPER SIDE RETAINER RR/RH	NOT NECESSARY	94.80	-
1	SEALANT SIKAFLEX	NOT NECESSARY	37.00	-
1	TAIL GATE DOOR GLASS MOULDING LH	NOT NECESSARY	29.40	-
1	TAIL GATE DOOR GLASS MOULDING RH	NOT NECESSARY	29.40	-
1	SEALANT W/SCREEN	NOT NECESSARY	37.00	-
1	MOULDING BACK WINDOW,LOWER NO 1	NOT NECESSARY	29.40	-
1	SEALANT W/SCREEN	NOT NECESSARY	37.00	-
1	PANEL ASSY,DECK LH	NOT NECESSARY	307.00	-

Report Ref No. CS/EGI18010404/Vvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	PANEL ASSY,DECK RH	NOT NECESSARY	307.00	-
1	TAIL LAMP BRACKET LH	NOT NECESSARY	30.70	-
1	TAIL LAMP BRACKET RH	NOT NECESSARY	30.70	-
1	FENDER RR/LH	NOT NECESSARY	766.80	-
1	SMRT LOGO	NOT NECESSARY	7.80	-
1	STICKER DECAL 65558888	NOT NECESSARY	21.60	-
1	QUARTER GLASS RR/LH	NOT NECESSARY	168.10	-
1	SEALANT W/SCREEN	NOT NECESSARY	37.00	-
1	FENDER LINER RR/LH	NOT NECESSARY	141.30	-
1	SOLAR FILM	NOT NECESSARY	125.00	-
1	UNDER COVER SUB-ASSY,RR FLOOR	NOT NECESSARY	514.50	-
1	BUMPER SEAL,RR LH	SERVICEABLE	88.90	-
1	END PANEL	TO REPAIR SEE LABOUR	602.10	-
1	TAILGATE ASY	TO REPAIR SEE LABOUR	1,007.90	-
			8,830.10	3,425.38
	LABOUR			
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	PANEL BEATING & BODY WORK.INCLUSIVE OF THE REPAIR OF END PANEL AND TAILGATE ASY.		1,183.00	600.00
	SPRAY PAINT.		1,674.00	600.00
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	40.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		100.00	50.00
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.		120.00	40.00
	TO TRANSFER REAR TAILGATE MECHANISM.		120.00	60.00
	TO REMOVE AND REFIX REAR WINDSCREEN.		120.00	60.00
	TO REMOVE/REFIT SEAT.	NOT NECESSARY	120.00	-
	TO REMOVE & REFIT REAR QUARTER GLASS LH.	NOT NECESSARY	120.00	-
	TO INSPECT RR LIGHTING,MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE.		120.00	60.00
	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.		120.00	60.00

Report Ref No. CS/EGI18010404/Vvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REPLACE SUNDRY PARTS.		100.00	20.00
			4,037.00	1,590.00
	GRAND TOTAL		12,867.10	5,015.38
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,350.00

Report Ref No. CS/EGI18010404/Vvd3n2

SATHYA SAI KATHIRASEN

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.