

ASS. REC. BY: Kenneth REF: CS/FCI 1800410/ Ksd307 Special Instruction:

Surveyor: CWS ASSIGNMENT (Office)

From (Person): Eileen Lee of FCI Date/Time: 7/6/18 @ 3:31pm

Estimated Cost: _____ Bill to: _____

OD TP WS/TP RES / OD RES / EVA / INV / MV ? CS

To Inspect Vehicle No: SJK 8795K Insured: SH 6588P

at Workshop m/s Leong Auto Tel: 62666

of 160 Sin Ming Drive # 02-13

Policy No: _____ Claim No: D18004553MFSTH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 06/06/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS 1up? 08/06/2018

Date/Time: 409pm @ 7/6/18 Person Contacted: cady H.O.D. Endorsement: _____

Vehicle: IN/OUT

Date/Time	Action/Instruction	Estimate
	<u>SJK 8795K-X</u>	
	<u>SH 6588P-CC3/CTI16016603/H1wb3q2</u>	
<u>11/06/18</u>	<u>@ 14:55 p.m. revised PA to Eileen via email.</u>	
<u>20/7</u>	<u>CI by 84000 email & confirmed</u>	

REF:

FCI

ASSIGNMENT

From

Date: 08/06/2018

Estimated Cost:

OD ☒ TP ☐ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SJK 8795K

at Workshop m/s

Leong Auto

of

160 Sin Ming Drive # 02-13

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

810,500

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

08

days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

lup

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SJK 8795K Yr Regn: 11 08

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Axiom X C.C. 1496

Colour:

M. Silver

A/C: Insured / Std / NI / NA

Sp. Reading

293036

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

NBE 141 0089657

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/70R14

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR ☒ SUMI

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

3

mm

L/Bal.

5

mm

L/Bal.

3

mm

D.O.A.

01/01/18

D.O.I.

01/01/18

Survey held at

✓

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

11/6 File para to Corrine

(\$ 9,716.80 Red - 71%)

RECEIVED 23 JUL 2018

Date/Time File Pass to?

23/07/18

1)

Fast

Date/Time File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$) 4,000.00 45

Days Of Repair:

8

Resurvey No. of Trip:

1

Add Fee:

☐ Site Insp (\$☐ Interview (\$☐ Tech Invs (\$☐ Weekend (\$

Survey Fee:

Transportation

) S + RS. SI

) Photos

) Others

TOTAL

3x15

1704.45

50

50

23

338

MOTOR SURVEY ASSIGNMENT

Date	06-06-2018	Our Ref No. D18004553MFSH
Accident Date	06-06-2018	Claim Type. Third Party
Insured Vehicle	SH6588P	Third Party Vehicle. SJK8795K
Survey Location	160 Sin Ming Drive #02-13 Sin Ming AutoCity	
Contact Person.	EMELLENE TENG	
Contact No.	62666448/ 97370733	Fax No. 62666358
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	LEONG AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/241212)



PRI Documents



Close



PRI Header Details

Claim No	D18004553MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & LEONG AL
Workshop Name	LEONG AUTO PTE LTD (Contact Person : EMELLENE TENG)	Survey Location & Contact Details	160 Sin Ming Drive #02-13 Sin Ming AutoCity Mobile: 97370733 , Phone: 62666448 , Fax: 62666351 EmailId: TJH@LEONGAUTO.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SH6588P	TP Vehicle No	SJK8795K
PRI Recieved Date	06-06-2018 08:18:42 PM	Surveyor Appointed Date	07-06-2018 03:30:13 PM	Surveyor Accept Date	07-06-2018 0

Survey Report Upload

Surveyor Inspection Date *:	<input type="text"/>	Surveyor Report Date	07-06-2018	Upload Survey Report *:	<input type="button" value="Choose File"/>
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select Year"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

<input type="button" value="Upload Multiple Documents"/>	
File Name	Action

Surveyor Job Remarks

Remarks	<input type="text"/>	<input type="button" value="Save"/>
---------	----------------------	-------------------------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18010410/Ksd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 07-06-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 6588P	Veh. Inspected	SJK 8795K
Policy No.		Coverage (\$)	0.00
Claim No.	D18004553MFSH	Excess (\$)	0.00
Assign From	CWS (EILENE LEE)	Assign Date	07/06/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	06/06/2018	Inspection Date	
Survey held at	LEONG AUTO PTE LTD 160 SIN MING DRIVE #02-13 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8754H
Vehicle Details	
Vehicle No.:	SJK8795K
Vehicle to be Exported:	No
Intended De-registration Date:	11 Jun 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA AXIO 1.5X A
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	1N2C926285
Chassis No.:	NZE1416069657
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$11,721.00
Original Registration Date:	07 Nov 2008
First Registration Date:	07 Nov 2008
Transfer Count:	0
Actual ARF Paid:	\$11,721.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Nov 2018
PARF Rebate Amount:	\$5,860.00
Intended COE Rebate Details	
COE Expiry Date:	06 Nov 2018
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$10,455.00
COE Rebate Amount:	\$422.00
Total Rebate Amount:	\$6,282.00

The information contained herein is correct as at 11 Jun 2018

OK

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 11 June 2018 2:55 PM
To: 'Claim Workflow System'; EILEENLEE@MSFIRSTCAPITAL.COM.SG
Cc: sur@lkkauto.com; 'Nivitha (LKK Auto)'; ASSIGNMENTS@LKKAUTO.COM
Subject: RE: SURVEY ASSESSMENT - D18004553MFSH/1
Attachments: SJK 8795K - Preli Advise.pdf

Dear Eileen,

Enclosed herewith preliminary advice of SJK 8795K.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Thursday, 7 June 2018 4:14 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; ASSIGNMENTS@LKKAUTO.COM
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; sur@lkkauto.com
Subject: RE: SURVEY ASSESSMENT - D18004553MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Thursday, 7 June 2018 3:30 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; EILEENLEE@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18004553MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System

Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18004553MFSH

Date: 11 June 2018

Our Ref: CS/FCI18010410/Ksd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJK 8795K .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 08/06/2018 at the premises of M/s Leong Auto Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>13,716.80</u> .
Revised Estimate Amount	: S\$ <u>6,645.96</u> .
"Check" Items Amount	: S\$ <u>657.23</u> .
Market Value	: S\$ _____ .
LTA Reimbursement Value	: S\$ _____ .
Nett Value	: S\$ _____ .

Description of Damage:

The vehicle sustained damages at the rear o/s portion.



Comments/ Present Status:

Damages Consistent.

Repair days: 8 Days

Yours faithfully,
Kenneth Kong
Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/06/2018 15:40
Date Of Accident	06/06/2018 09:00
Exact Location Of Accident	SLIP ROAD COMPASSVALE ST TO PUNGGOL ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJK8795K
Insured/Policyholder	
Name Of Registered Owner	GUAY BAK SIONG
NRIC No	S0008754H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90274158
Alternative Phone No	OFFICE-90274158

Vehicle Particulars

Manufacturer	TOYOTA
Model	AXIO-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5095471770
Cover Note Number	

Driver

Name of Driver	GUAY BAK SIONG
NRIC No	S0008754H
Date Of Birth	04/02/1948
Occupation	INDOOR
Date Of Driving Pass	06/09/1965
Driving Experience	52 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90274158
Fax Number	
Contact Number	OFFICE-90274158
EMail Address	NOEMAIL

Sketch Plan Pg. 1


SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: 6/6/12 @ 12-1pm
NRIC/FIN No.:



LEONG AUTO PTE LTD

160, Sin Ming Drive, Sin Ming Autocity, #02-13, Singapore 575722
Tel: 62666448 Fax: 62666358 Email: Sales@leongauto.com.sg
Business Registration No. 201312846W
GST Registration No. 201312846W

ESTIMATE

Date: 6/6/2018
DOA: 6/6/2018

Vehicle No: SJK8795K

Make & Model: Toyota Corolla Axio 1.5

S/N	Qty	Item Description	Parts Price	Surveyor
1	1	Boot Lid	\$ 1,055.00	✓
2	1	Boot Lid Lock	\$ 225.40	X
3	1	Boot Lid Lock Catch	\$ 59.10	X
4	1	Boot Lid Inner Trim	\$ 213.50	X
5	1	Boot Lid Weatherstrip	\$ 280.90	50% ✓
6	1	Boot Lid Emblem "Axio"	\$ 63.10	✓
7	1	Boot Lid Emblem "X"	\$ 58.40	✓
8	1	Boot Lid Centre Logo	\$ 66.70	4
9	2	Boot Lid No. Plate Lamp	\$ 111.30	X
10	1	Tail Lamp RH	\$ 423.60	✓
11	1	Tail Lamp RH Retainer	\$ 74.60	✓
12	1	Tail Lamp LH	\$ 423.60	X
13	1	Tail Lamp LH Retainer	\$ 74.60	X
14	2	Tail Lamp Panel	\$ 384.60	4
15	1	R/H Fender	\$ 862.90	✓
16	1	R/H Fender Inner Trim	\$ 676.30	X
17	2	Fender Mud Flap	\$ 235.70	X
18	1	Rear Windscreen Moulding	\$ 178.70	✓
19	1	Rear Bumper	\$ 1,021.90	✓
20	1	Rear Bumper Retainer RH	\$ 91.90	✓
21	1	Rear Bumper Retainer LH	\$ 91.90	X
22	2	Rear Bumper Bracket	\$ 125.50	4
23	1	Rear End Panel	\$ 562.20	✓
24	1	Rear End Panel Top Garnish	\$ 276.30	X
25	1	Spare Tyre Panel	\$ 791.80	X
26	1	Spare Tyre Panel Tools Sponge	\$ 252.10	X
27	1	Spare Tyre Panel Windnut	\$ 134.20	X
28	1	Spare Tyre Top Board	\$ 406.60	X
			\$ 9,222.40	
		Less 25%	\$ 2,305.60	
			\$ 6,916.80	
		Special Nett Items		
1		Sundries	\$ 50.00	X
2	1 set	Boot Lid Outer Garnish Clips	\$ 50.00	X
3	2 sets	Rear Tail Lamp Clips	\$ 60.00	4
4	2	Rear Tail Lamp Panel Sealant	\$ 100.00	20% ✓
5	1	Rear End Panel Sealant	\$ 120.00	30% ✓
6	1 set	Rear End Panel Top Garnish Clips	\$ 80.00	X
7	1	Spare Tyre Panel Sealant	\$ 120.00	X
8	1	Spare Tyre Panel Insulator Pad	\$ 350.00	X
9	1	Fender L/H Sealant	\$ 120.00	30% ✓
10	2 sets	Rear Fender Inner Trim Clips	\$ 100.00	X
11	1	Rear Windscreen Moulding Sealant	\$ 120.00	40% ✓
12	1	Rear Windscreen Moulding Damping Seal	\$ 120.00	30% ✓

13	1 set	Rear Reverse Camera	Sn	\$	380.00	X
14	1 set	Rear Reverse Sensor	Sn	\$	300.00	2005m
15	1 set	Rear Bumper Clips	mc	\$	50.00	✓
16	1 set	Number Plate with Garnish	Sn	\$	80.00	X
				\$	2,200.00	
		Total parts		\$	9,116.80	
	S/N	Labour Description		Amount	Amount	
	1	Labour for panel beating, cut, weld, straighten and replace rear damaged parts.		\$ 1,800.00	1200l	
	2	To putty and spray painting rear portion.		\$ 1,600.00	900l	
	3	To check rear lighting and wiring.		\$ 80.00	20h	
	4	To remove and install rear boot lid lock mechanism.		\$ 120.00	50l	
	5	To remove and install inner garnish and trim to facilitate the repair.		\$ 350.00	120l	
	6	To apply anti rust proofing to rear affected area.		\$ 250.00	90l	
	7	To remove and install rear reverse sensor.		\$ 80.00	50l	
	8	To remove and install rear reverse windscreen.		\$ 120.00	✓	
	9	To remove and install rear reverse camera.		\$ 80.00	40m	
	10	To remove & refit boot lid componenet to replace boot lid, check & re-adjust the close gap and alignment and water seepage		\$ ~ 120.00	X	
		Total labour :		\$ 4,600.00		
		Total parts :		\$ 9,116.80		
		Total labour :		\$ 4,600.00		
		Total repair cost : (Before GST)		\$ 13,716.80		

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

570.50
2590




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18010410/Ksd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 02-08-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 6588P	Veh. Inspected	SJK 8795K	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18004553MFSH	Excess (\$)	0.00	
Assign From	EILENE LEE	Assign Date	07/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA AXIO X (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	NZE1416069657	Colour	METALLIC SILVER	
Odometer	293036	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/70 R14	SUMITOMO	5 mm	
L/H Front Tyre	185/70 R14	SUMITOMO	5 mm	
R/H Rear Tyre	185/70 R14	SUMITOMO	3 mm	
L/H Rear Tyre	185/70 R14	SUMITOMO	3 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/06/2018	Inspection Date	08/06/2018	
Survey held at	LEONG AUTO PTE LTD 160 SIN MING DRIVE #02-13 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJK 8795K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BOOT LID	BUCKLED	1,055.00	1,055.00
1	BOOT LID LOCK	TO REPAIR SEE LABOUR	225.40	-
1	BOOT LID LOCK CATCH	TO REPAIR SEE LABOUR	59.10	-
1	BOOT LID INNER TRIM	SERVICEABLE	213.50	-
1	BOOT LID EMBLEM "AXIO"	NECESSARY	63.10	63.10
1	BOOT LID EMBLEM "X"	NECESSARY	58.40	58.40
1	BOOT LID CENTRE LOGO	NOT NECESSARY	66.70	-
2	BOOT LID NO. PLATE LAMP	SERVICEABLE	111.30	-
1	TAIL LAMP RH	CRACKED	423.60	423.60
1	TAIL LAMP RH RETAINER	CRACKED	74.60	74.60
1	TAIL LAMP LH	SERVICEABLE	423.60	-
1	TAIL LAMP LH RETAINER	SERVICEABLE	74.60	-
2	TAIL LAMP PANEL	O/S BENT	384.60	192.30
1	R/H FENDER	BENT	862.90	862.90
1	R/H FENDER INNER TRIM	SERVICEABLE	676.30	-
2	FENDER MUDFLAP	SERVICEABLE	235.70	-
1	REAR WINDSCREEN MOULDING	NECESSARY	178.70	178.70
1	REAR BUMPER	BENT / CRACKED	1,021.90	1,021.90
1	REAR BUMPER RETAINER RH	CRACKED	91.90	91.90
1	REAR BUMPER RETAINER LH	SERVICEABLE	91.90	-
2	REAR BUMPER BRACKET	O/S BENT	125.50	62.75
1	REAR END PANEL	BENT	562.20	562.20
1	REAR END PANEL TOP GARNISH	SERVICEABLE	276.30	-
1	SPARE TYRE PANEL	TO REPAIR SEE LABOUR	791.80	-
1	SPARE TYRE PANEL TOOLS SPONGE	SERVICEABLE	252.10	-
1	SPARE TYRE PANEL WINDNUT	SERVICEABLE	134.20	-
1	SPARE TYRE TOP BOARD	SERVICEABLE	406.60	-

Report Ref No. CS/FCI18010410/Ksd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 25% DISCOUNT		-2,235.38	-1,161.84
			6,706.12	3,485.51
1	BOOT LID WEATHERSTRIP (50%) (SN)	DISTORTED / CUT	280.90	140.45
	LESS 25% DISCOUNT		-70.23	-
			210.67	140.45
	<u>SPECIAL NETT ITEMS</u>			
1	SUNDRIES (SN)	NOT NECESSARY	50.00	-
1	SET BOOT LID OUTER GARNISH CLIPS (SN)	NOT NECESSARY	50.00	-
2	SETS REAR TAIL LAMP CLIPS (SN)	O/S NECESSARY	60.00	30.00
2	REAR TAIL LAMP PANEL SEALANT (SN)	O/S NECESSARY	100.00	20.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	120.00	30.00
1	SET REAR END PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	80.00	-
1	SPARE TYRE PANEL SEALANT (SN)	NOT NECESSARY	120.00	-
1	SPARE TYRE PANEL INSULATOR PAD (SN)	NOT NECESSARY	350.00	-
1	FENDER L/H SEALANT (SN)	NECESSARY	120.00	30.00
2	SETS REAR FENDER INNER TRIM CLIPS (SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN MOULDING SEALANT (SN)	NECESSARY	120.00	40.00
1	REAR WINDSCREEN MOULDING DAMPING SEAL (SN)	NECESSARY	120.00	30.00
1	SET REAR REVERSE CAMERA (SN)	SERVICEABLE	380.00	-
1	SET REAR REVERSE SENSOR (SN)	SCRATCHED	300.00	200.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
1	SET NUMBER PLATE WITH GARNISH (SN)	SERVICEABLE	80.00	-
			2,200.00	430.00
	<u>LABOUR</u>			
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN AND REPLACE REAR DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF BOOT LID LOCK, BOOT LID LOCK CATCH AND SPARE TYRE PANEL.		1,800.00	1,200.00
	TO PUTTY AND SPRAY PAINTING REAR PORTION.		1,600.00	900.00
	TO CHECK REAR LIGHTING AND WIRING.		80.00	20.00
	TO REMOVE AND INSTALL REAR BOOT LID LOCK MECHANISM.		120.00	50.00

Report Ref No. CS/FC118010410/Ksd3e2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND INSTALL INNER GARNISH AND TRIM TO FACILITATE THE REPAIR.	NOT NECESSARY	350.00	120.00
	TO APPLY ANTI RUST PROOFING TO REAR AFFECTED AREA.		250.00	90.00
	TO REMOVE AND INSTALL REAR REVERSE SENSOR.		80.00	50.00
	TO REMOVE AND INSTALL REAR REVERSE WINDSCREEN.		120.00	120.00
	TO REMOVE AND INSTALL REAR REVERSE CAMERA.		80.00	40.00
	TO REMOVE & REFIT BOOT LID COMPONENT TO REPLACE BOOT LID, CHECK & RE-ADJUST THE CLOSE GAP AND ALIGNMENT AND WATER SEEPAGE.		120.00	-
			4,600.00	2,590.00
GRAND TOTAL			13,716.79	6,645.96
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,000.00

Report Ref No. CS/FCI18010410/Ksd3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.