

22/03/2002

ASS. REC. BY:

REF: CS/GAI18010422/K9d307

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Rachel Tan

of

GAI

Date/Time:

7/6/18 @ 5:19pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLE 9342K

Insured:

GW 4264A

at Workshop m/s

Esteem performance

Tel:

6484 1221

of

Bik 5033 # 01-259 AMK Ind. Park 2

Policy No:

Claim No:

CLMOMVCOU003187

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

05/06/2018

CA / REV / REP. / REV 24 HRS

'wp)

08/06/2018

H.O.D. Endorsement:

Date/Time:

5:28pm @ 7/6/18

Person Contacted:

Serence

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓) Estimate

SLE 9342K-X

GW 4264A-X

11/6/18 @ 2:44pm

revised to Rachel Tan by email.

19/7

CLM 8348a email Recs from (Red \$5750.20, 63%)

REF: GAI

ASSIGNMENT

From

Date: 8/6/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLE 9342K

at Workshop m/s

Esteem Performance

of BLK 5033 # 01-259 Amk hd. Park 2

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5-8 days

Res.: Yes or No

Lum Sum:

1.13.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

1up

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLE 9342K Yr Regn: 08 16

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mit Attrage

C.C.

1193

Colour

White

A/C: Insured / Std / NI / NA

Sp. Reading

6800

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

NMBS TA 13A1H800359

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD ☒ A/Rim or

Tyre Size:

F:

185/55R15

R:

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

5/6/18

D.O.I.

8/6/18

Survey held at

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

11/6 File pass to Customer

RECEIVED 23 JUL 2018

Date/Time File Pass to?

☐

Preli. Report

1) 20/7 1up

☐

Final Report

Date/Time File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

1

Survey Fee:

250

Transportation

) S + RS. SI

) Photos

) Others

TOTAL

250

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

TP

Lump Sum / I.B.I. (\$

3450



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

GREAT AMERICAN INSURANCE COMPANY

Ref : CS/GAI18010422/Kqd3

3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
SINGAPORE 039190

Date : 07-06-2018



Code : GAI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GW 4264A	Veh. Inspected	SLE 9342K
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	RACHEL TAN	Assign Date	07/06/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	05/06/2018	Inspection Date	
Survey held at	ESTEEM PERFORMANCE PTE LTD BLK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-259 SINGAPORE 569536		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Nivitha (LKK Auto)

From: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Sent: Thursday, 7 June 2018 5:19 PM
To: serence@esteemperf.com.sg
Cc: LKK Assignments
Subject: PRI SURVEY SLE9342K (GW4264A - GA)
Attachments: SCAN0929.pdf

Without prejudice

Hi Serence

As requested, we will arrange for LKK to conduct Survey.

Dear LKK, please accept assignment to conduct TP survey.

Regards

Rachel Tan

Executive, Motor Claims, Great American Insurance Company

Tel: 6804 7846

From: Ng, Sharon
Sent: Thursday, June 7, 2018 4:51 PM
To: Tan, Rachel <Rachel.Tan@sg.gaig.com>
Cc: serence@esteemperf.com.sg
Subject: FW: [External] REQUEST FOR PRI SURVEY SLE 9342 K

Hi Rachel

Please inform TP workshop who to send to in future.

Regards

Sharon

GAIC

From: serence ctc <serence@esteemperf.com.sg>
Sent: Thursday, June 07, 2018 4:32 PM
To: Ng, Sharon <Sharon.Ng@sg.gaig.com>
Cc: Ngian, Kelvyna <Kelvyna.Ngian@sg.gaig.com>; jenny chong <jenny@esteemperf.com.sg>; Carmen Lim <carmen@esteemperf.com.sg>
Subject: [External] REQUEST FOR PRI SURVEY SLE 9342 K

Dear Sir / Madam,

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PRE-ACTION PROTOCOAL FOR NON INJURY MOTOR ACCIDENT CASES (NIMA)

We act for Goldbell Car Rental Pte Ltd who has appointed the under-mentioned workshop to repair his motor vehicle no.SLE 9342 K

Please be informed that the said vehicle can be inspected at :

Name of workshop : Esteem Performance Pte Ltd

Address : BLK 5033 #01-259 ANG MO KIO IND PARK 2 S 569536


Tel : 6753 2112

Fax : 6451 0394

We hereby give 2 clear days notice to conduct a pre-repair inspection of the said vehicle at the above-mentioned workshop during office hours.

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday. The above-mentioned workshop will commence repairs should you fail to conduct the pre-repair inspection.

--



Freundliche Grüße / Best Regards

Serence Chee

Claims Assistant | Operation Division

Esteem Performance Pte Ltd

P: 6484 1221

E: serence@esteemperf.com.sg

5033 Ang Mo Kio Industrial Park 2 #01-259

(Head Office)

385 Sin Ming Drive Vicom Inspection Centre

(Showroom)

www.esteemperformance.com



The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 11 June 2018 2:44 PM
To: 'Tan, Rachel'; assignments
Cc: SUR
Subject: RE: PRI SURVEY SLE9342K (GW4264A - GA)
Attachments: CSGAI18010422Kqd3.pdf

Dear Rachel,

Enclosed herewith preliminary advice of SLE 9342K.

Kindly provide us the claim number of above mentioned.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 7 June 2018 5:32 PM
To: 'Tan, Rachel' <Rachel.Tan@sg.gaig.com>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: PRI SURVEY SLE9342K (GW4264A - GA)

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan, Rachel [<mailto:Rachel.Tan@sg.gaig.com>]
Sent: Thursday, 7 June 2018 5:19 PM
To: serence@esteemperf.com.sg
Cc: LKK Assignments <assignments@lkkauto.com>
Subject: PRI SURVEY SLE9342K (GW4264A - GA)

Without prejudice

Hi Serence

As requested, we will arrange for LKK to conduct Survey.

* Dear LKK, please accept assignment to conduct TP survey.

Regards

Rachel Tan



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: GW 4264A

Date: 11th June 2018

Our Ref: CS/GAI18010422/Kqd3

The Motor Claims Department
Great American Insurance Company

Attn: Rachel

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SLE 9342K .


We thank you for the instruction on 07/06/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 08/06/2018 at the premises of M/s ESTEEM PERFORMANCE and have the following to report:-

Workshop Estimate Amount	: S\$ <u>9,200.20</u> .
Revised Estimate Amount	: S\$ <u>4,676.20</u> .
"Check" Items Amount	: S\$ <u>500.40</u> .
Market Value	: S\$ <u>-</u> .
Salvage Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages consistent.

We have NOT authorise repair.

Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0651D
Vehicle Details	
Vehicle No.:	SLE9342K
Vehicle to be Exported:	No
Intended De-registration Date:	11 Jun 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	ATTRAGE 1.2 CVT
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	3A92UDB8031
Chassis No.:	MMBSTA13AHH000359
Maximum Power Output:	57.0 kW (76 bhp)
Open Market Value:	\$13,930.00
Original Registration Date:	08 Aug 2016
First Registration Date:	08 Aug 2016
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Aug 2026
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	07 Aug 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,000.00
COE Rebate Amount:	\$43,226.00
Total Rebate Amount:	\$46,976.00

The information contained herein is correct as at 11 Jun 2018

OK

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SLE9342K		
Vehicle Type :	R10 - Private Hire (Self-Drive) Motor Car		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	MITSUBISHI		
Vehicle Model :	ATTRAGE 1.2 CVT		
Chassis No. :	MMBSTA13AHH000359		
Propellant :	Petrol		
Engine No. :	3A92UDB8031		
Engine Capacity :	1193 cc		
Maximum Power Output :	57.0 kW (76 bhp)		
Maximum Laden Weight :	1335 kg		
Unladen Weight :	940 kg		
Year Of Manufacture :	2016		
Original Registration Date :	08 Aug 2016		
Lifespan Expiry Date :	-		
COE Category :	A - Car up to 1600cc & 97kW (130bhp)		
Quota Premium :	\$53,000.00		
COE Expiry Date :	07 Aug 2026		
Road Tax Expiry Date :	07 Aug 2018		
PARF Eligibility Expiry Date :	07 Aug 2026		
Inspection Due Date :	07 Aug 2019		
Intended Transfer Date :	11 Jun 2018		
CO2 Emission :	113.00 (g/km)		
CEV/VES Rebate Utilised Amount :	\$8,930.00		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
The current road tax expiry is 07 Aug 2018. You may renew the road tax from 08 May 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 07 Aug 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable (From 08 Aug 2018 to 07 Feb 2019)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	253.00	-	253.00
Total Amount Payable :			278.00
Amount Payable (From 08 Aug 2018 to 07 Aug 2019)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	506.00	-	506.00
Total Amount Payable :			531.00

You may print this page for reference.

OK

Print

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/06/2018 10:14
Date Of Accident	05/06/2018 18:20
Exact Location Of Accident	BKE TOWARDS SLE NEAR MANDAI EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLE9342K
Insured/Policyholder	
Name Of Registered Owner	GOLDBELL CAR RENTAL PTE LTD
Co Reg No	-
Email Address	MOSESSES_796@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-96822933
Alternative Phone No	OFFICE-96822933

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	ATTRAGE
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD18V00034/VPZ/R03
Cover Note Number	

Driver

Name of Driver	LEE LEONG HWA
NRIC No	S7814365G
Date Of Birth	17/05/1978
Occupation	OUTDOOR
Date Of Driving Pass	27/02/2001
Driving Experience	17 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96822933
Fax Number	
Contact Number	
Email Address	MOSESSES_796@HOTMAIL.COM

Address	BLK 276 YISHUN STREET 22 #11-246
Postcode	760276
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER STATEMENT (ATTENDED BY: JAMES NG)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GW4264A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	PANNER SELVAM PRAPAHARAM
NRIC/Passport Number	G6263716T
Contact Number	83464353
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the Insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law firms/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers/agencies (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature & Time


Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

NG WING KIN JAMES

S7927881E





Describe Circumstance of the Accident *

On travel back home along BKE road
 of SLE along Mandin Road. Traffic was heavily
 . As such, I travel slowing as many vehicles
 in front of me. Sudden, one lorry lorry onto
 my vehicle back as mention in the report
 few pages of the report. During the accident
 nobody sustain injuries. However, traffic
 was too heavily in the expressway. As
 such, we exchange particulars and make
 some photo of the accident and left the
 scene.

Declaration
 I/We declare the foregoing particulars are true in every respect.

 
 Policyholder's Signature / Stamp

 *
 Driver's Signature (if driver is not the policyholder) / Date
 & Time
 5/6/13 P
 2100hrs


 Witnessed by Reporting Centre Personnel
 NG WING KIN JAMES
 S7927881E



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLE 9342 K

Parts	(a) Cost / List Price Items	_____
	Plus/Less	_____
	Total of Cost / List	_____
	(b) Nett Price Items	\$ 5,428.00
	Less 10%	\$ 542.80
	Total of Nett Item	\$ 4,885.20
	(c) Special Nett Items	\$ 45.00
Total Parts Cost		\$ 4,930.20
Labour		\$ 4,270.00
Total		\$ 9,200.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kennerth
Company : LKK
Survey conducted on : 8/6/18 at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 05 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : LK Date: 8/6/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SLE 9342 K**
Make & Model : **MITSUBISHI ATTRAGE**
Chassis No : **MMBSTA13AHH000359**

Submit By : **Carmen Lim**
Year Manufacture : **2016**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor <i>Red</i>	2	\$260.00		<i>200.00</i>
2	Rear number plate <i>Red</i>	1	\$45.00	S.N	<i>✓</i>
3	Rear No.plate lamp LH <i>Sn</i>	1	\$48.00		<i>X</i>
4	Rear No.plate lamp RH <i>cm</i>	1	\$48.00		<i>240 ✓</i>
5	Rear bumper <i>740.00</i> <i>By</i>	1	\$750.00		<i>✓</i>
6	Rear bumper clip <i>me</i>	10	\$30.00		<i>✓</i>
7	Rear bumper side retainer LH <i>Di's</i>	1	\$26.00		<i>✓</i>
8	Rear bumper side retainer RH <i>Sn</i>	1	\$26.00		<i>X</i>
9	Rear bumper bracket LH <i>R</i>	1	\$29.00		<i>X</i>
10	Rear bumper bracket RH <i>R</i>	1	\$29.00		<i>X</i>
11	Rear bumper sponge	1	N/A		
12	Rear bumper reinforcement	1	N/A		
13	Rear bumper reflector LH <i>Sn</i>	1	\$20.00		<i>X</i>
14	Rear bumper reflector RH <i>Sn</i>	1	\$20.00		<i>X</i>
15	Bootlid <i>798.00</i> <i>By</i>	1	\$828.00		<i>✓</i>
16	Bootlid lock <i>Red</i>	1	\$206.00		<i>✓</i>
17	Bootlid hinge LH <i>R</i>	1	\$192.00		<i>X</i>
18	Bootlid hinge RH <i>R</i>	1	\$192.00		<i>X</i>
19	Bootlid emblem <i>38.00</i> <i>me</i>	1	\$41.00		<i>✓</i>
20	Wording "ATTRAGE" <i>26.00</i> <i>me</i>	1	\$38.00		<i>✓</i>
21	Bootlid chrome <i>243.00</i> <i>cm</i>	1	\$318.00		<i>✓</i>
22	Tail end panel <i>R</i>	1	\$402.00		<i>X</i>
23	Tail end panel garnish <i>Red</i>	1	\$62.00		<i>✓</i>

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : **SLE 9342 K**
 Make & Model : **MITSUBISHI ATTRAGE**
 Chassis No : **MMBSTA13AHH000359**

Submit By : **Carmen Lim**
 Year Manufacture : **2016**
 Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Tail end panel garnish clip <i>me</i>	8	\$48.00		✓
25	Boot weatherstrip <i>dis / me</i>	1	\$148.00		✓
26	Tail lamp LH <i>me / me</i>	1	\$276.00		✓
27	Tail lamp RH <i>me</i>	1	\$276.00		X
28	Tail lamp clip <i>me 2A</i>	2	\$24.00		✓
29	Spare tyre well panel <i>R</i>	1	\$906.00		X
30	Spare tyre board <i>me</i>	1	\$185.00		✓
31					
32					
33					
34					
35					
36					
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SLE 9342 K** Submit By : **Carmen Lim**
Make & Model : **MITSUBISHI ATTRAGE** Year of Manufacture : **2016**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER,BOOTLID,END PANEL, SPARE TYRE WELL PANEL,LHR FENDER,RHR FENDER)	\$1,800.00	700
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER,BOOTLID,END PANEL, SPARE TYRE WELL PANEL,LHR FENDER,RHR FENDER)	\$1,600.00	800
3	To check wiring	\$50.00	20
4	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	60
5	To tuff coat.	\$250.00	60
6	To remove & refit reverse sensor to assit work load	\$120.00	50
7	To transfer boot mechanism to new boot	\$120.00	50
8	To conduct water leakage tests to ensure proper air and sealing	\$120.00	20
9	Towing <i>nn</i>	\$60.00	X

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
GREAT AMERICAN INSURANCE COMPANY			Ref : CS/GAI18010422/Kqd3e2	
3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190			Date : 25-07-2018	
			Code : GAI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GW 4264A	Veh. Inspected	SLE 9342K	
Policy No.		Coverage (\$)	0.00	
Claim No.	CLMOMVC000003287	Excess (\$)	0.00	
Assign From	RACHEL TAN	Assign Date	07/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI ATTRAGE (A)	c.c	1193	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	MMBSTA13AHH000359	Colour	WHITE	
Odometer	6800	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/55 R15	BRIDGESTONE	9 mm	
L/H Front Tyre	185/55 R15	BRIDGESTONE	9 mm	
R/H Rear Tyre	185/55 R15	BRIDGESTONE	9 mm	
L/H Rear Tyre	185/55 R15	BRIDGESTONE	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/06/2018	Inspection Date	08/06/2018	
Survey held at	ESTEEM PERFORMANCE PTE LTD BLK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-259 SINGAPORE 569536			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 9342K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR NO PLATE LAMP LH	SERVICEABLE	48.00	-
1	REAR NO PLATE LAMP RH	CRACKED	48.00	48.00
1	REAR BUMPER	BENT	750.00	740.00
10	REAR BUMPER CLIP	NECESSARY	30.00	30.00
1	REAR BUMPER SIDE RETAINER LH	DISTORTED	26.00	26.00
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	26.00	-
1	REAR BUMPER BRACKET LH	TO REPAIR SEE LABOUR	29.00	-
1	REAR BUMPER BRACKET RH	TO REPAIR SEE LABOUR	29.00	-
1	REAR BUMPER REFLECTOR LH	SERVICEABLE	20.00	-
1	REAR BUMPER REFLECTOR RH	SERVICEABLE	20.00	-
1	BOOTLID	BENT	828.00	798.00
1	BOOTLID LOCK	DENTED	206.00	206.00
1	BOOTLID HINGE LH	TO REPAIR SEE LABOUR	192.00	-
1	BOOTLID HINGE RH	TO REPAIR SEE LABOUR	192.00	-
1	BOOTLID EMBLEM	NECESSARY	41.00	38.00
1	WORDING "ATTRAGE"	NECESSARY	38.00	26.00
1	BOOTLID CHROME	CRACKED	318.00	243.00
1	TAIL END PANEL	TO REPAIR SEE LABOUR	402.00	-
1	TAIL END PANEL GARNISH	DENTED	62.00	62.00
8	TAIL END PANEL GARNISH CLIP	NECESSARY	48.00	48.00
1	BOOT WEATHERSTRIP	DISTORTED / DENTED	148.00	148.00
1	TAIL LAMP LH	MTG CRACKED	276.00	276.00
1	TAIL LAMP RH	SERVICEABLE	276.00	-
4	TAIL LAMP CLIP	NECESSARY-2PCS ONLY	24.00	12.00
1	SPARE TYRE WELL PANEL	TO REPAIR SEE LABOUR	906.00	-
1	SPARE TYRE BOARD	CRACKED	185.00	185.00
	LESS 10% DISCOUNT		-516.80	-288.60
			4,651.20	2,597.40

Report Ref No. CS/GAI18010422/Kqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REVERSE SENSOR (SN)	DENTED	260.00	200.00
	LESS 10% DISCOUNT		-26.00	-
			234.00	200.00
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMBER PLATE (SN)	DENTED	45.00	45.00
			45.00	45.00
	<u>LABOUR</u>			
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, BOOTLID, END PANEL, SPARE TYRE WELL PANEL, LHR FENDER, RHR FENDER). INCLUSIVE OF THE REPAIR OF REAR BUMPER BRACKET LH, REAR BUMPER BRACKET RH, BOOTLID HINGE LH, BOOTLID HINGE RH, TAIL END PANEL AND SPARE TYRE WELL PANEL.		1,800.00	700.00
	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, BOOTLID, END PANEL, SPARE TYRE WELL PANEL, LHR FENDER, RHR FENDER)		1,600.00	800.00
	TO CHECK WIRING.		50.00	20.00
	TO REMOVE & REFIT SPARE TYRE, SPARE TYRE BOARD, CARPET TRIM TO ASSIST WORK LOAD.		150.00	60.00
	TO TUFF COAT.		250.00	60.00
	TO REMOVE & REFIT REVERSE SENSOR TO ASSIST WORK LOAD.		120.00	50.00
	TO TRANSFER BOOT MECHANISM TO NEW BOOT.		120.00	50.00
	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING.		120.00	20.00
	TOWING.	NOT NECESSARY	60.00	-
			4,270.00	1,760.00
GRAND TOTAL			9,200.20	4,602.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,450.00

Report Ref No. CS/GAI18010422/Kqd3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.