

ASS. REC. BY:

REF:

CS/FC118010423/Krd3ⁿ²

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

CWS

From (Person):

Karen Tan

of

PES

Date/Time: 7/6/18 @ 5:22pm

Estimated Cost:

Bill to:

OD (TP) WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLQ 9454H

Insured:

SHD 3186L

at Workshop m/s

Lim Jun Motor

Tel:

64520893

of

81K 176 81a Ming Drive # 03-09

Policy No:

Claim No:

D18004424MP8H

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

01/06/2018

CA / REV / REP. / REV 24 HRS

'DS'

12.06.2018 @ after 1030am

H.O.D. Endorsement:

Date/Time:

5:26pm @ 7/6/18

Person Contacted:

Richard

Vehicle IN (OUT)

Date/Time

Action/Instruction (✓) Estimate

SLQ 9454H-X

SHD 3186L-CC3/LCR18009088/K/pq3

DOA: 16/5/18

Revert thru email

Confirm \$425K.88 @ 7 days

Red: \$2036, 32%.

REF: FCI

ASSIGNMENT

From:

Date: 12/06/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLQ 9454H

at Workshop m/s Lim kun motor
of BIK 176, Sin Ming Drive # 03-09

Insured:

Policy No.:

Claims No.:

Sum Insured:


Excess:

(Client's Record)

After 10:30am

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$ 87k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 07 days Res.: Yes or No

Lum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS wup

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLQ 9454H Regn: 07 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda A) Wagon Freed C.C. 1496

Colour:

M. Grey A/C: Insured / Std / NI / NA

Sp. Reading:

13343 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

GB7 1032064

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 205/55ZR16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Maxxis

Front

R/Bal.

mm

Rear

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

1/6/18

D.O.I.

12/6/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

13/6 File pass to Catherine

RECEIVED 2-2 JUN 2018

Date/Time: File Pass to?



Preli. Report



Final Report

1) Typist

Date/Time: File Return to?

2)

Days Of Repair: 7

Resurvey No. of Trip: 1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation

) S + RS.)

Photos

Others

TOTAL

Report Format: 1+

Lump Sum / I.B.I. (\$) 4254.88

145
50
50
16
261



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18010423/Krd3

36 ROBINSON ROAD

#16-01 CITY HOUSESINGAPORE 068877

Date : 07-06-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 3186L	Veh. Inspected	SLQ 9454H
Policy No.		Coverage (\$)	0.00
Claim No.	D18004424MFSH	Excess (\$)	0.00
Assign From	CWS (KAREN TAN)	Assign Date	07/06/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	01/06/2018	Inspection Date
Survey held at	LIM TAN MOTOR PTE LTD BLK 176 SIN MING DRIVE #03-09 SIN MING AUTOCARE SINGAPORE 575721	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18004424MFSH

Our Ref: CS/FCI18010423/Krd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLQ 9454H

Please be informed that we had conducted the inspection of the above mentioned vehicle on 12.06.2018 at the premises of M/s LIM TAN MOTOR PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ <u>6,290.00</u>
Revised Estimate Amount	: S\$ <u>4,254.88</u>
"Check" Items Amount	: S\$ <u> </u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages
at n/s body.



Yours faithfully
KENNETH
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	04-06-2018	Our Ref No. D18004424MFSH
Accident Date	01-06-2018	Claim Type. Third Party
Insured Vehicle	SHD3186L	Third Party Vehicle. SLQ9454H
Survey Location	BLK 176 SIN MING DRIVE #03-09/10/06 SIN MING AUTOCARE	
Contact Person.	VENUS LEE	
Contact No.	64520893/ 97921329	Fax No. 64589127
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	LIM TAN MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/241046)



PRI Documents



Close



PRI Header Details

Claim No	D18004424MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & LIM TAN M
Workshop Name	LIM TAN MOTOR PTE LTD (Contact Person : VENUS LEE)	Survey Location & Contact Details	BLK 176 SIN MING DRIVE #03-09/10/06 SIN MING AUT Mobile: 97921329 , Phone: 64520893 , Fax: 6458912 EmailId: VENUS@LTM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHD3186L	TP Vehicle No	SLQ9454H
PRI Recieved Date	07-06-2018 04:49:36 PM	Surveyor Appointed Date	07-06-2018 05:21:35 PM	Surveyor Accept Date	07-06-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	07-06-2018	Upload Survey Report *:	Choose File
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

[Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 1947G

Vehicle Details

Vehicle No.: SLQ9454H
Vehicle to be Exported: Yes
Intended De-registration Date: 06 Jun 2018
Vehicle Make: HONDA
Vehicle Model: FREED 1.5G HYBRID AUTO
Primary Colour: Silver
Manufacturing Year: 2017
Engine No.: LEB5558499
Chassis No.: GB71032064
Maximum Power Output: 101.0 kW (135 bhp)
Open Market Value: \$25,422.00
Original Registration Date: 27 Jul 2017
First Registration Date: 27 Jul 2017
Transfer Count: 0
Actual ARF Paid: \$5,000.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 26 Jul 2027
PARF Rebate Amount: \$3,750.00

Intended COE Rebate Details

COE Expiry Date: 26 Jul 2027
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$50,001.00
COE Rebate Amount: \$40,000.00
Total Rebate Amount: \$43,750.00

The information contained herein is correct as at 06 Jun 2018

OK

Kr



ESTIMATE TO REPAIR

VEHICLE NO. : SLQ 9454 H
MAKE : HONDA
MODEL : FREED 1.5 G (A)
YEAR : 2017
CHASSIS NO : GB71032064

SURVEYOR NAME : Kenneth (LKC)
DATE OF SURVEY : 12.06.2018
TIME OF SURVEY : 10.30am

DATE : 7-Jun-17
DATE OF ACCIDENT : 1-Jun-17
THIRD PARTY REF : SHD 3186 C / FIRST CAPITAL

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	n/s front door				\$1,064.30
1 pc	n/s front door regulator				\$393.90
2 pcs	n/s front door frame tape		\$56.90		\$113.80
1 pc	n/s rear sliding door				\$1,300.20
2 pcs	n/s rear sliding door tape		\$56.90		\$113.80
1 pc	n/s rear sliding door rubber				\$325.00
1 pc	n/s centre pillar <i>Repair</i>				\$1,250.00
1 pc	n/s rocker panel				\$489.00
					\$5,050.00
	Less 20%				\$1,010.00
					\$4,040.00
	To putty & spray paint				\$1,000.00
	To transfer door fitting				\$80.00
	To remove & refit cushion seat & carpet				\$250.00
	To anti-rust				\$120.00
	Labour Charges				\$800.00
TG-VL/-	Total				\$6,290.00
	<i>Not Authorized</i> <i>1.B.1</i> <i>Refinery B4 paint</i> <i>7 days</i> <i>Paints \$3081.10</i> <i>Less 20% \$616.22</i> <i>\$2464.88</i> <i>Labour \$1790.00</i> <i>PRP \$4254.88</i> <i>ok</i>				

LTM Auto Consultants hereby notify the Repairer of the following:
• To resurvey before after spray painting
• To display damaged parts during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• (Legal modifications) is allowed
• Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company
Acknowledged by Repairer
Signature: *[Signature]*
Date: *18/6/18*

Bik 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
Tel 65-64520893 Fax 65-64589127 Email edmund@LTM.sg Website www.LTM.sg
Co Reg No. 199307277D GST Reg No. M2-0019086-0

This document must not be reproduced in whole or in part, or disclosed to third party or parties without the prior written



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18010423/Krd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 26-06-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 3186L	Veh. Inspected	SLQ 9454H	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18004424MFSH	Excess (\$)	0.00	
Assign From	KARENT	Assign Date	07/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA FREED (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	GB71032064	Colour	METALLIC GREY	
Odometer	13343	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 ZR16	MAXXIS	8 mm	
L/H Front Tyre	205/55 ZR16	MAXXIS	8 mm	
R/H Rear Tyre	205/55 ZR16	MAXXIS	8 mm	
L/H Rear Tyre	205/55 ZR16	MAXXIS	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/06/2018	Inspection Date	12/06/2018	
Survey held at	LIM TAN MOTOR PTE LTD BLK 176 SIN MING DRIVE #03-09 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 9454H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	N/S FRONT DOOR	BENT	1,064.30	1,064.30
1	N/S FRONT DOOR REGULATOR	TO REPAIR SEE LABOUR	393.90	-
2	N/S FRONT DOOR FRAME TAPE @\$56.90	NECESSARY	113.80	113.80
1	N/S REAR SLIDING DOOR	BENT	1,300.20	1,300.20
2	N/S REAR SLIDING DOOR TAPE @\$56.90	NECESSARY	113.80	113.80
1	N/S REAR SLIDING DOOR RUBBER	SERVICEABLE	325.00	-
1	N/S CENTRE PILLAR	TO REPAIR SEE LABOUR	1,250.00	-
1	N/S ROCKER PANEL	BENT	489.00	489.00
	LESS 20% DISCOUNT		-1,010.00	-616.22
			4,040.00	2,464.88
	<u>LABOUR</u>			
	TO PUTTY & SPRAY PAINT.		1,000.00	800.00
	TO TRANSFER DOOR FITTING.		80.00	80.00
	TO REMOVE & REFIT CUSHION SEAT & CARPET.		250.00	120.00
	TO ANTI-RUST.		120.00	90.00
	LABOUR CHARGES INCLUSIVE OF THE REPAIR OF N/S FRONT DOOR REGULATOR AND N/S CENTRE PILLAR.		800.00	700.00
			2,250.00	1,790.00
	GRAND TOTAL		6,290.00	4,254.88
	RECOMMENDED COST OF REPAIRS			4,254.88

Report Ref No. CS/FCI18010423/Krd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.