













PAR Automotive Consultancy

Regn. No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0045-18-TCA

29 January 2018

ACCIDENT VEHICLE SURVEY REPORT

Ng Ting Ji Kelvin
150 Tamarind Road
Singapore 806097

VEHICLE INFORMATION:

<i>Vehicle Reg No.:</i>	SLC9547Y	<i>Odometer:</i>	17971km
<i>Make & Model:</i>	Mazda 3 1.5L	<i>Colour:</i>	Grey
<i>Chassis number:</i>	JM6BM44A8G0342724	<i>Date of accident:</i>	14/06/2017
<i>Year of Regn.:</i>	30/05/2016	<i>Date inspected:</i>	04/07/2017
<i>Repairer at:</i>	Twincar Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-17 Kaki Bukit Auto Hub Singapore 417921	<i>Date inspected (After Repair):</i>	10/07/2017

RE-INSPECTION

We had carried out re-inspection during works in progress and post repair inspection on the above vehicle. Attached in Annex B are the re-inspection photos, showing the work in progress and our re-inspection to the hidden part that were damaged.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.



