

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5363P
 Ref. No : TAX/06/18/2018
 Reg. Date : 14/12/2017
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS4
 Name of Driver : NG KOK HOONG
 Type of Accident : HEAD TO SIDE
 Date / Time of Accident : 05/06/2018 09:30:00 PM
 Accident Reported Date / Time : 06/06/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024096455
 Special Instruction to ARC, if any :
 SLC5883C - AIG - LKK
 Prepared Date : 06/06/2018 10:50:48 AM



Jatuya Sai

6/6/2018

sebastranyang@lkkauto.com

- Part by Part repair
- Question mark item photo
- Photo before paint.

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU603576687

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 338.00	0.00
Total Spray Painting Charges	: 738.00	0.00
Total Material Charges	: 2,325.69	2,325.69
Other Charges	: 260.00	0.00
TOTAL	: 3,661.69	0.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 3.00	0.00 2 days
Prepared / Adjusted By	:	
Arc / Surveyor Sign Off Date	: 06/06/2018 01:42:39 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 06/06/2018 01:41:28 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	338.00	0.00 200
Total Labour	338.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY FILLER RR BUMPER RH	180.00	0.00 ?
TO RESPRAY BUMPER BEAM	180.00	0.00 ?
Total Spray Painting & Panel Beating	738.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 40
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 50
TO WASH AND VACUUM	60.00	0.00 x
Total Other Costs	260.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
5215947913			COVER, RR BUMPER ASSY ✓ _{SCR}	1	423.90	25.00	317.92	Replace	Replace	No
5216116010			CLIPS PIECE, FRT & RR BUMPER ✓ _{NEC}	10	1.50	25.00	11.25	Replace	Replace	No
5256547900			FILLER, RR BUMPER ? , RH	1	119.90	25.00	89.92	Replace	Replace	No
5246247030			PAD, RR BUMPER, ? RH & LH , 1	2	3.80	25.00	5.70	Replace	Replace	No
5246247020			PAD, RR BUMPER, ? RH & LH , 2	2	3.80	25.00	5.70	Replace	Replace	No
5246247010			PAD, RR BUMPER, ? RH & LH , 3	2	3.80	25.00	5.70	Replace	Replace	No
5219147030			SEAL, RR BUMPER ? ARM, RH & LH	2	11.00	25.00	16.50	Replace	Replace	No
8159147010			LENS & BODY ASSY RR BUMPER , LH X _{NN}	1	486.80	10.00	438.12	Replace	Replace	No
5202347030			REAR BUMPER REINFORCEMENT ?	1	318.80	25.00	239.10	Replace	Replace	No
5259147050			SEAL, RR BUMPER , ? RH	1	85.20	25.00	63.90	Replace	Replace	No
5257647040			RETAINER, RR BUMPER, LH X _{NN}	1	111.50	25.00	83.62	Replace	Replace	No
5257547040			RETAINER, RR BUMPER, RH ?	1	112.70	25.00	84.52	Replace	Replace	No
5245347010			GUARD, RR BUMPER LOWER ? XXXXXXXXXX	1	558.30	25.00	418.72	Replace	Replace	No
5216947020			COVER, GUARD RR BUMPER LOWER ✓ _{CUT}	1	14.80	25.00	11.10	Replace	Replace	No
5246147010			PAD, RR BUMPER, ? CTR	3	2.20	25.00	4.95	Replace	Replace	No
5839847050			COVER, REAR FLOOR UNDER , RH ✓ _{Deform}	1	169.50	25.00	127.12	Replace	Replace	No
6563747060			LINER, REAR FENDER , RH X _{NN}	1	135.80	25.00	101.85	Replace	Replace	No
			SENSOR REVERSE ?	1	180.00	0.00	180.00	Replace	Replace	No
			PIXEL STICKER ✓ _{NEC}	2	60.00	0.00	120.00	Replace	Replace	No
TOTAL MATERIALS								2,325.72	2,325.69	
TOTAL MATERIALS(Discounted)							2,325.69	2,325.69		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									