

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD
 64 CECIL ST #04-05 IOB BUILDING
 049711

Attention : Motor Claim Department
 Contact : 6223 8122

Estimate : ES000151

Date : 05/06/2018
 Vehicle Num. : SLH 8314H (LCR)
 Make/Model : HONDA SHUTTLE HYBRID
 Chassis/Eng# :
 Accident Date : 04/06/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR BOOT LID ✓DT		1,200.00
2.	1	REAR WINDSCREEN GLASS MOULDING ✓NEC		250.00
3.	1	REAR BOOT HYBRID EMBLEM (SHUTTLE) ✓NEC		100.00
4.	1	REAR BOOT SHUTTLE EMBLEM (SHUTTLE) ✓NEC		100.00
5.	1	REAR BOOT WEATHER STRIP ✓Deform		180.00
6.	1	REAR NUMBER PLATE LAMP GARNISH X NN		460.00
7.	1	REAR BOOT REFLECTOR LAMP LH may ?		580.00
8.	1	REAR TAIL LAMP - LH ?		580.00
9.	1	REAR BUMPER ✓DMG		1,150.00
10.	1	REAR BUMPER RETAINER LH ?		58.00
11.	1	REAR BUMPER REFLECTOR GARNISH LH ✓BR		130.00
12.	1	REAR BUMPER REFLECTOR LENS - LH ✓BR		120.00
13.	1	REAR BUMPER INNER FOAM - LH ✓CRK		150.00
14.	1	REAR FENDER LH ✓Deform		1,100.00
15.	1	REAR FENDER AIR GRILLE LH ✓Deform		150.00
16.	1	REAR FENDER INNER TRIM COVER LH ✓Deform		345.00
17.	1	REAR END PANEL ?		950.00
18.	1	REAR END PANEL TOP GARNISH ✓DT		260.00
19.	1 LH	REAR TAILLAMP PANEL ✓DT		450.00
List TotalS\$:				8,313.00
20.00% Discount S\$:				1,662.60
				6,650.40
SPECIAL NETT ITEMS :				
1.	1	REAR BUMPER CLIP		50.00
2.	1	REAR FENDER INNER TRIM COVER CLIPS		50.00
3.	1	REAR END PANEL TOP GARNISH CLIPS		50.00

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

INDIA INTERNATIONAL INSURANCE PTE LTD
 64 CECIL ST #04-05 IOB BUILDING
 049711

Attention : Motor Claim Department
 Contact : 6223 8122

Estimate : ES000151

Date : 05/06/2018
 Vehicle Num. : SLH 8314H (LCR)
 Make/Model : HONDA SHUTTLE HYBRID
 Chassis/Eng# :
 Accident Date : 04/06/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
4.	1	REVERSE SENSOR ✓ <i>sc</i>		280.00
5.	1	REAR WINDSCREEN SEALANT ✓		120.00
Special Nett Total S\$:				550.00
LABOUR :				
REMOVE & REFIT REAR WINDSCREEN GLASS				180.00 420
TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES				180.00 100
REMOVE & REPLACE FENDER 1/4 GLASS				180.00 100
LABOUR TO REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS.				1,400.00 1000
PUTTY & SPRAY PAINT ALL AFFECTED AREAS (INNER/ OUTER)				1,200.00 200
TO REMOVE AND INSTALL HIGH VOLTAGE HYBRID BATTERY AS A REQUIREMENTS FOR SAFETY PRECAUTIONS.				380.00 200
TO CONDUCT A STANDARD OF OPEARTING PROCEDURE POST REPAIRS DIAGNOSTIC SCAN TEST A REQUIREMENT FOR HYBRID CARS UPON COMPLETION OF COLLISION REPAIRS.				380.00 200
REMOVE REAR UPHOLSTERY IN ORDER TO FACILITATE REPAIRS AND REFIT BACK SAME				280.00 120
Labour Total S\$:				4,180.00

E. & O.E.

Total S\$: 11,380.40

for WORLD AUTO PTE LTD

Sathya Sai
 6/6/2018
 98072012

- Part by Part Repair
- Question mark item photo
- Photo before paint

6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: