

PDI TUAS

PDI TUAS

CHAY WEN YEE (XIE WENYI)
121 SUNSET WAY
#02-02
Singapore, 597153
Singapore

Tanpin 97495749
WP
13/6/18 @ 1545
Resurvey after repair
SVC @ (Khanh)
5 days

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV030272
Quote No. SER/QUO/1800912
QuoteDate 06/06/18
Salesperson Delsie Ong
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make	Model Description	Mileage	Service Advisor
Volkswagen Passeng	Golf 1.0 TSI 81 kW Trendline	0	Cheong Pearlyn
License No.	VIN	Initial Registration	Sales Advisor
SLX4945D	WVWZZZAUZJW180226	29/03/18	Delsie Ong
Engine Code	Labor Type	Engine No.	Model Code
	1T	CHZ 664838	BQ12AZ

No.	Description	Qty.	UoM	Unit Price	Amount
P B&P ALEX LABOUR	LABOUR	4	UNIT	2.5 x 800	2100 3,360.00
P B&P ALEX PAINT	SPRAY PAINTING	4	UNIT		2400 3,200.00
P B&P DIAG	PROGRAMMING & CALIBRATION	1	Time Un		480.00
P B&P MECH	COMPULSORY TO DO AFTER AC				
	CHECK WIRE HARNESS, ECU, S	1	Time Un		280.00
	Nett				
	Sum Labor				7,320.00

Sum Labor 7,320.00

Explanations

P = Proportionately Charged

Payment Terms No Credit

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total	SGD	7,320.00	7,320.00
7% GST			512.40
Total SGD Incl. GST			7,832.40

Payments to:

- BBN: - Acc.-No.: