

HWA SENG SPRAY PAINTING COMPANY

1 of 1

160 Sin Ming Drive, #05-11,

Sin Ming AutoCity

Singapore 575722

(Registration no :095744/00B)

Tel : 64533100, Fax 62669932

Date of accident : 01/06/2018

Your Insured
Vehicle No : SHD 6244K

Estimate repair cost to TOYOTA HARRIER reg no : SJZ 8098 K

1pc o/s/f fender	S\$	Bur 1012.10	✓
1pc o/s/f fender inner shield		SL 409.10	X
1pc front bumper o/s retainer		D.I 99.40	✓
1pc o/s headlamp		3187.40	?
		4708.00	
	Less 25%	1177.00	
		3531.00	
<u>Special Nett item</u>			
1pc front bumper		CM 2500.00	✓
		2500.00	
<u>Labour & misc charges</u>			
Panel knocking		500.00	400
Spray painting		700.00	500
Wire checking		50.00	200
		6692.47	

HWA SENG SPRAY PAINTING COMPANY



Not Notified

LLR @ ?

Resurvey After Repair

4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: