



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SKC2594T

Chassis No : JHMRU1810GX202266

Model : HRV DX-SIN CVT YM 2016

Owner's Name : PEETHAMBARAN GOPAL

Ins Policy No. : TP DIRECT SETTLEMENT

Date of Accident : 30/5/2018

Document No. : SQT18002205

Page 1

Date : 30. May 2018

Customer No. : WZA006

Svc Advisor : JASON HENG

Engine No : L15B4532266

Date | Time : 30. May 2018 3:52:03 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	THIRD PARTY CLAIMS (J/NO:) OWNER: PEETHAMBARAN GOPAL OWNER INSURER: TOKIO MARINE INSURANCE ACC DATE: 30/5/18 SURVEYED BY: DATE: TP INSURER: AXA INSURANCE S'PORE PTE LTD TP VEH: SHD9706Y						
33505-T7A-J01	REFLECTOR ASSYR.RR. X	1	151.80	25	113.85	7.97	121.82
33555-T7A-J01	REFLECTOR ASSYL.RR. ✓BR	1	151.80	25	113.85	7.97	121.82
71501-T7B-000	FACE RR.BUMPER ✓OMG	1	762.60	25	571.95	40.04	611.99
04718-T7A-000ZZ	FACEL.RR.BUMPER CORNER ✓CUT	1	92.30	25	69.22	4.85	74.07
71593-T7A-000	SPACERR.RR.BUMPER SIDE X	1	11.50	25	8.62	0.60	9.22
71598-T7A-000	SPACERL.RR.BUMPER SIDE ✓NEC	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIPBUMPER ✓NEC	8	2.00	25	12.00	0.84	12.84
74450-T7B-003	PROTECTOR,L.RR.WHEEL ARCH ✓CUT	1	172.10	25	129.07	9.03	138.10
74592-T7A-010	FENDERL.RR.INNER X	1	90.40	25	67.80	4.75	72.55
91501-TR0-003	CLIPINNER FENDER X	8	2.30	25	13.80	0.97	14.77
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR ✓SCR	1	320.00		320.00	22.40	342.40
66100-T7A-300ZZ	PANEL COMPRR. ?	1	365.70	25	274.27	19.20	293.47
75722-T7W-A01	EMBLEMRR. ✓NEC	1	12.90	25	9.67	0.68	10.35
75725-T8N-T00	EMBLEM,RR. I-VTEC ✓NEC	1	14.10	25	10.57	0.74	11.31
68100-T8P-U10ZZ	TAILGATE COMP ✓DT	1	838.90	25	629.17	44.04	673.21
74827-S2G-010	PROTECTORLICENSE PLATE *** ✓NEC	2	2.00	25	3.00	0.21	3.21
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER ✓NEC	1	19.30	25	14.47	1.01	15.48
73226-SZW-000	DAMPERSTD 5X5 ✓NEC	1	8.30	25	6.22	0.44	6.66
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER ✓NEC	1	19.30	25	14.47	1.01	15.48
76711-T6A-003	CAPPIVOT ✓NEC	1	4.70	25	3.52	0.25	3.77
91501-S70-003	FASTENER BW/SHIELD ✓NEC	4	3.20	25	9.60	0.67	10.27
91502-S70-003	FASTENER B ✓NEC	2	4.90	25	7.35	0.51	7.86

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SKC2594T

Chassis No : JHMRU1810GX202266

Model : HRV DX-SIN CVT YM 2016

Owner's Name : PEETHAMBARAN GOPAL

Ins Policy No. : TP DIRECT SETTLEMENT

Date of Accident : 30/5/2018

Document No. : SQT18002205 Page 2

Date : 30. May 2018

Customer No. : WZA006

Svc Advisor : JASON HENG

Engine No : L15B4532266

Date | Time : 30. May 2018 3:52:03 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
91536-SS0-J01	FASTENER AW/SHIELD ✓ NEC	2	3.50	25	5.25	0.37	5.62
BO-WS-SEALANT	WINDSCREEN SEALANT (N) ✓ NEC	2	60.00		120.00	8.40	128.40
Sum Item					2536.34	177.55	2,713.89
BOSUN	SUNDRIES	1	100.00 20		100.00	7.00	107.00
BG02R	REPLACE RR. WINDSCREEN.(N)	1	300.00 280		300.00	21.00	321.00
BODAMKIT	WINDSCREEN DAM KIT.	1	100.00 80		100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	160.00 ✓		160.00	11.20	171.20
BOJSE	BODY JOINT SEALANT FOR TAILGATE	1	100.00 80		100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT FOR END PANEL	1	100.00 80		100.00	7.00	107.00
BOMISC1	RESET & CALIBRATE REAR VIEW CAMERA (N)	1	160.00 ✓		160.00	11.20	171.20
BOMISC1	RESET & CALIBRATE SMART ENTRY SYSTEM (N)	1	160.00 ✓		160.00	11.20	171.20
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	650.00 560		650.00	45.50	695.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	650.00 ? / 560		650.00	45.50	695.50
BKRP02S	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS.	1	3920.00 1680		3920.00	274.40	4194.40
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	2700.00 1350		2700.00	189.00	2889.00
Sum Labor					9100.00	637.00	9,737.00

Survey By _____

Date & Time _____

Excess _____

Status _____

Signature _____

Total Amount 11,636.34 814.55 12,450.89

Total (Inclusive of GST) **12,450.89**

6-7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 5/6/2018 4:32:40 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

Sathya Sai
3/7/2018

- Part by Part

- Question mark item

- Photo before paint.