

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/649/2018/PH
Date : 4-Jun-18

Booked 02/06/18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Lim Kim Huat
Address : Blk 289 Bishan St 24
#12-21
Singapore 570289
Telephone : HP +65 92278620
Type of Claim : Own Damage Claim
Policy No. : 1700047720
Vehicle No : **SGC 8218 M**
Model Code : Audi A3 1.0 TFSI
Model / Year : Sep-17
Engine No : CHZ 515241
Chassis No : WAUZZZ8VXJ1008407
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 29-May-18
Place of Accident : 39 Jurong West Ave 1

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGC 8218 M.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer lhs front door's multi-lock system and power window devices.	S/N \$ 280.00	✓
2	To dismantle and renew lhs front door, align to position. Reinstall all parts removed.	\$ 900.00 500	
3	To respray lhs front door, door handle and lhs sill panel.	\$ 1,800.00 650	
4	To carry out diagnostic checks.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ <u>3,172.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGC 8218 M

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	DOOR - LH <i>perked</i>	\$ 2,190.00	✓
2	OUTER DOOR SEAL - LH <i>new</i>	\$ 139.00	✓
3	BONDING AGENT <i>?</i>	\$ 43.00	?
4	CLEANING SOLUTION <i>?</i>	\$ 64.00	?
5	DOOR CATCH <i>new</i>	\$ 92.00	+
6	DOOR HANDLE, EXTERIOR - LH <i>perked</i>	\$ 207.00	✓
7	MOUNTING BAR <i>new</i>	\$ 143.00	+
8	WINDOW REGULATOR WITHOUT MOTOR <i>new</i>	\$ 232.00	+
9	SUNDRIES <i>?</i>	\$ 200.00	?
SPARE PARTS		:	\$ 3,310.00
LABOUR CHARGES		:	\$ 3,172.00
GRAND TOTAL		:	\$ 6,482.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 07/06/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Authorised Repairs, 03 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant