

Signature: *Taufik*

REF:

A/G CC3/MLG18010461/Tiger

ASSIGNMENT

Form: _____ Date: _____
 Estimated Cost: _____
☒ TP / WS / TP RES / QD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop no: _____
 of: _____
 Insured: _____
 Policy No: 1700090330
 Claims No: 083029917254
 Sum Insured: _____ Excess: 4469 1000 13/6/18
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: 4300K
 IDAC Accident Report: Consistent? Yes or No
 GIA / PR Seen: Consistent? Yes or No
 Est. Repairs: days Res: Yes or No
 Lump Sum: % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Vehicle: SLV5222K Yr Regn: 2017 Dec
 Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Audi S&S 2995
 Colour: Blue AC: Insured / Std / NI / NA
 Sp Reading: 8655 T/Radio: Insured / Std / NI / NA
 Engine: _____
 C/No: WA4ZZZ FG 4J2028544
 Gen. Cond: ☒ Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: _____ R: 255/40R21
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ PIR / SUMI /
 TOYO / YOKO or
 Front: _____ Rear: _____
 R/Bal: 2 mm R/Bal: 7 mm
 L/Bal: 7 mm L/Bal: 2 mm
 D.O.A: _____ D.O.I: 7/6/18 R 8pm
 Survey held at: Premium (bawoi)
 Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or
 Rear o/s
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction 4 More than 8K revert 206/F

SLV 5222K - NBA / INC 18010461 / Y
 08/6/18 @ 3.15pm Verant to Victor via Meimner.
 12/6/18 @ 12.26pm Andy informed C/A via Meimner.
 13/6/18 @ 7.01pm Informed Thana C/A & Ex: 61000 by email.
 22/07/18 @ 2.40pm Repair 30 days, confirmed with Carline Aral fig 5.50/75.36
 (Ref 6.39407.40, 44%)

RECEIVED 16 MAY 2019

Close Time: Fill Pass in: ☐ Preli. Report
☒ Final Report

Days Of Repair: 30
 Resurvey No. of Trip: 4

Add Fee: ☐ Site Insp IS
☐ Interview IS
☐ Park Visit IS
☐ Workshop IS

Report Format: MER-00
 Lump Sum / I.B.I: 50175.36

Survey Fee	200
Transportation	
Food & Accommodation	
Other	
Total	10
	210

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 22 February 2019 2:16 PM
To: 'Carrine Leong'; SUR
Cc: jiajee.yap@premiumauto.com.sg; 'Chang Chee Sing'
Subject: RE: FINAL REVISION - SLV5222K - OD AIG - SURVEYED 7 JUN 18 - TAUFH

Dear Carrine,

WITHOUT PREJUDICE

Confirm final fig \$50,175.36 before excess \$1,000.00 & GST and 30 repair days.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Carrine Leong <carrine.leong@premiumauto.com.sg>
Sent: Thursday, 21 February 2019 4:02 PM
To: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; Shiau Chan (LKKAuto) <siewsc@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: jiajee.yap@premiumauto.com.sg; 'Chang Chee Sing' <claims@premiumauto.com.sg>
Subject: RE: FINAL REVISION - SLV5222K - OD AIG - SURVEYED 7 JUN 18 - TAUFH
Importance: High

Dear Adrian and all,

Reminder

We have yet receive your confirmation of repair cost and days of repair for above vehicle.

Revised estimate was mailed to you on 22 Nov 2018 & 22 Jan 2019.

We sincerely appreciate your early closure.

Thanks & Best Regard

Carrine Leong

Claims Administrator

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9925 f. +65 6841 1183

e. carrine.leong@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 13 June 2018 2:01 PM
To: Claims Dept; SUR
Subject: RE: Accident OD claim for SLV 5222 K on 28/05/2018

Dear Phua,

As instructed by our client, please proceed to repair the insured vehicle **SLV 5222K (Excess \$1,000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Dept [mailto:claims@premiumauto.com.sg]
Sent: Wednesday, 6 June 2018 6:33 PM
To: SUR <sur@lkkauto.com>
Cc: 'Claims Dept' <claims@premiumauto.com.sg>
Subject: Accident OD claim for SLV 5222 K on 28/05/2018

Good afternoon all,

Kindly assist on the accident claim of the above mentioned vehicle. The vehicle is in @ Benoi. Here are the attachment of GIA and estimate for your kind reference.

Thank you.

Best Regards,

Phua

Claims Advisor

Premium Automobiles Pte Ltd (Reg No 189902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	28 May 2018 18:35	Clim Veh Model Changed		[] Merimen Administrator
2	28 May 2018 18:35	Clim Created	Reg No: SLV5222K. Policy No: 1700090330. Acct Date: 2018/05/28. Claim Type: S C. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:MNA418069599	[I] Merimen Administrator
3	08 Jun 2018 10:55	Clim Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] CATHERINE CHONG KAI LING
4	08 Jun 2018 10:55	Adj Clim Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] CATHERINE CHONG KAI LING
5	08 Jun 2018 10:55	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] CATHERINE CHONG KAI LING
6	08 Jun 2018 10:55	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/06/20	[A] CATHERINE CHONG KAI LING
7	08 Jun 2018 10:55	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] CATHERINE CHONG KAI LING
8	08 Jun 2018 10:55	Clim Registration Modified	Rep:1137->204491.	[A] CATHERINE CHONG KAI LING
9	08 Jun 2018 10:55	Clim Veh Model Changed	(203236) AUDI SQ5 3.0 TFSI quattro (A).	[A] CATHERINE CHONG KAI LING
10	08 Jun 2018 10:55	Adj Adjuster Assigned	[None] -> MOHD TAUFIKH BIN HAMID	[A] CATHERINE CHONG KAI LING
11	08 Jun 2018 14:12	Adj Rpt Initiated		[A] SHIAU CHAN
12	08 Jun 2018 14:12	Clim Dtl Modified	JPJ Reg. Date: -> 2017/12/30.	[A] SHIAU CHAN
13	08 Jun 2018 14:12	Clim Details Notified		[A] SHIAU CHAN
14	08 Jun 2018 15:15	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/06/20	[A] SHIAU CHAN
15	08 Jun 2018 15:15	Adj Mandate Request	Cur.Req:61857.00:DAMAGES CONSISTENT, REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
16	12 Jun 2018 09:46	Clim Registration Modified	Init.Est.:>5,000 - 6,000. Excess: -> 1000.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Loo, Tong Shing
17	12 Jun 2018 09:46	Label Added	(20226):Coverage Confirmed.	[A] Merimen Administrator
18	12 Jun 2018 12:26	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/06/20. Mandate Remarks: to commence repairs, all check and supplementary items to be supplemented with clear damage photographs	[I] Fong, Andy-SY
19	12 Jun 2018 12:26	Adj Mandate Set	Approved:61857.00:to commence repairs, all check and supplementary items to be supplemented with clear damage photographs	[I] Fong, Andy-SY

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1827971	08/06/2018 14:12	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLV5222K		10.70

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 08 Jun 2018

Preliminary Advice

Vehicle No	: SLV5222K	Accident Date	: 28/05/2018
Make	: AUDI SQ5	Policy No.	: 1700090330
Assignment Date	: 08/06/2018	Excess	: S\$0.00
Date of Inspection	: 08/06/2018	Est. Duration of Repair	: 20.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (BENOI) 24 BENOI SECTOR SINGAPORE 629857		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	87,001.00
Insurance Amount	:S\$	30,306.00
Repairs (Estimated)	:S\$	31,551.00
Total	:S\$	61,857.00

Long Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

Estimated Old Value	:S\$	
Residual Value	:S\$	300,000.00
GRF Rebate	:S\$	96,856.00
Adjusted Value	:S\$	
Amount for Repair	:S\$	203,144.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us know your finalisation.
- () The vehicle is not repairable. If the vehicle is to be repaired, you are advised to invite tender for the wreck.
- () Other comments:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9061F
Vehicle Details	
Vehicle No.:	SLV5222K
Vehicle to be Exported:	Yes
Intended De-registration Date:	08 Jun 2018
Vehicle Make:	AUDI
Vehicle Model:	SQ5 3.0 TFSI QU
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	CWG028683
Chassis No.:	WAUZZZFY4J2028594
Maximum Power Output:	260.0 kW (348 bhp)
Open Market Value:	\$59,448.00
Original Registration Date:	30 Dec 2017
First Registration Date:	30 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$79,007.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Dec 2027
PARF Rebate Amount:	\$59,255.00
Intended COE Rebate Details	
COE Expiry Date:	29 Dec 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,002.00
COE Rebate Amount:	\$37,601.00
Total Rebate Amount:	\$96,856.00

The information contained herein is correct as at 08 Jun 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/05/2018 18:24
Date Of Accident	28/05/2018 09:40
Exact Location Of Accident	AYE TOWARDS TUAS(BEFORE SOUTH BUONA VISTA EXIT 8)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLV5222K
Insured/Policyholder	
Name Of Registered Owner	LUO CHUAN
NRIC No	S7069061F
Email Address	DANNYLUO0209@ICLOUD.COM
Mobile Phone No	(LOCAL) +65-96726186
Alternative Phone No	OTHERS-96726186

Vehicle Particulars

Manufacturer	AUDI
Model	SQ5
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700090330
Cover Note Number	

Driver

Name of Driver	LUO CHUAN
NRIC No	S7069061F
Date Of Birth	09/02/1970
Occupation	INDOOR
Date Of Driving Pass	24/02/2010
Driving Experience	8 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	+65-96726186
Fax Number	
Contact Number	OTHERS-96726186
Email Address	DANNYLUO0209@ICLOUD.COM

Address	13 COVE DRIVE #04-04
Postcode	098327
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : YANG BIN BIN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP6220L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to regulate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Person's Signature
Name:
NRIC/FIN No:

Accident Sketch Plan

SKETCH PLAN



A = SLV 5222K

B = YP 6220L

A/E to Tuas

(Before South Buona Vista Road Exit 8)

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 28.05.18 at about 09:40 hours along AYE towards Tuas (Before South Buona Vista Road Exit 8). I was travelling straight on the lane 3, when I was about filtering to lane 4 and I saw a vehicle approaching fast on my left and not allowed me to filter, hence I slowed down my vehicle (A).

Suddenly I heard a loud bang from behind. When I alighted I realised it was vehicle (B) which had hit onto rear portion of my vehicle (A). I wish to state that I have 1 passenger inside my vehicle (A).

Vehicle (A): SLV 5222K

Vehicle (B): YP 6220L

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's Signature
Date & Time:

[Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature] 28/05/2018

Reporting Centre Personnel's Signature
Name: *[Signature]*
NRIC/ID No.:

Addendum Sheet



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #18-00 Singapore 048580
Tel (65) 6224 0010 Fax (65) 6224 0090
Operating Hours: Monday to Friday, 09:00 - 17:00
GSTN: S64386000 / GST Reg. No.: S640037735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No: MNA 4130 64544 Vehicle Registration No: SLV 5222X
Name(s) shown in NRIC: Lee Chun NRIC/FIN/Passport No: 57069061 F
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address: _____ Singapore
Contact (Tel): _____ Mobile No.: 9672 6186
Email Address: _____
Date of Accident: 28/5/18 Time of Accident: 0940
Place of Accident: AYE Towards Tuas (Before South Bypass Vista Exit 8)
Insurance Company: ALL

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

convert report from TP claim to DD claim

[Signature]
Policyholder / Driver's Signature
Date:

[Signature]
Reporting Centre Personnel's Signature
Name: ROSLI WATARS
NRIC/FIN No.:
Date: 31/05/2018

Addendum Sheet



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
 6 Raffles Quay #18-00 Singapore 048580
 Tel (65) 6324 0010 Fax (65) 6324 0080
 Operating Hours: Monday to Friday, 09:00 - 17:00
 UEN: S443500300 / GST Reg. No.: M420017733

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No: MA418069599-01 Vehicle Registration No: SLV 5222 K
 Name (as shown in NRIC): Leo Chuan NRIC/FIN/Passport No: 87069061 F
 (*Vehicle Driver / Vehicle Owner) Please delete as appropriate
 Address: _____ Singapore ()
 Contact (Tel): _____ Mobile No.: 96726186
 Email Address: _____
 Date of Accident: 28/05/2018 Time of Accident: 09:40
 Place of Accident: AYR TOWARDS TUNE (BEFORE SOUTH BRUNIA VISTA E4178)
 Insurance Company: BIG

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

INSURED VEHICLE NUMBER TO SLV 5222K ON SKRATCH PIAU

Policyholder / Driver's Signature
 Date: _____

Reporting Centre Personnel's Signature
 Name: Popli, waghara
 NRIC/FIN No.: _____
 Date: 07/06/2018

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0661/2018/PH
Date : 6-Jun-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Luo Chuan
Address : 13 Cove Drive
#04-04
Singapore 098327
Telephone : HP +65 96726186
Type of Claim : Own Damage Claim
Policy No. : 1700090330
Vehicle No : **SLV 5222 K**
Model Code : Audi SQ 5 3.0 TFSI
Model / Year : Dec-17
Engine No : CWG028683
Chassis No : WAUZZZF4J2028594
Mileage : -
Date In : -
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 28-May-18
Place of Accident : AYE towards Tuas(Before South Buona Vista Exit 8)

Tan Jiah 97493749
20 days

Revert, Not Authorise

7/6/18 @ Spun

Resurvey before print

See @ (premiumauto.com)

Ex : to be advise


13/6/18

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLV 5222 K.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
8	To remove and reinstall rear suspension assy for car-o-liner repairs.	S/N \$ 3,200.00	photo ? ✓
9	To set up vehicle on car-o-liner repair bench	S/N \$ 1,800.00	photo ? 1200 ✓
10	To dismantle rear bumper and rear lid .Cut out and weld rear end panels,rhs rear fender,inner D-pillar and reinforcements,roof panel and attachments.Renew rear lid and rear bumper assy.Reinstall all parts removed.	\$ 16,800.00	8000 4000 ✓
9	To carry out corocoat treatment and joint sealer works on roof channel,drain panels,end panelling,entrance channel and base primer work.	S/N \$ 1,200.00	✓ un
11	To respray rear bumper,lower spoiler,rear lid,roof spoiler,both rear fender,rhs sill panel,door entrance,rhs rear door,roof panel,both roof channels,drain panel and end panelling.To carry out joint sealer works and stone chip treatment.	\$ 8,000.00	4400. 4700 ✓
12	To renew center and both rear exhaust silencers.Align to position.	S/N \$ 480.00	photo ? ✓
13	To carry out wheel alignment.Inspect rear subframe for damages.	S/N \$ 240.00	photo ? ✓
14	To carry out diagnostic check	S/N \$ 768.00	* to check amount ✓ 384 ✓
TOTAL LABOUR CHARGES		\$ 40,048.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLV 5222 K .

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To carry out first measurement on car-o-liner	S/N \$ 800.00	✓
2	To remove and transfer rear parking aid.Check function	S/N \$ 280.00	✓
3	To renew rhs 1/4 glass and rear windscreen to facilitate fender renewal.	S/N \$ 600.00	✓
4	To remove and renew front windscreen for roof renewal	S/N \$ 480.00	✓
5	To remove and transfer rear lid's convenience lock system,wire harness for tail lights,rear wiper assy and automatic tailgate assy.Inspect for damages and renew accordingly	S/N \$ 600.00	✓
6	To remove and reinstall rear wire harness for lights,battery manager,fuse and relay trays,electrical and audio equipment.Inspect for damages	S/N \$ 1,600.00	✓
7	To remove front and rear seats,hat tray speaker trim,ABCD pillar trims,roof lining,roof rails,lights,curtain air bags,controls,sensors,safety belts and carpets.Inspect for damages and renew if necessary.	S/N \$ 3,200.00	✓
SUB-LABOUR CHARGES		: \$ 7,560.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLV 5222 K .

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER	\$ 1,896.00	de ✓ 1516.80
2	BUMPER SUPPORT	2 \$ 174.00	X u u.
3	REAR BUMPER SPOILER	\$ 862.00	cut - 689.20
4	TAIL LIGHT - LH & RH bumper.	2 \$ 1,238.00	LH-X, RH-cut - 959.
5	TRIM ALUMINIUM	\$ 1,566.00	X u u.
6	GUIDE SECTION - LH&RH	2 \$ 142.00	LH-X, RH-cut - 56.2
7	FOAM FILLER PIECE- LH & RH	2 \$ 106.00	? X u u.
8	BUMPER CARRIER - REAR	\$ 786.00	? bt ✓ 628.80
9	HOLDING STRAP	\$ 142.00	X u u.
10	SENSOR - REAR	2 \$ 421.00	X u u.
11	WIRING SET FOR BUMPER - REAR	\$ 440.00	X u u.
12	WHEEL ARCH TRIM - LH REAR	\$ 455.00	nei ✓ 363.60
13	WHEEL ARCH TRIM - RH REAR	\$ 455.00	de ✓ 363.60
14	WHEEL COVER - REAR LH	\$ 37.00	nei ✓ 29.20
15	WHEEL COVER - RH REAR	\$ 37.00	nei ✓ 29.20
16	REAR LID	\$ 3,776.00	bt ✓ 3020.80
17	1 SET ATTACHMENT PARTS FOR REAR LID	\$ 105.00	nei ✓ 83.20
18	LID HINGE - LH & RH	2 \$ 400.00	bt ✓ 320
19	1 SET ATTACHMENT PARTS FOR REAR LID	\$ 105.00	X Repeated.
20	REAR BOOT BRACKET - RH	\$ 40.00	bt ✓ 31.84
SUB-TOTAL SPARE PARTS		\$ 13,183.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLV 5222 K .

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	BRACKET - RH	\$ 40.00	<i>Run.</i>
22	DRIVE UNIT FOR REAR LID	\$ 1,557.00	<i>? dis ✓ 1245.60</i>
23	GASKET FOR FLAP	\$ 338.00	<i>? ne ✓ 270.40</i>
24	STOP BUFFER	2 \$ 48.00	<i>ne ✓ 37.76</i>
25	LOCK STRIKER	\$ 75.00	<i>? bt ✓ 59.52</i>
26	LID LOCK WITH MICRO SWITCH	\$ 195.00	<i>? de ✓ 156</i>
27	SERVOMOTOR FOR REAR LID	\$ 266.00	<i>? bt ✓ 212.80</i>
28	PUSH BUTTON WITH CAMERA	\$ 1,205.00	<i>? de ✓ 974.40</i>
29	PACKING ADHESIVE	\$ 15.00	<i>ne ✓ 11.60</i>
30	AUDI EMBLEM	\$ 108.00	<i>ne ✓ 86</i>
31	S SQ5' EMBLEM	\$ 108.00	<i>ne ✓ 86</i>
32	REAR LID SPOILER	\$ 1,828.00	<i>? de ✓ 1462.40</i>
33	1 SET FIXING PARTS FOR SPOILER	\$ 18.00	<i>ne ✓ 13.04</i>
34	1 SET OF FOAM STRIPS	\$ 30.00	<i>ne ✓ 22.24</i>
35	REAR WINDSCREEN	\$ 1,020.00	<i>Car ✓ 816</i>
36	GLASS PRIMER	\$ 19.00	<i>ne ✓ x 111</i>
37	WINDSCREEN SPOILER - LH & RH	2 \$ 402.00	<i>ne ✓ 320.80</i>
38	REAR FENDER - RH	\$ 3,913.00	<i>bac ✓ 3130.40</i>
39	REAR FENDER INNER PRIME - RH REAR	\$ 1,414.00	<i>? bt ✓ 1131.20</i>
40	D PILLAR	\$ 393.00	<i>Run.</i>
SUB-TOTAL SPARE PARTS		\$ 12,992.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLV 5222 K.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
41	REINFORCEMENT FOR D-PILLAR PRIMED - RH LOWER	\$ 477.00	X m.
42	CONNECTING PLATE - RH REAR	\$ 323.00	? bt ✓ 358
43	REAR CROSS PANEL	\$ 494.00	? bt ✓ 394.80
44	REINFORCEMENT FOR LOCK CARRIER	\$ 147.00	? bt ✓ 117.60
45	ROOF	\$ 4,190.00	Ry
46	ROOF REINFORCEMENT	\$ 217.00	X m
47	ROOF FRAME	\$ 184.00	X m
48	CLOSING ELEMENT	\$ 135.00	X m
49	ROOF RAIL - RH	\$ 1,613.00	X m
50	BALANCER ELEMENT	\$ 252.00	X m
51	SIDE 1/4 GLASS - RH	\$ 724.00	del ✓ 579.20
52	GLASS PRIMER	2 \$ 38.00	del ✓ 29.12
53	FUEL FLAP THROTTLE CONTROL ELEMENT	\$ 91.00	del ✓ 73.56
54	FUEL FLAP INSERT	\$ 135.00	del ✓ 108
55	REAR LID TRIM PANEL - LOWER	\$ 650.00	int ✓ 519.60
56	REAR LID TRIM PANEL - UPPER	\$ 246.00	int ✓ 196.80
57	LUGGAGE COMPARTMENT TRIM - RH	\$ 880.00	? del ✓ 704
58	TRIM FOR REAR CROSS PANEL	\$ 397.00	? del ✓ 317.60
59	LUGGAGE COMPARTMENT FLOOR - REAR	\$ 920.00	X m
60	COVER BLIND FOR LUGGAGE COMPARTMENT	\$ 1,376.00	X m
SUB-TOTAL SPARE PARTS		\$ 13,489.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLV 5222 K .

		Damage Parts & Prices	
S/N	Parts Description	S/NETT	REMARKS
61	WHEEL HOUSING LINER - RH	\$ 231.00	7ide ✓ 134.50
62	FRONT WINDSCREEN	\$ 2,506.00	X
63	GEL FOIL FOR RAIN SENSOR	\$ 128.00	X
64	GLASS PRIMER	\$ 19.00	X
65	REAR NUMBER PLATE	S/N \$ 25.00	X
66	FRONT WINDSCREEN SEALANT	S/N \$ 200.00	X
67	REAR WINDSCREEN SEALANT	S/N \$ 200.00	nei //
68	1/4 GLASS SEALANT	S/N \$ 100.00	nei //
69	ARCYLIC SEALER	S/N \$ 540.00	nei 360 //
70	CAVITY WAX	S/N \$ 420.00	nei 180 //
71	STONE CHIP	S/N \$ 360.00	nei 180 //
72	METAL FILLER POWDER	S/N \$ 560.00	nei 280 //
73	SUNDRIES	\$ 2,000.00	168.72 nei //
TOTAL SPARE PARTS		\$ 46,953.00	
TOTAL LABOUR CHARGES		\$ 40,048.00	
GRAND TOTAL		\$ 87,001.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

89616.76

89582.76



Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0661/2018/PH
Date : 6-Jun-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian/Taufikh

You recommended 20 days

We took 52 days exclude 9 Sundays

and 1 PH - jb - 22 Nov 18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Luo Chuan
Address : 13 Cove Drive
#04-04
Singapore 098327
Telephone : HP +65 96726186
Type of Claim : Own Damage Claim
Policy No. : 1700090330
Vehicle No : **SLV 5222 K**
Model Code : Audi SQ 5 3.0 TFSI
Model / Year : Dec-17
Engine No : CWG028683
Chassis No : WAUZZZFY4J2028594
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 28-May-18
Place of Accident : AYE towards Tuas(Before South Buona Vista Exit 8)

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLV 5222 K.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To carry out first measurement on car-o-liner	S/N \$ 800.00	
2	To remove and transfer rear parking aid.Check function	S/N \$ 280.00	\$ 280.00
3	To renew rhs 1/4 glass and rear windscreen to facilitate fender renewal.	S/N \$ 600.00	\$ 600.00
4	To remove and renew front windscreen for roof renewal	S/N \$ 480.00	
5	To remove and transfer rear lid's convenience lock system,wire harness for tail lights,rear wiper assy and automatic tailgate assy.Inspect for damages and renew accordingly	S/N \$ 600.00	\$ 600.00
6	To remove and reinstall rear wire harness for lights,battery manager,fuse and relay trays,electrical and audio equipment.Inspect for damages	S/N \$ 1,600.00	\$ 1,600.00
7	To remove front and rear seats,hat tray speaker trim,ABCD pillar trims,roof lining,roof rails,lights,curtain air bags,controls,sensors,safety belts and carpets.Inspect for damages and renew if necessary.	S/N \$ 3,200.00	\$ 3,200.00
SUB-LABOUR CHARGES		: \$ 7,560.00	\$ 6,280.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLV 5222 K .

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
		c/f		\$ 6,280.00
8	To remove and reinstall rear suspension assy for car-o-liner repairs.	S/N	\$ 3,200.00	\$ 3,200.00
9	To set up vehicle on car-o-liner repair bench	S/N	\$ 1,800.00	\$ 1,200.00
10	To dismantle rear bumper and rear lid .Cut out and weld rear end panels,rhs rear fender,inner D-pillar and reinforcements,roof panel and attachments.Renew rear lid and rear bumper assy.Reinstall all parts removed. <i>(Adrian please review)</i>		\$ 16,800.00	\$ 8,000.00
9	To carry out corocoat treatment and joint sealer works on roof channel,drain panels,end panelling,entrance channel and base primer work.	S/N	\$ 1,200.00	
11	To respray rear bumper,lower spoiler,rear lid,roof spoiler,both rear fender,rhs sill panel,door entrance,rhs rear door,roof panel,both roof channels,drain panel and end panelling.To carry out joint sealer works and stone chip treatment.		\$ 8,000.00	\$ 4,700.00
12	To renew center and both rear exhaust silencers.Align to position. <i>(Exhaust assy and fuel tank removed)</i>	S/N	\$ 480.00	\$ 480.00
13	To carry out wheel alignment.Inspect rear subframe for damages.	S/N	\$ 240.00	\$ 240.00
13a	Added labour charges	S/N	\$ 400.00	\$ 400.00
14	To carry out diagnostic check	S/N	\$ 768.00	\$ 384.00
TOTAL LABOUR CHARGES		:	<u>\$ 40,448.00</u>	<u>\$ 24,884.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLV 5222 K .

S/N	Parts Description	<u>Damage Parts & Prices</u>	
		S/NETT	REMARKS
1	REAR BUMPER	\$ 1,896.00	\$ 1,516.80
2	BUMPER SUPPORT	2 \$ 174.00	
3	REAR BUMPER SPOILER	\$ 862.00	\$ 689.20
4	TAIL LIGHT - LH & RH	2 \$ 1,238.00	\$ 989.60
5	TRIM ALUMINIUM	\$ 1,566.00	
6	GUIDE SECTION - LH&RH	2 \$ 142.00	\$ 56.80
7	FOAM FILLER PIECE- LH & RH	2 \$ 106.00	
8	BUMPER CARRIER - REAR	\$ 786.00	\$ 628.80
9	HOLDING STRAP	\$ 142.00	
10	SENSOR - REAR	2 \$ 421.00	
11	WIRING SET FOR BUMPER - REAR	\$ 440.00	
12	WHEEL ARCH TRIM - LH REAR	\$ 455.00	\$ 363.60
13	WHEEL ARCH TRIM - RH REAR	\$ 455.00	\$ 363.60
14	WHEEL COVER - REAR LH	\$ 37.00	\$ 29.20
15	WHEEL COVER - RH REAR	\$ 37.00	\$ 29.20
16	REAR LID	\$ 3,776.00	\$ 3,020.80
17	1 SET ATTACHMENT PARTS FOR REAR LID	\$ 105.00	\$ 83.20
18	LID HINGE - LH & RH	2 \$ 400.00	\$ 320.00
19	1 SET ATTACHMENT PARTS FOR REAR LID	\$ 105.00	
20	REAR BOOT BRACKET - RH	\$ 40.00	\$ 31.84
SUB-TOTAL SPARE PARTS		\$ 13,183.00	\$ 8,122.64

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLV 5222 K .

S/N	Parts Description	Damage Parts & Prices		
		S/NETT	REMARKS	
			\$	8,122.64
		c/f		
21	BRACKET - RH	\$	40.00	
22	DRIVE UNIT FOR REAR LID	\$	1,557.00	\$ 1,245.60
23	GASKET FOR FLAP	\$	338.00	\$ 270.40
24	STOP BUFFER	2 \$	48.00	\$ 37.76
25	LOCK STRIKER	\$	75.00	\$ 59.52
26	LID LOCK WITH MICRO SWITCH	\$	195.00	\$ 156.00
27	SERVOMOTOR FOR REAR LID	\$	266.00	\$ 212.80
28	PUSH BUTTON WITH CAMERA	\$	1,205.00	\$ 974.40
29	PACKING ADHESIVE	\$	15.00	\$ 11.60
30	AUDI EMBLEM	\$	108.00	\$ 86.00
31	S SQ5' EMBLEM	\$	108.00	\$ 86.00
32	REAR LID SPOILER	\$	1,828.00	\$ 1,462.40
33	1 SET FIXING PARTS FOR SPOILER	\$	18.00	\$ 13.04
34	1 SET OF FOAM STRIPS	\$	30.00	\$ 22.24
35	REAR WINDSCREEN	\$	1,020.00	\$ 816.00
36	GLASS PRIMER	\$	19.00	
37	WINDSCREEN SPOILER - LH & RH	2 \$	402.00	\$ 320.80
38	REAR FENDER - RH	\$	3,913.00	\$ 3,130.40
39	REAR FENDER INNER PRIME - RH REAR	\$	1,414.00	\$ 1,131.20
40	D PILLAR	\$	393.00	
	SUB-TOTAL SPARE PARTS	:	\$ 12,992.00	\$ 18,158.80

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLV 5222 K .

S/N	Parts Description		Damage Parts & Prices	
			S/NETT	REMARKS
		c/f	\$	18,158.80
41	REINFORCEMENT FOR D-PILLAR PRIMED - RH LOWER		\$ 477.00	
42	CONNECTING PLATE - RH REAR		\$ 323.00	\$ 258.00
43	REAR CROSS PANEL		\$ 494.00	\$ 394.80
44	REINFORCEMENT FOR LOCK CARRIER		\$ 147.00	\$ 117.60
45	ROOF		\$ 4,190.00	
46	ROOF REINFORCEMENT		\$ 217.00	
47	ROOF FRAME		\$ 184.00	
48	CLOSING ELEMENT		\$ 135.00	
49	ROOF RAIL - RH		\$ 1,613.00	
50	BALANCER ELEMENT		\$ 252.00	
51	SIDE 1/4 GLASS - RH		\$ 724.00	\$ 579.20
52	GLASS PRIMER	2	\$ 38.00	\$ 29.12
53	FUEL FLAP THROTTLE CONTROL ELEMENT		\$ 91.00	\$ 72.56
54	FUEL FLAP INSERT		\$ 135.00	\$ 108.00
55	REAR LID TRIM PANEL - LOWER		\$ 650.00	\$ 519.60
56	REAR LID TRIM PANEL - UPPER		\$ 248.00	\$ 196.80
57	LAGGUAGE COMPARTMENT TRIM - RH		\$ 880.00	\$ 704.00
58	TRIM FOR REAR CROSS PANEL		\$ 397.00	\$ 317.60
59	LAUGGUAGE COMPARTMENT FLOOR - REAR		\$ 920.00	
60	COVER BLIND FOR LUGGAGE COMPARTMENT		\$ 1,376.00	
SUB-TOTAL SPARE PARTS			\$ 13,489.00	\$ 21,456.08

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLV 5222 K .

S/N	Parts Description		Damage Parts & Prices	
			S/NETT	REMARKS
		c/f	\$	21,456.08
61	WHEEL HOUSING LINER - RH		\$ 231.00	\$ 184.80
62	FRONT WINDSCREEN		\$ 2,506.00	
63	GEL FOIL FOR RAIN SENSOR		\$ 128.00	
64	GLASS PRIMER		\$ 19.00	
65	REAR NUMBER PLATE	S/N	\$ 25.00	
66	FRONT WINDSCREEN SEALANT	S/N	\$ 200.00	
67	REAR WINDSCREEN SEALANT	S/N	\$ 200.00	\$ 200.00
68	1/4 GLASS SEALANT	S/N	\$ 100.00	\$ 100.00
69	ARCYLIC SEALER	S/N	\$ 540.00	\$ 360.00
70	CAVITY WAX	S/N	\$ 420.00	\$ 180.00
71	STONE CHIP	S/N	\$ 360.00	\$ 180.00
72	METAL FILLER POWDER	S/N	\$ 560.00	\$ 280.00
73	SUPPLEMENTARY		\$ 2,760.00	\$ 2,181.76
75	SUNDRIES		\$ 2,000.00	\$ 168.72
	TOTAL SPARE PARTS	:	\$ 49,713.00	\$ 25,291.36
	TOTAL LABOUR CHARGES	:	\$ 40,448.00	\$ 24,884.00
	GRAND TOTAL	:	\$ 90,161.00	\$ 50,175.36

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0661/2018/PH 6-Aug-18 CHANG 1 of 1 SLV 5222 K Audi SQ5 3.0 TFSI	
Quantity	Description		Unit Price	Amount
Labour				
1	To install rear widescreen and 1/4 glass window flim	S/N	\$ 400.00	\$ 400.00
Parts				
1	REAR LID LOCK BOWDEN CABLE		\$ 34.00	\$ 26.48
2	REAR LUGGAGE COMP. LIGHT		\$ 80.00	\$ 64.00
3	REAR LID HINGE REINFORCEMENT PLATE	2	\$ 28.00	\$ 56.00
4	REAR LID NOISE INSULATION PLATE	2	\$ 31.00	\$ 62.00
5	REAR WHEEL HOUSE LINER ATTACHMENT PARTS		\$ 33.00	\$ 25.68
6	FUEL CHARCOAL CONTAINER		\$ 374.00	\$ 299.20
7	REAR FILLER PIECE		\$ 164.00	\$ 131.20
8	REAR LUGGAGE COMP. TRIM COVER - LH		\$ 103.00	\$ 82.00
9	BOTTOM PLATE - RH		\$ 428.00	\$ 342.00
10	FUEL FLAP WIRE CONNECTOR		\$ 14.00	\$ 10.72
11	FUEL FLAP CONNECTOR WIRING		\$ 21.00	\$ 16.16
12	FUEL FLAP WIRING BUTT	2	\$ 18.00	\$ 36.00
13	LED TAIL LIGHT - LH		\$ 1,432.00	\$ 1,145.60
	Materials		\$ 2,760.00	\$ 2,181.76
	Labour		\$ 400.00	\$ 400.00
	Total		\$ 3,160.00	\$ 2,581.76

For Premium Automobiles Pte Ltd

 Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLV 5222 K

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0611/2018/MAS

15 May 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SLV 5222 K, Audi SQ5 3.0 TFSI Qu

With reference to the above-mentioned vehicle, no. **SLV 5222 K**, claimant, **Mr. Luo Chuan**, please find the related document per attached.

1. A copy of the Original invoice no. 85013735 – S\$52,617.64
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLV 5222 K

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159908
Main Telephone: 6386 2223
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159908
Telephone: 6386 2223
Telefax: 6471 3733

UBI Service Centre
55 Ubi Road 1
Singapore 408723

Customer Service
Service Appointment
Your Breakdown Service
(Email)

6386 2223
6828 1233
customers.care@premiumauto.com.sg

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 1 17:28

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Invoice: 85013735
Date : 06/05/2019
Order : SLV5222K
Term : 30

Account: A0006 (T 0)
AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No.: SLV5222K (V 36082) Regn Date: 30/12/2017 Mileage: 26303 WIP No.: 12047
Model: S95 3.0 TFSI qu tiptronic FYB8 Chassis: WAUZZZF4J2028594 Engine: CMB 028683 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
S	SUBLET	M: TO RE-APPLY REAR WINDSCREEN & RHS REAR 1/4 GLASS SOLAR FILM.	400.00	1.00	400.00
Q	EXC	M: 8888 Insurance Excess/Liability	-1000.00	1.00	-1,000.00
S	BODYWORK	M: TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION	280.00	1.00	280.00
S	BODYWORK	M: TO RENEW RHS 1/4 GLASS AND REAR WINDSCREEN TO FACILITATE FENDER RENEWAL	600.00	1.00	600.00
S	BODYWORK	M: TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHTS, REAR WIPER ASSY AND AUTOMATIC TAILGATE ASSY. INSPECT FOR DAMAGES AND RENEW ACCORDINGLY	600.00	1.00	600.00
S	BODYWORK	M: TO REMOVE AND REINSTALL REAR WIRE HARNESS FOR	1600.00	1.00	1,600.00
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore
261 Alexandra Road
Singapore 159038
Main Telephone: 6386 2223
Main Telefax: 6471 2733

Alexandra Service Centre
261 Alexandra Road
Singapore 159038
Telephone: 6386 2223
Telefax: 6471 1023

UBi Service Centre
55 Ubi Road 1
Singapore 408731

Customer Service
Service Appointment
Your Breakdown Service
Email: customer.care@premiumauto.com.sg

6386 2223
9628 1233

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 2 17:28

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85813735 Date : 06/05/2019 Order : SLV5222K Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLV5222K (V 36082)	Regn Date: 30/12/2017	Mileage: 26303	WIP No.: 12047
Model: SQ5 3.0 TFSI qu tiptronic FYBS	Chassis: WAUZZZF4J2028594	Engine: CMG 028683	Dept: U
VSB No.:			
You have been assisted by :- UB-Jiayee (33)			

		Details	Qty	Unit Price	Amount
S	BODYWORK	LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGES M: TO REMOVE FRONT AND REAR SEATS, HAT TRAY SPEAKER TRIM, ABCD PILLAR TRIMS, ROOF LINING, ROOF RAILS, LIGHTS, CURTAIN AIRBAGS, CONTROLS, SENSOR, SAFETY BELTS AND CARPETS. INSPECT FOR DAMAGES AND RENEW IF NECESSARY	3200.00	1.00	3,200.00
S	BODYWORK	M: TO REMOVE AND REINSTALL REAR SUSPENSION ASSY FOR CAR-O-LINER REPAIRS.	3200.00	1.00	3,200.00
S	BODYWORK	M: TO SET UP VEHICLE ON CAR-O-LINER REPAIR BENCH	1200.00	1.00	1,200.00
S	BODYWORK	M: TO DISMANTLE REAR BUMPER AND REAR LID. CUT OUT AND WELD REAR END PANELS, RHS REAR FENDER, INNER	6000.00	1.00	6,000.00

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore

281 Alexandra Road

Singapore 159938

Main Telephone: 6346 2223

Page 3 of 3 17:28

Alexandra Service Centre

281 Alexandra Road

Singapore 159938

Telephone: 6346 2223

Telex: 6475 1023

Ubi Service Centre

55 Ubi Avenue 1

Singapore 408009

Telephone: 6346 2223

Telex: 6475 1023

Customer Service

281 Alexandra Road

Singapore 159938

24 Hour Breakdown Service

Email: customer.care@premiumauto.com.sg

6346 2523

9828 1233

INSURANCE INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Invoice: 85013735

Date : 06/05/2019

Order : SLV5222K

Term : 30

Account: 00006 (T 0)

AIG ASIA PACIFIC INSURANCE PTE LTD

MOTOR CLAIM DEPT

AIG BUILDING

78 SHENTON WAY

#07-16

SINGAPORE 079120

AIG ASIA PACIFIC INSURANCE PTE LTD

MOTOR CLAIM DEPT

AIG BUILDING

78 SHENTON WAY

#07-16

SINGAPORE 079120

Regn No.: SLV5222K (V 36082)

Regn Date: 30/12/2017

Mileage: 26303

WIP No.: 12047

Model: SQ5 3.0 TFSI qu tiptronic FYBS

Chassis: WAUZZZF4J2028594

Engine: CMB 028683

Dept: U

VSB No.:

You have been assisted by :- UB-Jiayee

(33)

		Details	Qty	Unit Price	Amount
S	BODYWORK	D-PILLAR AND REINFORCEMENT, ROOF PANEL AND ATTACHMENT. RENEW REAR LID AND REAR BUMPER. REINSTALL ALL PARTS REMOVED M: TO RESPRAY REAR BUMPER, LOWER SPOILER, REAR LID, ROOF SPOILER, RHS REAR FENDER, RHS SILL PANEL, DOOR ENTRANCE, RHS REAR DOOR, ROOF PANEL, ROOF CHANNEL, DRAIN PANEL AND END PANELLING. TO CARRY OUT JOINT SEALER WORK AND STONE CHIP TREATMENT	4700.00	1.00	4,700.00
S	BODYWORK	M: TO REMOVE AND REINSTALL CENTRE AND BOTH REAR EXHAUST SILENCERS. ALIGN TO POSITION	488.00	1.00	488.00
S	BODYWORK	M: TO CARRY OUT WHEEL ALIGNMENT. INSPECT REAR SUBFRAME FOR DAMAGES	240.00	1.00	240.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	384.00	1.00	384.00

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6386 2223
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6386 2223
Telefax: 6471 3733

Ubi Service Centre
55 Ubi Road 1
Singapore 408713
Telephone: 6386 2113

Customer Service
Service Appointment
Breakdown Service
Email: customer.care@premiumauto.com.sg

6386 2223
6828 1234

INS TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Page 4 17:28

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Invoice: 85013735
Date : 06/05/2019
Order : SLV5222K
Term : 30

Account: A0006 (T 0)
AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No.: SLV5222K (V 36082) Regn Date: 30/12/2017 Mileage: 26303 WIP No.: 12047
Model: S05 3.0 TFSI qu tiptronic FYBS Chassis: WAUZZZF4YJ2028594 Engine: CMG 020683 Dept: U
USB No.:
You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO SUPPLY REAR WINDSCREEN SEALANT, 1/4 GLASS SEALANT, ACRYLIC SEALER, CAVITY WAX, STONE CHIP AND METAL FILLER POWDER	1300.00	1.00	1,300.00
X	AN 90511507	NUT (SK) (A) Less 020%	4.00	2.00	6.40
X	A00A027705A	WTHRSTRIP (SK) (A) Less 020%	1.00	338.00	270.40
X	A00A009038 STL	SUBPART (Ger) (V) Less 020%	1.00	3913.00	3,130.40
X	A00A063800S HCK	LINING (Ger) (A) Less 020%	1.00	800.00	784.00
X	A00A054909	COVER Less 020%	1.00	36.50	29.20
X	A00A054990	COVER (Ger) (A) Less 020%	1.00	36.50	29.20
X	A00A090617	ATT. PARTS (Ger) (A) Less 020%	1.00	104.00	83.20
X	A00A027499	BUMPER Less 020%	2.00	23.60	37.76
X	A00A027933A GRU	SPOILER (Ger) (V) Less 020%	1.00	1828.00	1,462.40
X	A00A090940A	REPAIR KIT (Ger) (V) Less 020%	1.00	27.80	22.24
X	A00A009052 STL	SIDE PANEL (Ger) (V) Less 020%	1.00	1414.00	1,131.20
X	A00A045290K NVB	SIDE WINDO (Ger) (A) Less 020%	1.00	724.00	579.20
X	A00A062153	ACTUATOR (Ger) (A) Less 020%	1.00	90.70	72.56
X	A00A009906	INSERT (Ger) (A) Less 020%	1.00	135.00	108.00
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6886 2223
Main Telefax: 6471 3333

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6886 2223
Telefax: 6471 3333

Ubi Service Centre
55 Ubi Road 1
Singapore 408733
Telephone: 6886 2223
Telefax: 6471 3333

Customer Service
Service Appointment
Your Breakdown Service
Email: customer.care@premiumauto.com.sg
6468 1223
9828 1233

INS TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Page 5 17:28

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013735 Date : 06/05/2019 Order : SLV5222K Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLV5222K (V 36082)	Regn Date: 30/12/2017	Mileage: 26303	WIP No.: 12047
Model: S05 3.0 TFSI qu tiptronic FY06	Chassis: WAUZZZF4J2028594	Engine: CM6 028683	Dept: U
VSB No.:			
You have been assisted by :- UB-Jiayee (33)			

		Details		Qty	Unit Price	Amount
X	A00A0657979A 4PK	TRIM PANEL (Ger) (A)	Less 020%	1.00	649.50	519.60
X	A00A0657973A 4PK	TRIM PANEL (Ger) (A)	Less 020%	1.00	246.00	196.80
X	A00C959121	SWITCH (SK) (A)	Less 020%	1.00	64.00	64.00
X	A00A007669	GASKET (Ger) (V)	Less 020%	2.00	2.30	3.68
X	A0U00272990	HINGE (SK) (V)	Less 020%	1.00	200.00	160.00
X	A0U0027300E	HINGE (Ger) (V)	Less 020%	1.00	200.00	160.00
X	A00A027604A STL	BRACKET (Ger) (V)	Less 020%	1.00	39.80	31.84
X	AM 91261101	BOLT (Ger) (V)	Less 020%	4.00	1.20	3.84
X	AMHT005287	SCREW (Ger) (V)	Less 020%	4.00	1.00	3.20
X	A00A009992 STL	PLATE (Ger) (V)	Less 020%	1.00	322.50	258.00
X	A00A013331TASTL	REINFORCEM (Ger) (V)	Less 020%	1.00	147.00	117.60
X	A00A013705	DEADENER (Ger) (V)	Less 020%	2.00	15.20	24.32
X	A00A002016A STL	FLOOR PAN (Ger) (V)	Less 020%	1.00	427.50	342.00
X	A3V5827887B	MOTOR (SK) (A)	Less 020%	1.00	266.00	212.80
X	A00A027520	COVER (Ger) (A)	Less 020%	1.00	6.10	4.88
X	A00A027507	PLATE (SK) (A)	Less 020%	1.00	74.40	59.52
X	A0M0027566E	PUSHBUTTON (Ger) (A)	Less 020%	1.00	1218.00	974.40
X	A0M0027713	PLUG (SK) (A)	Less 020%	4.00	1.20	3.84

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6386 2223
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6386 2223
Telefax: 6475 1025

Ubi Service Centre
35 Ubi Road 1
Singapore 408721

Customer Service
Service Appointment
Your Breakdown Service
Email: customer.care@premiumauto.com.sg

6386 2323
9826 1235

INS TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Page 6 17:28

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013735 Date : 06/05/2019 Order : SLV5222K Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLV5222K (V 36082)	Regn Date: 30/12/2017	Mileage: 26303	WIP No.: 12047
Model: SQ5 3.0 TFSI qu tiptronic FYBS	Chassis: WAUZZZFV4J2028594	Engine: CMG 028683	Dept: U
VSB No.:			
You have been assisted by :- UB-Jiayee (33)			

		Details		Qty	Unit Price	Amount
X	A00A013303A STL	REAR APRON (SK) (A)	Less 020%	1.00	493.50	394.80
X	A00A010172A	WHEEL HOUS (Ger) (A)	Less 020%	1.00	231.00	184.80
X	A00A0201797E	EVAPCANIST (SK) (A)	Less 020%	1.00	374.00	299.20
X	A00A064483E 4PK	TRIM PANEL (SK) (A)	Less 020%	1.00	397.00	317.60
X	A00A061828C GW8	INSERT (Ger) (A)	Less 020%	1.00	164.00	131.20
X	RM 90874703	SCREW (Ger) (A)	Less 020%	2.00	1.40	2.24
X	A00A063488B 4PK	COVER (Ger) (A)	Less 020%	1.00	102.50	82.00
X	A00A0827506A	LATCH (V)	Less 020%	1.00	195.00	156.00
X	A00A0945094B	TAIL LIGHT	Less 020%	1.00	1432.00	1,145.60
X	A00A053817B GRU	COVER (SK) (A)	Less 020%	1.00	454.50	363.60
X	A00A053818B GRU	COVER (SK) (A)	Less 020%	1.00	454.50	363.60
X	A00A0807434D GRU	SPOILER (Ger) (V)	Less 020%	1.00	661.50	529.20
X	A00A0807309	BRACKET (SK) (A)	Less 020%	1.00	786.00	628.80
X	A00A045501 NVB	REARWINDOW	Less 020%	1.00	1020.00	816.00
X	A00A0827025D STL	LID	Less 020%	1.00	3776.00	3,020.80
X	A00A0807067D GRU	COVER (Ger) (V)	Less 020%	1.00	1896.00	1,516.80
X	A1J0973119	HOUSING	Less 020%	1.00	13.40	10.72
X	A011807577C	NUT	Less 020%	2.00	1.30	2.00

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119938
Main Telephone: 6386 2223
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 119938
Telephone: 6386 2223
Telefax: 6471 3733

Ubi Service Centre
55 Ubi Road 1
Singapore 408723
Telephone: 6386 2223
Telefax: 6471 3733

Customer Service
Service Appointment
Service Breakdown Service
Email: customer.care@premiumauto.com.sg

6386 2223
6471 3733

INS TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Page 7 17:28

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013735 Date : 06/05/2019 Order : SLV5222K Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLV5222K (V 36082) Regn Date: 30/12/2017 Mileage: 26303 WIP No.: 12047
Model: SQ5 3.0 TFSI qu tiptronic FYBS Chassis: WAUZZZF4YJ2028594 Engine: CWB 028683 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (33)

		Details		Qty	Unit Price	Amount
X	A00A090629	ATT PARTS	Less 020%	1.00	32.10	25.68
X	A00A053735 2Z2	INSCRIPTION 'S 05'	Less 020%	1.00	107.50	86.00
X	A405053742 2Z2	AUDI SIGN	Less 020%	1.00	107.50	86.00
X	A00A090941	PARTS KIT	Less 020%	1.00	16.30	13.04
X	A6A0019465B	TRIM (V)	Less 020%	1.00	59.30	47.44
X	A00A053419F	PACKING	Less 020%	1.00	14.50	11.60
X	A400027310	CLIP	Less 020%	2.00	2.10	3.36
X	A1K0003583B	PLUG (SK) (A)	Less 020%	4.00	2.60	8.32
X	A00A006373	GROMMET	Less 020%	4.00	3.80	12.16
X	A0K5027261	CAP	Less 020%	1.00	2.10	1.68
X	A0X0027654	SCREW	Less 020%	2.00	1.00	1.60
X	A0P4027951A	PLUG	Less 020%	2.00	1.70	2.72
X	A00A027851A	DRIVE UNIT	Less 020%	1.00	1557.00	1,245.60
X	A405027469	BUMPER	Less 020%	1.00	2.60	2.08
X	A00A027535	BOWD CABLE	Less 020%	1.00	33.10	26.48
X	A00A007454	GUIDE (Ger) (A)	Less 020%	1.00	71.00	56.80
X	A00A054671 5F0	SPOILER	Less 020%	1.00	200.50	160.40
X	A00A054672 5F0	SPOILER	Less 020%	1.00	200.50	160.40

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119038
Main Telephone: 6366 2222
Main Telefax: 6471 3755

Alexandra Service Centre
281 Alexandra Road
Singapore 119038
Telephone: 6366 2222
Telefax: 6471 3755

Ubi Service Centre
55 Ubi Road 1
Singapore 408721

Customer Service
Service Appointment
Singapore Breakdown Service
Email: customer.care@premiumauto.com.sg

6366 2222
9828 1233

INSURANCE TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Page 8 17:28

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013735 Date : 06/05/2019 Order : SLV5222K Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLV5222K (V 36082) Regn Date: 30/12/2017 Mileage: 26303 WIP No.: 12047

Model: S05 3.0 TFSI qu tiptronic FY05 Chassis: WAUZZZF4J2028594 Engine: CMG 028683 Dept: U

USB No.:

You have been assisted by :- UB-Jiayee (33)

		Details		Qty	Unit Price	Amount
X	A000979940	CONNECTOR (WHITE)	Less 020%	2.00	9.00	14.40
X	A000979019EA	WIRES	Less 020%	1.00	20.20	16.16
X	AD 00320002	PRIMER (DG)	Less 020%	2.00	18.20	29.12
X	A00A945070	TAILLIGHT	Less 020%	1.00	618.50	494.80
X	A00A945069	TAILLIGHT	Less 020%	1.00	618.50	494.80
X	AN 90809502	BOLT (SK) (A)	Less 020%	10.00	2.30	18.40
X	AMHT000748	NUT	Less 020%	2.00	0.70	1.12
X	AN 90368203	SPEED NUT	Less 020%	2.00	2.90	4.64
X	AN 90511505	NUT	Less 020%	2.00	1.60	2.56
X	AN 10621301	NUT	Less 020%	8.00	1.70	10.88
X	AN 90648102	NUT	Less 020%	1.00	4.60	3.68
X	AMHT005100	BOLT	Less 020%	2.00	7.70	12.32
X	AN 90652602	BOLT	Less 020%	10.00	0.70	5.60

Parts 23,991.36
Labour 0.00
Sublet 26,184.00
Menus 0.00
Lubricant 0.00

Sub-Total 49,175.36

7% GST 3,442.28

Grand Total 52,617.64



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer

Premium Automobiles

Telefax

to AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLV5222K

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0661/2018/TF
17 August 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi SQ5 3.0 TFSI qu tiptronic
Vehicle Chassis No. : WAUZZZF4J2028594
Vehicle Regn No. : SLV5222K
Vehicle Mileage : 8657KM
Vehicle Owner : Mr. Luo Chuan
Certificate No : 1700090330
Policy Excess : S\$1,070.00 (Inclusive GST)
Accident Date : 28 May 2018
Place : AYE towards Tuas (Bef South Buona Vista Exit 8)
Repair Cost : \$ 52,617.64
WIP No. : 12047
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :



Time :

Date :

17/8/18

REPUBLIC OF SINGAPORE DRIVING LICENCE

Portrait photo of a man.

License Number: S7069061F

Name: LUO CHUAN

Birth Date: 09 Feb 1970

Issue Date: 24 Feb 2010

001833142A

Barcode

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3 Motor Cars $\leq$ 3000kg with $\leq$ 7 passengers, exclusive of the driver; and other motor vehicles $\leq$ 2500kg 24 Feb 2010

NP 428A

Licence No: S7069061F

Barcode

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Jun 2018		08 Jun 2018 10:55 Edit Adj Rpt	S\$50,175.36 Edit Estimates	S\$50,175.36 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: LUO CHUAN , ID: S7069061F, Tel: +6596726186, Email: dannyluo0209@icloud.com									
Vehicle Reg. No.: SLV5222K		Date of Loss: 28/05/2018 09:00 - :59 [4 Months and 28 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / 0830299172SG		Policy/Cover Note No.: 1700090330 (Comprehensive)							
		Excess: S\$1,000.00							
Repairer: Premium Automobiles Pte Ltd (Benoi) 24 Benoi Sector, 629857 Pioneer - Tel: 67689911 / 63882323									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Loo, Tong Shing] TongShing.Loo@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 20/06/2018]									
Driver/Custodian: LUO CHUAN (48 / Male) , NRIC: S7069061F, Tel: +6596726186 Email: dannyluo0209@icloud.com									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG (12/06/2018): Alert - Adj Mandate Approved (S\$61857.00) - SLV5222K - Claim Handler: Loo, Tong ...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLV5222K (0830299172SG)

OD

May 28 2018 9:40AM

[LUO CHUAN]

Premium Automobiles Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Assessment Reports			1 per page 1 ☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/06/18 15:15	Adjuster Immediate Advice	Load HTML	☒
Photos/Images			3 per page 3 ☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/06/18 14:11	Odometer Reading	Load JPG	☒
2	08/06/18 14:11	Chassis Number	Load JPG	☒
3	08/06/18 14:11	General View	Load JPG	☒
4	08/06/18 14:11	General View	Load JPG	☒
5	08/06/18 14:11	General View	Load JPG	☒
6	08/06/18 14:11	General View	Load JPG	☒
7	08/06/18 14:11	General View	Load JPG	☒
8	08/06/18 14:11	General View	Load JPG	☒
9	08/06/18 14:11	General View	Load JPG	☒
10	08/06/18 14:11	General View	Load JPG	☒
11	08/06/18 14:11	General View	Load JPG	☒
12	08/06/18 14:11	General View	Load JPG	☒
13	08/06/18 14:11	General View	Load JPG	☒
14	08/06/18 14:11	General View	Load JPG	☒
15	08/06/18 14:11	General View	Load JPG	☒
16	08/06/18 14:11	General View	Load JPG	☒
17	08/06/18 14:11	General View	Load JPG	☒
18	08/06/18 14:11	General View	Load JPG	☒
19	08/06/18 14:11	General View	Load JPG	☒
20	08/06/18 14:11	General View	Load JPG	☒
21	08/06/18 14:11	General View	Load JPG	☒
22	08/06/18 14:11	General View	Load JPG	☒
23	08/06/18 14:11	General View	Load JPG	☒
24	08/06/18 14:11	General View	Load JPG	☒
25	08/06/18 14:11	General View	Load JPG	☒
26	08/06/18 14:11	General View	Load JPG	☒
27	08/06/18 14:11	General View	Load JPG	☒
28	08/06/18 14:11	General View	Load JPG	☒
29	08/06/18 14:11	General View	Load JPG	☒
30	08/06/18 14:11	General View	Load JPG	☒
31	08/06/18 14:11	General View	Load JPG	☒
32	08/06/18 14:11	General View	Load JPG	☒
33	08/06/18 14:11	General View	Load JPG	☒
34	08/06/18 14:11	General View	Load JPG	☒
35	08/06/18 14:11	General View	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	08/06/18 14:11	General View	 Load JPG	☒
37	08/06/18 14:11	General View	 Load JPG	☒
38	08/06/18 14:11	General View	 Load JPG	☒
39	08/06/18 14:11	General View	 Load JPG	☒
40	08/06/18 14:11	General View	 Load JPG	☒
41	08/06/18 14:11	General View	 Load JPG	☒
42	08/06/18 14:11	General View	 Load JPG	☒
43	08/06/18 14:11	General View	 Load JPG	☒
44	08/06/18 14:11	General View	 Load JPG	☒
45	08/06/18 14:11	General View	 Load JPG	☒
46	08/06/18 14:11	General View	 Load JPG	☒
47	08/06/18 14:11	General View	 Load JPG	☒
48	08/06/18 14:11	General View	 Load JPG	☒
49	08/06/18 14:11	General View	 Load JPG	☒
50	08/06/18 14:11	General View	 Load JPG	☒
51	08/06/18 14:11	General View	 Load JPG	☒
52	08/06/18 14:11	General View	 Load JPG	☒
53	08/06/18 14:11	General View	 Load JPG	☒
54	08/06/18 14:11	General View	 Load JPG	☒
55	08/06/18 14:11	General View	 Load JPG	☒
56	08/06/18 14:11	General View	 Load JPG	☒
57	08/06/18 14:11	General View	 Load JPG	☒
58	08/06/18 14:11	General View	 Load JPG	☒
59	08/06/18 14:11	General View	 Load JPG	☒
60	08/06/18 14:11	General View	 Load JPG	☒
61	08/06/18 14:11	General View	 Load JPG	☒
62	22/02/19 14:09	Reinspection Photo	 Load JPG	☒
63	22/02/19 14:09	Reinspection Photo	 Load JPG	☒
64	22/02/19 14:09	Reinspection Photo	 Load JPG	☒
65	22/02/19 14:09	Reinspection Photo	 Load JPG	☒
66	22/02/19 14:09	Reinspection Photo	 Load JPG	☒
67	22/02/19 14:09	Reinspection Photo	 Load JPG	☒
68	22/02/19 14:09	Reinspection Photo	 Load JPG	☒
69	22/02/19 14:09	Reinspection Photo	 Load JPG	☒
70	22/02/19 14:09	Reinspection Photo	 Load JPG	☒
71	22/02/19 14:09	Reinspection Photo	 Load JPG	☒
72	22/02/19 14:09	Reinspection Photo	 Load JPG	☒
73	22/02/19 14:09	Reinspection Photo	 Load JPG	☒
74	22/02/19 14:09	Reinspection Photo	 Load JPG	☒
75	22/02/19 14:09	Reinspection Photo	 Load JPG	☒
76	22/02/19 14:09	Reinspection Photo	 Load JPG	☒
77	22/02/19 14:09	Reinspection Photo	 Load JPG	☒
78	22/02/19 14:09	Reinspection Photo	 Load JPG	☒
79	22/02/19 14:09	Reinspection Photo	 Load JPG	☒
80	22/02/19 14:09	Reinspection Photo	 Load JPG	☒
81	22/02/19 14:09	Reinspection Photo	 Load JPG	☒
82	22/02/19 14:09	Reinspection Photo	 Load JPG	☒
83	22/02/19 14:09	Reinspection Photo	 Load JPG	☒
84	22/02/19 14:09	Reinspection Photo	 Load JPG	☒
85	22/02/19 14:09	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
86	22/02/19 14:09	Reinspection Photo		☒
87	22/02/19 14:09	Reinspection Photo		☒
88	22/02/19 14:09	Reinspection Photo		☒
89	22/02/19 14:09	Reinspection Photo		☒
90	22/02/19 14:09	Reinspection Photo		☒
91	22/02/19 14:09	Reinspection Photo		☒
92	22/02/19 14:09	Reinspection Photo		☒
93	22/02/19 14:09	Reinspection Photo		☒
94	22/02/19 14:09	Reinspection Photo		☒
95	22/02/19 14:09	Reinspection Photo		☒
96	22/02/19 14:09	Reinspection Photo		☒
97	22/02/19 14:09	Reinspection Photo		☒
98	22/02/19 14:09	Reinspection Photo		☒
99	22/02/19 14:09	Reinspection Photo		☒
100	22/02/19 14:09	Reinspection Photo		☒
101	22/02/19 14:09	Reinspection Photo		☒
102	22/02/19 14:09	Reinspection Photo		☒
103	22/02/19 14:09	Reinspection Photo		☒
104	22/02/19 14:09	Reinspection Photo		☒
105	22/02/19 14:09	Reinspection Photo		☒
106	22/02/19 14:09	Reinspection Photo		☒
107	22/02/19 14:09	Reinspection Photo		☒
108	22/02/19 14:09	Reinspection Photo		☒
109	22/02/19 14:09	Reinspection Photo		☒
110	22/02/19 14:09	Reinspection Photo		☒
111	22/02/19 14:09	Reinspection Photo		☒
112	22/02/19 14:09	Reinspection Photo		☒
113	22/02/19 14:09	Reinspection Photo		☒
114	22/02/19 14:09	Reinspection Photo		☒
115	22/02/19 14:09	Reinspection Photo		☒
116	22/02/19 14:09	Reinspection Photo		☒
117	22/02/19 14:09	Reinspection Photo		☒
118	22/02/19 14:09	Reinspection Photo		☒
119	22/02/19 14:09	Reinspection Photo		☒
120	22/02/19 14:09	Reinspection Photo		☒
121	22/02/19 14:09	Reinspection Photo		☒
122	22/02/19 14:09	Reinspection Photo		☒
123	22/02/19 14:09	Reinspection Photo		☒
124	22/02/19 14:09	Reinspection Photo		☒
125	22/02/19 14:09	Reinspection Photo		☒
126	22/02/19 14:09	Reinspection Photo		☒
127	22/02/19 14:09	Reinspection Photo		☒
128	22/02/19 14:09	Reinspection Photo		☒
129	22/02/19 14:09	Reinspection Photo		☒
130	22/02/19 14:09	Reinspection Photo		☒
131	22/02/19 14:09	Reinspection Photo		☒
132	22/02/19 14:09	Reinspection Photo		☒
133	22/02/19 14:09	Reinspection Photo		☒
134	22/02/19 14:09	Reinspection Photo		☒
135	22/02/19 14:09	Reinspection Photo		☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
136	22/02/19 14:09	Reinspection Photo		☒
137	22/02/19 14:09	Reinspection Photo		☒
138	22/02/19 14:09	Reinspection Photo		☒
139	22/02/19 14:09	Reinspection Photo		☒
140	22/02/19 14:09	Reinspection Photo		☒
141	22/02/19 14:09	Reinspection Photo		☒
142	22/02/19 14:09	Reinspection Photo		☒
143	22/02/19 14:09	Reinspection Photo		☒
144	22/02/19 14:09	Reinspection Photo		☒
145	22/02/19 14:09	Reinspection Photo		☒
146	22/02/19 14:09	Reinspection Photo		☒
147	22/02/19 14:09	Reinspection Photo		☒
148	22/02/19 14:09	Reinspection Photo		☒
149	22/02/19 14:09	Reinspection Photo		☒
150	22/02/19 14:10	Reinspection Photo		☒
151	22/02/19 14:10	Reinspection Photo		☒
152	22/02/19 14:10	Reinspection Photo		☒
153	22/02/19 14:10	Reinspection Photo		☒
154	22/02/19 14:10	Reinspection Photo		☒
155	22/02/19 14:10	Reinspection Photo		☒
156	22/02/19 14:10	Reinspection Photo		☒
157	22/02/19 14:10	Reinspection Photo		☒
158	22/02/19 14:10	Reinspection Photo		☒
159	22/02/19 14:10	Reinspection Photo		☒
160	22/02/19 14:10	Reinspection Photo		☒
161	22/02/19 14:10	Reinspection Photo		☒
162	22/02/19 14:10	Reinspection Photo		☒
163	22/02/19 14:10	Reinspection Photo		☒
164	22/02/19 14:10	Reinspection Photo		☒
165	22/02/19 14:10	Reinspection Photo		☒
166	22/02/19 14:10	Reinspection Photo		☒
167	22/02/19 14:10	Reinspection Photo		☒
168	22/02/19 14:10	Reinspection Photo		☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/06/18 14:10	Singapore Accident Statement		☐
2	08/06/18 14:10	Certificate of Insurance		☐
3	08/06/18 14:10	Driver's Driving License		☐
4	08/06/18 14:10	ESTIMATE		☐
5	22/02/19 14:14	SUPPLEMENTARY LIST		☐
6	17/05/19 12:55	Workshop Invoice		☐
7	17/05/19 12:55	Discharge Voucher		☐

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
1	28/05/18 18:35	Accident Statement		☐
2	31/05/18 12:52	Addendum Sheet		☒
3	31/05/18 12:52	Accident Statement Addm. #1		☐

Assessment Reports				1 per page	☒
No	Finalized On	National Assessment Centre Services (Bukit Merah)		Thumbnail	Print
4	07/06/18 17:34	Addendum Sheet		Load JPG	☒
5	07/06/18 17:34	Accident Statement Addm. #2		Load HTM	
Photos/Images				3 per page	☒
No	Finalized On	National Assessment Centre Services (Bukit Merah)		Thumbnail	Print
1	28/05/18 18:31	Accident Photo		Load JPG	☒
2	28/05/18 18:31	Accident Photo		Load JPG	☒
3	28/05/18 18:31	Accident Photo		Load JPG	☒
4	28/05/18 18:31	Accident Photo		Load JPG	☒
5	28/05/18 18:31	Accident Photo		Load JPG	☒
6	28/05/18 18:31	Accident Photo		Load JPG	☒
7	28/05/18 18:31	Accident Photo		Load JPG	☒
8	28/05/18 18:31	Accident Photo		Load JPG	☒
9	28/05/18 18:31	Accident Photo		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	National Assessment Centre Services (Bukit Merah)		Thumbnail	Print
1	28/05/18 18:33	Sketch Plan		Load JPG	☒
2	07/06/18 17:34	Accident Sketch Plan		Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-18
Singapore 079120

Our File No: CC3/AIG18010451/T1QBE2

Date: 17/05/2019

REFERENCE

Insured/Claimant: LUO CHUAN Policy No: 1700090330
Date of Loss: 28/05/2018 Nature of Claim: OD Claim No: 0830299172SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLV5222K**
Make & Model: AUDI SQ5, 3.0 TFSI quattro (A) Engine No: CWG028683
Reg. Date: 30/12/2017 (Man. Year: 2017) Chassis No: WAUZZZF4J2028594
Colour: Blue Odometer: 8655 km
Engine Capacity: 2995 cc
Market Value/New Car Price: S\$300,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/40 R21 Rear Tyre Size: 255/40 R21
Front Left Side: Pirelli 7 mm Rear Left Side: Pirelli 7 mm
Front Right Side: Pirelli 7 mm Rear Right Side: Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	49,162.76	25,291.36	23,871.40	48.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	40,448.00	24,884.00	15,564.00	38.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	89,610.76	50,175.36	39,435.40	44.01
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	88,610.76	49,175.36	39,435.40	44.50
+ GST 7.00/7.00% (S\$)	6,202.75	3,442.28	2,760.47	44.50
Nett Amount (S\$)	94,813.51	52,617.64	42,195.87	44.50

INSPECTION

Date of Assignment: 08/06/2018
Date Inspected: 07/06/2018 Inspected At: Premium Automobiles Pte Ltd (Benoi)
24 Benoi Sector
Singapore 629857
Estimated Period of Repair: 30.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,896.00 FS	*1,516.80 FS
2	2		*BUMPER SUPPORT	Not Necessary	174.00 FS	*- FS
3	1		*REAR BUMPER SPOILER	Cut	862.00 FS	*689.20 FS
4	2		*TAIL LIGHT - LH & RH	Cracked	1,238.00 FS	*989.60 FS
5	1		*TRIM ALUMINIUM	Not Necessary	1,566.00 FS	*- FS
6	1		*GUIDE SECTION - LH & RH	N/S Not Necessary/O/S Deformed	142.00 FS	*56.80 FS
7	2		*FOAM FILLER PIECE - LH & RH	Not Necessary	106.00 FS	*- FS
8	1		*BUMPER CARRIER - REAR	Bent	786.00 FS	*628.80 FS
9	1		*HOLDING STRAP	Not Necessary	142.00 FS	*- FS
10	2		*SENSOR - REAR	Not Necessary	421.00 FS	*- FS
11	1		*WIRING SET FOR BUMPER - REAR	Not Necessary	440.00 FS	*- FS
12	1		*WHEEL ARCH TRIM - LH REAR	Necessary	455.00 FS	*363.60 FS
13	1		*WHEEL ARCH TRIM - RH REAR	Deformed	455.00 FS	*363.60 FS
14	1		*WHEEL COVER - REAR LH	Necessary	37.00 FS	*29.20 FS
15	1		*WHEEL COVER - RH REAR	Necessary	37.00 FS	*29.20 FS
16	1		*REAR LID	Bent	3,776.00 FS	*3,020.80 FS
17	1		*SET ATTACHMENT PARTS FOR REAR LID	Necessary	105.00 FS	*83.20 FS
18	2		*LID HINGE - LH & RH	Bent	400.00 FS	*320.00 FS
19	1		*SET ATTACHMENT PARTS FOR REAR LID	Repeated	105.00 FS	*- FS
20	1		*REAR BOOT BRACKET - RH	Distorted	40.00 FS	*31.84 FS
21	1		*BRACKET - RH	Not Necessary	40.00 FS	*- FS
22	1		*DRIVE UNIT FOR REAR LID	Distorted	1,557.00 FS	*1,245.60 FS
23	1		*GASKET FOR FLAP	Necessary	338.00 FS	*270.40 FS
24	2		*STOP BUFFER	Necessary	48.00 FS	*37.76 FS
25	1		*LOCK STRIKER	Bent	75.00 FS	*59.52 FS
26	1		*LID LOCK WITH MICRO SWITCH	Deformed	195.00 FS	*156.00 FS
27	1		*SERVOMOTOR FOR REAR LID	Bent	266.00 FS	*212.80 FS
28	1		*PUSH BUTTON WITH CAMERA	Deformed	1,205.00 FS	*974.40 FS
29	1		*PACKING ADHESIVE	Necessary	15.00 FS	*11.60 FS
30	1		*AUDI EMBLEM	Necessary	108.00 FS	*86.00 FS
31	1		*S SQ5 EMBLEM	Necessary	108.00 FS	*86.00 FS
32	1		*REAR LID SPOILER	Deformed	1,828.00 FS	*1,462.40 FS
33	1		*SET FIXING PARTS FOR SPOILER	Necessary	18.00 FS	*13.04 FS
34	1		*SET OF FOAM STRIPS	Necessary	30.00 FS	*22.24 FS
35	1		*REAR WINDSCREEN	Cracked	1,020.00 FS	*816.00 FS
36	1		*GLASS PRIMER	Not Necessary	19.00 FS	*- FS
37	2		*WINDSCREEN SPOILER - LH & RH	Necessary	402.00 FS	*320.80 FS
38	1		*REAR FENDER - RH	Buckled	3,913.00 FS	*3,130.40 FS
39	1		*REAR FENDER INNER PRIME - RH REAR	Bent	1,414.00 FS	*1,131.20 FS
40	1		*D PILLAR	Not Necessary	393.00 FS	*- FS
41	1		*REINFORCEMENT FOR D-PILLAR PRIMED - RH LOWER	Not Necessary	477.00 FS	*- FS
42	1		*CONNECTING PLATE - RH REAR	Bent	323.00 FS	*258.00 FS
43	1		*REAR CROSS PANEL	Bent	494.00 FS	*394.80 FS
44	1		*REINFORCEMENT FOR LOCK CARRIER	Bent	147.00 FS	*117.60 FS
45	1		*ROOF	Repair	4,190.00 FS	*- FS
46	1		*ROOF REINFORCEMENT	Not Necessary	217.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*ROOF FRAME	Not Necessary	184.00 FS	*- FS
48	1		*CLOSING ELEMENT	Not Necessary	135.00 FS	*- FS
49	1		*ROOF RAIL - RH	Not Necessary	1,613.00 FS	*- FS
50	1		*BALANCER ELEMENT	Not Necessary	252.00 FS	*- FS
51	1		*SIDE 1/4 GLASS - RH	Necessary	724.00 FS	*579.20 FS
52	2		*GLASS PRIMER	Necessary	38.00 FS	*29.12 FS
53	1		*FUEL FLAP THROTTLE CONTROL ELEMENT	Distorted	91.00 FS	*72.56 FS
54	1		*FUEL FLAP INSERT	Deformed	135.00 FS	*108.00 FS
55	1		*REAR LID TRIM PANEL - LOWER	Cut	650.00 FS	*519.60 FS
56	1		*REAR LID TRIM PANEL - UPPER	Cut	246.00 FS	*196.80 FS
57	1		*LAGGUAGE COMPARTMENT TRIM - RH	Deformed	880.00 FS	*704.00 FS
58	1		*TRIM FOR REAR CROSS PANEL	Deformed	397.00 FS	*317.60 FS
59	1		*LAUGGUAGE COMPARTMENT FLOOR - REAR	Not Necessary	920.00 FS	*- FS
60	1		*COVER BLIND FOR LUGGAGE COMPARTMENT	Not Necessary	1,376.00 FS	*- FS
61	1		*WHEEL HOUSING LINER - RH	Deformed	231.00 FS	*184.80 FS
62	1		*FRONT WINDSCREEN	Not Necessary	2,506.00 FS	*- FS
63	1		*GEL FOIL FOR RAIN SENSOR	Not Necessary	128.00 FS	*- FS
64	1		*GLASS PRIMER	Not Necessary	19.00 FS	*- FS
65	1		*REAR NUMBER PLATE	Not Necessary	25.00 FS	*- FS
66	1		*FRONT WINDSCREEN SEALANT	Not Necessary	200.00 FS	*- FS
67	1		*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
68	1		*1/4 GLASS SEALANT	Necessary	100.00 FS	*100.00 FS
69	1		*ACRYLIC SEALER	Necessary	540.00 FS	*360.00 FS
70	1		*CAVITY WAX	Necessary	420.00 FS	*180.00 FS
71	1		*STTONE CHIP	Necessary	360.00 FS	*180.00 FS
72	1		*METAL FILLER POWDER	Necessary	560.00 FS	*280.00 FS
73	1		*SUNDRIES	Necessary	2,000.00 FS	*168.72 FS
74	1		*REAR LID LOCK BOWDEN CABLE	Distorted	26.48 FS	*26.48 FS
75	1		*REAR LUGGAGE COMP. LIGHT	Distorted	64.00 FS	*64.00 FS
76	2		*REAR LID HINGE REINFORCEMENT PLATE	Not Necessary	28.00 FS	*- FS
77	2		*REAR LID NOISE INSULATION PLATE	Deformed	24.32 FS	*24.32 FS
78	1		*REAR WHEEL HOUSE LINER ATTACHMENT PARTS	Necessary	25.68 FS	*25.68 FS
79	1		*FUEL CHARCOAL CONTAINER	Deformed	299.20 FS	*299.20 FS
80	1		*REAR FILLER PIECE	Distorted	131.20 FS	*131.20 FS
81	1		*REAR LUGGAGE COMP. TRIM COVER - LH	Deformed	82.00 FS	*82.00 FS
82	1		*BOTTOM PLATE - RH	Bent	342.00 FS	*342.00 FS
83	1		*FUEL FLAP WIRE CONNECTOR	Distorted	10.72 FS	*10.72 FS
84	1		*FUEL FLAP CONNECTOR WIRING	Distorted	16.16 FS	*16.16 FS
85	2		*FUEL FLAP WIRING BUTT	Distorted	14.40 FS	*14.40 FS
86	1		*LED TAIL LIGHT - LH	Cracked	1,145.60 FS	*1,145.60 FS

F=Franchise part. S=SpccNett.

Total Parts (\$\$) 49,162.76 25,291.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CARRY OUT FIRST MEASUREMENT ON CAR-O-LINER	New	800.00	0.00
2	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION	New	280.00	280.00
3	TO RENEW RHS 1/4 GLASS AND REAR WINDSCREEN TO FACILITATE FENDER RENEWAL	New	600.00	600.00
4	TO REMOVE AND RENEW FRONT WINDSCREEN FOR ROOF RENEWAL	New	480.00	0.00
5	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHTS, REAR WIPER ASSY AND AUTOMATIC TAILGATE ASSY. INSPECT FOR DAMAGES AND RENEW ACCORDINGLY	New	600.00	600.00
6	TO REMOVE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGES	New	1,600.00	1,600.00
7	TO REMOVE FRONT AND REAR SEATS, HAT TRAY SPEAKER TRIM, ABCD PILLAR TRIMS, ROOF LINING, ROOF RAILS, LIGHTS, CURTAIN AIR BAGS, CONTROLS, SENSORS, SAFETY BELTS AND CARPETS. INSPECT FOR DAMAGES AND RENEW IF NECESSARY	New	3,200.00	3,200.00
8	TO REMOVE AND REINSTALL REAR SUSPENSION ASSY FOR CAR-O-LINER REPAIRS	New	3,200.00	3,200.00
9	TO SET UP VEHICLE ON CAR-O-LINER REPAIR BENCH	New	1,800.00	1,200.00
10	TO DISMANTLE REAR BUMPER AND REAR LID. CUT OUT AND WELD REAR END PANELS, RHS REAR FENDER, INNER D-PILLAR AND REINFORCEMENTS, ROOF PANEL AND ATTACHMENTS. RENEW REAR LID AND REAR BUMPER ASSY. REINSTALL ALL PARTS REMOVED	New	16,800.00	8,000.00
11	TO CARRY OUT COROCOAT TREATMENT AND JOINT SEALER WORKS ON ROOF CHANNEL, DRAIN PANELS, END PANELLING, ENTRANCE CHANNEL AND BASE PRIMER WORK	New	1,200.00	0.00
12	TO RESPRAY REAR BUMPER, LOWER SPOILER, REAR LID, ROOF SPOILER, BOTH REAR FENDER, RHS SILL PANEL, DOOR ENTRANCE, RHS REAR DOOR, ROOF PANEL, BOTH ROOF CHANNELS, DRAIN PANEL AND END PANELLING. TO CARRY OUT JOINT SEALER WORKS AND STONE CHIP TREATMENT	New	8,000.00	4,700.00
13	TO RENEW CENTER AND BOTH REAR EXHAUST SILENCERS. ALIGN TO POSITION	New	480.00	480.00
14	TO CARRY OUT WHEEL ALIGNMENT. INSPECT REAR SUBFRAME FOR DAMAGES	New	240.00	240.00
15	TO CARRY OUT DIAGNOSTIC CHECK	New	768.00	384.00
16	TO INSTALL REAR WINDSCREEN AND 1/4 GLASS WINDOW FILM	New	400.00	400.00
Gross Labour Cost (\$\$)			40,448.00	24,884.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >