

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0667/2018/GC
Date : 8-Jun-18

Vehicle not IN workshop. Kindly arrange for survey.

Your insured vehicle number : SLP 267 X

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Song ZhiWei
Address : Blk 627 Senja Road
#07-174
Singapore 670627
Telephone : HP +65 93890921
Type of Claim : Third Party Claims
Policy No. : DHOM120034311800
Vehicle No : **SLC 234 J**
Model Code : Audi A1 SB 1.0 TFSI S TRONIC
Model / Year : Apr-16
Engine No : CHZ077391
Chassis No : WAUZZZ8X9GB083376
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 6-Jun-18
Place of Accident : Bukit Timah Road

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97495749
- WP
11/6/18 @ 115pm
Resurvey before part.
5 days
sur @ 11/6/18

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLC 234 J.

S/n	Nature of Jobs	Estimated Charges
1	To remove and transfer rear parking aid. Check function	S/N \$ 280.00 ✓
2	To dismantle and renew rear bumper. Repair rhs rear fender. Re-organise rear crash management components. Reinstall all parts removed.	750. \$ 1,200.00
3	To respray rear bumper, rhs rear fender and rhs rear door.	1650. \$ 2,100.00
4	To carry out diagnostic checks.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ 3,772.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLC 234 J.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER	\$ 1,281.00	de ✓
2	FIXING PARTS FOR REAR BUMPER	\$ 64.00	?
3	REAR BUMPER SPOILER	\$ 366.00	ant ✓
4	REAR GUIDE SECTION RHS	\$ 42.00	?
5	REAR LIGHT REFLECTOR RHS	\$ 26.00	?
8	SUNDRIES	\$ 200.00	?
TOTAL SPARE PARTS CHARGES		\$ 1,979.00	
TOTAL LABOUR CHARGES		\$ 3,772.00	
GRAND TOTAL		\$ 5,751.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Rear RH Tyre 70% ant ✓
Rear RH Rim ant ✓

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant