

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chhia Nyuk Pui

Date: 11 Jun 2018

Preliminary Advice

Insured Vehicle No	: SBK1655Y	Accident Date	: 07/06/2018
TP Vehicle No	: SHD1128T	Assignment Date	: 08/06/2018
Make	: HYUNDAI I40	Est. Duration of Repair	: 3.00
Date of Inspection	: 08/06/2018		
Inspection At	: KOMOCO MOTORS - (ALEXANDRA) (HQ) 253 ALEXANDRA ROAD SINGAPORE 159936		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,042.89
Revised Amount	:S\$	1,432.72
Check Items (Estimated)	:S\$	530.17
Total	:S\$	1,962.89

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.