

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	To refill aircon gas	New	100.00
2	To repair front damage	New	660 720.00
3	To spray painting (Pearl)	New	800 950.00
Gross Labour Cost (S\$)			1,770.00

Vin's Motor Pte Ltd/SLN7543M/07/06/2018 16:27, Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

VIN'S MOTOR PTE LTD

160 Sin Ming Drive, Sin Ming AutoCity, #03-03, Singapore 575722. Tel: 6453 2121 (4 Lines) Fax: 6459 9795

Our Ref : OD/062018/3560
 Accident date: 07/06/2018
 Your Ref : PNPV2018-00005067

Tax Invoice:

Date : 09/06/2018

MOTOR CLAIM DEPARTMENT
 FWD Singapore Pte Ltd
 6 Temasek Boulevard, #18-01
 Suntec Tower 4
 Singapore 038986

SUPPLEMENTARY COST OF REPAIRS TO HONDA VEZEL SLN7543M

- 2 pcs Front headlamp lower plastic bracket @ \$20.00
 1 pc Front RH headlight top plastic bracket
 1 pc Front bonnet lock garnish
 1 pc Front radar sensor

\$	<i>Di</i>	40.00	✓
\$	<i>Ry</i>	10.00	✓
\$	<i>cm</i>	25.00	✓
<i>short</i> \$		1,900.00	✓
		<u>\$</u>	<u>1,975.00</u>

VIN'S MOTOR PTE LTD


LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

VIN'S MOTOR PTE LTD

BLOCK 12, SIN MING ROAD, #01-67, SINGAPORE 575656. TEL : 6453 2121 (4 LINES) FAX : 6459 9795

(SUPPLEMENTARY)INSURER: **FWD Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (Own Damage)	Ref. No:	OD/062018/3560
Policy No:	PNPV2018-00005067	Date of Loss:	07/06/2018
Vehicle Reg. No.:	SLN7543M	Driveable?	
Driver Age/Info:	38 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	NG WEI TAT, EDWIN (HUANG WEIDA, EDWIN)	Contact No:	+6596978078
Driver:	NG WEI TAT, EDWIN (HUANG WEIDA, EDWIN)		

Make/Model:	HONDA VEZEL, 1.5 HYBRID X (A)	Vehicle Reg. Date:	17/05/2017
Vehicle Colour:	Red	Chassis No:	RU31238236
Engine No:	LEB5938251		
Odometer:	0 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	8

Description of Accident/Loss	REFER TO SKETCH PLAN
Present Location:	VIN'S MOTOR PTE LTD (SIN MING)

COST OF CLAIMS

	Amount
Parts	0.00
Miscellaneous Items	0.00
Labour	400.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	400.00
+ GST 7.00% (S\$)	28.00
Nett Amount (S\$)	428.00
+ Previous Estimates (S\$)	8,714.08
Claim Total (S\$)	9,142.08

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	Reset front radar sensor	New	400.00 /
Gross Labour Cost (\$\$)			400.00

Vin's Motor Pte Ltd/SLN7543M/14/06/2018 14:45. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



WELTUNE AUTO SERVICES

BLOCK 1019, YISHUN INDUSTRIAL PARK A, #01-374, SINGAPORE 768761

TEL: 6755 4064 FAX: 6755 7719 H/P: 9755 4064

BUSINESS REG. NO.: 362071-00D

VIN S MOTOR PTE LTD
160 #03-03 Sing Ming Auto City
575656

Tax Invoice : RS018505

Invoice Date : 14/06/2018
Vehicle Num. : SLN7543M
Make/Model : Honda Vezel
Mileage(Km) :
PO/WO/RO# :
Ref./Remark :

Contact : 64532121 98212255 Fax No. : 64581111

S/N	Quantity	Particular	Unit Price	Amount S\$
1.		To Program	400.00	400.00

PAID

SingDollars : Four Hundred Twenty-Eight Only

E. & O.E.

Total S\$: 400.00
GST@7% S\$: 28.00
Amount Due S\$: 428.00

Terms :

Customer's Signature/Co. Stamp


for Weltune Auto Services

GST REG. NO. M90389542J

E.&O.E.

6/7/2018

Repairer Estimates

GST REG NO : 19-8906087-G , REG. NO: 199905087G

VIN'S MOTOR PTE LTD

BLOCK 12, SIN MING ROAD, #01-67, SINGAPORE 575856. TEL : 6453 2121 (4 LINES) FAX : 6459 9795

INSURER: **FWD Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD/062018/3560
Policy No:	PNPV2018-00005067	Date of Loss:	07/06/2018
Vehicle Reg. No.:	SLN7543M	Driveable?	
Driver Age/Info:	38 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	NG WEI TAT, EDWIN (HUANG WEIDA, EDWIN)	Contact No:	+6596978078
Driver:	NG WEI TAT, EDWIN (HUANG WEIDA, EDWIN)		

Make/Model:	HONDA VEZEL, 1.5 HYBRID X (A)	Vehicle Reg. Date:	17/05/2017
Vehicle Colour:	RED	Chassis No:	RU31238236
Engine No:	LEB5938251		
Odometer:	0 KM		

Paint Type:
 Total Loss? **NO**
 Est. Duration of Repair (day) **8 6 days**



Not Authn
1.B.1
Recovery B4 claim
Ex 8500
Fax: 62564315

Description of Accident/Loss: **REFER TO SKETCH PLAN**
 Present Location: **VIN'S MOTOR PTE LTD (SIN MING)**

COST OF CLAIMS

	Amount
Parts	4,899.00
Miscellaneous Items	0.00
Labour	1,770.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	6,669.00
- Excess (S\$)	500.00
(S\$)	6,169.00
+ GST 7.00% (S\$)	431.83
Nett Amount (S\$)	6,600.83

This claim is handled by: **YAP JIN HUI**

Generated using Merlman e-Claims Internet Estimation & Adjusting System

AIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 07 Jun 2018)
 Parts: M1-SUV HONDA VEZEL 1.5 HYBRID X (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Vin's Motor Pte Ltd/SLN7543M/07/06/2018 16:27

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front bonnet	0.00	0.00	R ₁ *440.00 F ✓
2	2		*Front bonnet hinge @ \$30/pc	0.00	0.00	old D17 *60.00 F ✓
3	8		*Front bonnet insulator clips @ \$3.50/pc	0.00	0.00	R ₁ *28.00 F ✓
4	20		*Front bonnet rubber clips @ \$3/pc	0.00	0.00	R ₁ *60.00 F ✓
5	1		*Front bonnet lock	0.00	0.00	D17 *60.00 F ✓
6	2		*Front headlamp @ \$880/pc	0.00	0.00	mtg CM *1,760.00 F ✓
7	1		*Front support panel	0.00	0.00	B ₁ *310.00 F ✓
8	1		*Front support panel top cover	0.00	0.00	CM *40.00 F ✓
9	2		*Front support panel top cover clips @ \$4/pc	0.00	0.00	R ₁ *36.00 F ✓
10	1		*Front grille	0.00	0.00	CM *260.00 F ✓
11	1		*Front grille chrome cover	0.00	0.00	R ₁ *50.00 F ✓
12	1		*Front grille emblem	0.00	0.00	D17 *15.00 F ✓
13	1		*Front bumper	0.00	0.00	B ₁ *300.00 F ✓
14	1		*Front bumper top beam	0.00	0.00	R ₁ *30.00 F ✓
15	1		*Front bumper reinforcement	0.00	0.00	R ₁ *210.00 F ✓
16	1		*Front bumper towing cover	0.00	0.00	R ₁ *10.00 F ✓
17	2		*Front bumper side retainer @ \$10/pc	0.00	0.00	D17 *20.00 F ✓
18	1		*Front bumper lower grille	0.00	0.00	*50.00 F ?
19	1		*Front air condensor	0.00	0.00	BT1R ₁ *340.00 F ✓
20	1		*Front radiator	0.00	0.00	*760.00 F ?
21	1		*Front number plate	0.00	0.00	CM *40.00 F ✓

F=Franchise part.

Total Parts (\$\$)

4,899.00

Vin's Motor Pte Ltd/SLN7543M/07/06/2018 16:27. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Repairer Estimates

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

- 1 To refill aircon gas
- 2 To repair front damage
- 3 To spray painting (Pearl)

New

100.00 ✓

New

660 720.00

New

800 950.00

Gross Labour Cost (\$)

1,770.00

Vin's Motor Pte Ltd/SLN7543M/07/06/2018 16:27. Not valid without Reference section.
Generated using Merlmen e-Claims IEAS

< END OF ESTIMATES >



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

VIN'S MOTOR PTE LTD
160 SIN MING DRIVE #08-09
SIN MING AUTOCITY
SECTOR B
SINGAPORE 575722
TEL : 64532121 VINCENT FAX : 64599795 ACC/64590433
ATTN : 4532121

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9909



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE AR201806-05124
DATE 08/06/2018
CUSTOMER ID VIN002
VEH REG. NO. SLN7543M
TERMS 30 days
PO NO.
PAGE NO. Page 1 of 2
CURR. SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1.	H60100-T7A-000ZZ RU1	✓ BONNET	WH HI.1-D18	1	440.00	440.00
2.	H60170-T7A-000ZZ RU1	✓ BONNET HINGE LH	WH HI.2-G8-F	1	30.00	30.00
3.	H60120-T7A-000ZZ RU1	✓ BONNET HINGE RH	WH HI.2-G8-F	1	30.00	30.00
4.	H91501-SWA-003	✓ CLIPS, INSULATOR	WH I.2-77-29	8	3.50	28.00
5.	H74121-T7A-003 RU1	? SEAL BONNET RH (CENTRE)	WH HL2-D13-43	1	30.00	30.00
6.	H74128-T7A-003 RU1	? SEAL BONNET LH (CENTRE)	WH HI.2-D13-16	1	30.00	30.00
7.	H74120-T7A-003 RU1	✓ LOCK ASSY HOOD	WH HI.2-G8-D	1	60.00	60.00
8.	H33100-T7A-J11/J12 RU1 RU3	✓ HEADLAMP RH	WH HI.1-B3	1	880.00	880.00
9.	H33150-T7A-J11/J12 RU1	✓ HEADLAMP LH	WH HI.1-B3	1	880.00	880.00
10.	H60400-T7B-Z00ZZ	✓ SUPPORT PANEL	WH HI.1-H4	1	310.00	310.00
11.	H71129-T7A-000 RU1	✓ COVER FRT GRILLE	WH HI.2-G5-F	1	40.00	40.00
12.	H91505-TM8-003 GM2	✓ CLIPS	WH HI.2-D13-37	9	4.00	36.00
13.	H71126-T7B-Z01 RU3-2016	✓ GRILLE BASE	WH NEW	1	260.00	260.00
14.	H71123-T7B-Z01 RU3 2016	✓ GRILLE LOWER CHROME	WH I.2-M5-A	1	50.00	50.00
15.	H75700-S9A-G00T BE1 CL7 FD1	✓ "H" EMBLEM	WH HI.2-D13-21	1	15.00	15.00
16.	H04711-T7A-N00ZZ	✓ FR BUMPER	WH HI.1-N26	1	300.00	300.00

CONTINUE NEXT PAGE
ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

VIN'S MOTOR PTE LTD
160 SIN MING DRIVE #08-09
SIN MING AUTOCITY
SECTOR B
SINGAPORE 575722
TEL : 64532121 VINCENT FAX : 64599795 ACC/64590433
ATTN : 4532121

WINDSHIELD GLASS
Dept Direct: 6417 9701 / 6745 9939



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea)
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201806-05124
DATE : 08/06/2018
CUSTOMER ID : VIN002
VEH REG. NO. : SLN7543M
TERMS : 30 days
PO NO. :
PAGE NO. : Page 2 of 2
CURR. : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
17. H71150-T7A-000 RU1	✓ UP BEAM FRT GRILL	WH HT.2-C20-A	1	30.00	30.00
18. H71130-T7A-N00Z7 RU3	✓ RENFORCEMENT	WH HT.1-H6	1	210.00	210.00
19. H71104-T7A-000Z.A	✓ TOW COVER	WH HT.2-D13-17	1	10.00	10.00
20. H71193-T7A-000 RU1	✓ SPACER FR RH	WH HT.2-G8-A	1	10.00	10.00
21. H71198-T7A-000 RU1	✓ SPACER FR LH	WH I.2-Q5-I	1	10.00	10.00
22. H71103-T7A-000 RU1	✓ BUMPER GRILL	WH HT.3-D4	1	50.00	50.00
23. H80110-T7A-J01 RU1	✓ CONDENSER COMP	WH HT.1-C8	1	340.00	340.00
24. H19010-51E-J01/J02 RU3	✓ RADIATOR MS	WH HT.1-G8	1	780.00	780.00

SUB-TOTAL : 4,859.00
ADD GST 7.00 % 340.13

E. & O.E TOTAL AMOUNT SGD : 5,199.13

[P] 08/06/2018 6:12:39PM

[E] 08/06/2018 5:56:18PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : CHEN



* A R 2 0 1 8 0 6 - 0 5 1 2 4 *

This is computer generated document.

No signature is required.

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

VIN'S MOTOR PTE LTD
160 SIN MING DRIVE #08-09
SIN MING AUTOCITY
SECTOR B
SINGAPORE 575722
TEL : 64532121 VINCENT FAX : 64599795 ACC/64590433
ATTN : 4532121

WINDSCREEN GLASS
Dept Direct: 9417 9791 / 9745 9609



Dept Direct: 8305 9610

Dept Direct: 8305 9611

Dept Direct: 8417 9792



Dept Direct: 9417 9794

Dept Direct: 9417 9795

Dept Direct: 9417 9796

Dept Direct: 9417 9793

Wiper blade: NWB (Nippon Wiper blade), Sliper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201806-05385
DATE : 09/06/2018
CUSTOMER ID : VIN002
VEH REG. NO. : SLN7543M
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. H71140-T7A-000	BEAM,R FR BUMPER	WH HT.2-G9-B	1	20.00	20.00
2. H71190-T7A-000 RU1	BRACKET,L FR BUMPER	WH HT.2-G9-B	1	20.00	20.00
3. H71151-T7A-000 RU1	UP BEAM RH FRT GRIL	WH HT.2-C24-H	1	10.00	10.00
4. H36802-T7A-J02 RU1	MILLIMETER WAVE RADAR	WH HT.2-K17-E	1	1900.00	1,900.00
5. H74125-TDJ-000	BONNET LOCK COVER	WH NEW	1	25.00	25.00

SUB-TOTAL : 1,975.00
ADD GST 7.00 % 138.25

E. & O.E

TOTAL AMOUNT SGD : 2,113.25

[P] 09/06/2018 11:59:18AM

[E] 09/06/2018 11:51:37AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : CHEN



* A R 2 0 1 8 0 6 - 0 5 3 8 5 *

This is computer generated document.
No signature is required.

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Jun 2018 Sendback Est	07 Jun 2018 16:27 S\$6,669.00	07 Jun 2018 17:30 Edit Adj Rpt	S\$8,834.00 Edit Estimates	S\$8,834.00 View Rpt		Pending for Survey Report Cancel Case
Supp #1	09 Jun 2018 10:15	09 Jun 2018 10:16 S\$1,975.00	09 Jun 2018 10:16			(Combined)	Combined with Main Uncombine Suppl.
Supp #2	14 Jun 2018 14:43	14 Jun 2018 14:45 S\$400.00	14 Jun 2018 14:45			(Combined)	Combined with Main Uncombine Suppl.

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	NG WEI TAT, EDWIN (HUANG WEIDA, EDWIN), ID: S7935646H, Tel: +6596978078, Email: EDWIN2005S@MSN.COM		
Vehicle Reg. No.:	SLN7543M	Date of Loss:	07/06/2018 08:00 - :59 [12 Months and 21 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 1201800007043	Policy/Cover Note No.:	PNPV2018-00005067 (Comprehensive) Coverage: 17/05/2018 - 16/05/2019
		Excess:	S\$500.00
Repairer:	Vin's Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive, #03-03, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64532121		
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Josey Loh]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 19/06/2018]		
Driver/Custodian:	NG WEI TAT, EDWIN (HUANG WEIDA, EDWIN) (38 / Male), NRIC: S7935646H, Tel: +6596978078		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- FWD_SG (12/07/2018): Alert - Adj Mandate Approved (S\$8834.00) - SLN7543M - Claim Handler: Josey Loh
- FWD_SG (11/07/2018): Alert - Adj Mandate Approved (S\$8794.00) - SLN7543M - Claim Handler: Josey Loh
- FWD_SG (10/07/2018): Alert - Adj Mandate Approved (S\$8394.00) - SLN7543M - Claim Handler: Josey Loh
- FWD_SG (08/06/2018): Alert - Adj Mandate Approved (S\$6429.00) - SLN7543M - Claim Handler: Josey Loh

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SLN7543M (1201800007043)

OD

Jun 7 2018 8:00AM

[NG WEI TAT, EDWIN (HUANG WEIDA, EDWIN)]

Vin's Motor Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
View [View in Browser](#) ▼

Assessment Reports

1 per page ▼ ☒

No	Finalized On	Vin's Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	07/06/18 16:27	Repairer Estimates	1	Load HTM	
2	09/06/18 10:16	Repairer Estimates Suppl. #1	1	Load HTM	
3	14/06/18 14:45	Repairer Estimates Suppl. #2	1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	08/06/18 15:36	Adjuster Immediate Advice	1	Load HTM	
2	10/07/18 09:47	Adjuster Immediate Advice	1	Load HTM	
3	11/07/18 09:32	Adjuster Immediate Advice	1	Load HTM	
4	12/07/18 11:45	Adjuster Immediate Advice	1	Load HTM	

Photos/Images

3 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	10/07/18 09:26	General View	1	Load JPG	☒
2	10/07/18 09:26	General View	1	Load JPG	☒
3	10/07/18 09:26	General View	1	Load JPG	☒
4	10/07/18 09:26	General View	1	Load JPG	☒
5	10/07/18 09:26	General View	1	Load JPG	☒
6	10/07/18 09:26	General View	1	Load JPG	☒
7	10/07/18 09:26	General View	1	Load JPG	☒
8	10/07/18 09:26	General View	1	Load JPG	☒
9	10/07/18 09:26	General View	1	Load JPG	☒
10	10/07/18 09:26	General View	1	Load JPG	☒
11	10/07/18 09:26	General View	1	Load JPG	☒
12	10/07/18 09:26	General View	1	Load JPG	☒
13	10/07/18 09:26	General View	1	Load JPG	☒
14	10/07/18 09:26	General View	1	Load JPG	☒
15	10/07/18 09:26	General View	1	Load JPG	☒
16	10/07/18 09:26	General View	1	Load JPG	☒
17	10/07/18 09:26	General View	1	Load JPG	☒
18	10/07/18 09:26	General View	1	Load JPG	☒
19	10/07/18 09:26	General View	1	Load JPG	☒
20	10/07/18 09:26	General View	1	Load JPG	☒
21	10/07/18 09:26	General View	1	Load JPG	☒
22	10/07/18 09:26	Odometer Reading	1	Load JPG	☒
23	10/07/18 09:26	General View	1	Load JPG	☒
24	10/07/18 09:26	Chassis Number	1	Load JPG	☒
25	10/07/18 09:32	Reinspection Photo	1	Load JPG	☒
26	10/07/18 09:32	Reinspection Photo	1	Load JPG	☒
27	10/07/18 09:32	Reinspection Photo	1	Load JPG	☒
28	10/07/18 09:32	Reinspection Photo	1	Load JPG	☒

Assessment Reports				
No	Finalized On	Vin's Motor Pte Ltd (Sin Ming)	Thumbnail	Print
29	10/07/18 09:32	Reinspection Photo	 Load JPG	☒
30	10/07/18 09:32	Reinspection Photo	 Load JPG	☒
31	10/07/18 09:32	Reinspection Photo	 Load JPG	☒
32	10/07/18 09:32	Reinspection Photo	 Load JPG	☒
33	10/07/18 09:32	Reinspection Photo	 Load JPG	☒
34	10/07/18 09:32	Reinspection Photo	 Load JPG	☒
35	10/07/18 09:32	Reinspection Photo	 Load JPG	☒
36	10/07/18 09:32	Reinspection Photo	 Load JPG	☒
37	10/07/18 09:32	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/06/18 15:36	ESTIMATE	 Load PDF	
2	13/07/18 08:57	SUPPLEMENTARY	 Load PDF	
3	13/07/18 08:57	PARTS INVOICE	 Load PDF	

Linked Accident Report Documents

Assessment Reports			View	View in Browser
No	Finalized On	Vin's Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	07/06/18 09:32	Accident Statement	 Load HTM	
Photos/Images			3 per page	
No	Finalized On	Vin's Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	07/06/18 09:31	Accident Photo	 Load JPG	☒
2	07/06/18 09:31	Accident Photo	 Load JPG	☒
3	07/06/18 09:31	Accident Photo	 Load JPG	☒
4	07/06/18 09:31	Accident Photo	 Load JPG	☒
5	07/06/18 09:31	Accident Photo	 Load JPG	☒
6	07/06/18 09:31	Accident Photo	 Load JPG	☒
7	07/06/18 09:31	Accident Photo	 Load JPG	☒
8	07/06/18 09:31	Accident Photo	 Load JPG	☒
9	07/06/18 09:31	Accident Photo	 Load JPG	☒
Documentation			1 per page	
No	Finalized On	Vin's Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	07/06/18 09:32	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower 4
Singapore 038986

Our File No: CS/FWD18010463/KSD3S2
Date: 13/07/2018

REFERENCE

Insured/Claimant: NG WEI TAT, EDWIN (HUANG WEIDA, EDWIN) Policy No: PNPV2018-00005067
Date of Loss: 07/06/2018 Nature of Claim: OD Claim No: 1201800007043

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN7543M	Engine No:	LEB5938251
Make & Model:	HONDA VEZEL, 1.5 HYBRID X (A)	Chassis No:	RU31238236
Reg. Date:	17/05/2017 (Man. Year: 2017)	Odometer:	14096 km
Colour:	Metallic Red		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	S\$90,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/55R17	Rear Tyre Size:	215/55R17
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8 mm

The above values represent the remaining tyre treads depth

	Repairer's	Adjuster's	Difference	Diff %
COST OF CLAIMS				
Parts	6,874.00	6,874.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,170.00	1,960.00	210.00	9.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,044.00	8,834.00	210.00	2.32
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	8,544.00	8,334.00	210.00	2.46
+ GST 7.00/7.00% (S\$)	598.08	583.38	14.70	2.46
Nett Amount (S\$)	9,142.08	8,917.38	224.70	2.46

INSPECTION

Date of Assignment:	07/06/2018	Present Location:	Vin's Motor Pte Ltd (Sin Ming)
Date Inspected:	08/06/2018	Inspected At:	Vin's Motor Pte Ltd 160 Sin Ming Drive, #03-03, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	6.0 days		

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Jul 2018)
Parts:	M1-SUV	HONDA VEZEL 1.5 HYBRID X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLN7543M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Front bonnet	Bent	440.00 F	*440.00 F
2	2		*Front bonnet hinge @ \$30/pc	N/s Bent / O/s Distorted	60.00 F	*60.00 F
3	8		*Front bonnet insulator clips @ \$3.50/pc	Necessary	28.00 F	*28.00 F
4	20		*Front bonnet rubber clips @ \$3/pc	Necessary	60.00 F	*60.00 F
5	1		*Front bonnet lock	Distorted	60.00 F	*60.00 F
6	2		*Front headlamp @ \$880/pc	Mtg Cracked	1,760.00 F	*1,760.00 F
7	1		*Front support panel	Buckled	310.00 F	*310.00 F
8	1		*Front support panel top cover	Cracked	40.00 F	*40.00 F
9	9		*Front support panel top cover clips @ \$4/pc	Necessary	36.00 F	*36.00 F
10	1		*Front grille	Cracked	260.00 F	*260.00 F
11	1		*Front grille chrome cover	Necessary	50.00 F	*50.00 F
12	1		*Front grille emblem	Missing	15.00 F	*15.00 F
13	1		*Front bumper	Buckled	300.00 F	*300.00 F
14	1		*Front bumper top beam	Bent	30.00 F	*30.00 F
15	1		*Front bumper reinforcement	Bent	210.00 F	*210.00 F
16	1		*Front bumper towing cover	Dented	10.00 F	*10.00 F
17	2		*Front bumper side retainer @ \$10/pc	Distorted	20.00 F	*20.00 F
18	1		*Front bumper lower grille	Cracked	50.00 F	*50.00 F
19	1		*Front air condensor	Bent / Punctured	340.00 F	*340.00 F
20	1		*Front radiator	Punctured	780.00 F	*780.00 F
21	1		*Front number plate	Cracked	40.00 F	*40.00 F
Supplementary #1						
22	2		*Front headlamp lower plastic bracket @ \$20.00	Distorted	40.00 F	*40.00 F
23	1		*Front RH headlight top plastic bracket	Bent	10.00 F	*10.00 F
24	1		*Front bonnet lock garnish	Cracked	25.00 F	*25.00 F
25	1		*Front radar sensor	Shorted	1,900.00 F	*1,900.00 F
					Total Parts (S\$)	6,874.00 6,874.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	To refill aircon gas	New	100.00	100.00
2	To repair front damage	New	720.00	660.00
3	To spray painting (Pearl)	New	950.00	800.00
<u>Supplementary #2</u>				
<u>Labour Items</u>				
4	Reset front radar sensor	New	400.00	400.00
Gross Labour Cost (S\$)			2,170.00	1,960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >