

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Josey Loh

Date: 12 Jul 2018

Preliminary Advice

Vehicle No	: SLN7543M	Accident Date	: 07/06/2018
Make	: HONDA VEZEL	Policy No.	: PNPF2018-00005067
Assignment Date	: 07/06/2018	Excess	: S\$500.00
Date of Inspection	: 08/06/2018	Est. Duration of Repair	: 6 days
Inspection At	: Vin's Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive, #03-03, Sin Ming AutoCity Singapore 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 9,044.00
Revised Amount	:S\$ 8,834.00
Check Items (Estimated)	:S\$ 0.00
Total	:S\$ 8,834.00
 Lump Sum Repair	:S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :