

ASS. REC. BY: _____ REF: CS/PCI18010467/ Urd3 | n2 Special Instruction:

Surveyor: Marcell ASSIGNMENT (Office)

From (Person): May chua of PCI Date/Time: 7/6/18 @ 5.31pm

Estimated Cost: _____ Bill to: _____

OD / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLK 5924B Insured: SHA 2500K

at Workshop m/s: Jin Auto Services Tel: 6289 8126

of BIK 14 # 01-110/112 Defu June 10

Policy No: _____ Claim No: D18004332 MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 28/05/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS ^(up) H.O.D. Endorsement: _____

Date/Time: 9am @ 8/6/18 Person Contacted: Jouis Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SLK 5924B - X</u>
	<u>SHA 2500K - CC3/ICR/7024348/K/WS362 DOA: 20/12/17</u>
	<u>Revert thm email.</u>

08/11/13 wef
ASS. REC. BY: Marcus

REF:

FCI/

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLK5924

at Workshop m/s J. A. B. C.

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GA / PR Seen: 2 Consistent?: Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 137 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS L7A66135

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLK5924B Yr Regn: 1, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA1

Make: Toyota Corolla cc 1986

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 5-3191 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ZSU 60 0085987

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 235/55R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front R/Bal. 7 mm

Rear R/Bal. 7 mm

L/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 28/5/18

D.O.I. 19/6/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time Action / Instruction

22/7/18 continued final ty # 2524.69 - with Jouis.

Ref: 84165.23, 627.

RECEIVED 20 JUL 2019

Date/Time, File Pass to? Prel. Report

1) tympst Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

Report Format: TP

Lump Sum / I.B.I: (\$ 2524.69)

Survey Fee: 145

Transportation: 50

Sir-R6, SI 50

Photos 36

Others

TOTAL

281



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18010467/Urd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 08-06-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 2500K	Veh. Inspected	SLK 5924B
Policy No.		Coverage (\$)	0.00
Claim No.	D18004332MFSH	Excess (\$)	0.00
Assign From	CWS (MAY CHUA)	Assign Date	08/06/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	28/05/2018	Inspection Date	
Survey held at	JIN AUTO SERVICES PTE LTD BLK 14 DEFU LANE 10 #01-412 SINGAPORE 539195		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

MOTOR SURVEY ASSIGNMENT

Date	31-05-2018	Our Ref No. D18004332MFSH
Accident Date	28-05-2018	Claim Type. Third Party
Insured Vehicle	SHA2500K	Third Party Vehicle. SLK5924B
Survey Location	BLK 14 #01-410/412 DEFU LANE 10	
Contact Person.	JOUIS SEOW	
Contact No.	62898126/ 0	Fax No. 62870590
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	JIN AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/240937)



PRI Documents



Close



PRI Header Details

Claim No	D18004332MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & JIN AUTO
Workshop Name	JIN AUTO SERVICES PTE LTD (Contact Person : JOUIS SEOW)	Survey Location & Contact Details	BLK 14 #01-410/412 DEFU LANE 10 Mobile: 0 , Phone: 62898126 , Fax: 62870590 EmailId: JOUIS@JINAUTO.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA2500K	TP Vehicle No	SLK5924B
PRI Recieved Date	07-06-2018 03:05:49 PM	Surveyor Appointed Date	07-06-2018 05:30:20 PM	Surveyor Accept Date	08-06-2018 0

Survey Report Upload

Surveyor Inspection Date *:	<input type="text"/>	Surveyor Report Date	08-06-2018	Upload Survey Report *:	<input type="button" value="Choose File"/>
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select Year"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

<input type="button" value="Upload Multiple Documents"/>	
File Name	Action

Surveyor Job Remarks

Remarks	<input type="text"/>	<input type="button" value="Save"/>
----------------	----------------------	-------------------------------------



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18004332MFSH

Our Ref: CS/FCI18010467/Urd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLK 5924B

Please be informed that we had conducted the inspection of the above mentioned vehicle on 19.06.2018 at the premises of M/s JIN AUTO SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ <u>6,689.92</u>
Revised Estimate Amount	: S\$ <u>2,524.69</u>
“Check” Items Amount	: S\$ <u> </u>
Market Value	: S\$ <u> </u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:

The vehicle sustained damages
at rear o/s portion.



Yours faithfully
MARCUS
Automotive Assessor

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7048J
Vehicle Details	
Vehicle No.:	SLK5924B
Vehicle to be Exported:	No
Intended De-registration Date:	19 Jun 2018
Vehicle Make:	TOYOTA
Vehicle Model:	HARRIER 2.0 PREMIUM AT AIRBAG 2WD 5DR
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	3ZRB851958
Chassis No.:	ZSU600085987
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$34,482.00
Original Registration Date:	20 Jan 2017
First Registration Date:	20 Jan 2017
Transfer Count:	0
Actual ARF Paid:	\$35,275.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Jan 2027
PARF Rebate Amount:	\$26,456.00
Intended COE Rebate Details	
COE Expiry Date:	19 Jan 2027
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$50,010.00
COE Rebate Amount:	\$39,679.00
Total Rebate Amount:	\$66,135.00

The information contained herein is correct as at 19 Jun 2018

OK

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

*Not Allowed
Take photo before work
19/6/18
3 dy.*

*L1010
P/P \$ 2524.69*

DATE: 8/6/2018

M/S FIRST CAPITAL INSURANCE

DATE OF ACCIDEN :28/5/18

DEAR SIR / MADAM

ESTIMATE REPAIR COST FOR SLK5924B

TO SUPPLY :

NO	QTY	DESCRIPTION	LIST PRICE
1	1 PC	TAILGATE	2 \$ 1,806.25 X
2	1 PC	TAILGATE HARRIER EMBLEM	see \$ 65.90 —
3	1 PC	TAILGATE GLASS MOULDING	11 \$ 210.35 X
4	1 PC	REAR BUMPER	D.S \$ 1,028.45 =
5	10PCS	REAR BUMPER CLIPS	see \$ 30.00 =
6	1 PC	REAR BUMPER SPONGE	7011 \$ 118.45 ✓
7	1 PC	REAR BUMPER RH SIDE RETAINER	sy \$ 110.35 =
8	1 PC	REAR BUMPER LOWER BLACK GARNISH	Grand \$ 453.10 ✓
9	1 PC	REAR RH BUMPER REFLECTOR	11 \$ 66.50 X
10	1 PC	REAR END PANEL	2 \$ 599.45 X
			\$ 4,488.80
			25% less 10% -\$ 448.88
			\$ 4,039.92

SPECIAL NETT ITEM :

11	SEALANT	1/2 \$ 80.00 X
12	REMOVE AND REFIX SENSOR	\$ 80.00 50
13	REMOVE AND REAR WINDSCREEN	11 \$ 120.00 X
14	TUFF COAT	11 \$ 120.00 X
15	TO REMOVE AND RENEW REAR PARTS	\$ 1,100.00 600
16	WIRING CHECK (REAR)	\$ 50.00 20
17	SPRAY PAINTING (REAR)	\$ 1,100.00 500
		\$ 6,689.92

LKY Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

*P-180625
1354.69
2524.69*



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18010467/Urd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 23-07-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 2500K	Veh. Inspected	SLK 5924B
Policy No.	D-18088936MFSH	Coverage (\$)	0.00
Claim No.	D18004332MFSH	Excess (\$)	0.00
Assign From	MAY CHUA	Assign Date	07/06/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA HARRIER (A)	c.c	1986
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	ZSU600085987	Colour	WHITE
Odometer	53191	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	235/55 R18	BRIDGESTONE	7 mm
L/H Front Tyre	235/55 R18	BRIDGESTONE	7 mm
R/H Rear Tyre	235/55 R18	BRIDGESTONE	7 mm
L/H Rear Tyre	235/55 R18	BRIDGESTONE	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	28/05/2018	Inspection Date	19/06/2018
Survey held at	JIN AUTO SERVICES PTE LTD BLK 14 DEFU LANE 10 #01-412 SINGAPORE 539195		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 5924B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAILGATE	TO REPAIR SEE LABOUR	1,806.25	-
1	TAILGATE HARRIER EMBLEM	NECESSARY	65.90	65.90
1	TAILGATE GLASS MOULDING	NOT NECESSARY	210.35	-
1	REAR BUMPER	DISTORTED	1,028.45	1,028.45
10	REAR BUMPER CLIPS	NECESSARY	30.00	30.00
1	REAR BUMPER SPONGE	TORN	118.45	118.45
1	REAR BUMPER RH SIDE RETAINER	BENT	110.35	110.35
1	REAR BUMPER LOWER BLACK GARNISH	GRAZED	453.10	453.10
1	REAR RH BUMPER REFLECTOR	NOT NECESSARY	66.50	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	599.45	-
	LESS 10% DISCOUNT		-448.88	-
	LESS 25% DISCOUNT		-	-451.56
			4,039.92	1,354.69
	SPECIAL NETT ITEMS			
1	SEALANT (SN)	NOT NECESSARY	80.00	-
			80.00	-
	LABOUR			
	REMOVE AND REFIX SENSOR.		80.00	50.00
	REMOVE AND REAR WINDSCREEN.	NOT NECESSARY	120.00	-
	TUFF COAT.	NOT NECESSARY	120.00	-
	TO REMOVE AND RENEW REAR PARTS.INCLUSIVE OF THE REPAIR OF TAILGATE AND REAR END PANEL.		1,100.00	600.00
	WIRING CHECK (REAR).		50.00	20.00
	SPRAY PAINTING (REAR).		1,100.00	500.00
	-		-	-
	-		-	-
	-		-	-
			2,570.00	1,170.00
	GRAND TOTAL		6,689.92	2,524.69



RECOMMENDED COST OF REPAIRS			2,524.69
-----------------------------	--	--	-----------------

Report Ref No. CS/FCI18010467/Urd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.