

REPAIR ESTIMATE*

VEHICLE NO : SHD 4164T

MAKE :

MODEL : HYUNDAI SONATA

Ag Asia - USum

DATE 6/7/2018

TS

LKK - Kalvin

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Radiator Grille U Moulding /			\$ 108.90
	Front Bumper Cover /			\$ 538.80
	Front Bumper Sponge ?			\$ 136.30
	Front Bumper Bracket Top (RH) ?			\$ 22.40
	Front Bumper Protector (RH) x repair			\$ 29.20
	Front Bumper Bracket (RH) ?			\$ 20.10
	Headlamp Support Panel Assy (RH) ?			\$ 1,023.00
	Headlamp (RH) /			\$ 797.90
	Front Fender (RH) /			\$ 593.00
	Front Fender Shield (RH) ?			\$ 86.00
	Front Wheel Hub Cap (RH) X			\$ 145.00
	SUB TOTAL			\$ 3,500.60
	LESS 20%			\$ 700.12
	DISCOUNTED TOTAL			\$ 2,800.48
	Front Fender Advertisement Logo (RH) /			\$ 100.00
				Nett
				\$ 100.00
	Labour Charge			
	Panel Beating			\$ 1,000.00 ⁴⁰⁰
	Spray Painting Charge			\$ 750.00 ⁴⁰⁰
	Wiring Charge			\$ 50.00 ²⁰
	Tuff Kote			\$ 50.00 ²⁰
	FRT Wheel Alignment			\$ 80.00 X
	Remove/Refix Aircon & Refill Gas			\$ 150.00 X
	TOTAL LABOUR			\$ 2,080.00
	ESTIMATE TOTAL			\$ 4,980.48

Kalvin LKK
 // 7/6/18 1340hrs
 3 Dpy.
 US
 After Repair p LKK

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.