

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATIONGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer	: EQ INSURANCE COMPANY LTD 5 MAXWELL ROAD #17-00 TOWER BLK MND BUILDING SINGAPORE 069110	Document No.	: SQT18002346	Page	1
Registration No	: SJH4586P	Date	: 6. Jun 2018		
Chassis No	: SJH4586P	Customer No.	: WZE011		
Model	: CIVIC TYPE R / FD2-1403138	Svc Advisor	: JASON HENG		
Owner's Name	: RANDELL GOON WEI FATT	Engine No	:		
Ins Policy No.	:	Date Time	: 6. Jun 2018 6:27:13 PM		
Date of Accident	:	Surveyor Name	:		
		Survey Date	:		
		Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	THIRD PARTY CLAIMS (J/NO:) OWNER: RANDELL GOON WEI FATT OWNER INSURER: TOKIO MARINE INSURANCE ACC DATE: 1/6/18 SURVEYED BY: DATE: TP INSURER: EQ INSURANCE COMPANY LTD TP VEH: GBE3505A						
71501-SNW-000ZC	FACE RR BUMPER ✓CRK	1	1042.60	25	781.95	54.74	836.69
71503-SNW-000ZA	FACE RR LWR BUMPER ?	1	244.30	25	183.22	12.83	196.05
71504-SNW-000ZA	FACE RR LWR BUMPER ?	1	342.50	25	256.87	17.98	274.85
71505-SNW-000ZA	FACE RR LWR BUMPER ?	1	119.10	25	89.32	6.25	95.57
71593-SNA-A01	SPACERR.RR.BUMPER SIDE ✓NEC	1	15.30	25	11.47	0.80	12.27
71598-SNA-A01	SPACERL RR BPR SIDE ✓NEC	1	15.30	25	11.47	0.80	12.27
91503-SZ3-003	CLIP ABUMPER ✓NEC	10	3.90	25	29.25	2.05	31.30
	Sum Item				1363.55	95.45	1,459.00
BOSUN	SUNDRIES	1	100.00 ✕		100.00	7.00	107.00
BKBU02R	REMOVE & RENEW RR BUMPER.	1	1200.00 1120		1200.00	84.00	1284.00
BP01R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (1P)	1	900.00 450		900.00	63.00	963.00
	Sum Labor				2200.00	154.00	2,354.00

Survey By _____
 Date & Time _____
 Excess _____
 Status _____
 Signature _____

Total Amount 3,563.55 249.45 3,813.00

Total (Inclusive of GST) 3,813.00

Printed on 6/6/2018 8:01:10 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

Sathya Sew
14/6/2018
98072012

- Part by part repair
 - Question mark item photo
 - Photo before paint.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2 days