

INS. CASE OWNER:

CL

CC 4, Asm 180

10481, K1ha39

LKK:  
IDAC:

50623

Surveyor:

KAWIN

DOI:

ASSIGNMENT

8/6/18

Date / Time:

8/6/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKS 86726

Name of Insured:

Cheong Tin Peng

Insured Tel No.:

HP:

Excess Sec II :\$5

D.O.A.:

6/6/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

MR. 13340011 B. ABOM UNMAP

Driver Tel No.:

8444624

(V/L) (YES / NO)

Claim No.:

S8M00J2N

Policy No.:

GA 36 xpb

Make / Model:

Suzuki Wagon

Place of Accident:

Kragang St 51

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:

CANE

Kragang



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

17/10  
2/11

11/07/17 - X: SKS 86726 - X  
 - FINISHED  
 - ORIGINAL TP LOO IN.  
 - OLD TP FRIENDS. ASK FRIENDS BLS

26/06/18 @ 2N

GROUP TO OLD. BUSY AT THE WORKSHOP.  
 CALL OI. WORKING WORKSHOP. MUE REPAIRING.  
 OLD REPAIR-EMBED TP. SEND LETTER &  
 BULK TO OI.

04/09/18  
12/09/18

SEND 1ST OFFER TO TP.  
 RECEIVED ORIG. DV. TP ACCEPTED OFFER.  
 IN GOOD IN ORDER.  
 TO CLOSE.

RECEIVED 12 SEP 2018

STAGE

DATE / PIC

Non-Reporting Itr (1st)

Non-Reporting Itr (2nd)

Non-Reporting Itr (Final)

Notification Itr (if non-pickup)

Call OI

After call Itr to OI: 26/06/18 - vic

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

4/6

Sent By:

JH

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

LIS

SS 3,180.00 (3 days) Reduction: 73 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

04/09/18

Confirm with:

WIKI

Email ☒ Call ☐

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost: (w/IGOT)

SS

3,540.30

Loss of Rental (LOR):

SS

346.40

(5 days)

X 4119.28

Loss of Use (LOU):

SS

250.00

(50 x 5 days)

Loss of Income (LOI):

SS

-

(5 x days)

LOR only ☐ LOU only ☐

LOR + LOU

☐

LOR + LOI

☒

[Tick only one]

GIA/LTA Search

SS

7.49

Medical:

SS

-

Disbursement:

SS

-

Legal Cost

SS

-

(e.g. Tow/Independent)

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$380.00

Total:

SS

4,224.39

Global Sum SS:

4,200.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

SS

4,200.00

Name 1:

COMFORTABLE ENGINEERING PTE LTD

Payee 2: (Strike if N.A.)

SS

-

Name 2:

-

Payee 3: (Strike if N.A.)

SS

-

Name 3:

-

CHARTER

Kalvin

REF:

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

insured \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No. \_\_\_\_\_

SH137605 Yr Regn: 14 Aug 201x

Type: M.Car / M.Cycle / Bus / Van / Lorry / T/ Prime Mover /

Truck / Trailer or

Make: \_\_\_\_\_

Hyundai 240

G.C

1685

Colour

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

403679

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: \_\_\_\_\_

KMHLDK14AB4052726

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / Rim or

Tyre Size: F: \_\_\_\_\_

R: \_\_\_\_\_

205/60R6

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Wetplate

Front

Rear

R/Bal.

2

mm

R/Bal.

2

mm

L/Bal.

2

mm

L/Bal.

2

mm

D.O.A.

6/6/18

D.O.I.

8/6/18

Survey held at

CDHE (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

13/6/18

Sub 428 3150 / 324

(2200: 8 B. 603.90 / 73%)

AA  
4

Date/Time. File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time. File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) 8 + RS. SI

) Photos

) Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

Report Format :



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |  |                             |            |   |
|--|--|-----------------------------|------------|---|
| AXA INSURANCE PTE LTD  |  | Ref : CC4/ASM18010481/K1ha3 |            |   |
| 8 SHENTON WAY #24-01<br>AXA TOWERSINGAPORE 068811  |  | Date : 08-06-2018           |            |  |
|  |  | Code : ASM                  |            |   |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>  |  |                             |            |   |
| Insured Veh.   | SKS 8672C  | Veh. Inspected              | SHC 3760J  |   |
| Policy No.   |  | Coverage (\$)               | 0.00       |   |
| Claim No.  |  | Excess (\$)                 | 0.00       |   |
| Assign From  |  | Assign Date                 | 08/06/2018 |   |
| <b>2. Vehicle Particulars &amp; Condition</b>  |  |                             |            |   |
| Make & Model   |  | c.c                         | 0          |   |
| Engine No.   | HIDDEN   | Year of Reg.                |            |   |
| Chassis No.  |  | Colour                      |            |   |
| Odometer   | -  | Steering                    |            |   |
| Brakes   |  | Modification                |            |   |
| General  |  |                             |            |   |
| <b>3. Conditions of Tyres</b>  |  |                             |            |   |
|  | Size   | Make                        | Balance    |   |
| R/H Front Tyre   |  |                             | mm         |   |
| L/H Front Tyre   |  |                             | mm         |   |
| R/H Rear Tyre  |  |                             | mm         |   |
| L/H Rear Tyre  |  |                             | mm         |   |
| <b>4. Description of Damages</b>   |  |                             |            |   |
|  |  |                             |            |   |
| <b>5. General Information</b>  |  |                             |            |   |
| Accident Date  | 06/06/2018   | Inspection Date             | 08/06/2018 |   |
| Survey held at   | COMFORTDELGRO ENGINEERING PTE LTD<br>59 LOYANG DRIVE<br>SINGAPORE 508969 |                             |            |   |
| <b>5a. Remarks</b>   |  |                             |            |   |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |                             |            |   |

A member of COMFORTDELGRO

Date/Time: 07.06.2018 17:36 Page : 1

Team: ARC Repair TP(CLSO)1 JOB CARD Sales Order: JC NO305170925

|                                   |                   |                      |
|-----------------------------------|-------------------|----------------------|
| STOMER                            | REGN NO           | MILEAGE              |
| MS COMFORT TRANSPORTATION PTE LTD | SHC3760J          |                      |
| STOMER NO 7010045                 | MAKE              | FUEL                 |
| RESS 383 SIN MING DRIVE           | HYUNDAI           | E 1/2 F              |
| Singapore SINGAPORE 575717        | MODEL             | DATE/TIME IN         |
| 65508755 (P) (O)                  | I-40              | 06.06.2018 22:40     |
|                                   | YR OF MANU        | TARGET DATE          |
|                                   | 14.08.2014        |                      |
|                                   | CHASSIS CODE      | COMPLETION DATE/TIME |
|                                   | KMHLB41UMEU057726 |                      |

COUNT CARD NO.

JOB DESCRIPTION

Accident Date: 06.06.2018  
NATURE: 3P 06.06.2018

| S/NO | LABOR CODE | DESCRIPTION      |
|------|------------|------------------|
|      | AXA-       | taxi flex damage |

CHECKED & PASSED OUT BY:

SERVICE ADVISOR CUSTOMER'S SIGNATURE

|   |                              |
|---|------------------------------|
| Acknowledgement Slip                          | Exit Pass                    |
| Vehicle No.: SHC3760J LARRY                   | Vehicle No.: SHC3760J        |
| Signature/Date                                | Signature/Date               |
| Name of Service Advisor                       | Name of Service Advisor      |
| Date  | Date                         |
| returned to Service Reception upon collection | To be kept by Security Guard |

## REPAIR ESTIMATE\*

MAKE :

MODE L

DATE 8/6/2018 9:29

DOA: 06-06-18

Larry Ng

SHC 3760J

| Q-ty   | Parts Description/ Labour              | Type | Unit Price | Amount                                |
|--|--|------|------------|---------------------------------------|
|  | <b>Labour Charge</b>                   |      |            |                                       |
|  | Panel Beating                          |      |            | \$ <del>1,000.00</del> <sup>600</sup> |
|  | Spray Painting Charge                  |      |            | \$ <del>1,000.00</del> <sup>600</sup> |
|  | Wiring Charge                          |      |            | \$ <del>50.00</del> <sup>20</sup>     |
|  | Tuff Kote                              |      |            | \$ <del>50.00</del> <sup>X 2</sup>    |
|  | Remove/Refix Cushion & Upholstery Rear |      |            | \$ <del>150.00</del> <sup>50</sup>    |
|  | Remove/Refix Rear Windscreen Glass     |      |            | \$ <del>120.00</del> <sup>X 2</sup>   |
|  | Remove/Refix Reverse Sensor            |      |            | \$ <del>120.00</del> <sup>70</sup>    |
|  | Remove/Refix Exhaust Pipe              |      |            | \$ <del>150.00</del> <sup>50</sup>    |
|  | <b>TOTAL LABOUR</b>                    |      |            | <b>\$ 2,640.00</b>                    |
|  | <b>ESTIMATE TOTAL</b>                  |      |            | <b>\$ 11,833.98</b>                   |
| <p><i>Kabwa 11/11/14</i></p> <p><i>U 8/6/18 1315hrs.</i></p> <p><i>3 Dr.</i></p> <p><i>4/5</i></p> <p><i>After Repair photo</i></p>  |  |      |            |                                       |
| <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>• To resurvey before/after spray painting</li> <li>• To display damaged part(s) during resurvey</li> <li>• Parts prices are subject to confirmation</li> <li>• Third party survey is on a "Without Prejudice" basis</li> <li>• No illegal modification is allowed</li> <li>• Supplementary bill(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p> |  |      |            |                                       |
| <p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>  |  |      |            |                                       |

Larry Ng

## REPAIR ESTIMATE\*

**MODEL : HYUNDAI i40**

DOA: 06.06.18

| Qty | Parts Description/ Labour                   | Type | Unit Price | Amount              |
|-----|---|------|------------|---------------------|
|     | Boot Lid X                                  |      |            | \$ 1,681.40         |
|     | Boot Lid Lock Upper X                       |      |            | \$ 137.90           |
|     | Boot Lid Lock Lower X                       |      |            | \$ 31.70            |
|     | Boot Lid 'H' Emblem +                       |      |            | \$ 27.20            |
|     | Boot Lid CRDI Plate /                       |      |            | \$ 41.00            |
|     | Boot Lid Lamp (RH) /                        |      |            | \$ 556.80           |
|     | Bootlid Moulding X                          |      |            | \$ 85.00            |
|     | Bootlid i40 Emblem /                        |      |            | \$ 41.00            |
|     | Bootlid Lower Garnish X <i>Agd</i>          |      |            | \$ 398.00           |
|     | Rear Bumper /                               |      |            | \$ 603.60           |
|     | Rear Bumper Reinforcement ?                 |      |            | \$ 504.35           |
|     | Rear Bumper Reinforcement Bracket (LH/RH) ? | \$   | 180.00     | \$ 360.00           |
|     | Rear Bumper Side Bracket ?                  | \$   | 49.00      | \$ 98.00            |
|     | Rear Bumper Clips /                         |      |            | \$ 22.00            |
|     | Rear Bumper Sponge ?                        |      |            | \$ 143.40           |
|     | Rear Bumper Under Cover /                   |      |            | \$ 225.00           |
|     | Rear Bumper Reflector Lamp (RH) /           |      |            | \$ 32.00            |
|     | Tail Lamp (RH) /                            |      |            | \$ 565.60           |
|     | Rear Panel X                                |      |            | \$ 592.30           |
|     | Rear Panel Garnish X                        |      |            | \$ 57.70            |
|     | Rear Panel Lower Panel X <i>Agd</i>         |      |            | \$ 495.50           |
|     | Exhaust Pipe Insulator ?                    |      |            | \$ 58.55            |
|     | Exhaust Silencer /                          |      |            | \$ 954.00           |
|     | Exhaust Pipe Hanger ?                       |      |            | \$ 58.55            |
|     | Exhaust Pipe Centre ?                       |      |            | \$ 1,150.30         |
|     | Rear Fender (RH) X <i>Agd</i>               |      |            | \$ 2,020.10         |
|     | Rear Fender Inner Lining (RH) X             |      |            | \$ 164.40           |
|     | Rear Windscreen Moulding X                  |      |            | \$ 60.00            |
|     | <b>SUB TOTAL</b>                            |      |            | <b>\$ 11,165.35</b> |
|     | <b>LESS 20%</b>                             |      |            | <b>\$ 2,233.07</b>  |
|     | <b>DISCOUNTED TOTAL</b>                     |      |            | <b>\$ 8,932.28</b>  |
|     | Boot Lid Comfort Logo & Tel No. Sticker X   |      |            | \$ 30.00            |
|     | Rear Bumper Reverse Sensor /                |      |            | \$ 135.70           |
|     | Rear Bumper Rubber Mat /                    |      |            | \$ 50.00            |
|     | Rear Windscreen Sealant X                   |      |            | \$ 46.00            |
|     |   |      |            | <b>\$ 261.70</b>    |

Larry Ng

| Qty  | Parts Description/ Labour              | Type | Unit Price | Amount                     |
|--|--|------|------------|----------------------------|
|  | <b>Labour Charge</b>                   |      |            | <del>600</del>             |
|  | Panel Beating                          |      |            | \$ <del>1,000.00</del>     |
|  | Spray Painting Charge                  |      |            | \$ <del>1,000.00</del> 600 |
|  | Wiring Charge                          |      |            | \$ <del>50.00</del> 20     |
|  | Tuff Kote                              |      |            | \$ <del>50.00</del> X      |
|  | Remove/Refix Cushion & Upholstery Rear |      |            | \$ <del>150.00</del> 50    |
|  | Remove/Refix Rear Windscreen Glass     |      |            | \$ <del>120.00</del> X     |
|  | Remove/Refix Reverse Sensor            |      |            | \$ <del>120.00</del> 30    |
|  | Remove/Refix Exhaust Pipe              |      |            | \$ <del>150.00</del> 50    |
|  | <b>TOTAL LABOUR</b>                    |      |            | <b>\$ 2,640.00</b>         |
|  | <b>ESTIMATE TOTAL</b>                  |      |            | <b>\$ 11,833.98</b>        |
| <p><i>Kalua illele</i><br/> <i>U 8/6/18 1315hrs.</i><br/> <i>3 hrs.</i><br/> <i>4/5</i><br/> <i>After Repair photo</i></p>   |  |      |            |                            |
| <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>• To resurvey before/after spray painting</li> <li>• To display damaged parts during resurvey</li> <li>• Parts prices are subject to confirmation</li> <li>• Third party claims is on a "Without Prejudice" basis</li> <li>• No illegal mod (sponges) is allowed</li> <li>• Supplementary material must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer<br/> Signature:<br/> Date:</p> |  |      |            |                            |
| <p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>  |  |      |            |                            |

Larry Ng



Auto  
Consultants  
Pte Ltd

Company Registration No: 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

## Immediate Advice

To : AXA Insurance Pte Ltd

Date: 11/6/2018

### Survey Details:

|                     |             |
|---------------------|-------------|
| Date of loss        | 6-Jun-18    |
| Date of appointment | 8-Jun-18    |
| Date of survey      | 8-Jun-18    |
| Location of survey  | CDGE Loyang |

### Vehicle Details:

|                      |                      |
|----------------------|----------------------|
| Claim Type:          | THIRD PARTY CLAIM    |
| Vehicle number       | SHC 3760J            |
| Make and Model       | HYUNDAI I40 - 1685cc |
| Date of registration | 14-Aug-14            |
| Excess               |                      |
| Market Value         | \$ -                 |
| Parf Rebate          | \$ -                 |
| Nett Loss            | \$ -                 |

### Repair details:

|                  |              |
|------------------|--------------|
| Initial Estimate | \$ 11,833.98 |
|------------------|--------------|

### Proposed/Revised repair cost:

|                         |             |
|-------------------------|-------------|
| Parts                   | \$ 2,618.50 |
| Check items (estimate)  | \$ 1,898.52 |
| Labour                  | \$ 1,350.00 |
| Total                   | \$ 5,867.02 |
| Lump Sum(if applicable) | \$ -        |

|                           |               |
|---------------------------|---------------|
| Number of days for repair | <u>3 days</u> |
|---------------------------|---------------|

Our Ref : T 0618/ SHC3760J /WT(st)

Your Ref :

Date : 18-Jun-18

CDGE Taxi Claims Dept  
59 Loyang Drive 4th Flr  
Singapore 508969

ComfortDelGro Engineering Pte Ltd  
205 Braddell Road Singapore 579701

Mainline +65 6383 6280  
Facsimile +65 6280 9755

www.cdge.com.sg

Company Registration No: 198603470

**AXA Insurance Pte Ltd**  
**8 Shenton Way**  
**#24-01, AXA Tower**  
**Singapore 068811**

**Attn : Motor Claims Department**

**WITHOUT PREJUDICE**

Dear Sir

**ACCIDENT INVOLVING OUR TAXI SHC3760J YOUR INSURED SKS8672C**  
**AND OTHER ON 06.06.18**

We are the authorised repair workshop for Comfort Transportation Pte Ltd, the owner of motor vehicle No : **SHC3760J** which was involved in the captioned accident with your insured vehicle. The vehicle owner and the taxi driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving **SKS8672C** we are submitting these claim for your consideration on behalf of the claimants.

## TAXI OWNER'S CLAIM

|                    |   |                    |
|--------------------|---|--------------------|
| 1                  | Cost of Repair                              | \$ 3,370.50        |
| 2                  | 5.5 days Loss of Rental @ \$ 119.28 per day | \$ 656.04          |
| 3                  | Survey Report Fees (Surveyed by M/s LKK)    | \$ -               |
| 4                  | GIA / LTA Search Fee                        | \$ 7.49            |
| 5                  | GIA / Police Report Fees                    | \$ -               |
| 6                  | Towing / Medical / Transportation Fees      | \$ -               |
| <b>Sub Total :</b> |   | <b>\$ 4,034.03</b> |

## HIRER'S CLAIM

|                      |   |                    |
|----------------------|---|--------------------|
| 7                    | 5.5 days Loss of Income @ \$ 80.00 per days | \$ 440.00          |
| <b>Total Claims:</b> |   | <b>\$ 4,474.03</b> |

We enclose herewith the following documents to support the claims: -

- a) Original repair bill and photocopies of photographs 8 pcs
- b) LTA search slip/s of : SKS8672C
- c) GIA / Police report/s of : SHC3760J
- d) Letter of authority from owner / hirer / operator
  - ( X ) Photocopy/s of Accident Scene Photo/s ( ) Traffic Compound ( ) PIR
  - ( ) Witness statement/s ( x ) Rental Rate letter ( x ) Downtime/Mileage record

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully

*William Tan*

Deputy Manager

CDGE Claims Department

Tel: 6214 8737 Fax: 6214 1843 Email: williamtan@cdge.com.sg

This is a computer generated letter. No signature is required.

A member of

**COMFORTDELGRO**





Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

26 JUNE 2018

CHEONG TIN PENG  
BLOCK 1010 BUKIT MERAH LANE 3  
#01-115  
SINGAPORE 159724

By Post and By Email

Dear Sir/Madam,

OUR REF : CC4/ASM18010481/K1ha3  
YOUR REF : SKS 8672C  
ACCIDENT INVOLVING SKS 8672C AND SHC 3760J ALONG HOUGANG STREET 51  
ON 06.06.2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third-party claim against your policy.

We have received a claim from M/s COMFORTDELGRO ENGINEERING PTE LTD, acting on behalf of the owner of SHC 3760J against your motor insurance policy.

Based on the accident report, accident scenario and available evidence at hand, it was reported that your vehicle had collided to the Third-Party vehicle SHC 3760J. As such, liability may not be to your favour.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) within 7 days from the date of this letter **if not provided at AXA's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com).

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,



Vic Alpeh  
Case Handler  
DID: 6841 2096  
FAX: 6741 4108  
Email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)

c.c. AXA Insurance Pte Ltd (AXA)  
(Motor Claims Dept)

[thccser@gmail.com](mailto:thccser@gmail.com) / [m.izzddin425@gmail.com](mailto:m.izzddin425@gmail.com)  
(Email)

## Vic (LKKAUTO)

---

**From:** Vic (LKKAUTO)  
**Sent:** Tuesday, 26 June, 2018 12:11 PM  
**To:** thccser@gmail.com  
**Cc:** m.izzddin425@gmail.com; Admin A; Vic (LKKAUTO)  
**Subject:** YOUR REF: SKS 8672C\_ACCIDENT INVOLVING SKS 8672C AND SHC 3760J ALONG HOUGANG STREET 51 ON 06.06.2018



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

26 JUNE 2018

**CHEONG TIN PENG**  
**BLOCK 1010 BUKIT MERAH LANE 3**  
**#01-115**  
**SINGAPORE 159724**

**By Post and By Email**

Dear Sir/Madam,

**OUR REF : CC4/ASM18010481/K1ha3**  
**YOUR REF : SKS 8672C**  
**ACCIDENT INVOLVING SKS 8672C AND SHC 3760J ALONG HOUGANG STREET 51 ON 06.06.2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third-party claim against your policy.

We have received a claim from M/s COMFORTDELGRO ENGINEERING PTE LTD, acting on behalf of the owner of SHC 3760J against your motor insurance policy.

Based on the accident report, accident scenario and available evidence at hand, it was reported that your vehicle had collided to the Third-Party vehicle SHC 3760J. As such, liability may not be to your favour.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) within 7 days from the date of this letter if not provided at AXA's reporting centre. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (if any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)

- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com).

Please quote the claim reference when you contact us that we can assist you more effectively.

Best Regards,

**Vic Alpeh** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2096 | email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

 Auto Consultants Pte Ltd *Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

## LETTER OF AUTHORISATION

(NAF / PAF)

ACCIDENT INVOLVING  
ALONG40 SHC3760J , SKS8672C  
HOUGANG STREET 61 TWDS HOUGANG AVE 4.  
(INFRONT OF BLOCK 554)

ON 06-Jun-18 21:40

I / We

MOHAMED AMIR BIN MO... (Hirer) NRIC No.: S7211933I

and/or

(Relief) NRIC No.:

Taxi Number

SHC3760J

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
3. To sign Discharge Voucher on my/our behalf.
4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of "ComfortDelGro Engineering Pte Ltd".

Date

07-Jun-2018

Name of Hirer

MOHAMED AMIR BIN MOHAMED ALI

Hirer NRIC

S7211933I

Signature :



Address

193 PASIR RIS STREET 12 #09-64  
510193

Contact No.

98296668



redefining / insurance

CLAIM REF : S8M00JZN  
INSURED : CHEONG TIN PENG

**DISCHARGE VOUCHER**

We, **COMFORTDELGRO ENGINEERING PTE LTD** confirm that by letter of authorisation dated **07/06/2018**, we are authorised to and do hereby give this discharge for ourselves and on behalf of **COMFORT TRANSPORTATION PTE LTD** and the Hirer, **MOHAMED AMIR BIN MOHAMED ALI** of vehicle no. **SHC 3760J**.

Now we **COMFORTDELGRO ENGINEERING PTE LTD** for ourselves and the said Hirer and the driver jointly and severally:-

- agree to accept the sum of Singapore Dollars **FOUR THOUSAND TWO HUNDRED** only (**S\$4,200.00**) in the aggregate in full and final settlement of all claims of whatever kind including damages for personal injuries and/or damage to property that all and any of us may have against **AXA INSURANCE PTE LTD** and/or their Insured and/or the driver of vehicle no **SKS 8672C** arising out of an accident with **SHC 3760J** on **06/06/2018**.
- declare that **AXA INSURANCE PTE LTD** and/or their Insured and/or the driver of the Insured vehicle shall not be liable for any further claim(s) whatsoever or howsoever present or future that any of us may have against **AXA INSURANCE PTE LTD** and/or their Insured and/or the driver of vehicle no. **SKS 8672C** arising directly/indirectly as a consequence of the accident and hereby give our full and final discharge.
- We hereby declare that I/we am/are the person(s) entitled to receive the above settlement and hereby undertake to indemnify **AXA INSURANCE PTE LTD** against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made in favour of **COMFORTDELGRO ENGINEERING PTE LTD** is made without any admission of liability whatsoever on the part of **AXA INSURANCE PTE LTD** and/or their Insured and/or the driver of vehicle no. **SKS 8672C**.

Dated this 4<sup>th</sup> day of September 2018

Signed by [Signature]  
(AUTHORISED SIGNATORY)

Company Stamp COMFORTDELGRO ENGINEERING PTE LTD  
33 LUYANG DRIVE  
SINGAPORE 730003

Witness : [Signature]

Name : CLAIM DEPARTMENT

I/C No : COMFORTDELGRO ENGINEERING PTE LTD

Address : 33 LUYANG DRIVE  
SINGAPORE 730003

Please forward your cheque made payable to:  
**COMFORTDELGRO ENGINEERING PTE LTD**

"The contents of this document apply to vehicle damages only  
All personal injuries and damages arising therefrom are excluded  
from the ambit and application of this document"

AXA Insurance Pte Ltd (Company Reg. No. 199903512M)  
8 Shenton Way, #24-01 AXA Tower, Singapore 068811  
Customer Centre #B1-01  
Tel: +65 6880 4888 Fax: +65 6338 2522 Website: www.axa.com.sg

Our Ref: CT18060214

Date: 14 June 2018



**TO WHOM IT MAY CONCERN**

Dear Sir/Madam

ACCIDENT ON 06/06/2018 @ 21:40 hrs  
ALONG HOUGANG STREET 61 TWDS HOUGANG AVE 4.  
INVOLVING SKS8672C

We refer to the above-mentioned accident and wish to inform that **Comfort Transportation Pte Ltd** is the registered owner of the taxi bearing vehicle registration number **SHC3760J** (the "Taxi"). The Taxi was hired to **MOHAMED AMIR BIN MOHAMED ALI IC NO S7211933I** a registered hirer-operator of **Comfort Transportation Pte Ltd** at the time of occurrence of the aforementioned accident at a rental rate **\$119.28** per day (inclusive of GST).

Please be advised that the Taxi was insured with **MS First Capital Insurance Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay  
Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.

SAC 37603

| DATE      | NAME OF DRIVER | MILEAGE READING |   |   |   |   | MILEAGE TRAVELLED (KM) | HOURS OPERATED (TIME) |      |
|-----------|----------------|-----------------|---|---|---|---|------------------------|-----------------------|------|
|           |                | 3               | 9 | 0 | 1 | 5 |                        | FROM                  | TO   |
| 13/4-16/4 | Amir           | 3               | 9 | 0 | 1 | 5 | 4                      | 1500                  | 0140 |
| 16/4/18   | Amir           | 3               | 9 | 0 | 1 | 6 | 8                      | 0905                  | 0940 |
| 16/4-23/4 | Amir           | 3               | 9 | 2 | 1 | 4 | 0                      | 1530                  | 0045 |
| 23/4/18   | Amir           | 3               | 9 | 2 | 2 | 3 | 5                      | 0800                  | 1200 |
| 23/4-25/4 | Amir           | 3               | 9 | 2 | 9 | 0 | 2                      | 1300                  | 0200 |
| 25/4      | Amir           | 3               | 9 | 3 | 0 | 2 | 0                      | 0800                  | 1400 |
| 25/4-23/5 | Amir           | 3               | 9 | 9 | 7 | 6 | 2                      | 1500                  | 0330 |
| 23/5/18   | Amir           | 3               | 9 | 9 | 8 | 0 | 0                      | 0700                  | 1000 |
| 23/5      | Amir           |                 |   |   |   |   |                        | 1300                  |      |
| 06.06.18  | ACCIDENT       |                 |   |   |   |   |                        | 2240                  | -    |
| 11.06.18  | Repair         |                 |   |   |   |   |                        | -                     | 1700 |

ATED (TIME)

TO

2100

05:55 AM

2135

0030

735 PM

0030

2030

2245

2245

0030

**Enquire Vehicle Insurer**

| Vehicle No. | Incident Date/Time     | Search Status | Insurance Company Code | Insurance Company Name |
|-------------|------------------------|---------------|------------------------|------------------------|
| SKS8672C    | 06 Jun 2018 / 21:40:00 | Successful    | A12                    | AXA INSURANCE PTE LTD  |

Previous OK

Service Request Details

Claim

SBM0012N

Reference

CC4/ASM18010481/KTha3a2

Loss Date

6 June 2018

Request Date

8 June 2018

Due Date

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Vehicle Information

Incident Vehicle Registration #

S4C37801

Make

TPVO HYUNDAI

Model

I40

Service Address

Primary Contact/Insured

CHEONG TIN PENG

1010 BUNGT MERAH LANE 3, #01-115, 159724, Singapore

THCCSER@GMAIL.COM

Claim Handler

LOH Cynthia

6548804843

cynthia.loh@axa.com.sg

Actions















Next Step

Wait for Approve Invoice

Send Reminder

Additional Instructions

| Messages                    | Invoices | History | Documents                  | Assessment                        | Metrics | Notes             |
|-----------------------------|----------|---------|----------------------------|-----------------------------------|---------|-------------------|
| Document Type               |          |         | Document SubType           |                                   |         |                   |
| <div>Upload Documents</div> |          |         |                            |                                   |         |                   |
| NAME                        |          | TYPE    | SUB-TYPE                   | AUTHOR                            |         | DATE UPLOADED     |
| LKKInvoice1 (3).pdf         |          | Invoice | Surveyor/ Assessor expense | LKK AUTO CONSULTANTS PTE LTD (TP) |         | 20 September 2018 |













| NAME   | TYPE                          | SUB-TYPE                            | AUTHOR                               | DATE<br>UPLOADED     |
|--|-------------------------------|-------------------------------------|--------------------------------------|----------------------|
|  LKKInvoice1 (3).pdf            | Invoice                       | Surveyor/ Assessor<br>expense       | LKK AUTO CONSULTANTS PTE<br>LTD (TP) | 20 September<br>2018 |
|  LKKInvoice1 (3).pdf            | Invoice                       | Surveyor/ Assessor<br>expense       | LKK AUTO CONSULTANTS PTE<br>LTD (TP) | 20 September<br>2018 |
|  payment breakdown94C 37601.pdf | Forms / Claim<br>Documents    | Others                              | LKK AUTO CONSULTANTS PTE<br>LTD (TP) | 20 September<br>2018 |
|  RENTAL RECEIPT.pdf             | Forms / Claim<br>Documents    | Others                              | LKK AUTO CONSULTANTS PTE<br>LTD (TP) | 20 September<br>2018 |
|  LTA SEARCH.pdf                 | Forms / Claim<br>Documents    | Others                              | LKK AUTO CONSULTANTS PTE<br>LTD (TP) | 20 September<br>2018 |
|  LOD.pdf                        | Forms / Claim<br>Documents    | Others                              | LKK AUTO CONSULTANTS PTE<br>LTD (TP) | 20 September<br>2018 |
|  DISCHARGE VOUCHER.pdf          | Forms / Claim<br>Documents    | Satisfaction / Discharge<br>Voucher | LKK AUTO CONSULTANTS PTE<br>LTD (TP) | 20 September<br>2018 |
|  AUTHORISATION TO ACT FORM.pdf  | Forms / Claim<br>Documents    | POA / Authority Letter              | LKK AUTO CONSULTANTS PTE<br>LTD (TP) | 20 September<br>2018 |
|  WORKSHOP INVOICE.pdf           | Invoice                       | Repairs                             | LKK AUTO CONSULTANTS PTE<br>LTD (TP) | 20 September<br>2018 |
|  AXA IA MANDATE.aha            | Reports & Statement           | Others                              | LKK AUTO CONSULTANTS PTE<br>LTD (TP) | 12 September<br>2018 |
|  TP LOD.pdf                   | Reports & Statement           | Others                              | LKK AUTO CONSULTANTS PTE<br>LTD (TP) | 4 September<br>2018  |
|  LKK REINSPECTION PHOTOS.pdf  | Reports & Statement           | Others                              | LKK AUTO CONSULTANTS PTE<br>LTD (TP) | 4 September<br>2018  |
|  LETTER TO CI.pdf             | Letters and<br>Correspondence | Others                              | LKK AUTO CONSULTANTS PTE<br>LTD (TP) | 26 June 2018         |
|  Email to CI dtd 260618.pdf   | Letters and<br>Correspondence | Others                              | LKK AUTO CONSULTANTS PTE<br>LTD (TP) | 26 June 2018         |

| NAME  | TYPE                       | SUB-TYPE             | AUTHOR                            | DATE<br>UPLOADED |
|---|----------------------------|----------------------|-----------------------------------|------------------|
|  TP ESTIMATE - MARKED.pdf                                | Reports & Statement        | Estimate / Quotation | LKK AUTO CONSULTANTS PTE LTD (TP) | 12 June 2018     |
|  LKK RESURVEY PHOTO.pdf                                  | Reports & Statement        | Others               | LKK AUTO CONSULTANTS PTE LTD (TP) | 11 June 2018     |
|  LKK SURVEY PHOTO.pdf                                    | Reports & Statement        | Others               | LKK AUTO CONSULTANTS PTE LTD (TP) | 11 June 2018     |
|  Immediate Advice.pdf                                    | Reports & Statement        | Others               | LKK AUTO CONSULTANTS PTE LTD (TP) | 11 June 2018     |
|  TP PRI RECEIVED FROM WORKSHOP WITH GIA AND ESTIMATE.mig | Letters and Correspondence | Workshop             | DHANAJ Raghav                     | 8 June 2018      |
|  SHC3760J TP GIA REPORT.PDF                              | Reports & Statement        | GIA Report           | DHANAJ Raghav                     | 8 June 2018      |
|  SK58672C INSD GIA.PDF                                   | Reports & Statement        | GIA Report           | DHANAJ Raghav                     | 8 June 2018      |

Assessment Details

| General & Workshop Details |       |           |          | Vehicle & Driver Details |  | Vehicle Condition |                        | Taxes & Ratio |           | Parts & Labour |            | Miscellaneous |                 | Summary        |        | Parts |  |
|----------------------------|-------|-----------|----------|--------------------------|--|-------------------|------------------------|---------------|-----------|----------------|------------|---------------|-----------------|----------------|--------|-------|--|
| EDIT                       | SN NO | QUAN TITY | MATERIAL | SIDE                     | PART NAME                                | PART NUMBER       | REPAIR/REPLACE (PARTS) | CONDITION     | LBT PRICE | DEPL/ BTYRS    | DISC QUNTY | SALY AGES     | PART PRICE(NET) | ACTION (PARTS) | REMOVE |       |  |
|                            |       | 1         | 1        |                          | BOOT LID                                 |                   |                        | Serviceable   | 0         | 0              | 0          | 0             | 0               | Deny           |        |       |  |
|                            |       | 2         | 1        |                          | BOOT LID LOCK UPPER                      |                   |                        | Serviceable   | 0         | 0              | 0          | 0             | 0               | Deny           |        |       |  |
|                            |       | 3         | 1        |                          | BOOT LID LOCK LOWER                      |                   |                        | Serviceable   | 0         | 0              | 0          | 0             | 0               | Deny           |        |       |  |
|                            |       | 4         | 1        |                          | BOOT LID 'H' EMBLEM                      |                   |                        | Serviceable   | 0         | 0              | 0          | 0             | 0               | Deny           |        |       |  |
|                            |       | 5         | 1        |                          | BOOT LID CRDI PLATE                      |                   |                        | Necessary     | 41        | 0              | 20         | 0             | 32.8            | Approve        |        |       |  |
|                            |       | 6         | 1        |                          | BOOT LID LAMP(RH)                        |                   |                        | Cracked       | 556.8     | 0              | 20         | 0             | 445.44          | Approve        |        |       |  |
|                            |       | 7         | 1        |                          | BOOTLID MOULDING                         |                   |                        | Serviceable   | 0         | 0              | 0          | 0             | 0               | Deny           |        |       |  |
|                            |       | 8         | 1        |                          | BOOTLID 'H0' EMBLEM                      |                   |                        | Necessary     | 41        | 0              | 20         | 0             | 32.8            | Approve        |        |       |  |
|                            |       | 9         | 1        |                          | BOOTLID LOCK GARNISH                     |                   |                        | Repair        | 0         | 0              | 0          | 0             | 0               | Deny           |        |       |  |
|                            |       | 10        | 1        |                          | REAR BUMPER                              |                   |                        | Deformed      | 603.6     | 0              | 20         | 0             | 482.88          | Approve        |        |       |  |
|                            |       | 11        | 1        |                          | REAR BUMPER REINFORCEMENT                |                   |                        | Serviceable   | 0         | 0              | 0          | 0             | 0               | Deny           |        |       |  |
|                            |       | 12        | 2        |                          | REAR BUMPER REINFORCEMENT BRACKET (L/RH) |                   |                        | Serviceable   | 0         | 0              | 0          | 0             | 0               | Deny           |        |       |  |
|                            |       | 13        | 2        |                          | REAR BUMPER SIDE BRACKET                 |                   |                        | Serviceable   | 0         | 0              | 0          | 0             | 0               | Deny           |        |       |  |
|                            |       | 14        | 1        |                          | REAR BUMPER CLIPS                        |                   |                        | Necessary     | 22        | 0              | 20         | 0             | 17.8            | Approve        |        |       |  |
|                            |       | 15        | 1        |                          | REAR BUMPER SPONGE                       |                   |                        | Serviceable   | 0         | 0              | 0          | 0             | 0               | Deny           |        |       |  |

|        | EDIT | SR NO | QUAN TITY | MATERIAL                | SIDE | PART NAME                       | PART NUMBER | REPAIR/REPLACE (PARTS) | CONDITION     | LIST PRICE | DEPR./ RTTRN% | DBSC QUANTY     | SALY AGE% | PART PRICE(NET) | ACTION (PARTS) | REMOVE |
|--------|------|-------|-----------|-------------------------|------|---------------------------------|-------------|------------------------|---------------|------------|---------------|-----------------|-----------|-----------------|----------------|--------|
|        |      | 16    | 1         |                         |      | REAR BUMPER UNDER COVER         |             |                        | Cracked       | 225        | 0             | 20              | 0         | 180             | Approve        |        |
|        |      | 17    | 1         |                         |      | REAR BUMPER REFLECTOR LAMP (RH) |             |                        | Cracked       | 32         | 0             | 20              | 0         | 25.6            | Approve        |        |
|        |      | 18    | 1         |                         |      | TAIL LAMP (RH)                  |             |                        | Cracked       | 565.6      | 0             | 20              | 0         | 452.48          | Approve        |        |
|        |      | 19    | 1         |                         |      | REAR PANEL                      |             |                        | Serviceable   | 0          | 0             | 0               | 0         | 0               | Deny           |        |
|        |      | 20    | 1         |                         |      | REAR PANEL GARNISH              |             |                        | Serviceable   | 0          | 0             | 0               | 0         | 0               | Deny           |        |
|        |      | 21    | 1         |                         |      | REAR PANEL LOWER PANEL          |             |                        | Repair        | 0          | 0             | 0               | 0         | 0               | Deny           |        |
|        |      | 22    | 1         |                         |      | EXHAUST PIPE INSULATOR          |             |                        | Serviceable   | 0          | 0             | 0               | 0         | 0               | Deny           |        |
|        |      | 23    | 1         |                         |      | EXHAUST SILENCER                |             |                        | Bent          | 954        | 0             | 20              | 0         | 763.2           | Approve        |        |
|        |      | 24    | 1         |                         |      | EXHAUST PIPE HANGER             |             |                        | Serviceable   | 0          | 0             | 0               | 0         | 0               | Deny           |        |
|        |      | 25    | 1         |                         |      | EXHAUST PIPE CENTRE             |             |                        | Repair        | 0          | 0             | 0               | 0         | 0               | Deny           |        |
|        |      | 26    | 1         |                         |      | REAR FENDER (RH)                |             |                        | Repair        | 0          | 0             | 0               | 0         | 0               | Deny           |        |
|        |      | 27    | 1         |                         |      | REAR FENDER INNER LINING (RH)   |             |                        | Serviceable   | 0          | 0             | 0               | 0         | 0               | Deny           |        |
|        |      | 28    | 1         |                         |      | REAR WINDSCREEN MOULDING        |             |                        | Serviceable   | 0          | 0             | 0               | 0         | 0               | Deny           |        |
| Labour |      |       |           |                         |      |                                 |             |                        |               |            |               |                 |           |                 |                |        |
|        | EDIT |       | SR NO     | REPAIR/REPLACE (LABOUR) |      | PART NAME                       |             | LABOUR R&R             | LABOUR REPAIR | PAINT      |               | ACTION (LABOUR) |           | COMMENT         |                | REMOVE |
|        |      |       | 1         |                         |      | PANEL BEATING                   |             | 600                    | 0             | 0          |               | Approve         |           |                 |                |        |
|        |      |       | 2         |                         |      | SPRAY PAINTING CHARGE           |             | 600                    | 0             | 0          |               | Approve         |           |                 |                |        |

| EDIT  | SIR NO | REPAIR/REPLACE (LABOUR) | PART NAME                               | LABOUR HHR | LABOUR REPAIR | PAINT | ACTION (LABOUR) | COMMENT | REMOVE  |
|---|--------|-------------------------|---|------------|---------------|-------|-----------------|---------|---|
|  | 3      |                         | WIRING CHARGE                           | 20         | 0             | 0     | Approve         |         |  |
|  | 4      |                         | TUFF KOTE                               | 0          | 0             | 0     | Deny            |         |  |
|  | 5      |                         | REMOVE /REFIX CUSHION & UPHOLSTERY REAR | 50         | 0             | 0     | Approve         |         |  |
|  | 6      |                         | REMOVE/REFIX REAR WINDSCREEN GLASS      | 0          | 0             | 0     | Deny            |         |  |
|  | 7      |                         | REMOVE /REFIX REVERSE SENSOR            | 30         | 0             | 0     | Approve         |         |  |
|  | 8      |                         | REMOVE /REFIX EXHAUST PIPE              | 50         | 0             | 0     | Approve         |         |  |

Assessment Details

General & Workshop Details    Vehicle & Driver Details    Vehicle Condition    Taxes & Rate    Parts & Labour    Miscellaneous    Summary

| EDIT | SIR NO | NAME                                   | ACTION  | AMOUNT | COMMENT       | REMOVE |
|------|--------|--|---------|--------|---------------|--------|
|      | 1      | DAYS OF REPAIR 3 DAYS                  | Approve |        |               |        |
|      | 2      | ROOF LID COMFORT LOGO & TEL NO.3TICKER | Deny    | 0      | NOT NECESSARY |        |
|      | 3      | REAR BUMPER REVERSE SENSOR             | Approve | 135.7  | SHORTED       |        |
|      | 4      | REAR BUMPER RUBBER MAT                 | Approve | 50     | NECESSARY     |        |
|      | 5      | REAR WINDSCREEN SEALANT                | Deny    | 0      | NOT NECESSARY |        |

Assessment Details

|                            |  |                          |                   |               |                |               |         |              |
|----------------------------|--|--------------------------|-------------------|---------------|----------------|---------------|---------|--------------|
| General & Workshop Details |  | Vehicle & Driver Details | Vehicle Condition | Taxes & Ratio | Parts & Labour | Miscellaneous | Summary | Claim Amount |
| Claim Amount               |  | \$3,968.50               |                   |               |                |               |         | \$3,968.50   |
| CATEGORY                   |  | ESTIMATE                 | REVISED AMOUNT    |               |                |               |         |              |
| Spare Parts                |  | \$2,432.80               |                   |               |                |               |         | \$2,432.80   |
| Labour                     |  | \$1,360.00               |                   |               |                |               |         | \$1,360.00   |
| Miscellaneous              |  | \$185.70                 |                   |               |                |               |         | \$185.70     |

Assessment Details

| General & Workshop Details |  | Vehicle & Driver Details |  | Vehicle Condition |  | Taxes & Ratio  |  | Parts & Labour |  | Miscellaneous |  | Summary |  | Claim Amount |  |
|----------------------------|--|--------------------------|--|-------------------|--|----------------|--|----------------|--|---------------|--|---------|--|--------------|--|
| Claim Amount               |  | \$3,150.00               |  |                   |  |                |  |                |  |               |  |         |  | \$3,150.00   |  |
| CATEGORY                   |  | ESTIMATE                 |  |                   |  | REVISED AMOUNT |  |                |  |               |  |         |  |              |  |
| Miscellaneous              |  | \$3,150.00               |  |                   |  | \$3,150.00     |  |                |  |               |  |         |  |              |  |

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

|                   |                      |        |                  |
|-------------------|----------------------|--------|------------------|
| Vehicle No:       | SKS 8672C (Insd veh) | Model: | TPVD HYUNDAI I40 |
|                   | SHC 3760J (TP veh)   |        |                  |
| Date of Accident: | 06/06/2018           |        |                  |

|                       |   |   |                             |
|-----------------------|---|---|-----------------------------|
| Global Sum Settlement | : | <input checked="" type="checkbox"/> Yes | <input type="checkbox"/> No |
| Repair Estimate       | : | \$                                      | 12,662.36                   |
| Final Repair Cost     | : | \$                                      | 3,370.50                    |
| Loss of Token Sum     | : | \$                                      | 250.00                      |
| Rental (if any)       | : | \$                                      | 596.40                      |
| LTA / GIA Search Fee  | : | \$                                      | 7.49                        |

|         |   |    |      |
|---------|---|----|------|
| Others: | : | \$ | 0.00 |
|---------|---|----|------|

|                                   |   |    |          |
|-----------------------------------|---|----|----------|
|                                   | : | \$ |          |
| Final Settlement Sum (Global Sum) | : | \$ | 4,200.00 |

|   |  |
|---|--|
| Is Third Party Workshop GIA Registered? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO (Kindly indicate below) |  |
| A) For Non GIA Registered Workshop:   | Agreed Liability _____ (%)                       |
| B) For GIA Registered Workshop:   | BOLA Applicable: Yes/ No BOLA Scenario No: _____ |
| BOLA Liability: _____ 100 _____ (%)   | Assessed Liability (*): _____ (%)                |
| * Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.                                |  |
| Remarks<br>_____<br>_____   |  |

| Payment Instruction: Payee's Breakdown |                                   |             |
|--|-----------------------------------|-------------|
| 1)                                     | COMFORTDELGRO ENGINEERING PTE LTD | \$ 4,200.00 |

\_\_\_\_\_  
JOANNE LEE KHANG MIN  
LKK Auto Consultants Pte Ltd

\_\_\_\_\_  
20/09/2018  
Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))