

REPAIR ESTIMATE*

DATE 8/6/2018 9:29

MAKE :

MODEL : HYUNDAI i40

DOA: 06-06-18

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid X			\$ 1,681.40
	Boot Lid Lock Upper X			\$ 137.90
	Boot Lid Lock Lower X			\$ 31.70
	Boot Lid 'H' Emblem +			\$ 27.20
	Boot Lid CRDI Plate /			\$ 41.00
	Boot Lid Lamp (RH) /			\$ 556.80
	Bootlid Moulding X			\$ 85.00
	Bootlid i40 Emblem /			\$ 41.00
	Bootlid Lower Garnish X repair			\$ 398.00
	Rear Bumper /			\$ 603.60
	Rear Bumper Reinforcement ?			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH) ?		\$ 180.00	\$ 360.00
	Rear Bumper Side Bracket ?		\$ 49.00	\$ 98.00
	Rear Bumper Clips /			\$ 22.00
	Rear Bumper Sponge ?			\$ 143.40
	Rear Bumper Under Cover /			\$ 225.00
	Rear Bumper Reflector Lamp (RH) /			\$ 32.00
	Tail Lamp (RH) /			\$ 565.60
	Rear Panel X			\$ 592.30
	Rear Panel Garnish X			\$ 57.70
	Rear Panel Lower Panel X repair			\$ 495.50
	Exhaust Pipe Insulator ?			\$ 58.55
	Exhaust Silencer /			\$ 954.00
	Exhaust Pipe Hanger ?			\$ 58.55
	Exhaust Pipe Centre ?			\$ 1,150.30
	Rear Fender (RH) X repair			\$ 2,020.10
	Rear Fender Inner Lining (RH) X			\$ 164.40
	Rear Windscreen Moulding X			\$ 60.00
	SUB TOTAL			\$ 11,165.35
	LESS 20%			\$ 2,233.07
	DISCOUNTED TOTAL			\$ 8,932.28
	Boot Lid Comfort Logo & Tel No. Sticker X			\$ 30.00
	Rear Bumper Reverse Sensor /			\$ 135.70
	Rear Bumper Rubber Mat /			\$ 50.00
	Rear Windscreen Sealant X			\$ 46.00
				\$ 261.70

Larry Ng

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			600
	Panel Beating			\$ 1,000.00
	Spray Painting Charge			\$ 1,000.00 600
	Wiring Charge			\$ 50.00 20
	Tuff Kote			\$ 50.00 X
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 50
	Remove/Refix Rear Windscreen Glass			\$ 120.00 X
	Remove/Refix Reverse Sensor			\$ 120.00 30
	Remove/Refix Exhaust Pipe			\$ 150.00 50
	TOTAL LABOUR			\$ 2,640.00
	ESTIMATE TOTAL			\$ 11,833.98
<i>Kalvin 11/11/14</i> <i>U 8/6/18 1315hrs.</i> <i>3 Dp.</i> <i>4s</i> <i>After Repair photo</i>				
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Larry Ng