

Rene

REF: LPC

6691F

ASSIGNMENT

From: Date: 14062018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKS 9681U

at Workshop mis: Borneo Motor
2 Pandan Garden

of

Insured

Policy No

Claims No

Sum Insured


Excess:

(Client's Record) Make of Velt: Thomas @ 9847 6171

10am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? Yes or No

GIA / FR Seed: Consistent? Yes or No

Est. Repairs: 7 days Res: Yes or No

Lum Sum: - % 3 Val. Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKS 9681U

Yr Regn: 2015 May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Suzuki S-cross 1.6 C.C. 1586

Colour: Blue A/C Insured / Std / NI / NA

Sp. Reading: 47602 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: TSM JYA 22S 00 2021 10

Gen. Cond: Good (F) / Poor / Burnt

Steering: (order) / Jammed / Leaked / Burnt or

Brake: (order) / Jammed / Leaked / Burnt or

Modi: Nil / (S)Rim / STD A/Rim or

Tyre Size: F: 215/452R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or: FALKEN

Front

Rear

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A. 01/06/18 D.O.I. 14/06/18

Survey held at: Borneo Motor

Des. of Damages: Frt (Red) / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

r/r \$8,420.37
(2000: \$6,022.95 / 41%)

Date/Time: File Pass to:

☐

: Prell. Report

11

☐

: Final Report

Date/Time: File Return to:

12

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

Add Fee: ☐ Site Insp. 1\$

☐ Interview 1\$

☐ Tech. Insp. 1\$

☐ Workshop 1\$

Report Format :

Lump Sum / L.B.R. 1\$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC4/LPC18010488/hb3	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 08-06-2018	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SFA 6429G	Veh. Inspected	SKS 9681U	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	08/06/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	01/06/2018	Inspection Date		
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/LPC18010488/R1hb3

Date: 20.06.2018

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SKS9681U

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 14.06.2018 at the premises of M/s Borneo Motors (S) Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	14,443.32
Revised Estimate Amount	: S\$	7,990.67
"Check" Items Amount	: S\$	1,917.60
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 7 days

Yours faithfully,

MOHD. RASUL
Licensed Appraiser

Identification Card

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8636691F



Name

LEE YANMEI
(LI YANMEI)

李炎嫻

Race

CHINESE

Date of birth

27-12-1986

Country/Place of birth

SINGAPORE

Sex

F



REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number S8636691F

Name

LEE YANMEI
(LI YANMEI)

Birth Date 27 Dec 1986

Issue Date 18 May 2006



00141962K

Mohammad A

Identification Card

5817748



NRIC No. S8636691F



Date of issue
24-10-2017


Address

APT BLK 526 JELAPANG ROAD
#05-01
SINGAPORE 670526

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3 Motor Cars $\leq$ 3000kg with $\leq$ 7 passengers, exclusive of the driver; and other motor vehicles $\leq$ 2500kg 18 May 2004



Licence No: S8636691F

Mohamma

TAX INVOICE

ESTIMATE

GST Registration No.: MR-8500000-9
RCB Registration No.: 195000068E

Account Detail		Account No.	Customer Detail	
THIRD PARTY CLAIM		S8000025 / TPCL	Ms Lee Yan Mei (Li Yanmei) 526 Jelapang Road #05-61 Singapore 670528 Mobile: 84993961	
		Invoice No.		
		Invoice Date		
		0		
		06/06/2018		

Year	Make	Model	Reg. Date	Veh. Reg. No.	Kilometers	WIP No.	Order No./Remarks
14	KK1119JMGH5AU	SX4	18/05/2015	SKS9681U	0	11512	72/DS/SKS9681U
Chassis No.	Engine No.	TWC No.	Terms	SA/Counter	Vehicle In	Collected On	
TSMJYA22S00202110	M16A1892089	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	S	S-BMS TP INS: <i>TP INS: 100</i> TP VEH: SFA6429G DATE OF ACC : 01.06.2018	1	100.00		100.00
2	S	S-BMS DRILL HOLE AND INSTALL REVERSE SENSOR (N ETT)		138.00		138.00
3	S	S-BMS CHECK WIRING AND CONDUCT WATER TEST (NET T)		138.00		138.00
4	S	S-BMS SUPPLY JOINT PANEL SEALANT (NETT)		200.00		200.00
5	S	S-BMS REMOVE AND TRANSFER TAILGATE COMPONENTS ONTO NEW TAILGATE (NETT)		227.00		227.00
6	S	S-BMS R/I REAR REVERSE CAMERA TO FAC REPAIR (N ETT)		227.00		227.00
7	S	S-BMS REPLACE TAILGATE GLASS (NETT)		414.00		414.00
8	S	S-BMS SUPPLY 3M SOLAR FILM (NETT)		480.00		480.00
9	S	S-BMS REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR (NETT)		552.00		552.00
10	S	S-BMS SUPPLY REAR NO PLATE (NETT)		80.00		80.00
11	S	S-BMS REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS		2760.00		2760.00
Champion Motors is the only authorized workshop to maintain your Suzuki. Service your Suzuki at Champion Motors every 6 mths or 10,000 km (whichever earlier) to enjoy warranty benefits.						

For & on behalf of	Customer's Signature	Change Summary	Total
Champion Motors (1975) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

TO SECURITY GUARD

06/06/2018 07:58

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO. SKS9681U

CUSTOMER

SIGNATURE FOR Champion Motors (1975) Pte Ltd

003487

003487

inchcape

TAX INVOICE

ESTIMATE

GST Registration No.: MR-8500000-9
RCB Registration No.: 195000068E

Account Detail	Account No.	Customer Detail
THIRD PARTY CLAIM	S8000025 / TPCL	Ms Lee Yan Mei (Li Yanmei) 526 Jelapang Road #05-61 Singapore 670528 Mobile: 84993961
	Invoice No. 0	
	Invoice Date 06/06/2018	

Year	Make	Model	Reg. Date	Veh. Reg. No.	Kilometers	WIP No.	Order No./Remarks
14	KK1119JMGH5AU	SX4	18/05/2015	SKS9681U	0	11512	72/DS/SKS9681U

Chassis No.	Engine No.	TWC No.	Terms	SA/Counter	Vehicle In	Collected On
TSMJYA22S00202110	H16A1892089	60	Thomas Pang W T	--/--/----	0.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
12	8	S-BMS RESPRAY ACC AFFECTED AREAS		2736.00		2736.00
13	1	H35650-61M10-000 LAMP UNIT REAR COMB.R AKK416	1.00	403.95		403.95
14	2	H35670-61M10-000 LAMP UNIT REAR COMB.L AKK416	1.00	403.95		403.95
15	3	H36254-61M00-000 LAMP ASSY, BACK	1.00	213.85		213.85
16	4	H36274-61M00-000 LAMP ASSY, BACK UP, L	1.00	213.85		213.85
17	5	H35970-79J02-000 REFLECTOR, RR RW416F	1.00	30.10		30.10
18	6	H35950-79J02-000 REFLECTOR, RR RW416F	1.00	30.10		30.10
19	7	H37735-61M10-ZUM PARKING SENSOR RR AKK416	4.00	238.80		955.20
20	8	H65560-61MA1-000 MEMBER COMP REAR BUMPER	1.00	225.60		225.60
21	9	H65500-61MA0-000 PANEL, BACK AKK416	1.00	396.90		396.90
22	0	H71811-61M10-799 BUMPER, REAR UPPER AKK416	1.00	449.65		449.65
23	1	H71821-61M00-5PK BUMPER AKK416	1.00	381.55		381.55
24	2	H71822-61M00-5PK COVER, REAR FOG LAMP (BLACK)	1.00	4.55		4.55
25	3	H71871-61M10-PER GARNISH, RR BUMPER LOWER AKK416	1.00	194.75		194.75
26	4	H71831-61M00-000 HOLDER, RR BUMPER SIDE, R	1.00	14.45		14.45
27	5	H71832-61M00-000 HOLDER, RR BUMPER SIDE AKK416	1.00	14.45		14.45
28	6	H71891-61M00-000 STAY, RR BUMPER, R, AKK416	1.00	37.70		37.70
29	7	H71892-61M00-000 STAY, RR BUMPER, L, AKK416	1.00	37.70		37.70
30	8	H76191-61M00-5PK TRIM, TAIL END (BLACK) AKK416	1.00	100.05		100.05
31	9	H76192-61M00-5PK CAP, TAIL END TRIM AKK416	1.00	50.00		50.00

Champion Motors is the only authorized workshop to maintain your Suzuki. Service your Suzuki at Champion Motors every 6 mths or 10,000 km (whichever earlier) to enjoy warranty benefits.

For & on behalf of Champion Motors (1975) Pte Ltd	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle:	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

06/06/2018
07:58

DATE
TIME

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO
LEAVE THE COMPANY PREMISES.

VEHICLE NO. SKS9681U

CUSTOMER

SIGNATURE
FOR Champion Motors (1975) Pte Ltd



TAX INVOICE

ESTIMATE

GST Registration No.: MR-8500000-9
RCB Registration No.: 195000069E

Account Detail			Account No.	Customer Detail		
THIRD PARTY CLAIM			S8000025 / TPCL	MS Lee Yan Mei (Li Yanmei) 526 Jelapang Road #05-61 Singapore 670528 Mobile: 84993961		
			Invoice No. 0			
			Invoice Date 06/06/2018			

Year	Make	Model	Reg. Date	Veh. Reg. No.	Kilometers	WIP No.	Order No./Remarks
14	KK1119JMGH5AU	SX4	18/05/2015	SKS9681U	0	11512	72/DS/SKS9681U

Chassis No.	Engine No.	TWC No.	Terms	SA/Counter	Vehicle In	Collected On
TSMJYA22S00202110	M16A1892089	60	Thomas Pang W T	--/--/----	0.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
32	0	H77330-61M00-000 OUTLET, VENTILATOR	2.00	29.45		58.90
33	1	H77821-79J00-0PG EMBLEM, SUZUKI (CHROME)	1.00	18.30		18.30
34	2	H77811-65J00-0PG EMBLEM, MARK (S) (CHROME) A5B424	1.00	47.65		47.65
35	3	H77831-61M00-0PG EMBLEM AKK416	1.00	27.00		27.00
36	4	H69100-61M01-000 PANEL ASSY, BACK DOOR AKK416	1.00	856.85		856.85
37	5	H84570-61M00-000 GLASS, BACK DOOR WINDOW AKK416	1.00	593.95		593.95
38	6	H84681-61M02-000 WEATHERSTRIP, BACK DOOR AKK416	1.00	93.90		93.90
39	7	L0882608609 SUPER FAST URETHANE BLACK	1.00	90.08		90.08
40	8	L0882608682 SINGLE STEP PRIMER	1.00	173.44		173.44
41	9	H82510-61MA1-000 LATCH, BACK DOOR AKK416	1.00	272.90		272.90

Handwritten notes:
Repair
Hq 900 00068
7 days
14/06/18 P1015
Resy by part

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
Champion Motors is the only authorized workshop to maintain your Suzuki. Service your Suzuki at Champion Motors every 6 mths or 10,000 km (whichever earlier) to enjoy warranty benefits.

For & on behalf of Champion Motors (1975) Pte Ltd		Customer's Signature	Change Summary		Total	14,443.32
Date:		Please acknowledge receipt of vehicle	Parts	6,391.32	GST 7.00%	1,011.03
			Labour	0.00		
			Materials	8,052.00	Less	0.00
			Lubrication/Fluid	0.00		
			Others	0.00		
					Amount Due	15,454.35

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

06/06/2018 07:58

DATE TIME

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO. SKS9681U

CUSTOMER

SIGNATURE FOR Champion Motors (1975) Pte Ltd

003489

003489





Champion Motors (1975) Pte Ltd
No 2 Pandan Crescent
Singapore 128462
Tel: (65) 6531 1118
Website: www.suzukicar.com.sg

TAX INVOICE

ESTIMATE

GST Registration No.: MR-8500000-9
RCB Registration No.: 195000068E

Account Detail	Account No.	Customer Detail
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower	S8000012 / WILI01	Ms Lee Yan Mei (Li Yanmei) 526 Jelapang Road #05-61 Singapore 670528 Mobile: 84993961
	Invoice No. 0	
	Invoice Date 22/06/2018	

Year	Make	Model	Reg. Date	Veh. Reg. No.	Kilometers	WIP No.	Order No./Remarks
14	KK1119JMGH5AU	SX4	18/05/2015	SKS9681U	44839	11512	72/DS/SKS9681U

Chassis No.	Engine No.	TWC No.	Terms	SA/Counter	Vehicle In	Collected On
TSMJYA22S00202110	M16A1892089	60	Thomas Pang W T	--/--/----	0.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	S	S-BMS TP INS: LONPAC INSURANCE B002 TP VEH: SPA6429G DATE OF ACC : 01.06.2018 BY:LKK-RASUL @ 14.06.2018 07 WORKING DAYS		50.00		50.00
2	S	S-BMS DRILL HOLE AND INSTALL REVERSE SENSOR (NETT) B002 ETT) PO:1466		138.00		138.00
3	S	S-BMS CHECK WIRING AND CONDUCT WATER TEST (NETT) B002 T) PO:1466		138.00		138.00
4	S	S-BMS SUPPLY JOINT PANEL SEALANT (NETT) B002 PO:1466		100.00		100.00
5	S	S-BMS REMOVE AND TRANSFER TAILGATE COMPONENTS B002 ONTO NEW TAILGATE (NETT) PO:1466		227.00		227.00
6	S	S-BMS R/I REAR REVERSE CAMERA TO FAC REPAIR (NETT) B002 ETT) PO:1466		227.00		227.00
7	S	S-BMS REPLACE TAILGATE GLASS (NETT) B002 PO:1466		414.00		414.00
8	S	S-BMS SUPPLY 3M SOLAR FILM (NETT) B002 PO:1466		480.00		480.00

Champion Motors is the only authorized workshop to maintain your Suzuki. Service your Suzuki at Champion Motors every 6 mths or 10,000 km (whichever earlier) to enjoy warranty benefits.

For & on behalf of Champion Motors (1975) Pte Ltd	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

001034

001034

22/06/2018
13:56

SKS9681U

WORKSHOP



TAX INVOICE

ESTIMATE

GST Registration No.: MR-8500000-9
RCB Registration No.: 195000068E

Account Detail	Account No.	Customer Detail
Longac Insurance Berhad 100 Beach Road #19-00 Shaw Tower	S8000012 / WILI01	Ms Lee Yan Mei (Li Yanmei) 526 Jelapang Road #05-61 Singapore 670528 Mobile: 84993961
	Invoice No. 0	
	Invoice Date 22/06/2018	

Year	Make	Model	Reg. Date	Veh. Reg. No.	Kilometers	WIP No.	Order No./Remarks
14	KK1119JMGH5AU	SK4	18/05/2015	SKS9681U	44839	11512	72/DS/SKS9681U

Chassis No.	Engine No.	TWC No.	Terms	SA/Counter	Vehicle In	Collected On
TSMJYAZ2500202110	M16A1892089	60	Thomas Pang W T	--/--/----	0.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
9	S	S-BMS REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR#002 (NETT) PO:1466		276.00		276.00
10	S	S-BMS SUPPLY REAR NO PLATE (NETT) PO:1467	E33	80.00		80.00
11	S	S-BMS REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS PO:1466	B002	1656.00		1656.00
12	S	S-BMS RESPRAY ACC AFFECTED AREAS PO:1466	B002	1368.00		1368.00
13	1	H71811-61M10-799 BUMPER, RR UPPER (PRIMARY)	1.00	449.65		449.65
14	2	H71821-61M00-5PK BUMPER, REAR LOWER (BLACK	1.00	381.55		381.55
15	3	H71831-61M00-000 HOLDER, RR BUMPER SIDE RH	1.00	14.45		14.45
16	4	H71832-61M00-000 HOLDER, RR BUMPER SIDE LH	1.00	14.45		14.45
17	5	H71891-61M00-000 STAY, RR BUMPER RH	1.00	37.70		37.70
18	6	H71892-61M00-000 STAY, RR BUMPER LH	1.00	37.70		37.70
19	7	H77821-79J00-0PG EMBLEM, SUZUKI (CHROME)	1.00	18.30		18.30
20	8	S77811-65J00-0PG EMBLEM, MARK S	1.00	28.30		28.30
21	9	H77831-61M00-0PG EMBLEM	1.00	27.00		27.00
22	0	H69100-61M01-000 PANEL ASSY, BACK DOOR	1.00	856.85		856.85

Champion Motors is the only authorized workshop to maintain your Suzuki. Service your Suzuki at Champion Motors every 6 mths or 10,000 km (whichever earlier) to enjoy warranty benefits.

For & on behalf of Champion Motors (1975) Pte Ltd	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

001035

001035

22/06/2018
13:56

SKS9681U

TAX INVOICE

ESTIMATE

GST Registration No.: MR-8500000-9
RCB Registration No.: 195000068E

Account Detail Lampoo Insurance Berhad 100 Beach Road #19-00 Shaw Tower	Account No. S8000012 / WILI01	Customer Detail Ms Lee Yan Mei (Li Yanwei) 526 Jelapang Road #05-61 Singapore 670528 Mobile: 84993961
	Invoice No. 0	
	Invoice Date 22/06/2018	

Year	Make	Model	Reg. Date	Veh. Reg. No.	Kilometers	WIP No.	Order No./Remarks
14	KC1119JHGH5AU	SK4	18/05/2015	SKS9681U	44839	11512	72/DS/SKS9681U

Chassis No.	Engine No.	TWC No.	Terms	SA/Counter	Vehicle In	Collected On
TSMJVA22300202110	H16A1692089	60	THOMAS Pang W T	--/--/----	0.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
23	1	UR4570-61M00-000 GLASS, BACK DOOR WINDOW (GREEN)	1.00	593.95		593.95
24	2	H84681-61M02-000 WEATHERSTRIP, BACK DOOR AKK416	1.00	93.90		93.90
25	3	L0882608609 SUPER FAST URETHANE BLACK	1.00	90.08		90.08
26	4	L0882608682 SINGLE STEP PRIMER	1.00	173.44		173.44
27	5	H82510-54P10-000 LATCH, BACK DOOR APK416 LHD	1.00	164.55		164.55
28	6	H65560-61MA1-000 MEMBER COMP REAR BUMPER	1.00	225.60		225.60
29	7	H77330-61M00-000 OUTLET, VENTILATOR	1.00	29.45		29.45
30	8	H77330-61M00-000 OUTLET, VENTILATOR	1.00	29.45		29.45

Champion Motors is the only authorized workshop to maintain your Suzuki. Service your Suzuki at Champion Motors every 6 mths or 10,000 km (whichever earlier) to enjoy warranty benefits.

8,420.37

For & on behalf of Champion Motors (1975) Pte Ltd	Customer's Signature	Change Summary	Total	5,420.37
		3,266.37	GST 7.00%	589.43
	Please acknowledge receipt of vehicle	Parts 0.00		
		Labour 5,154.00		
		Materials 0.00	Less	0.00
		Lubrication/Fluid 0.00		
		Others		
			Amount Due	9,009.80

001036

001036

22/06/2018
13:56

SKS9681U

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Friday, 8 June 2018 9:20 AM
To: Siti.Nabilah@inchcape.com.sg; assignments@lkkauto.com; 'SUR' (sur@lkkauto.com)
Cc: MT_Claim_SG
Subject: RE: Direct Settlement(TP) - Accident Involving SKS9681U and SFA6429G DOA 01/06/2018 Our Ref: 18/18/18/VP05/020650
Attachments: SKS9681U 01062018_CI.PDF; SKS9681U 01062018_SAS_Damaged Photos.pdf

11:22am @ 8/6/18
person @ Thomas
vehicle not in

Without Prejudice

Dear Nabilah

Please liaise with LKK Auto Consultants Pte Ltd for assessment of quantum and liability.

Dear Catherine

Please arrange survey.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: GERALD POH WEE BIN
Sent: Friday, 8 June, 2018 8:56 AM
To: ERIC WOO JUN KIAT
Cc: MT_Claim_SG
Subject: FW: Direct Settlement(TP) - Accident Involving SKS9681U and SFA6429G DOA 01/06/2018

Dear Eric,

Kindly arrange.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Siti Nabilah PTCBC [mailto:Siti.Nabilah@inchcape.com.sg]
Sent: Thursday, 7 June, 2018 6:06 PM
To: GERALD POH WEE BIN
Cc: Siti Nabilah PTCBC
Subject: Direct Settlement(TP) - Accident Involving SKS9681U and SFA6429G DOA 01/06/2018

Hi,

Reference to the above-mentioned.

Please find attached herein a copy of our client's Accident Report, Damaged Photos & Estimate Invoice for your kind perusal.

As our client is claiming against your insured SFA6429G thus would appreciate if you could revert to us on the liability urgently or we could settle the case under Direct Settlement with Car Rental @ \$100 per day x no. of days as recommended by your appointed surveyor.

Kindly have your surveyor to contact our Motor Claim Assessor, **Thomas Pang @ 9847 6171 / 6631 1860** located at **2 Pandan Crescent, Level 4** for an appointment to inspect our client's vehicle. Vehicle grounded at our premises.

As for liability clearance, kindly revert to this email.

Your kind attention into the above is greatly appreciated.

Thank you very much in advance!

Best Regards,

Nabilah

TPR Team (Claims Accident Recovery Dpt)

DID 6631 1874 | FAX 6872 7260

Inchcape - Borneo Motors (S) Pte Ltd

Office Address: 2 Pandan Crescent, Inchcape Centre Level 4, Singapore 128462

www.borneomotors.com.sg | www.toyotasingapore.com.sg



This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.



Champion Motors

VIC

Champion Motors (1975) Pte Ltd
2 Pandan Crescent
(Off West Coast Highway)
Singapore 128462
www.suzukicar.com.sg
Co Reg No: 195000068E

Our Claim Ref: CMS2018/09/CM8035/DS(TP)
Your Ref: CC4/LPC18010488/hb3 (SFA6429G)

05 Apr 2019

BY HAND

M/S. LONPAC INSURANCE BERHAD/C/O LKK AUTO CONSULTANTS PTE LTD

Attention : Claims Payable / Officer In-Charge

Department : Motor Claims

RE: ACCIDENT INVOLVING SKS9681U & SFA6429G ON 01 Jun 2018

Reference to the above-mentioned.

Enclosed is the duly signed release voucher for your kind perusal.

Kindly let us have the cheque ***WITHIN 14 WORKING DAYS*** from date of this letter.

Please **quote our claim reference** on your cheque.

To avoid any inconvenience, please make the cheque payable as per details below:-

1. CHAMPION MOTORS (1975) PTE LTD - \$9,511.80

Cheque to be mail to:-

2 Pandan Crescent

Singapore 128462

Attention: Sipah (Ms)
TPR Department

Thank you.

Yours faithfully,

Sipah Buang

TPR Department

D: 6631 1856 F: 6872 7260

E: norsipahb.buang@inchcape.com.sg

encl.

(As this is a computer generated letter, no signature is required.)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC4/LPC18010488/R1hb3n2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 02-05-2019	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SFA 6429G	Veh. Inspected	SKS 9681U	
Policy No.	Z18VP05018436	Coverage (\$)	0.00	
Claim No.	18/18/18/VP05/020650	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	08/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	SUZUKI S-CROSS 1.6	c.c	1586	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	TSMJYA22S00202110	Colour	BLUE	
Odometer	47602	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/45 ZR17	FALKEN	6 mm	
L/H Front Tyre	215/45 ZR17	FALKEN	6 mm	
R/H Rear Tyre	215/45 ZR17	FALKEN	6 mm	
L/H Rear Tyre	215/45 ZR17	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/06/2018	Inspection Date	14/06/2018	
Survey held at	CHAMPION MOTORS (1975) PTE LTD NO 2 PANDAN CRESCENT (OFF WEST COAST HIGHWAY) SINGAPORE 128462			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKS 9681U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SUNDRIES (SN)	NECESSARY	100.00	50.00
1	REAR NO PLATE (SN)	BENT	80.00	80.00
1	LAMP UNIT REAR COMB .R AKK416 (SN)	SERVICEABLE	403.95	-
1	LAMP UNIT REAR COMB .L AKK416 (SN)	SERVICEABLE	403.95	-
1	LAMP ASSY ,BACK (SN)	SERVICEABLE	213.85	-
1	LAMP ASSY ,BACK UP,L (SN)	SERVICEABLE	213.85	-
1	REFLECTOR ,RR RW416F (SN)	SERVICEABLE	30.10	-
1	REFLECTOR ,RR RW416F (SN)	SERVICEABLE	30.10	-
4	PARKING SENSOR RR AKK416 (SN)	SERVICEABLE	955.20	-
1	MEMBER COMP REAR BUMPER (SN)	DEFORMED	225.60	225.60
1	PANEL ,BACK AKK416 (SN)	TO REPAIR SEE LABOUR	396.90	-
1	BUMPER ,REAR UPPER AKK416 (SN)	DEFORMED	449.65	449.65
1	BUMPER AKK416 (SN)	DEFORMED	381.55	381.55
1	COVER ,REAR FOG LAMP (BLACK) (SN)	NOT NECESSARY	4.55	-
1	GARNISH ,RR BUMPER LOWER AKK416 (SN)	SERVICEABLE	194.75	-
1	HOLDER,RR BUMPER SIDE ,R (SN)	NECESSARY	14.45	14.45
1	HOLDER,RR BUMPER SIDE AKK416 (SN)	NECESSARY	14.45	14.45
1	STAY ,RR BUMPER ,R, AKK416 (SN)	NECESSARY	37.70	37.70
1	STAY ,RR BUMPER ,L, AKK416 (SN)	NECESSARY	37.70	37.70
1	TRIM ,TAIL END (BLACK) AKK416 (SN)	SERVICEABLE	100.05	-
1	CAP ,TAIL END TRIM AKK416 (SN)	SERVICEABLE	50.00	-
2	OUTLET ,VENTILATOR (SN)	CRACKED	58.90	58.90
1	EMBLEM,SUZUKI (CHROME) (SN)	NECESSARY	18.30	18.30
1	EMBLEM ,MARK (S) (CHROME) A5B424 (SN)	NECESSARY	47.65	28.30
1	EMBLEM AKK416 (SN)	NECESSARY	27.00	27.00
1	PANEL ASSY ,BACK DOOR AKK416 (SN)	BENT	856.85	856.85
1	GLASS ,BACK DOOR WINDOW AKK416 (SN)	NECESSARY	593.95	593.95
1	WEATHERSTRIP ,BACK DOOR AKK416 (SN)	NECESSARY	93.90	93.90
1	SUPER FAST URETHANE BLACK (SN)	NECESSARY	90.08	90.08
1	LATCH ,BACK DOOR AKK416 (SN)	NECESSARY	173.44	173.44

Report Ref No. CC4/LPC18010488/R1hb3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	LATCH ,BACK DOOR AKK416 (SN)	CUT	272.90	164.55
			6,571.32	3,396.37
	LABOUR			
	DRILL HOLE AND INSTALL REVERSE SENSOR .		138.00	138.00
	CHECK WIRING AND CONDUCT WATER TEST.		138.00	138.00
	SUPPLY JOINT PANEL SEALANT .		200.00	100.00
	REMOVE AND TRANSFER TAILGATE COMPONENTS ONTO NEW TAILGATE.		227.00	227.00
	R/I REAR REVERSE CAMERA TO FAC REPAIR .		227.00	227.00
	REPLACE TAILGATE GLASS.		414.00	414.00
	SUPPLY 3M SOLAR FILM .		480.00	480.00
	REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR .		552.00	276.00
	REPLACE ACC DAMAGED PARTS AND STRAIGHTEN /REALIGN ACC AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF PANEL ,BACK AKK416.		2,760.00	1,656.00
	RESPRAY ACC AFFECTED AREAS.		2,736.00	1,368.00
			7,872.00	5,024.00
GRAND TOTAL			14,443.32	8,420.37
RECOMMENDED COST OF REPAIRS				8,420.37

Report Ref No. CC4/LPC18010488/R1hb3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.