

TAX INVOICE

ESTIMATE

GST Registration No.: MR-8500000-9

RCB Registration No.: 195000068E

Account Detail	Account No. S8000025 / TPCL	Customer Detail
THIRD PARTY CLAIM	Invoice No. 0	Ms Lee Yan Mei (Li Yanmei) 526 Jelapang Road #05-61 Singapore 670528 Mobile: 84993961
	Invoice Date 06/06/2018	

Year	Make	Model	Reg. Date	Veh. Reg. No.	Kilometers	WIP No.	Order No./Remarks
14	KK1119JMGH5AU	SX4	18/05/2015	SKS9681U	0	11512	72/DS/SKS9681U

Chassis No.	Engine No.	TWC No.	Terms	SA/Counter	Vehicle In	Collected On
TSMJYA22S00202110	M16A1892089	60	Thomas Pang W T	--/--/----	0.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	S	S-BMS TP INS: TP VEH:SFA6429G DATE OF ACC :01.06.2018		100.00		50 100.00
2	S	S-BMS DRILL HOLE AND INSTALL REVERSE SENSOR (N ETT)		138.00		138.00
3	S	S-BMS CHECK WIRING AND CONDUCT WATER TEST (NET T)		138.00		138.00
4	S	S-BMS SUPPLY JOINT PANEL SEALANT (NETT)		200.00		100 200.00
5	S	S-BMS REMOVE AND TRANSFER TAILGATE COMPONENTS ONTO NEW TAILGATE (NETT)		227.00		227.00
6	S	S-BMS R/I REAR REVERSE CAMERA TO FAC REPAIR (N ETT)		227.00		227.00
7	S	S-BMS REPLACE TAILGATE GLASS (NETT)		414.00		414.00
8	S	S-BMS SUPPLY 3M SOLAR FILM (NETT)		480.00		480.00
9	S	S-BMS REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR (NETT)		552.00		276 552.00
10	S	S-BMS SUPPLY REAR NO PLATE (NETT)		80.00		80 80.00
11	S	S-BMS REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS		2760.00		1656 2760.00

Champion Motors is the only authorized workshop to maintain your Suzuki. Service your Suzuki at Champion Motors every 6 mths or 10,000 km (whichever earlier) to enjoy warranty benefits.

For & on behalf of Champion Motors (1975) Pte Ltd	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

003487

TO SECURITY GUARD

003487

06/06/2018
 07:58
 PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO
 LEAVE THE COMPANY PREMISES.

DATE
 TIME

VEHICLE NO. SKS9681U

CUSTOMER

SIGNATURE
 FOR Champion Motors (1975) Pte Ltd



TAX INVOICE

ESTIMATE

GST Registration No.: MR-8500000-9

RCB Registration No.: 195000068E

Account Detail	Account No. S8000025 /TPCL	Customer Detail
THIRD PARTY CLAIM	Invoice No. 0	Ms Lee Yan Mei (Li Yanmei) 526 Jelapang Road #05-61 Singapore 670528 Mobile: 84993961
	Invoice Date 06/06/2018	

Year	Make	Model	Reg. Date	Veh. Reg. No.	Kilometers	WIP No.	Order No./Remarks
14	KK1119JMGH5AU	SX4	18/05/2015	SKS9681U	0	11512	72/DS/SKS9681U

Chassis No.	Engine No.	TWC No.	Terms	SA/Counter	Vehicle In	Collected On
TSMJYA22S00202110	M16A1892089	60	Thomas Pang W T	--/--/----	0.00	--/--/----

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
12	S	S-BMS RESPRAY ACC AFFECTED AREAS		2736.00		2736.00
13	1	H35650-61M10-000 LAMP UNIT REAR COMB.R AKK416	1.00	403.95		X 403.95
14	2	H35670-61M10-000 LAMP UNIT REAR COMB.L AKK416	1.00	403.95		X 403.95
15	3	H36254-61M00-000 LAMP ASSY, BACK	1.00	213.85		X 213.85
16	4	H36274-61M00-000 LAMP ASSY, BACK UP, L	1.00	213.85		X 213.85
17	5	H35970-79J02-000 REFLECTOR, RR RW416F	1.00	30.10		7 30.10
18	6	H35950-79J02-000 REFLECTOR, RR RW416F	1.00	30.10		7 30.10
19	7	H37735-61M10-ZUM PARKING SENSOR RR AKK416	4.00	238.80		7 955.20
20	8	H65560-61MA1-000 MEMBER COMP REAR BUMPER	1.00	225.60		7 225.60
21	9	H65500-61MA0-000 PANEL, BACK AKK416	1.00	396.90		R 396.90
22	0	H71811-61M10-799 BUMPER, REAR UPPER AKK416	1.00	449.65		DE 449.65
23	1	H71821-61M00-5PK BUMPER AKK416	1.00	381.55		DE 381.55
24	2	H71822-61M00-5PK COVER, REAR FOG LAMP (BLACK)	1.00	4.55		X 4.55
25	3	H71871-61M10-PER GARNISH, RR BUMPER LOWER AKK416	1.00	194.75		7 194.75
26	4	H71831-61M00-000 HOLDER, RR BUMPER SIDE, R	1.00	14.45		NE 14.45
27	5	H71832-61M00-000 HOLDER, RR BUMPER SIDE AKK416	1.00	14.45		NE 14.45
28	6	H71891-61M00-000 STAY, RR BUMPER, R, AKK416	1.00	37.70		NE 37.70
29	7	H71892-61M00-000 STAY, RR BUMPER, L, AKK416	1.00	37.70		NE 37.70
30	8	H76191-61M00-5PK TRIM, TAIL END (BLACK) AKK416	1.00	100.05		7 100.05
31	9	H76192-61M00-5PK CAP, TAIL END TRIM AKK416	1.00	50.00		7 50.00

Champion Motors is the only authorized workshop to maintain your Suzuki. Service your Suzuki at Champion Motors every 6 mths or 10,000 km (whichever earlier) to enjoy warranty benefits.

For & on behalf of Champion Motors (1975) Pte Ltd	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

003488

TO SECURITY GUARD

06/06/2018

DATE

07:58

TIME

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO
 LEAVE THE COMPANY PREMISES.

VEHICLE NO. **SKS9681U**

CUSTOMER

SIGNATURE
 FOR **Champion Motors (1975) Pte Ltd**

Inchca

TAX INVOICE

ESTIMATE

GST Registration No.: MR-8500000-9

RCB Registration No.: 195000068E

Account Detail	Account No. S8000025 / TPCL	Customer Detail
THIRD PARTY CLAIM	Invoice No. 0	MS Lee Yan Mei (Li Yanmei) 526 Jelapang Road #05-61 Singapore 670528 Mobile: 84993961
	Invoice Date 06/06/2018	

Year	Make	Model	Reg. Date	Veh. Reg. No.	Kilometers	WIP No.	Order No./Remarks
14	KK1119JMGH5AU	SX4	18/05/2015	SKS9681U	0	11512	72/DS/SKS9681U

Chassis No.	Engine No.	TWC No.	Terms	SA/Counter	Vehicle In	Collected On
TSMJYA22S00202110	M16A1892089	60	Thomas Pang W T	--/--/----	0.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
32	0	H77330-61M00-000 OUTLET, VENTILATOR	2.00	29.45		58.90
33	1	H77821-79J00-OPG EMBLEM, SUZUKI (CHROME)	1.00	18.30		18.30
34	2	H77811-65J00-OPG EMBLEM, MARK (S) (CHROME) A5B424	1.00	47.65		47.65
35	3	H77831-61M00-OPG EMBLEM AKK416	1.00	27.00		27.00
36	4	H69100-61M01-000 PANEL ASSY, BACK DOOR AKK416	1.00	856.85		856.85
37	5	H84570-61M00-000 GLASS, BACK DOOR WINDOW AKK416	1.00	593.95		593.95
38	6	H84681-61M02-000 WEATHERSTRIP, BACK DOOR AKK416	1.00	93.90		93.90
39	7	L0882608609 SUPER FAST URETHANE BLACK	1.00	90.08		90.08
40	8	L0882608682 SINGLE STEP PRIMER	1.00	173.44		173.44
41	9	H82510-61MA1-000 LATCH, BACK DOOR AKK416	1.00	272.90		272.90

Repair
Hp 9000068
7 days
14/06/18 @ 10:15
Resy by paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Champion Motors is the only authorized workshop to maintain your Suzuki. Service your Suzuki at Champion Motors every 6 mths or 10,000 km (whichever earlier) to enjoy warranty benefits.

For & on behalf of Champion Motors (1975) Pte Ltd	Customer's Signature	Change Summary	Total 14,443.32
Date:	Please acknowledge receipt of vehicle	Parts 6,391.32	GST 7.00%
		Labour 0.00	
		Materials 8,052.00	Less 0.00
		Lubrication/Fluid 0.00	
		Others 0.00	
			Amount Due 15,454.35

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

06/06/2018

07:58

DATE

TIME

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO
 LEAVE THE COMPANY PREMISES.

VEHICLE NO. SKS9681U

CUSTOMER

SIGNATURE
 FOR Champion Motors (1975) Pte Ltd

