



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLN 4125 G

Parts	(a) Cost / List Price Items	\$	1,925.80
	Plus/Less 25%	\$	481.45
	Total of Cost / List	\$	1,444.35
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items		
Total Parts Cost			
Labour		\$	1,420.00
Total		\$	2,864.35

Not Authorised

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor

Company

Survey conducted on

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 02 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$

(e) Signature of surveyor

Date: 19/6/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : SLN 4125 G
Make & Model : TOYOTA PRIUS
Chassis No : JTDKB3FU603556696

Submit By : Carmen Lim
Year Manufacture : 2017
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor <i>Sm</i>	1	\$200.00	S.N	X
2	Rear bumper	1	\$497.50		?
3	Rear bumper clip	10	\$40.00		?
4	Rear bumper side retainer LH <i>Sm</i>	1	\$112.70		X
5	Rear bumper side retainer RH <i>Sm</i>	1	\$112.70		X
6	Rear bumper reinforcement	1	\$398.90		?
7	Rear bumper lower garnish centre <i>Red/Grt</i>	1	\$582.60		✓
8	Rear bumper lower garnish RH <i>Sm</i>	1	\$149.70		X
9	Rear bumper tow cover <i>Sm</i>	1	\$31.70		X
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



Vehicle No. : SLN 4125 G Submit By : Carmen Lim
Make & Model : TOYOTA PRIUS Year of Manufacture : 2017

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.