

TP AXA.

Ceilia.

GZ 3692 m. 2006 March.

Nissan Cabstar. 3153 cc

JNISF4F23Z0860921.

Rear Number Plate Best

30(SN). ✓

Rear Number Plate Bracket.

NOT
new

94.20 ✗

Taillamp x 02 Cut

248.6 x 2 = 497.20. ✓

Taillamp Panel x 02 Rep's

172 x 2 = 344. ✗

Reverse Sensor Damaged

~~280(SN)~~ 200(SN) ✓

Stopper x 02 Missing

90 x 2 = 40(SN) ✓

Stopper Bracket x 02 Best

183.4 x 2 = 366.80 ✓

Tailgate Dented

1399.70 ✓

Tailgate Hinge x 03

1 piece
Best

52 x 2 = 156. S2

Tailgate lower Panel Rep's

418.80 ✗

Nissan Sticker ?

141.80 ✓

70km/h Sticker

Nec

10(SN) ✓

13 Pax Sticker

10(SN) ✓

Rear Lower Cross Member.

392.30 ✗

Rep's

GZ3692M.

Panel Beating

~~1000~~ 600

Spray Painting.

~~800~~ 400

Wiring.

~~50~~ 30

To remove reverse sensor

~~100~~ 50

Nett: 2457.50

Labour: 1080

Less 10% : 2211.75

total: 3581.75

S.N: 290

L/S: 2850

04 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: