

ASS. REC. BY:

REF: CS/LCR18010505/Krbn2 Special Instruction:

Surveyor

ASSIGNMENT (Office)

Front (Person): Muhammad Ashley Chan of LCR Date/Time: 08062018 1119am

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJW 3087R Insured: SLJ 1427Bat Workshop m/s Siong Lee Motor Tel: 6453 1255of 160 Sth Ming Drive #02-07Policy No: _____ Claim No: 723382404486003

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 05062018
(Client's Record)CA / REV / REP. / REV 24 HRS Wpi

H.O.D. Endorsement:

Date/Time: 08062018 Person Contacted: Kwee Pin Vehicle IN OUT

| Date/Time | Action/Instruction (✓) Estimate |
|-----------|---|
| | <u>SJW 3087R. x</u> |
| | <u>SLJ 1427B - CS/LCR1700012/Kwa3</u> <u>DeA: 14-1017</u> |
| | <u>11 Lys @ 4300 email</u> <u>PS</u> |
| | <u>Red: 3962.04, 481.</u> |

ASS. REC. BY:

REF:

A/G/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD (TP/WS/TP RES/OD RES/EVA/INV/MV)

To inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: 831k

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

06

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

11/6

File pass to Catherine

RECEIVED 24 SEP 2018

Veh No:

STW 3087R

Yr Regn:

03, 10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Wish

c.c.

1987

Colour:

M. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

111467

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDGT20W105002225

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Continental

Front

Rear

R/Bal.

7

mm

R/Bal.

46

mm

L/Bal.

7

mm

L/Bal.

46

mm

D.O.A.

5/6/18

D.O.I.

8/6/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?



: Prel. Report

1) typist



: Final Report

Date/Time, File Return to?

Days Of Repair: 6

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

250

20

Fixtures

Others

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

TOTAL

270

Report Format:

Lump Sum / I.B.I. (\$

- Pre repair inspection request - SJW3087R VS SLJ1427B (OI) DOA 05/06/2018

From: Chan, Yoke Shi
To: ASSIGNMENTS@LKKKAUTO.COM, admin-a@lkkauto.com
Cc: Tan, Lily (AIG), Fong, Andy-SY, Kaur, Baljit, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang, Supramaniam, Darshene, Mithoosingh, Aashweenjeetkaur, A
Sent: Friday, 8 June, 2018 11:19:35 AM
Attachments:  SKMBT_C364e18060709560.pdf

Hi,

Please refer to the enclosed request from **CHEONGHOH LAW CORPORATION**.

Claim no : 7233824044SG003
Case Owner : IVY YONG

If you have any queries/concerns, please let us know.
Kindly assist to assign Mohammed Rasul as Single Joint Expert as requested.

Thank you.

Regards,

Yoke Shi @ Ashley
AIG
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)
Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel +6 03 2719 6000 | Ext 1012102

yokeshi.chan@aig.com | www.aig.com

From: Cheonghoh Law [mailto:mail@cheonghoh.sg]
Sent: Friday, June 08, 2018 11:13 AM
To: Chan, Yoke Shi
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Supramaniam, Darshene; Mithoosingh, Aashweenjeetkaur; Azlan, Syazairdina
Subject: Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLJ1427B AND SJW3087R ON 05/06/2018 (Oref: LCH.lg/SMSL-80507.18)

confirm Mohammed Rasul as email dated 7 June 2018.

Thanks & regards
Catherine
CHEONGHOH LAW CORPORATION
Blk 53 Chin Swee Road #03-05
Singapore 160053
T: 6337 8700 | F: 6337 3700 | E: mail@cheonghoh.sg

On 8 Jun 2018, at 9:11 AM, Chan, Yoke Shi <yokeshi.chan@aig.com> wrote:

Dear Catherine

Please confirm that you are nominating Mohammed Rasul named in the list of surveyors to conduct the pre-repair survey and appointed as the **"Single Joint Expert"**.
Thank you.

Regards,

Yoke Shi @ Ashley
AIG
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)
Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel +6 03 2719 6000 | Ext 1012102

yokeshi.chan@aig.com | www.aig.com

From: Cheonghoh Law [mailto:mail@cheonghoh.sg]
Sent: Thursday, June 07, 2018 3:26 PM
To: Chan, Yoke Shi
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Supramaniam, Darshene; Mithoosingh, Aashweenjeetkaur; Azlan, Syazairdina
Subject: Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLJ1427B AND SJW3087R ON 05/06/2018 (Oref: LCH.lg/SMSL-80507.18)

Dear Sirs,

We refer to the above matter and to your email of even date.

Our client hereby nominate Mohammed Rasul of LKK Auto Consultants Pte Ltd named in list to conduct the pre-repair survey of the damages to our client's vehicle arising out of the above mentioned accident.

Please be informed that our client's vehicle, SJW 3087 R is currently laying at our client's workshop, Siong Lee Motor, 160 Sing Ming Drive #02-07 AutoCity Singapore 575722.

Contact Person : Mr Tan / Ms Kwee Pin
Telephone : 6453 1255

Kindly proceed to do the needful.

Thanks & regards
Catherine
CHEONGHOH LAW CORPORATION
Blk 53 Chin Swee Road #03-05
Singapore 160053
T: 6337 8700 | F: 6337 3700 | E: mail@cheonghoh.sg

On 7 Jun 2018, at 10:11 AM, Chan, Yoke Shi <yokeshi.chan@aig.com> wrote:

Without Prejudice

Your Reference : LCH.lg/SMSL-80507.18
Our Reference : SLJ1427B

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motorsurveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

| Name of Surveyor | Company Name |
|--------------------------|--|
| Lim Kok Chong | AIG Asia Pacific Insurance Pte Ltd |
| Kumar Uthaya | AIG Asia Pacific Insurance Pte Ltd |
| Ken Wong | AIG Asia Pacific Insurance Pte Ltd |
| Lawrence Ng Chun Kee | Priority Services |
| Jeffrey Ong Leng Kiat | Priority Services |
| Jimmy Lee | Priority Services |
| EC Looi | Automobile Inspection Services Pte Ltd |
| Ricky Teng | RT Appraisal Pte Ltd |
| Elson Teng | RT Appraisal Pte Ltd |
| Michael Cheong | RT Appraisal Pte Ltd |
| Pang Kiah Keen (Frankie) | Formteam Adjusters Pte Ltd |
| Ng You Han | Formteam Adjusters Pte Ltd |
| Soon HanXin (Gary) | Formteam Adjusters Pte Ltd |
| Chow Bo Xiong | Formteam Adjusters Pte Ltd |
| Chua Soo Teck (Benjamin) | Formteam Adjusters Pte Ltd |
| Kalvin Ang | LKK Auto Consultants Pte Ltd |
| Xing Guo Qiang | LKK Auto Consultants Pte Ltd |
| Marcus Chua | LKK Auto Consultants Pte Ltd |
| Mohamad Taufikh | LKK Auto Consultants Pte Ltd |
| Adrian Ling | LKK Auto Consultants Pte Ltd |
| Henry Ng | LKK Auto Consultants Pte Ltd |
| Mohammed Rasul | LKK Auto Consultants Pte Ltd |
| Steven Foong | LKK Auto Consultants Pte Ltd |
| Wei Jie | LKK Auto Consultants Pte Ltd |
| Ma Chin Fook | LKK Auto Consultants Pte Ltd |
| Kenneth Kong | LKK Auto Consultants Pte Ltd |

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

Yoke Shi @ Ashley
AIG
Claim Adjuster II, Singapore FNOL, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)
Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel +6 03 2719 6000 | Ext 1012102

yokeshi.chan@aig.com | www.aig.com

From: Cheonghoh Law [mailto:mail@cheonghoh.sg]
Sent: Thursday, June 07, 2018 10:04 AM
To: Supramaniam, Darshene
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Lim, Sheng Yang; Md Ishak, Mohd Imran; Chan, Yoke Shi; Supramaniam, Darshene; Chin, Lee-Ying
Subject: Re: PRS for SJW 3087 R involving vehicle SLJ 1427 B on 5 June 2018 along Slip Road of Punggol East (Oref: LCH.lg/SMSL-80507.18)

Dear Sirs,

We append below our letter of PRS and await your urgent reply.

Thanks & regards
Catherine
CHEONGHOH LAW CORPORATION
Blk 53 Chin Swee Road #03-05
Singapore 160053
T: 6337 8700 | F: 6337 3700 | E: mail@cheonghoh.sg

Begin forwarded message:

From: c364@cheonghoh.sg
Subject: Message from KMBT_C364e
Date: 7 June 2018 at 9:57:14 AM SGT
To: mail@cheonghoh.sg
Reply-To: c364@cheonghoh.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.
<SKMBT_C364e18060709560.pdf>

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.
<SKMBT_C364e18060709560.pdf>

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Cheonghoh Law Corporation

(Incorporated with limited liability) Blk 53 Chin Swee Road #03-05 . Singapore 160053
Co. Reg No.201108070G Tel: 63378700 Fax: 63373700 E-mail: mail@cheonghoh.sg

In reply please quote our Reference Number

Our Ref: LCH.lg/SMSL-80507.18

07.06.18



BY FAX NO. 68357416 AND BY HAND
AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way #07-18
Singapore 079120

BY CERTIFICATE OF POSTING
Lcrf Pte Ltd
60 Anson Road
#11-01 Mapletree Anson
Singapore 079914

BY CERTIFICATE OF POSTING

Dear Sirs

We are instructed by Wong Chee Pang Jere to notify you of a road traffic accident on 05.06.18 at about 7:40 pm at Slip Road of Punggol East involving our client's vehicle registration number SJW 3087 R and vehicle registration number SLJ 1427 B driven by your insured driver/you/your driver at the material time. A copy of the Singapore accident statement filed is available.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

For the avoidance of doubt, our client will be claiming for compensation for loss of use/rental of a replacement vehicle in the instances enumerated in the State Courts Practice Direction Amendment No. 1 of 2016 paragraphs 7.1 and 7.2 of the Appendix C of the Pre-action Protocol for Non-Injury Motor Accident Cases which compensation is additional to any other claim for loss of use/rental of a replacement vehicle which our client may make against your insured and/or your insured's driver and or you/your driver.

Yours faithfully

Cheonghoh Law Corporation

encs:

This is a computer-generated document and requires no signature

cc: client (via e-mail/fax only) - SJW 3087 R

Enquire Vehicle & Owner Information (Vehicle No. SLJ1427B As At 05 Jun 2018 / 19:40:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: LCH.LG/SMSL-80507.18

Current Owner Details

Owner ID Type: Company

Owner ID: 201624597K

Owner Name: LCRF PTE LTD

Registered Address Type: Private Residential (non-Condo Apt / non-House)

Registered Block/House
No.: 60

Registered Street Name: ANSON ROAD

Registered Unit No.: # 11 - 01

Registered Building Name: MAPLETREE ANSON

Registered Postal Code: 079914

Current Vehicle Details

Vehicle No.: SLJ1427B

Make Description/Model: HONDA / SHUTTLE 1.5 HYBRID CVT ABS D/AIRBAG 2WD

Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.



松 利 摩 哆 SIONG LEE MOTOR

Sin Ming Industrial Estate
Block 12 Sector B #01-73 Singapore 575656
Tel: 6457 0410, 6453 3478 Fax: 6552 0692

Company Reg No: 100838/00J

We specialise in repairing all kinds of vehicles and pre-inspection servicing.
We also undertake accident insurance claims for our customers.

7 June 2018

ATTN: MOTOR CLAIM DEPARTMENT

ATTN: WONG CHEE PANG JERE

H/P: 9181 1858

Dear Sirs / Madam,

**Accident Claim for Vehicle No.SJW 3087 R, Involving Vehicle No.SLJ 1427 B.
Accident on 05 JUNE 2018, AT SLIP ROAD OF PUNGGOL EAST.**

With reference to the above vehicle. We hereby submit a list of parts required to be changed and append below the charges for changing and repairing ;

| NO | SUPPLEMENTARY PARTS REPLACEMENT | QTY | LIST PRICE |
|----|--|------|--------------------------------------|
| 1 | REAR BUMPER <i>585-36</i> | 1PC | \$ <i>Bu</i> 622.65 |
| 2 | REAR BUMPER LOWER SPOILER | 1PC | \$ <i>CM/Bu</i> 620.30 |
| 3 | REAR BUMPER RETIANER | 2PS | \$ <i>ps.10</i> <i>211018</i> 210.20 |
| 4 | REAR BUMPER REFLECTOR | 2PCS | \$ <i>Sn</i> 182.62 |
| 5 | REAR BOOTLID <i>1480.44</i> | 1PC | \$ <i>Bu</i> 1,651.65 |
| 6 | REAR BOOTLID RUBBER <i>332.90</i> | 1PC | \$ <i>166.455N</i> <i>Ln</i> 458.67 |
| 7 | REAR BOOTLID EMBLEM | 1PC | \$ <i>Ne</i> 86.90 |
| 8 | REAR BOOTLID STICKER 'BORNEO MOTOR' | 1PC | \$ <i>Ne</i> 48.20 |
| 9 | REAR BOOTLID LOCK | 1PC | \$ <i>Ne</i> 373.60 |
| 10 | REAR BOOTLID LOCK CATCH | 1PC | \$ <i>R</i> 62.95 |
| 11 | REAR BOOTLID HINGE | 2PCS | \$ <i>R</i> 196.06 |
| 12 | REAR BOOTLID ABSORBER | 2PCS | \$ <i>Sn</i> 775.60 |
| 13 | REAR BOOTLID LAMP | 2PCS | \$ <i>Sn</i> 657.40 |
| 14 | REAR BOOTLID HANDLE | 1PC | \$ <i>Sn</i> 350.95 |
| 15 | REAR WINDSCREEN MOULDING | 1PC | \$ <i>Ne</i> 80.20 |
| 16 | REAR EXHAUST BOX | 1PC | \$ <i>Bu</i> 882.00 |
| 17 | REAR EXHAUST BOX END CHROME <i>1105N</i> | 1PC | \$ <i>Bu</i> 192.60 |
| | TOTAL LIST PRICE | | \$ 7,452.55 |
| | LESS 20% <i>25%</i> | | \$ (1,490.51) |
| | TOTAL AMOUNT | | \$ 5,962.04 |

| NO | PARTS REPLACEMENT | QTY | SPECIAL NETT PRICE |
|----|---------------------------------|------|----------------------------------|
| 1 | REAR BOOTLID WINDSCREEN SEALANT | 1SET | \$ <i>Ne</i> <i>405N</i> 60.00 |
| 2 | REAR BUMPER REVERSE SENSOR | 1SET | \$ <i>Sn</i> <i>2005N</i> 240.00 |
| | TOTAL SPECIAL NETT PRICE | | \$ 300.00 |

Not Notified
11 Lng 84300h
Recovery After Paving
6 days

| | | | |
|---|--|-----------|-----------------|
| | LABOUR : | | |
| 1 | LABOUR TO SPRAY PAINT | \$ | 800/- 980.00 |
| 2 | LABOUR TO PANEL BEATING | \$ | 700/- 800.00 |
| 3 | LABOUR TO DISMANTLE AND REFIX REAR WINDSCREEN GLASS. | \$ | 120/- 140.00 |
| 4 | LABOUR TO APPLY RUST-PROOFING ON REPAIRED AND REPLACED PARTS | \$ | 30/- 80.00 |
| | TOTAL LABOUR | \$ | 2,000.00 |
| | TOTAL AMOUNT | \$ | 8,262.04 |

THANK YOU

FROM:

SIONG LEE MOTOR

Mr Tan Leng Huat

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/LCR18010505/KRBN2

Date: 26/09/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994822
 Claimant Vehicle No: SJW3087R Insured Vehicle No: SLJ1427B
 Date of Loss: 05/06/2018 Nature of Claim: TP Claim No: 7233824044SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJW3087R Engine No: 3ZRA466868
 Make & Model: TOYOTA WISH, 1.8 (A) Chassis No: JTDGJ20W105002225
 Reg. Date: 17/03/2010 (Man. Year: 2010) Odometer: 111467 km
 Colour: Metallic Silver
 Engine Capacity: 1987 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16
 Front Left Side: Continental 7 mm Rear Left Side: Continental 6 mm
 Front Right Side: Continental 7 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

| | Repairer's | Adjuster's | Difference | Diff % |
|-----------------------------------|------------|------------|------------|--------|
| Parts | 6,262.04 | 3,713.02 | 2,549.02 | 40.71 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,000.00 | 1,650.00 | 350.00 | 17.50 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 8,262.04 | 5,363.02 | 2,899.02 | 35.09 |
| Approved Total (Overridden) (S\$) | | 4,300.00 | | |
| (S\$) | 8,262.04 | 4,300.00 | 3,962.04 | 47.95 |
| + GST 7.00/7.00% (S\$) | 578.34 | 301.00 | 277.34 | 47.95 |
| Nett Amount (S\$) | 8,840.38 | 4,601.00 | 4,239.38 | 47.95 |

INSPECTION

Date of Assignment: 08/06/2018
 Date Inspected: 08/06/2018 Inspected At: Siong Lee Motor 160 Sin Ming (HQ)
 160 Sin Ming Drive, #02-07 AutoCity
 Singapore 575722
 Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. Particulars | Condition | Repairer's | Amount |
|-----|-----|--------------------------------------|-----------------|-------------|--------------|
| 1 | 1 | *REAR BUMPER | Buckled | 622.65 FL | *585.36 FL |
| 2 | 1 | *REAR BUMPER LOWER SPOILER | Cracked/Buckled | 620.30 FL | *620.30 FL |
| 3 | 1 | *REAR BUMPER RETAINER | N/s Distorted | 210.20 FL | *105.10 FL |
| 4 | 2 | *REAR BUMPER REFLECTOR | Serviceable | 182.62 FL | *- FL |
| 5 | 1 | *REAR BOOTLID | Bent | 1,651.65 FL | *1,480.44 FL |
| 6 | 1 | *REAR BOOTLID EMBLEM | Necessary | 86.90 FL | *86.90 FL |
| 7 | 1 | *REAR BOOTLID STICKER BORNEO MOTOR | Necessary | 48.20 FL | *48.20 FL |
| 8 | 1 | *REAR BOOTLID LOCK | Dented | 373.60 FL | *373.60 FL |
| 9 | 1 | *REAR BOOTLID LOCK CATCH | Repair | 62.95 FL | *- FL |
| 10 | 2 | *REAR BOOTLID HINGE | Repair | 196.06 FL | *- FL |
| 11 | 2 | *REAR BOOTLID ABSORBER | Serviceable | 775.60 FL | *- FL |
| 12 | 2 | *REAR BOOTLID LAMP | Serviceable | 657.40 FL | *- FL |
| 13 | 1 | *REAR BOOTLID HANDLE | Serviceable | 350.95 FL | *- FL |
| 14 | 1 | *REAR WINDSCREEN MOULDING | Necessary | 80.20 FL | *80.20 FL |
| 15 | 1 | *REAR EXHAUST BOX | Bent | 882.00 FL | *882.00 FL |
| 16 | 1 | *REAR EXHAUST BOX END CHROME | Dented | 154.08 FS | *110.00 FS |
| 17 | 1 | *SET REAR BOOTLID WINDSCREEN SEALANT | Necessary | 60.00 FS | *40.00 FS |
| 18 | 1 | *SET REAR BUMPER REVERSE SENSOR | Scratched | 240.00 FS | *200.00 FS |
| 19 | 1 | *REAR BOOTLID RUBBER (50%) | Cut | 366.94 FS | *166.45 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|---|----------|----------|
| Sub Total (\$\$) | 7,622.30 | 4,778.55 |
| - List Item Discount on L Items 20.00/25.00% (\$\$) | 1,360.26 | 1,065.53 |
| Total Parts (\$\$) | 6,262.04 | 3,713.02 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-------------------------|--|----------|------------|----------|
| Labour Items | | | | |
| 1 | LABOUR TO SPRAY PAINT | New | 980.00 | 800.00 |
| 2 | LABOUR TO PANEL BEATING | New | 800.00 | 700.00 |
| 3 | LABOUR TO DISMANTLE AND REFIX REAR WINDSCREEN GLASS | New | 140.00 | 120.00 |
| 4 | LABOUR TO APPLY RUST-PROOFING ON REPAIRED AND REPLACED PARTS | New | 80.00 | 30.00 |
| Gross Labour Cost (S\$) | | | 2,000.00 | 1,650.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >