

22/03/2003

ASS. REC. BY:

REF:

CS/MSG18010507/ Agd32

Special Instruction:

Surveyor:

Menimen

Adnan

ASSIGNMENT (Office)

From (Person):

Fievel Poo

of

MSIG

Date/Time:

8/6/2014 @ 3:24pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLN 7846P

Insured:

YN 28297

at Workshop m/s

Kang Car Repairs

Tel:

67477636

of

No. 1 Kaki Bukit Ave 6 # 02-46

Policy No:

A29027503 MKC

Claim No:

560076

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

31/05/2018

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement:

Date/Time: 3:48pm @ 8/6/18

Person Contacted:

Sharon

Vehicle-IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLN 7846P-X
12/6/18 @ 3:20pm	Informed Fievel Poo, we are pending estimate from negotiator.
06/7/18 @ 9:48am	revised to Fievel Poo via Menimen.
	Final Fig \$4550.88, 4 days (Red \$1165.84, 20%.)

ASS. REC. BY: Adrian Ling

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLX7846P

Yr Regn:

2017, MengType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Tucson c.c. 1591

Colour:

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

3659A

T/Radio:

Insured / Std / NI / NA

Eng/No:

KMHJ3812VJ4491122

C/No:

Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/60R17

R:

225/60R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Kumho

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

11/06/18

Survey held at

KongDes. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop orFrnt, o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP MSLG

RECEIVED 11 JUL 2018

9/7/2018

Date/Time, File Pass to?

☐

: Preli. Report

1) 11/7/18 TP MSLG☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

Survey Fee:

200

Transportation:

S + RS. SI

Photos

Others

10

TOTAL

210

Report Format:

WER-TP

Lump Sum / L.B.I. (\$)

4550.88



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : GBA9870S
Make & Model : OPEL, COMBP VAN AZ, W0L0XCF2574413366
Year of Manufacture : 2007
Estimation No. : E18010088
DOA : 24/01/2018

No	Description	Qty	U/P	Amt
				Amt S\$ 2,560.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 2,560.00

Adrian L
L/S 30/01/18
OB Days

List Items Subtotal	S\$ 0.00
Special Nett Items Subtotal	S\$ 940.00
Labour Items Subtotal	S\$ 2,560.00
Total	S\$ 3,500.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18010507/Aqd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 08-06-2018	
		Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YN 2829T	Veh. Inspected	SLN 7846P
Policy No.	A29027503MKC	Coverage (\$)	0.00
Claim No.	560076	Excess (\$)	0.00
Assign From	MERIMEN (FIEVEL FOO)	Assign Date	08/06/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	31/05/2018	Inspection Date	
Survey held at	KANG CAR REPAIRERS PTE LTD NO.1 KAKI BUKIT AVE 6 #02-06 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	01 Jun 2018		08 Jun 2018 15:24 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	ALFA MOVERS SERVICES , Co. Reg. No.: NA		
Main Claimant:	WONG SHU YONG , ID: S7675063G		
Vehicle Reg. No.:	SLN7846P	Date of Loss:	31/05/2018 17:00 - :59 [12 Months and 13 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 560076	Policy/Cover Note No.:	A29027503MKC (Comprehensive) Coverage: 12/10/2017 - 11/10/2018
Vehicle Reg. No. (Insured):	YN2829T	Policy No. (Claimant):	
		Excess:	
Repairer:	Kang Car Repairers Pte Ltd (HQ) No 1 Kaki Bukit Ave 6, #02-06 AutoBay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67477636		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wenyao - 6643 1316]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 09/06/2018]		
Driver/Custodian (Insured):	SADELY BIN MOHAMED (), NRIC: S7522035I, Tel: +6591722032		
Adj Asg. Remarks:	Car in on 11/06/18. LIABILITY 100% SJE AGREE - LKK CONTACT SHARON AT 6747 7636		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Fievel Foo Wen-yao

Date: 06 Jul 2018

Preliminary Advice

Insured Vehicle No	: YN2829T	Accident Date	: 31/05/2018
TP Vehicle No	: SLN7846P	Assignment Date	: 08/06/2018
Make	: HYUNDAI TUCSON	Est. Duration of Repair	: 4.00
Date of Inspection	: 11/06/2018		
Inspection At	: KANG CAR REPAIRERS PTE LTD (HQ) NO 1 KAKI BUKIT AVE 6, #02-06 AUTOBAY@KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,716.72
Revised Amount	:S\$	4,550.88
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,550.88

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Shiau Chan (LKKAuto)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Tuesday, 12 June 2018 3:20 PM
To: do-not-reply@merimen.com
Cc: SUR
Subject: VEHICLE SLN 7846P (YOUR REF: 560076)

This mail is associated with :

***SLN7846P (560076)**

[YN2829T]

TP

WONG SHU YONG

May 31 2018 5:00PM

[ALFA MOVERS SERVICES]

Kang Car Repairers Pte Ltd

Dear Fievel,

Please be informed that we have inspected the vehicle SLN 7846P on 11/06/2018.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd
Tel: 6256 3561

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)

Claim Documents
***SKC8005M (800622086)**
TP
NG QIXING TERENCE
[Ho Tai Loon (He Dailun)]

[Upload Documents](#) [Upload Photos](#) [Compose New Letter](#) **View** [Use Viewer](#)

Letters/Correspondences			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	
1	(Draft)	Third Party Express Settlement - Payment Breakdown	<div><div></div><div>1</div><div>Edit</div></div>
			<div><div></div><div>1 per page</div><div>▲</div></div>
			<div><div></div><div>Thumbnail</div><div>Print</div></div>

Photos/Images 3 per page ▲

No Relabel/Reorder LKK Auto Consultants Pte Ltd (HQ)

1 12/12/12 11:01 Chassis Number

2 12/12/12 11:01 General View

3 12/12/12 11:01 General View

4 12/12/12 11:01 General View

5 12/12/12 11:01 General View

6 12/12/12 11:01 General View

7 12/12/12 11:01 General View

8 12/12/12 11:01 General View

9 12/12/12 11:01 General View

10 12/12/12 11:01 General View

11 12/12/12 11:01 General View

12 12/12/12 11:01 General View

13 12/12/12 11:01 General View

14 12/12/12 11:01 General View

15 12/12/12 11:02 Reinspection Photo

16 12/12/12 11:02 Reinspection Photo

17 12/12/12 11:02 Reinspection Photo

18 12/12/12 11:02 Reinspection Photo

19 12/12/12 11:02 Reinspection Photo

20 12/12/12 11:02 Reinspection Photo

21 12/12/12 11:02 Reinspection Photo

22 12/12/12 11:02 Reinspection Photo

23 12/12/12 11:02 Reinspection Photo

24 12/12/12 11:02 Reinspection Photo

25 12/12/12 11:02 Reinspection Photo

26 12/12/12 11:02 Reinspection Photo

27 12/12/12 11:02 Reinspection Photo

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	31/05/2018 23:58
Date Of Accident	31/05/2018 17:40
Exact Location Of Accident	TAMPINES CENTRAL 5
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN7846P
Insured/Policyholder	
Name Of Registered Owner	WONG SHU YONG
NRIC No	S7675063G
Email Address	EMAIL2HIM@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-88761011
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	HYUNDAI
Model	TUCSON-1.6 TL GLS (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5091373568-01
Cover Note Number	

Driver

Name of Driver	LUN WAI YEN
NRIC No	S7573198A
Date Of Birth	24/11/1975
Occupation	INDOOR
Date Of Driving Pass	05/05/2007
Driving Experience	11 YEARS AND 0 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-88761011
Fax Number	
Contact Number	
Email Address	EMAIL2HIM@YAHOO.COM.SG

Address	12 FLORA ROAD #06-01 AZALEA PARK CONDOMINIUM
Postcode	509730
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : WONG XIEN YEE GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	EMAIL TO MOTORVIDEO@INCOME.COM.SG
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN2829T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	SADELY BIN MOHAMED
NRIC/Passport Number	S7522035I
Contact Number	91722032
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "**Purposes**").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time

21/05/2018
2.05 PM

Driver's Signature

(If driver is not the policyholder)

Date & Time 21/05/2018
2.05 PM


Reporting Centre Personnel's Signature

Name: 李俊强 李俊强

NRIC/FIN No. 272257282

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the 31/05/2018 at 1740hrs, I was driving along Tampines Central 5 along the leftmost lane. I signalled right to change to the middle lane. When I was already in my lane, VN2829T veered into the middle lane without signaling. I honked but VN2829T did not stop, thus colliding into my right side. No injuries sustained in the accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 31/05/2018 17:40

Driver's Signature
(If driver is not the policyholder)
Date & Time: 31/05/2018 17:40

Reporting Centre Personnel's Signature
Name: [Signature]
NRIC/FIN No.: 9923 77023

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
 GST:201300201N

M/S : MSIG INSURANCE (SINGAPORE) PTE LTD
 4 SHENTON WAY
 #21-01 SGX CENTRE 2
 SINGAPORE 068807

TEL: 68277888 FAX: 62257402
 ATTN: Motor Claim Department

Estimate No: EST1800162

Date: 05 Jun 2018

Veh Reg No: SLN7846P

Make/Model: HYUNDAI TL TUCSON
 1.6GLS

Chasis No: KMHJ3812VJU491122

Reg. Date: 18/05/2017

Your Ref No: YN2829T

Claim Type: Third Party
Accident Date: 31/05/2018
TP Veh Reg No: YN2829T

xiao Chen

Estimate Repair Cost to Vehicle No :SLN7846P

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
List Price			
1	1 PC FRT FENDER RH <i>Dented</i>	634.80	✓
2	1 PC FRT FENDER COWLING RH <i>new</i>	130.60	+
3	1 PC FRT FENDER WHEEL ARCH GARNISH RH <i>Cut</i>	165.90	✓
4	1 PC FRT BUMPER <i>Rehd.</i>	594.70	✓
5	1 PC FRT BUMPER SIDE GARNISH RH <i>new</i>	126.70	+
6	1 PC FRT BUMPER RETAINER RH <i>new</i>	21.40	✓
7	1 PC HEADLAMP RH <i>Cracked</i>	2,677.90	✓
		4,352.00	
		Less 20%	870.40
			3,481.60
Special Net			
8	1 SET FRT FENDER COWLING CLIPS RH <i>new</i>	40.00	+
9	1 SET FRT FENDER WHEEL ARCH GARNISH CLIPS RH <i>new</i>	40.00	30
10	1 SET FRT BUMPER CLIPS <i>new</i>	40.00	30
		120.00	120.00
Labour			
11	1 TO CHECK WIRING	50.00	30
12	1 TO REMOVE AND REFIT FRT PARKING SENSOR	80.00	50
13	1 TO SPRAY UNDERSEAL	80.00	✓
14	1 TO SPRAY PAINTING	750.00	400
15	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	800.00	400
		1,760.00	1,760.00

Price Double check already.

*4094.70
3275.76*

60

880

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : MSIG INSURANCE (SINGAPORE) PTE LTD
4 SHENTON WAY
#21-01 SGX CENTRE 2
SINGAPORE 068807

TEL: 68277888 FAX: 62257402
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 31/05/2018
TP Veh Reg No: YN2829T

Estimate No: EST1800162
Date: 05 Jun 2018

Veh Reg No: SLN7846P
Make/Model: HYUNDAI TL TUCSON
1.6GLS
Chasis No: KMHJ3812VJU491122
Reg. Date: 18/05/2017
Your Ref No: YN2829T

Estimate Repair Cost to Vehicle No :SLN7846P

Quantity	Description	List Price	Amount
		SS	SS
	Total		S\$ 5,361.60
	Add GST @ 7%		375.31
	Total Amount Payable		S\$ 5,736.91

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND SEVEN HUNDRED THIRTY SIX AND CENTS NINETY ONE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

Adrian Lim
P/P 11/06/18

04 Days

Supplementary: 335.12

total: 4550.88 (P/P)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST: 201300201N

M/S : MSIG INSURANCE (SINGAPORE) PTE LTD
4 SHENTON WAY
#21-01 SGX CENTRE 2
SINGAPORE 068807

TEL: 68277888 FAX: 62257402
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 31/05/2018
TP Veh Reg No: YN2828T

Estimate No: EST1800162
Date: 13 Jun 2018

Veh Reg No: SLN7846P
Make/Model: HYUNDAI TL TUCSON
1.6GLS
Chasis No: KMHJ3812VJU491122
Reg. Date: 18/05/2017
Your Ref No: YN2829T

Estimate Repair Cost to Vehicle No :SLN7846P

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
	Supplementary Parts to Repair		
	List Price		
1	1 PC FRT LOWER BUMPER <i>ict</i>	381.40	
		305.12	
		381.40	
	Less 20%	76.28	305.12
	Special Net		
2	1 SET RH SIDE SKIRT CLIPS <i>rlor</i>	30	
		50.00	
		50.00	50.00
	Total		S\$ 355.12
	GST Amount		S\$ 24.86
	Total Amount Payable		S\$ 379.98

For Kang Car Repairers Pte Ltd


AUTHORISED SIGNATURE

Supplementary: 335.12.

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST 201300201N

M/S : MSIG INSURANCE (SINGAPORE) PTE LTD
4 SHENTON WAY
#21-01 SGX CENTRE 2
SINGAPORE 068807

TEL: 68277888 FAX: 62257402
ATTN: Motor Claim Department

Estimate No: EST1800162

Date: 05 Jun 2018

Veh Reg No: **SLN7846P**

Make/Model: HYUNDAI TL TUCSON
1.6GLS

Chasis No: KMHJ3812VJU491122

Reg. Date: 18/05/2017

Your Ref No: YN2829T

Claim Type: Third Party

Accident Date: 31/05/2018

TP Veh Reg No: YN2829T

Estimate Repair Cost to Vehicle No :SLN7846P

Quantity	Description	List Price	Amount
		SS	SS
List Price			
1	1 PC FRT FENDER RH <i>Dented</i>	634.80	✓
2	1 PC FRT FENDER COWLING RH <i>new</i>	130.60	X
3	1 PC FRT FENDER WHEEL ARCH GARNISH RH <i>Cut</i>	165.90	✓
4	1 PC FRT BUMPER <i>Dented</i>	594.70	✓
5	1 PC FRT BUMPER SIDE GARNISH RH <i>new</i>	126.70	X
6	1 PC FRT BUMPER RETAINER RH <i>new</i>	21.40	✓
7	1 PC HEADLAMP RH <i>Dented</i>	2,677.90	2 ✓
	<i>1pc front lower bumper 382.40</i>	4,352.00	
	<i>1 set side skirt clips - 50.00</i>	870.40	3,481.60
	Special Net		
8	1 SET FRT FENDER COWLING CLIPS RH <i>new</i>	40.00	+
9	1 SET FRT FENDER WHEEL ARCH GARNISH CLIPS RH <i>new</i>	40.00	30
10	1 SET FRT BUMPER CLIPS <i>new</i>	40.00	30
		120.00	120.00
Labour			
11	1 TO CHECK WIRING	50.00	30
12	1 TO REMOVE AND REFIT FRT PARKING SENSOR	80.00	50
13	1 TO SPRAY UNDERSEAL	80.00	X
14	1 TO SPRAY PAINTING	750.00	400
15	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	800.00	400
		1,760.00	1,760.00

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : MSIG INSURANCE (SINGAPORE) PTE LTD
4 SHENTON WAY
#21-01 SGX CENTRE 2
SINGAPORE 068807

TEL: 68277888 FAX: 62257402
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 31/05/2018
TP Veh Reg No: YN2829T

Estimate No: EST1800162

Date: 05 Jun 2018

Veh Reg No: SLN7846P

Make/Model: HYUNDAI TL TUCSON
1.6GLS

Chasis No: KMHJ3812VJU491122

Reg. Date: 18/05/2017

Your Ref No: YN2829T

Estimate Repair Cost to Vehicle No :SLN7846P

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
	Total		SS 5,361.60
	Add GST @ 7%		375.31
	Total Amount Payable		<u>SS 5,736.91</u>

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND SEVEN HUNDRED THIRTY SIX AND CENTS
NINETY ONE ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time
which may be required after work has begun.

For Kang Car Repairers Pte Ltd


AUTHORISED SIGNATURE

Adrian hong
P/P 11/06/18.
04 days.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Jun 2018		08 Jun 2018 15:24 Edit Adj Rpt	S\$4,550.88 Edit Estimates	S\$4,550.88 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------
































CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	ALFA MOVERS SERVICES, Co. Reg. No.: NA	
Main Claimant:	WONG SHU YONG, ID: S7675063G	
Vehicle Reg. No.:	SLN7846P	Date of Loss: 31/05/2018 17:00 - :59 [12 Months and 13 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 560076	Policy/Cover Note No.: A29027503MKC (Comprehensive) Coverage: 12/10/2017 - 11/10/2018
Vehicle Reg. No. (Insured):	YN2829T	Policy No. (Claimant):
		Excess:
Repairer:	Kang Car Repairers Pte Ltd (HQ) No 1 Kaki Bukit Ave 6, #02-06 AutoBay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67477636	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Fievel Foo Wenyao - 6643 1316]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 08/07/2018]	
Driver/Custodian (Insured):	SADELY BIN MOHAMED (), NRIC: S7522035I, Tel: +6591722032	
Adj Asg. Remarks:	Car in on 11/06/18. LIABILITY 100% SJE AGREE - LKK CONTACT SHARON AT 6747 7636	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

***SLN7846P (560076)**
[YN2829T]
TP
WONG SHU YONG
May 31 2018 5:00PM
[ALFA MOVERS SERVICES]
Kang Car Repairers Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	05/06/18 11:21	Accident Statement From: SC - Reg. No: YN2829T, Claimant: ALFA MOVERS SERVICES	 Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/07/18 09:48	Adjuster Immediate Advice	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/07/18 19:30	General View	 Load JPG	<input checked="" type="checkbox"/>
2	05/07/18 19:30	General View	 Load JPG	<input checked="" type="checkbox"/>
3	05/07/18 19:30	General View	 Load JPG	<input checked="" type="checkbox"/>
4	05/07/18 19:30	General View	 Load JPG	<input checked="" type="checkbox"/>
5	05/07/18 19:30	General View	 Load JPG	<input checked="" type="checkbox"/>
6	05/07/18 19:30	General View	 Load JPG	<input checked="" type="checkbox"/>
7	05/07/18 19:30	General View	 Load JPG	<input checked="" type="checkbox"/>
8	05/07/18 19:30	General View	 Load JPG	<input checked="" type="checkbox"/>
9	05/07/18 19:30	General View	 Load JPG	<input checked="" type="checkbox"/>
10	05/07/18 19:30	General View	 Load JPG	<input checked="" type="checkbox"/>
11	05/07/18 19:30	General View	 Load JPG	<input checked="" type="checkbox"/>
12	05/07/18 19:30	General View	 Load JPG	<input checked="" type="checkbox"/>
13	05/07/18 19:30	General View	 Load JPG	<input checked="" type="checkbox"/>
14	05/07/18 19:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
15	05/07/18 19:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
16	05/07/18 19:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
17	05/07/18 19:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
18	05/07/18 19:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
19	05/07/18 19:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
20	05/07/18 19:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
21	05/07/18 19:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
22	05/07/18 19:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
23	05/07/18 19:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
24	05/07/18 19:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
25	05/07/18 19:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
26	05/07/18 19:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	05/06/18 11:21	SLN7846P E-FILE REPORT From: SC - Reg. No: YN2829T, Claimant: ALFA MOVERS SERVICES	 Load PDF	
2	05/06/18 11:24	ESTIMATE	 Load PDF	
3	05/06/18 11:32	email to sharon Direct settlement	 Load TXT	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
4	05/06/18 13:29	Survey Agree on SJE - LKK		Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	17/07/18 15:03	Supplementary		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18010507/AQD3E2

Date: 17/07/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A29027503MKC

Claimant Vehicle No : SLN7846P

Insured Vehicle No : YN2829T

Date of Loss: 31/05/2018

Nature of Claim: TP

Claim No: 560076

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLN7846P

Make & Model: HYUNDAI TUCSON, 1.6 TL GLS (A)

Engine No: G4FJHU494889

Reg. Date: 18/05/2017 (Man. Year: 2017)

Chassis No: KMHJ3812VJU491122

Colour: Grey

Odometer: 36594 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/60 R17

Rear Tyre Size: 225/60 R17

Front Left Side: Kumho 6 mm

Rear Left Side: Kumho 6 mm

Front Right Side: Kumho 6 mm

Rear Right Side: Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,956.72	3,670.88	285.84	7.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,760.00	880.00	880.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,716.72	4,550.88	1,165.84	20.39
+ GST 7.00/7.00% (S\$)	400.17	318.56	81.61	20.39
Nett Amount (S\$)	6,116.89	4,869.44	1,247.45	20.39

INSPECTION

Date of Assignment: 08/06/2018

Date Inspected: 11/06/2018 Inspected At:

Kang Car Repairers Pte Ltd (HQ)
No 1 Kaki Bukit Ave 6, #02-06
AutoBay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 17 Jul 2018)
Parts: 143	HYUNDAI TUCSON 1.6 TL GLS (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLN7846P)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT FENDER RH	Dented	634.80 FL	*634.80 FL
2	1		*FRT FENDER COWLING RH	Not Necessary	130.60 FL	*- FL
3	1		*FRT FENDER WHEEL ARCH GARNISH RH	Cut	165.90 FL	*165.90 FL
4	1		*FRT BUMPER	Deformed	594.70 FL	*594.70 FL
5	1		*FRT BUMPER SIDE GARNISH RH	Not Necessary	126.70 FL	*- FL
6	1		*FRT BUMPER RETAINER RH	Necessary	21.40 FL	*21.40 FL
7	1		*HEADLAMP RH	Cracked	2,677.90 FL	*2,677.90 FL
8	1		*SET FRT FENDER COWLING CLIPS RH	Not Necessary	40.00 FS	*- FS
9	1		*SET FRT FENDER WHEEL ARCH GARNISH CLIPS RH	Necessary	40.00 FS	*30.00 FS
10	1		*SET FRT BUMPER CLIPS	Necessary	40.00 FS	*30.00 FS
11	1		*FRT LOWER BUMPER	Cut	381.40 FL	*381.40 FL
12	1		*SET RH SIDE SKIRT CLIPS	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,903.40	4,566.10
- List Item Discount on L Items 20.00/20.00% (S\$)	946.68	895.22
Total Parts (S\$)	3,956.72	3,670.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	30.00
2	TO REMOVE AND REFIT FRT PARKING SENSOR	New	80.00	50.00
3	TO SPRAY UNDERSEAL	New	80.00	0.00
4	TO SPRAY PAINTING	New	750.00	400.00
5	TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING / WELDING WORKS	New	800.00	400.00
Gross Labour Cost (S\$)			1,760.00	880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >