

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : MSIG INSURANCE (SINGAPORE) PTE LTD
4 SHENTON WAY
#21-01 SGX CENTRE 2
SINGAPORE 068807

TEL: 68277888 FAX: 62257402
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 31/05/2018
TP Veh Reg No: YN2828T

Estimate No: EST1800162
Date: 13 Jun 2018

Veh Reg No: SLN7846P
Make/Model: HYUNDAI TL TUCSON
1.6GLS
Chasis No: KMHJ3812VJU491122
Reg. Date: 18/05/2017
Your Ref No: YN2829T

Estimate Repair Cost to Vehicle No :SLN7846P

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
	Supplementary Parts to Repair		
	List Price		
1	1 PC FRT LOWER BUMPER <i>cit</i>	381.40 305.12	✓
		381.40	
	Less 20%	76.28	305.12
	Special Net		
2	1 SET RH SIDE SKIRT CLIPS <i>xler</i>	30 50.00	30
		50.00	50.00
	Total		S\$ 355.12
	GST Amount		S\$ 24.86
	Total Amount Payable		S\$ 379.98

For Kang Car Repairers Pte Ltd


AUTHORISED SIGNATURE

Supplementary: 335.12