

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9554D**AAD1806-036**

616118 In
 Not Notarised
 Car @ WLS
 1 Bny @ 3950/-

Vehicle No.:

SHB 9554D

Chassis No.:

KL1LA69RJBB124135

Vehicle Make:

CHEVROLET

Vehicle Model:

EPICA 2.0

Date of Accident :

4.6.2018

Third Party Insurer :

Akh

PART			LIST	
1	1	Rear Bumper	\$	Bu 1,202.00 ✓
2	1	Rear Bumper Beam	\$	Buc 239.94 ✓
3	1	Rear Bumper Centre Absorber	\$	Sm 260.00 X
4	1	Rear Bumper Side Retainer RH	\$	Sm 68.76 X
5	1	Rear Bumper Side Retainer LH	\$	Dis 68.76 ✓
6	1	Rear Bumper Reflectors RH	\$	Sm 119.74 X
7	1	Rear Bumper Reflectors LH	\$	Sm 119.74 X
8	1	Rear Bumper Tow Hook Cover	\$	Sm 93.00 X
9	1	Rear End Panel Outer	\$	Bu 623.76 ✓
10	1	Rear End Panel Inner Trim	\$	Sm 263.84 X
11	1	Rear Luggage Floor Panel	\$	Sm 973.00 X
12	1	Rear Luggage Floor Panel Insulator	\$	Sm 63.50 X
13	1	Rear Luggage Floor Panel Trim Board	\$	Sm 378.00 X
14	1	Bootlid	\$	Bu 973.00 ✓
15	1	Bootlid inner trim board	\$	Sm 400.00 X
16	1	Bootlid Weatherstrip	\$	Sm 344.28 X
17	1	Bootlid Lock - Top	\$	Sm 466.56 X
18	1	Bootlid 'CHEVROLET' Badge	\$	Sm 120.62 ✓
19	1	Bootlid Logo	\$	Sm 138.84 ✓
20	1	Bootlid 'EPICA LT' Badge	\$	Sm 119.84 ✓
21	1	Bootlid Reflector Centre	\$	Sm 217.97
22	1	Bootlid Reflector RH	\$	Sm 128.40
23	1	Bootlid Reflector LH	\$	Sm 128.40
24	1	Rear Tail Lamp RH	\$	Sm 479.30
25	1	Rear Tail Lamp LH	\$	Sm 479.30
26	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$	Sm 1,110.00
27	1	Rear Fender RH	\$	Sm 1,145.00
28	1	Rear Fender Inner Trim RH	\$	Sm 418.44
29	1	Rear Fender LH	\$	Sm 1,145.00

Trans-cab Auto Services Pte Ltd**AAD1806-036**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9554D

30	1	Rear Fender Inner Trim LH	\$	<i>Sn</i>	418.44	<i>X</i>
----	---	---------------------------	----	-----------	--------	----------

TOTAL	\$	12,707.43
10%	\$	1,270.74
	\$	11,436.69

Special Nett

1	1Set	Bootlid inner trim board Clip	\$	<i>nn</i>	40.00	<i>X</i>
2	1Set	Rear Bumper Parking Sensor	\$	<i>Shar</i>	300.00	<i>✓</i>
3	1Set	Rear Bumper Fastener Clip	\$	<i>nn</i>	44.00	<i>✓</i>
4	1Set	Rear Fender Inner Trim Clip LH	\$	<i>nn</i>	30.00	<i>X</i>
5	1Set	Rear Bumper End Dust Cover Clip	\$	<i>nn</i>	30.00	
6	1	Rear Exhaust Mounting	\$	<i>Sn</i>	300.00	
7	2	Rear Windscreen Sealant	\$	<i>nn</i>	80.00	
8	1	Rear Windscreen Inner Sponge Seal	\$	<i>nn</i>	100.00	
9	1	Spare Tyre	\$	<i>Sn</i>	180.00	
10	1	Spare Wheel Rim	\$	<i>Sn</i>	126.74	

TOTAL	\$	1,230.74
--------------	-----------	-----------------

TOTAL PARTS	\$	12,667.43
--------------------	-----------	------------------

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$	3,500.00	<i>6000</i>
----	----------	-------------

To Check Electrical Lighting Concerned.

\$	170.00	<i>200</i>
----	--------	------------

To Rust-Proofing Of The Affected Areas.

\$	170.00	<i>600</i>
----	--------	------------

Putty And Spray Painting Of The Affected
Portion.

\$	3,200.00	<i>6000</i>
----	----------	-------------

To reinstall rear bumper parking sensor.

\$	170.00	<i>600</i>
----	--------	------------

Trans-cab Auto Services Pte Ltd**AAD1806-036**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9554D

To transfer of end panel fittings and conduct
water seepage test.

\$ 170.00 *602*

To transfer of boot fittings and conduct water
seepage test.

\$ 170.00 *602*

To remove and refit interior fittings, trimings,
garnish, fittings and other, to enable repair.

\$ *nn* 380.00 *X*

To check steering geometry and computer
wheel alignment

\$ *nn* 220.00 *X*

\$ 8,150.00

TOTAL \$ 20,817.43

Repair Days (LUMP SUM)*10 Days**5 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: