

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9912T

AAD1806-011

Not Authorized

61 Imp @ 1450/

Vehicle No.:	SHD 9912T
Chassis No.:	VF1ABL15AUC277440
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE
Date of Accident :	31.5.2018
Third Party Insurer :	CHINA TAIPING

PART	LIST
1 DOOR PANEL REAR LH L70Y	\$ <i>R</i> 2,844.66 X
1 FENDER PANEL REAR LH	\$ <i>R</i> 3,299.13 X
1 FENDER PANEL INNER TRIM REAR	\$ <i>Sn</i> 671.45 X
1 WHEELARCH REAR LH	\$ <i>Sn</i> 543.47 X
1 BUMPER COVER REAR	\$ <i>Bu</i> 1,108.46 ✓
1 BUMPER LOWER REAR	\$ <i>Sn</i> 768.84 X
1 BUMPER BRACKET CTR REAR	\$ <i>Sn</i> 113.47 X
1 BUMPER RETAINER LH REAR	\$ <i>Di</i> 44.99 ✓
1 BUMPER BEAM REAR	\$ <i>R</i> 777.52
1 BUMPER BEAM BRACKET LH REAR	\$ <i>Sn</i> 225.95
1 TAILLAMP LH	\$ <i>Sn</i> 552.55 } X
1 FUEL FLAP	\$ <i>Sn</i> 343.57
1 ROCKER PANEL INNER GARNISH LH	\$ <i>Sn</i> 466.51
1 ROCKER PANEL INNER LH	\$ <i>R</i> 1,024.79
1 ROCKER PANEL CENTER LH	\$ <i>R</i> 990.25
	<hr/>
	\$ 13,775.61
	10% \$ 1,377.56
	<hr/>
	\$ 12,398.05
	<hr/> <hr/>

Special Nett

1 REAR DOOR STICKER '6555 3333'	\$ <i>nn</i> 80.00 X
	<hr/>
TOTAL	\$ 80.00
	<hr/>

TOTAL PARTS \$ 12,478.05

Trans-cab Auto Services Pte Ltd

AAD1806-011

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9912T

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,450.00	<i>30d</i>
Putty and spray painting of the affected portion.	\$	2,000.00	<i>44d</i>
To rust-proofing of the affected areas.	\$	<i>nn</i> 170.00	<i>X</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	<i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>15%</i>
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00	<i>X</i>

TOTAL \$ 3,490.00

Over All Total \$ 15,968.05

LUMP SUM (REPAIR DAY)

7 DAYS

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: