

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 9878U****AAD1806-048***Not Authorized  
L1 Smp \$3550/h*

Vehicle No.:  
Chassis No.:  
Vehicle Make:  
Vehicle Model:  
Date of Accident :  
Third Party Insurer :

**SHB 9878U**  
VF1ABL15AUC273363  
RENAULT  
LATITUDE  
4.6.2018  
**AIG**

| <b>PART</b> |                                 | <b>LIST</b> |                          |
|-------------|---------------------------------|-------------|--------------------------|
| 1           | BUMPER COVER FRT                | \$          | <i>Actual</i> 1,259.42 ✓ |
| 1           | BUMPER SPOILER FRT              | \$          | <i>SL</i> 181.75         |
| 1           | BUMPER ABSORBER FRT             | \$          | <i>SL</i> 394.68         |
| 1           | BUMPER RETAINER FRT RH          | \$          | <i>SL</i> 150.77 } X     |
| 1           | BUMPER SUPPORT FRT              | \$          | <i>SL</i> 123.88         |
| 1           | BUMPER UNDERTRAY FRT            | \$          | <i>SL</i> 472.83         |
| 1           | BUMPER GRILLE LOWER FRT         | \$          | <i>SL</i> 266.80         |
| 1           | BUMPER FOG LAMP GRILLE RH       | \$          | <i>SL</i> 207.21         |
| 1           | BUMPER BEAM FRT                 | \$          | <i>SL</i> 914.08         |
| 1           | HEADLAMP RH                     | \$          | <i>Actual</i> 1,184.43 ✓ |
| 1           | HEADLAMP PANEL FRT RH           | \$          | <i>R</i> 152.15 X        |
| 1           | FENDER PANEL FRT RH             | \$          | <i>R</i> 783.83 X        |
| 1           | WHEELARCH FRT RH                | \$          | <i>SL</i> 278.84 X       |
| 1           | FENDER BRACKET LOWER RH         | \$          | <i>SL</i> 15.79 X        |
| 1           | FENDER INSULATOR RH             | \$          | <i>SL</i> 130.84 X       |
| 1           | DOOR PANEL FRT RH               | \$          | <i>R</i> 2,844.66 X      |
| 1           | RADIATOR GRILLE                 | \$          | <i>EM</i> 1,707.78 ✓     |
| 1           | RADIATOR GRILLE BADGE 'RENAULT' | \$          | <i>R</i> 225.36 ✓        |
| 1           | RADIATOR GRILLE FRAME           | \$          | <i>SL</i> 1,353.75       |
| 1           | RADIATOR FAN COWLING            | \$          | <i>SL</i> 820.54         |
| 1           | RADIATOR FAN MOTOR LH           | \$          | <i>SL</i> 967.36         |
| 1           | RADIATOR FAN MOTOR RH           | \$          | <i>SL</i> 1,479.46       |
| 1           | FRAME FULL SUPPORT PANEL        | \$          | <i>SL</i> 615.90         |
| 1           | FRAME FULL SUPPORT BRACKET      | \$          | <i>R</i> 89.79 } X       |
| 1           | DOOR MIRROR ASSY RH             | \$          | <i>SL</i> 1,483.40       |
| 1           | DOOR PANEL FRT RH               | \$          | <i>R</i> 2,844.66        |
| 1           | BONNET                          | \$          | <i>R</i> 1,941.63        |
| 1           | BONNET INSULATOR                | \$          | <i>SL</i> 405.73         |
| 1           | BONNET STRUT LH                 | \$          | <i>SL</i> 88.61          |
| 1           | BONNET STRUT RH                 | \$          | <i>SL</i> 88.61          |

**Trans-cab Auto Services Pte Ltd**

AAD1806-048

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9878U

|   |                                |    |          |   |
|---|--------------------------------|----|----------|---|
| 1 | BONNET HINGE LH                | \$ | 348.31   | } |
| 1 | BONNET HINGE RH                | \$ | 348.31   |   |
| 1 | BONNET LOCK                    | \$ | 305.48   |   |
| 1 | BONNET CABLE                   | \$ | 119.19   |   |
| 1 | BONNET CABLE COVER             | \$ | 161.03   |   |
| 1 | BONNET SEAL OUTER              | \$ | 92.36    |   |
| 1 | BONNET SEAL INNER              | \$ | 157.28   |   |
| 1 | SUBFRAME OUTER FRT             | \$ | 2,652.45 |   |
| 1 | SUBFRAME BRACKET OUTER LH      | \$ | 92.36    |   |
| 1 | SUBFRAME BRACKET OUTER RH      | \$ | 92.36    |   |
| 1 | ENGINE UNDERTRAY               | \$ | 564.98   |   |
| 1 | A/C CONDENSER                  | \$ | 2,020.37 |   |
| 1 | A/C CONDENSER GARNISH LH UPPER | \$ | 39.67    |   |
| 1 | A/C CONDENSER GARNISH RH UPPER | \$ | 39.67    |   |
| 1 | A/C CONDENSER GARNISH LH       | \$ | 58.81    |   |
| 1 | A/C CONDENSER GARNISH RH       | \$ | 59.60    |   |
| 1 | LOWER ARM RH                   | \$ | 685.76   |   |
| 1 | KUNCKLE ARM RH                 | \$ | 846.98   |   |
| 1 | ABSORBER FRT RH                | \$ | 360.54   |   |
| 1 | STABILIZER BAR FRT             | \$ | 604.65   |   |
| 1 | DRIVESHAFT RH                  | \$ | 1,747.45 |   |
| 1 | WIPER RESERVOIR                | \$ | 348.25   |   |
| 1 | WIPER RESERVOIR NECK           | \$ | 136.11   |   |
| 1 | WIPER RESERVOIR MOTOR          | \$ | 270.06   |   |

|              |           |                  |
|--------------|-----------|------------------|
| <b>TOTAL</b> | <b>\$</b> | <b>35,626.53</b> |
| <b>10%</b>   | <b>\$</b> | <b>3,562.65</b>  |
|              | <b>\$</b> | <b>32,063.87</b> |

**Special Nett**

|      |                               |    |       |   |
|------|-------------------------------|----|-------|---|
| 1SET | BUMPER CLIP FRT               | \$ | 66.00 | } |
| 1    | BUMPER BRACKET CLIP FRT RH    | \$ | 12.00 |   |
| 1    | BUMPER SUPPORT CLIP FRT RH    | \$ | 10.50 |   |
| 1SET | BUMPER GRILLE LOWER CLIP      | \$ | 69.00 |   |
| 1SET | FRAME FULL SUPPORT PANEL CLIP | \$ | 70.00 |   |
| 2    | FRAME FULL SUPPORT PANEL NUT  | \$ | 20.00 |   |
| 2    | FRAME FULL SUPPORT PANEL STUD | \$ | 30.00 |   |

**Trans-cab Auto Services Pte Ltd****AAD1806-048**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 9878U**

|      |                               |    |           |       |   |
|------|-------------------------------|----|-----------|-------|---|
| 1SET | WHEELARCH CLIP FRT RH         | \$ | <i>na</i> | 30.50 | X |
| 6    | BONNET INSULATOR CLIP L70Y    | \$ | <i>na</i> | 7.30  | X |
| 2    | BONNET STRUT L70Y             | \$ | <i>na</i> | 88.61 | X |
| 2    | BONNET CABLE CLIP L70Y        | \$ | <i>na</i> | 6.31  | X |
| 2    | BONNET CABLE COVER SCREW L70Y | \$ | <i>na</i> | 10.85 | X |

|              |           |               |
|--------------|-----------|---------------|
| <b>TOTAL</b> | <b>\$</b> | <b>421.08</b> |
|--------------|-----------|---------------|

|                    |           |                  |
|--------------------|-----------|------------------|
| <b>TOTAL PARTS</b> | <b>\$</b> | <b>32,484.95</b> |
|--------------------|-----------|------------------|

**LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

|    |          |             |
|----|----------|-------------|
| \$ | 4,500.00 | <i>2001</i> |
|----|----------|-------------|

Putty and spray painting of the affected portion.

|    |          |             |
|----|----------|-------------|
| \$ | 4,000.00 | <i>2201</i> |
|----|----------|-------------|

To rust-proofing of the affected areas.

|    |           |          |
|----|-----------|----------|
| \$ | <i>na</i> | 170.00 X |
|----|-----------|----------|

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

|    |           |          |
|----|-----------|----------|
| \$ | <i>na</i> | 380.00 X |
|----|-----------|----------|

To check steering geometry and computer wheel alignment

|    |           |          |
|----|-----------|----------|
| \$ | <i>na</i> | 220.00 X |
|----|-----------|----------|

To transfer of tire, rim and on wheel balancing.

|    |           |          |
|----|-----------|----------|
| \$ | <i>na</i> | 170.00 X |
|----|-----------|----------|

To Check Electrical Lighting Concerned.

|    |        |             |
|----|--------|-------------|
| \$ | 170.00 | <i>2001</i> |
|----|--------|-------------|

To transfer of front fender fittings, attachment and perform water seepage test.

|    |           |          |
|----|-----------|----------|
| \$ | <i>na</i> | 380.00 X |
|----|-----------|----------|

To transfer of bonnet fittings, attachment and perform water seepage test.

|    |           |          |
|----|-----------|----------|
| \$ | <i>na</i> | 380.00 X |
|----|-----------|----------|

**Trans-cab Auto Services Pte Ltd**

AAD1806-048

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9878U

To vacuum, replace, refix and recharge air  
condenser \$ *na* 380.00 X

To replace, refix and top up coolant for radiator \$ *na* 170.00 X

To vacuum, replace, refix and recharge Air  
Intercooler \$ *na* 170.00 X

**TOTAL** \$ **11,090.00**

**Over All Total** \$ **43,574.95**

**LUMP SUM (REPAIR DAY)**~~15 DAYS~~*2 days*

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: