

Premium Autocare Centre

24 Benoi Sector, Singapore 629857.

Tel : 6474 3323 Fax : 6264 6786

Email: Nora.khai@premiumautocare.com.sg / claims@premiumautocare.com.sg

Telefax

Estimate : Accident Repairs
Workshop : 24 Benoi Sector
Contact No : 6474 3323
Fax No : 6264 6786
Reference : PAC/OD/0023/2018/GC
Date : 8-Jun-18

Vehicle not in workshop . Kindly arrange for survey.

Your insured vehicle number: SBR 7080 D

AXA Insurance Singapore Pte Ltd

8 Shenton Way
#27-01 AXA Tower
Singapore 068811

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax 6880 4838

Owner's Name : Ms. Lim Beng Choo Daisy
Address : Blk 5 Simei Street 4
#11-07
Singapore 529863
Telephone : (HP) 96422532
Type of Claim : Own Damage Claims
Policy No. : 2100475954-01000
Vehicle No : **SLE 6790 U**
Model Code : CITROEN C4 PICASSO 1.6 BLUEHDI EAT 6
Model / Year : Jul-16
Engine No : 10JBHD3028124
Chassis No : VF73DBHZTFJ866936
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Allan Wu
Accident Date : 7-Jun-18
Place of Accident : MCE

Premium Autocare Centre

24 Benoi Sector, Singapore 629857.

Tel : 6474 3323 Fax : 6264 6786

Telefax

Estimated Labour Charges for Accident Vehicle SLE 6790 U.

S/n	Nature of Jobs	Estimated Charges	Remarks
1	To dismantle and renew rear bumper and rear spoiler. Re-organise rear crash management components. Reinstall all parts removed.	\$ 600.00	
2	To respray rear bumper.	\$ 500.00	
3	To remove and transfer rear bumper & rear fitting wiring harness.	\$ 120.00	
4	To replace rear parking aid sensor	\$ 280.00	
5	Remove and refix rear trim compartment	\$ 280.00	
6	To carry out diagnostic check.	\$ 180.00	
TOTAL LABOUR CHARGES		: \$ 1,960.00	

Premium Autocare Centre

24 Benoi Sector, Singapore 629857.

Tel : 6474 3323 Fax : 6264 6786

Telefax

Material List for Accident Vehicle Regn No. SLE 6790 U.

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remark
1	REAR BUMPER	\$ 1,364.00	
2	REAR BUMPER CLIPS	10 \$ 66.00	
3	REAR BUMPER SIDE RETAINER INNER LH/RH	2 \$ 154.00	
4	REAR BUMPER SIDE RETAINER OUTER LH/RH	2 \$ 110.00	
5	REAR BUMPER REFLECTOR COVER LH/RH	2 \$ 528.00	
6	REAR BUMPER LOWER SPOILER	\$ 396.00	
7	REARE BUMPER CENTER BRACKET	\$ 220.00	
8	REAR REINFORCEMENT	\$ 550.00	
9	REVERSE SENSOR ORIGINAL MAT BLACK CENTER	2 \$ 572.00	
10	REVERSE SENSOR ORIGINAL BODY COLOR OUTER	2 \$ 660.00	
TOTAL SPARE PARTS CHARGES		: \$ 4,620.00	
TOTAL LABOUR CHARGES		: \$ 1,960.00	
GRAND TOTAL		: \$ 6,580.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Autocare Centre

24 Benoi Sector, Singapore 629857.

Tel : 6474 3323 Fax : 6264 6786

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
[Tel:6474 3323 for appointment.](tel:64743323)

Yours faithfully,
Premium Autocare Centre

Allan Wu
Body Shop Manager