

TP 111

SGL9493E.

Hyundai Elantra.

Vic.

KMH0841CMH4U99130.

Front Number Plate	Best	30(SN) ✓
Front Number Plate Holder	Cruld.	30(SN) ✓
Front Number Plate Garnish	Defound.	25 ✓
Front Bumper	Defound	574.40 ✓
Front Bumper Clips	nr	30 ✓
Front Bumper Side Holder	x02 nr	32x2=64 ✓
Front Bumper Reinforcement	} nr nr	550 +
Front Bumper Lower Beam		120 +
Front Bumper Sponge	cruld	145 -
Front Grille	cruld	460.20 -
Front Grille Logo	nr	32-10 ✓
Headlamp x02	cruld.	1298.8x2=2597.60 ✓
Front Bumper Undercovers	} nr nr	125 +
Front Bumper Undercovers Clips		30 +
Air Duct	} nr nr	105 +
Front Support Panel		949.30 +
Front LH Fender	Repair	380 +

SGK9493E.

Rees Number Plate	Best	30(SN) -
Rees Number Plate Holder	Behind	30(SN) -
Rees Bumper	Distorted	559.40 -
Rees Bumper Caps.	new	30 -
Rees Bumper Side Holder x 02	new	55 x 2 = 110 -
Rees Bumper Lower Garnish	Distorted.	250.10 -
Rees Bumper Reflector x 02	cracked.	31.9 x 2 = 63.80 -
Rees Bumper Reinforcement	Best.	394.80 -
Rees Bumper Side Undercover	cracked	45 -
Rees Bumper Reinforcement Bracket x 03	and	18 x 3 = 54 -
Reverse Sensor.	Damaged	280(SN) 200(SN)
Taillamp x 02	cracked	562.6 x 2 = 1125.20 ✓
Taillamp Sponge Gasket x 02	new	20 x 2 = 40 -
Taillamp Panel. x 02	Repair	181 x 2 = 362 x
Bootlid.	Distorted	1528 ✓ 5760
Bootlid Lock.	Damaged	105 -
Bootlid Weatherstripe	wt	100.90 -
Bootlid Hinge x 02	Best	85 x 2 = 170 -
Bootlid Reflector x 02	cracked.	330 x 2 = 660 ✓ 370
Bootlid Reflector Sponge Gasket x 02	new	20 x 2 = 40 -
Bootlid Inner Trim	crumpled	160.50 -
Bootlid Inner Trim Caps.	new	30 -

SGL9493E

Hyundai Logo. }
New

Elantra Emblem }
New

GLS Emblem. }
New

36 /

56 /

40.50 /

Rear Fender x02 Repis

1350 x 2 = 2700 x

Rear Fender Inner Trim Board x02 }
New

220.4 x 2 = 440.80 x

Rear Fender Inner Trim Board Clips. }
New

60. x

Rear Windscreen Moulding. }
New

75 x

Rear Windscreen Sealant. }
New

60(SN) x.

Spare Tyre Panel. Distorted

1103 -

Spare Tyre Panel Insulation Pad. New

250(SN) 200(SN)

Spare Tyre Panel Top Cover. Torn

195.40 /

Spare Tyre Lock Screw. Cracked

25.40 /

Spare Tyre Panel Sealant. New

60(SN) -

Rear Exhaust Pipe. New

960.90 x

Rear Exhaust Mounting. New

30.40 x

Rear Camera. Damaged

~~550(SN) x~~ 380(SN)

Rear End Panel Distorted

495 -

Rear End Panel Top Garnish. Dehd

135.60 -

Rear End Panel Sealant. New

60(SN) -

SGL9493E.

Panel Beating	3000 1700
Spray Painting	2500 1600
Wiring	150 60
To undersent.	150 60
To remove reverse sensor	100 50
To remove rear camera.	100 50
To remove upholstery and rear seat	350 200
To remove fuel tank	150 x
To remove rear windscreen.	180 x
To remove exhaust pipe.	150 80
To remove transfer bootlid fittings.	150 80
To remove condenser, radiator and to re-gas.	180 x.

list 11441.90

ten 20% = 9153.52

S.N: 960

Labour: 3880

total: 13993.52

H/S: 11.2K

12 Days

11.2K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: