

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd. From: LKK Auto Consultants Pte Ltd
3 Anson Road 51 Ubi Ave 1 #01-25
#16-00 Springleaf Tower Paya Ubi Industrial Park
Singapore 079909 Singapore 408933

Attn: Elaine Cheong Date: 12 Jun 2018

Preliminary Advice

Vehicle No	: GBG8335X	Accident Date	: 30/05/2018
Make	: TOYOTA DYNA 150	Policy No.	: DMCVSN1766881700
Assignment Date	: 11/06/2018	Excess	: S\$500.00
Date of Inspection	: 11/06/2018	Est. Duration of Repair	: 16 days
Inspection At	: Car City Auto Centre Pte Ltd (HQ) Blk 9006 #01-198, Tampines Street 93 Singapore 528840		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 17,073.00
Revised Amount	:S\$ 7,878.00
Check Items (Estimated)	:S\$ 4,825.00
Total	:S\$ 12,703.00
 Lump Sum Repair	:S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$ 65,000.00
COE / PARF Rebate	:S\$ 33,501.00
Salvage Value	:S\$
Margin for Repair	:S\$ 31,499.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :