

ISS/2/00

INS. CASE OWNER:

CC 6 ^{UR} / AIG 1801 0563, R2j6357LKK:
IDAC:

Surveyor:

R9sm

DOI:

ASSIGNMENT

8/6/18

Date / Time:

2/6/18

Registered in Merimen:

11/6/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLD 7687J

Name of Insured:

UR

Insured Tel No.:

HP:

6/6/18

Excess Sec II :SS

D.O.A.:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO. Driver Name / Age: NERVA MIHAEL (JARY).

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

12470402156

Policy No.:

Make / Model:

Honda

Place of Accident:

IN BET MERAM

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability:

% Final ? Yes / No

SLD 7687J

STP 6575E

SLP 7549J



INSRS:

WSP:

Tel:

Liability:

RMKS: 01



INSRS:

WSP:

Tel:

Liability:

RMKS: TP



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

18/6/18

DOA

DOA

DOA

3VC - OLD 3RD & LAST

6/6/18 (WED)

7 (S) 16 (FRI)

8 (S) 17 (SUN)

9 (S) 18 (MON)

10 (S) 19 (TUE)

11 (M) 20 (WED)

12 (T) 21 (THU)

13 (W) 22 (FRI)

14 (TH) 23 (SAT)

15 (F) 24 (SUN)

16 (S) 25 (MON)

17 (S) 26 (TUE)

18 (M) 27 (WED)

19 (T) 28 (THU)

RECEIVED 18 JUL 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(days) Reduction: %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with VINCENT

Email ☐ Call ☐

Final Liability:

%

(Agreed/Assessed) BOLA S/N No.: 28

If NO or B 28. Ass. Lia: 100

Repair Cost:

SS

5,000

Loss of Rental (LOR):

SS

1,800 (18 days) x 100

Loss of Use (LOU):

SS

(S x days)

Loss of Income (LOI):

SS

(S x days)

LOR only ☐LOU only ☐LOR + LOU ☐LOR + LO ☐

[Tick only one]

GIA/LTA Search

SS

Medical:

SS

Disbursement:

SS

(e.g. Tow/Independent)

Legal Cost

SS

Total:

SS

6,800.00 Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

SS

6,800

Name 1:

SOON JAN MOTOR TRADING

Payee 2: (Strike if N.A.)

SS

X

Name 2:

X

Payee 3: (Strike if N.A.)

SS

X

Name 3:

X

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Rome

REF: ALB

3384J

ASSIGNMENT

From: Date: 08062018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJR 6575E

at Workshop n/s Soon San Motor

of 3006 Ubi Rd 1 #01-390

Insured:

Policy No:

Claims No:


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

after 12pm



Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

13K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 14 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SJR 6575E Yr Regn: 2009 July

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai AVANTE 1.6A c.s 1591

Colour: WHITE A/C: Insured / Std / NI / NA

Sp Reading: 155355 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KMH0U41BR9U771763

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/452R17
R: .

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 06/06/18 D.O.I. 08/06/18

Survey held at Soon San

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

08/06/18 Msg to soon san w/shrp Vincent inform him repair limit 5K waiting for reply

L/S \$5,000

MV → \$13,000

LTAR - \$7,556

NETT \$5,444.XX

R (\$10,161.04/67%)

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair:

1) Date/Time, File Return to?

☐ : Final Report

Resurvey No. of Trip:

2)

Add Fee: ☐ Site Insp (\$

Survey Fee:

Transportation

) \$ + RS + SI

) Photos

) Other:

Report Format :

Lump Sum / I.B.I: (\$

☐ Interview (\$☐ Tech. Invs (\$☐ Weekend (\$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/LCR18010563/R1jb3		
78 SHENTON WAY #08-16 CHARTIS BUILDINGS SINGAPORE 079120		Date : 11-06-2018		
		Code : LCR		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLD 7687J	Veh. Inspected	SJR 6575E	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	11/06/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	06/06/2018	Inspection Date	08/06/2018	
Survey held at	SOON SAN MOTOR TRADING BLK 3006 UBI ROAD 1 #01-390 SINGAPORE 408716			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

SOON SAN MOTOR TRADING

Blk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

AIG ASIA PACIFIC PTE LTD

78, Shenton Way #09-16

AIG BUILDING

S,pore 079120

Accident date:06/06/18

Date:07/06/18

Estimate cost to repair vel: SJR 6575E (Hyundai Avante) claims under vel:SLD 7687J.

1pce boot lid	\$ 907.00	RT /
2pcs boot lid hinges@\$120	240.00	X SVC
1pce boot lid avante plate	35.00	na /
1pce boot lid s plate	30.00	na /
1pce boot lid emblem	24.00	na /
1pce boot lid s plate	21.00	na /
2pcs boot lid reflectors@\$165	330.00	LH-SVC / RH-X SVC
1pce boot lid top spoiler	550.00	X SVC
1pce boot lid centre garnish	210.00	GRA /
2pcs boot lid number plate lamp@\$35	70.00	X SVC
1pce boot lid reverse camera	350.00	X SVC
1pce boot lid top lock	108.30	RT /
1pce boot lid lower lock	41.60	RT /
1pce boot lid rubber	92.00	na /
1pce boot lid insulator	149.00	X SVC
2pcs tail lamps@\$374.60	749.20	CRA /
2pcs tail lamp inner panel@\$160.80	321.60	Repair
1pce rear bumper	446.00	RT /
1pce rear bumper inner sponge	119.20	CRA /
10pcs rear bumper inner clips@\$4	40.00	na /
2pcs rear bumper side holder@\$26	52.00	na /
1set rear bumper reverse sensors	350.00	na / S/N-220
2pcs rear bumper top clips@\$10	20.00	na /
1pce rear bumper reinforcement	247.20	CRA /
1pce rear bumper lower spoiler	560.00	DB / S/N 300
10pcs rear bumper lower spoiler clips@\$4	40.00	na /

page 1

P - 3347.50

S/N - 520

SOON SAN MOTOR TRADING

Blk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

AIG ASIA PACIFIC PTE LTD

78, Shenton Way #09-16

AIG BUILDING

S,pore 079120

Accident date:06/06/18

Date:07/06/18

Estimate cost to repair vel: SJR 6575E (Hyundai Avante) claims under vel:SLD 7687J.

5415.20

2pcs rear bumper reflectors@\$40	\$ 80.00	page 2	MS ✓
1pce rear bumper lower centre chrome	210.00		MS ✓
1pce rear panel	559.50		BMC ✓
1pce rear panel lower lock cover	98.00		X SVC
2pcs rear fender trim cover@\$169	338.00		cut ✓
1pce front bumper	435.00	DE ✓	
1pce front bumper inner sponge	120.00	CR ✓	
1pce front bumper reinforcement	254.30	TA ✓	
2pcs front bumper side holders@\$31	61.00	MS ✓	
10pcs front bumper inner clips@\$4	40.00	MS ✓	
2pcs front bumper top clips@\$10	20.00	MS ✓	
1pce front bumper lower spoiler	650.00	X SVC	
10pcs front bumper lower spoiler inner clips@\$4	40.00	X SVC	
2pcs head lamps@\$480	960.00	RH - TA / LH - CRA ✓	
1pce front griller	366.00	CRA ✓	
1pce support panel	791.30	CRA ✓	
1pce bonnet	1,017.00	TA ✓	
12pce bonnet insulator inner clips@\$5	60.00	MS ✓	
1pce bonnet lock	68.10	TA ✓	
1pce bonnet rubber	35.00	MS ✓	
2pcs bonnet hinges@\$85	170.00	X SVC	
	\$ 12,476.30		
Less 20%	2,495.26		
	\$ 9,981.04		

8762170
202
7010.16

SOON SAN MOTOR TRADING

Bik.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

AIG ASIA PACIFIC PTE LTD

78, Shenton Way #09-16

AIG BUILDING

S,pore 079120

Accident date:06/06/18

Date:07/06/18

Estimate cost to repair vel: SJR 6575E (Hyundai Avante) claims under vel:SLD 7687J.

S/N - 555

Page 3	\$ 9,981.04
2pcs rear number plate with cover@\$100	200.00
Lobour 1pce rear exhaust pipe	580.00
To rustproof front & rear	300.00
To focus headlamp & wiring	100.00
To dismantle/renew reverse camera	100.00
To dismantle/renew reverse sensors	100.00
To remove/refit rear interior to effect repair	100.00
To dismantle/renew boot lid top spoiler	100.00
To dismantle/renew rear bumper spoiler	100.00
To dismantle/renew front bumper spoiler	100.00
To dismantle/renew rear exhaust pipe	100.00
To dismantle/renew accident portion	1,800.00
To spray paint	1,500.00
Total:	\$ 15,161.04

S/N-35

3310

Rasmul

Hp 90010068

14 days

45

7010.16

555.00

3310.00

10875.16

208

8700.12

43-8,700

08/06/18 @ 1120

Repair after repair

due to COE xping,

u/slop accept

85000 / 14 days

45

SOON SAN MOTOR TRADING

Blk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

AIG ASIA PACIFIC PTE LTD

78, Shenton Way #09-16

AIG BUILDING

S,pore 079120

Accident date:06/06/18

Date:07/06/18

Estimate cost to repair vel: SJR 6575E (Hyundai Avante) claims under vel:SLD 7687J.

1pce boot lid	\$ 907.00	RH /
2pcs boot lid hinges@\$120	240.00	X
1pce boot lid avante plate	35.00	na /
1pce boot lid s plate	30.00	na /
1pce boot lid emblem	24.00	na /
1pce boot lid s plate	21.00	na /
2pcs boot lid reflectors@ <u>\$165</u>	330.00	LH-SLA / RH-X
1pce boot lid top spoiler	550.00	X
1pce boot lid centre garnish	210.00	CRA /
2pcs boot lid number plate lamp@\$35	70.00	X
1pce boot lid reverse camera	350.00	X
1pce boot lid top lock	108.30	RH /
1pce boot lid lower lock	41.60	M /
1pce boot lid rubber	92.00	na /
1pce boot lid insulator	149.00	X
2pcs tail lamps@\$374.60	749.20	CRA /
2pcs tail lamp inner panel@\$160.80	321.60	Repair
1pce rear bumper	446.00	dt /
1pce rear bumper inner sponge	119.20	CRA /
10pcs rear bumper inner clips@\$4	40.00	na /
2pcs rear bumper side holder@\$26	52.00	na /
1set rear bumper reverse sensors	350.00	na / S/N-220
2pcs rear bumper top clips@\$10	20.00	na /
1pce rear bumper reinforcement	247.20	CRA /
1pce rear bumper lower spoiler	560.00	DE / S/N 300
10pcs rear bumper lower spoiler clips@\$4	40.00	na /

SOON SAN MOTOR TRADING

Blk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

AIG ASIA PACIFIC PTE LTD

78, Shenton Way #09-16

AIG BUILDING

S,pore 079120

Accident date:06/06/18

Date:07/06/18

Estimate cost to repair vel: SJR 6575E (Hyundai Avante) claims under vel:SLD 7687J.

2pcs rear bumper reflectors@\$40	\$ 80.00	page 2	MUS /
1pce rear bumper lower centre chrome	210.00		MUS /
1pce rear panel	559.50		RM /
1pce rear panel lower lock cover	98.00		X
2pcs rear fender trim cover@\$169	338.00		cut /
1pce front bumper	435.00	DE /	
1pce front bumper inner sponge	120.00	T. CRA /	
1pce front bumper reinforcement	254.30	T. BA /	
2pcs front bumper side holders@\$31	61.00	re /	
10pcs front bumper inner clips@\$4	40.00	re /	
2pcs front bumper top clips@\$10	20.00	re /	
1pce front bumper lower spoiler	650.00	X	
10pcs front bumper lower spoiler inner clips@\$4	40.00	X	
2pcs head lamps@\$480	960.00	RH - 3/4 / LH - CRA /	
1pce front griller	366.00	CRA /	
1pce support panel	791.30	CRA /	
1pce bonnet	1,017.00	BA /	
12pce bonnet insulator inner clips@\$5	60.00	re /	
1pce bonnet lock	68.10	BA /	
1pce bonnet rubber	35.00	re /	
2pcs bonnet hinges@\$85	170.00	X	
	\$ 12,476.30		
Less 20%	2,495.26		
	\$ 9,981.04		

SOON SAN MOTOR TRADING

Blk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

AIG ASIA PACIFIC PTE LTD

78, Shenton Way #09-16

AIG BUILDING

S,pore 079120

Accident date:06/06/18

Date:07/06/18

Estimate cost to repair vel: SJR 6575E (Hyundai Avante) claims under vel:SLD 7687J.

Page 3	\$ 9,981.04	
2pcs rear number plate with cover@\$100	200.00	S/N -35
Lobour 1pce rear exhaust pipe	580.00	X
To rustproof front & rear	300.00	120
To focus headlamp & wiring	100.00	30
To dismantle/renew reverse camera	100.00	60
To dismantle/renew reverse sensors	100.00	60
To remove/refit rear interior to effect repair	100.00	60
To dismantle/renew boot lid top spoiler	100.00	60
To dismantle/renew rear bumper spoiler	100.00	60
To dismantle/renew front bumper spoiler	100.00	60
To dismantle/renew rear exhaust pipe	100.00	X
To dismantle/renew accident portion	1,800.00	1400
To spray paint	1,500.00	1400
Total:	\$ 15,161.04	

Rasul

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: *Hp 90010068*

Date: *08/06/18 @ 1120*

14 days

4/5

Resurvey after repair

SOON SAN MOTOR TRADING

Block 3006, Ubi Road 1, #01-390, Singapore 407800
Tel : 68414555 Fax : 67473546 408700

DISCHARGE VOUCHER

My / Our Hyundai Avante 1.6 (A)

Claim No. Vehicle No. SJR 6575E

I / We Tong moh Yien

NRIC No. S 1523354 J of BIK 120, #09-10

Bukit Merah View, S'152120

hereby declares that I have received my / our motor vehicle No.

SJR 6575E from the above company in satisfactory condition


after repairs and have no further claims what-so-ever for the repairs

done which have been involved in an accident on 06/06/18

The repairs were done to my satisfaction and what ever money due

Please pay to the repairers

Thank You.

Signature 

Date : 25/06/18

" The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est. Submitted	Adj. Assigned	Adj. Rpt	Adj. Submitted	Ins. Auth'd	Status
Main	11 Jun 2018 Edit Reg		08 Jun 2018 00:00 Edit Adj Rpt	S\$5,000.00 Edit Estimates	S\$5,000.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	LCRF Pte Ltd, Co. Reg. No.: 201624597K, Tel: +6590524967		
Main Claimant:	TONG MOH YIEN, ID: S1523354J		
Vehicle Reg. No.:	SJR6575E	Date of Loss:	06/06/2018 19:00 - :59 [107 Months and 2 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 1347040297SG	Policy/Cover Note No.:	0999994809 (Comprehensive)
Vehicle Reg. No. (Insured):	SLD7687J	Policy No. (Claimant):	10510021
		Excess:	
Repairer:	Soon San Motor Trading (HQ) BLK 3006 UBI ROAD 1 #01-390, 408700 Ubi - Tel: 68414445		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tee, Chee-Wah] Chee-Wah.Tee@aig.com		
Claimant's Insurer:	Aviva Ltd (HQ) - Tel: (65) 6827 9966		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 21/06/2018]		
Driver/Custodian (Insured):	NERVA MICHAEL GARY (), NRIC: S1547461J		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

Claim Documents

***SJR6575E (1347040297SG)**
[SLD7687J]

TP

TONG MOH YIEN
Jun 6 2018 7:00PM
[LCRF Pte Ltd]

Soon San Motor Trading

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View
[View in Browser](#)

Assessment Reports			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	13/06/18 15:32	Accident Statement From: SC - Reg. No: SLD7687J, Claimant: LCRF PTE LTD	Load HTM	

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/07/18 14:03	General View	Load JPG	☒
2	13/07/18 14:03	General View	Load JPG	☒
3	13/07/18 14:03	General View	Load JPG	☒
4	13/07/18 14:03	General View	Load JPG	☒
5	13/07/18 14:03	General View	Load JPG	☒
6	13/07/18 14:03	General View	Load JPG	☒
7	13/07/18 14:03	General View	Load JPG	☒
8	13/07/18 14:03	General View	Load JPG	☒
9	13/07/18 14:03	General View	Load JPG	☒
10	13/07/18 14:03	General View	Load JPG	☒
11	13/07/18 14:03	General View	Load JPG	☒
12	13/07/18 14:03	General View	Load JPG	☒
13	13/07/18 14:03	General View	Load JPG	☒
14	13/07/18 14:03	General View	Load JPG	☒
15	13/07/18 14:03	General View	Load JPG	☒
16	13/07/18 14:03	General View	Load JPG	☒
17	13/07/18 14:03	General View	Load JPG	☒
18	13/07/18 14:03	General View	Load JPG	☒
19	13/07/18 14:03	General View	Load JPG	☒
20	13/07/18 14:03	General View	Load JPG	☒
21	13/07/18 14:03	General View	Load JPG	☒
22	13/07/18 14:03	General View	Load JPG	☒
23	13/07/18 14:03	General View	Load JPG	☒
24	13/07/18 14:03	General View	Load JPG	☒
25	13/07/18 14:03	General View	Load JPG	☒
26	13/07/18 14:03	General View	Load JPG	☒
27	13/07/18 14:03	General View	Load JPG	☒
28	13/07/18 14:03	General View	Load JPG	☒
29	13/07/18 14:03	General View	Load JPG	☒
30	13/07/18 14:03	General View	Load JPG	☒
31	13/07/18 14:03	General View	Load JPG	☒

Assessment Reports				
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
32	13/07/18 14:03	General View	 Load JPG	
33	13/07/18 14:03	General View	 Load JPG	
34	13/07/18 14:03	General View	 Load JPG	
35	13/07/18 14:03	General View	 Load JPG	
36	13/07/18 14:03	General View	 Load JPG	
37	13/07/18 14:03	General View	 Load JPG	
38	13/07/18 14:03	General View	 Load JPG	
39	13/07/18 14:03	General View	 Load JPG	
40	13/07/18 14:03	General View	 Load JPG	
41	13/07/18 14:03	General View	 Load JPG	
42	13/07/18 14:03	General View	 Load JPG	
43	13/07/18 14:03	General View	 Load JPG	
44	13/07/18 14:03	General View	 Load JPG	
45	13/07/18 14:03	General View	 Load JPG	
46	13/07/18 14:03	General View	 Load JPG	
47	13/07/18 14:03	General View	 Load JPG	
48	13/07/18 14:03	General View	 Load JPG	
49	13/07/18 14:03	General View	 Load JPG	
50	13/07/18 14:03	General View	 Load JPG	
51	13/07/18 14:03	General View	 Load JPG	
52	13/07/18 14:03	General View	 Load JPG	
53	13/07/18 14:03	General View	 Load JPG	
54	13/07/18 14:03	General View	 Load JPG	
55	13/07/18 14:03	General View	 Load JPG	
56	13/07/18 14:03	General View	 Load JPG	
57	13/07/18 14:03	General View	 Load JPG	
58	13/07/18 14:03	General View	 Load JPG	
59	13/07/18 14:03	General View	 Load JPG	
60	13/07/18 14:03	General View	 Load JPG	
61	13/07/18 14:03	General View	 Load JPG	
62	13/07/18 14:03	General View	 Load JPG	
63	13/07/18 14:03	General View	 Load JPG	
64	13/07/18 14:03	General View	 Load JPG	
65	13/07/18 14:03	General View	 Load JPG	
66	13/07/18 14:03	General View	 Load JPG	
67	13/07/18 14:03	General View	 Load JPG	
68	13/07/18 14:03	General View	 Load JPG	
69	13/07/18 14:03	General View	 Load JPG	
70	13/07/18 14:03	General View	 Load JPG	
71	13/07/18 14:03	General View	 Load JPG	
72	13/07/18 14:03	General View	 Load JPG	
73	13/07/18 14:03	General View	 Load JPG	
74	13/07/18 14:03	General View	 Load JPG	
75	13/07/18 14:03	General View	 Load JPG	
76	13/07/18 14:03	General View	 Load JPG	
77	13/07/18 14:03	General View	 Load JPG	
78	13/07/18 14:03	General View	 Load JPG	
79	13/07/18 14:03	General View	Load JPG	

Assessment Reports				
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
80	13/07/18 14:03	General View	 Load JPG	
81	13/07/18 14:03	General View	 Load JPG	
82	13/07/18 14:03	General View	 Load JPG	
83	13/07/18 14:03	General View	 Load JPG	
84	13/07/18 14:03	General View	 Load JPG	
85	13/07/18 14:03	General View	 Load JPG	
86	13/07/18 14:03	General View	 Load JPG	
87	13/07/18 14:03	General View	 Load JPG	
88	13/07/18 14:03	General View	 Load JPG	
89	13/07/18 14:03	General View	 Load JPG	
90	13/07/18 14:03	General View	 Load JPG	
91	13/07/18 14:03	General View	 Load JPG	
92	13/07/18 14:03	General View	 Load JPG	
93	13/07/18 14:03	General View	 Load JPG	
94	13/07/18 14:03	General View	 Load JPG	
95	13/07/18 14:03	General View	 Load JPG	
96	13/07/18 14:03	General View	 Load JPG	
97	13/07/18 14:03	Reinspection Photo	 Load JPG	
98	13/07/18 14:03	Reinspection Photo	 Load JPG	
99	13/07/18 14:03	Reinspection Photo	 Load JPG	
100	13/07/18 14:03	Reinspection Photo	 Load JPG	
101	13/07/18 14:03	Reinspection Photo	 Load JPG	
102	13/07/18 14:03	Reinspection Photo	 Load JPG	
103	13/07/18 14:03	Reinspection Photo	 Load JPG	
104	13/07/18 14:03	Reinspection Photo	 Load JPG	
105	13/07/18 14:03	Reinspection Photo	 Load JPG	
106	13/07/18 14:03	Reinspection Photo	 Load JPG	
107	13/07/18 14:03	Reinspection Photo	 Load JPG	
108	13/07/18 14:03	Reinspection Photo	 Load JPG	
109	13/07/18 14:03	Reinspection Photo	 Load JPG	

Documentation

1 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/06/18 18:31	TP GIA REPORT	 Load PDF	
2	11/06/18 18:31	TP ESTIMATE- MARKED	 Load PDF	
3	20/06/18 17:08	LETTER TO LCRF	 Load PDF	
4	17/07/18 17:22	AUTHORISATION TO ACT	 Load PDF	
5	17/07/18 17:22	RELEASE VOUCHER	 Load PDF	
6	17/07/18 17:22	RENTAL RECEIPT	 Load PDF	
7	17/07/18 17:22	WORKSHOP INVOICE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLD7687J (Insd veh)	Model:	HYUNDAI HD AVANTE 1.6 A (BI-FUEL) 1.6 (A)
	SJR6575E (TP veh)		
Date of Accident:	06/06/2018		

Global Sum Settlement	:	[]	Yes	[X]	No
Repair Estimate	:	\$	15,161.04		
Final Repair Cost	:	\$	5,000.00		
Loss of Use	:	\$	days at \$0.00 per day		
Rental (if any)	:	\$	1,800.00	18	days
LTA / GIA Search Fee	:	\$			
Others:	:	\$			
	:	\$			
Final Settlement Sum	:	\$	6,800.00		
Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)					
A) For <u>Non GIA Registered Workshop</u> :			Agreed Liability ____ 100 ____ (%)		
B) For <u>GIA Registered Workshop</u> :			BOLA Applicable: Yes/ No BOLA Scenario No: ____		
BOLA Liability: ____ (%)			Assessed Liability (*): ____ 100 ____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.					
Remarks _____					

Payment Instruction: Payee's Breakdown			
1)	Soon San Motor Trading	:	\$ 6,800.00
2)		:	\$

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

17 Jul
2018

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/LCR18010563/R1JB3S2

Date: 17/07/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994809
 Claimant Vehicle No: SJR6575E Insured Vehicle No: SLD7687J
 Date of Loss: 06/06/2018 Nature of Claim: TP Claim No: 1347040297SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJR6575E**
 Make & Model: HYUNDAI HD AVANTE 1.6 A (BI-FUEL), 1.6 (A) Engine No: G4FC9U662076
 Reg. Date: 04/07/2009 (Man. Year: 2009) Chassis No: KMHJU41BR9U771763
 Colour: White Odometer: 155355 km
 Engine Capacity: 1591 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45ZR17 Rear Tyre Size: 215/45ZR17
 Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm
 Front Right Side: Toyo 6 mm Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,761.04	7,565.16	3,195.88	29.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,400.00	3,310.00	1,090.00	24.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,161.04	10,875.16	4,285.88	28.27
Approved Total (Overridden) (S\$)		5,000.00		
Nett Amount (S\$)	15,161.04	5,000.00	10,161.04	67.02
+ Car Rental (18.0 x S\$100.00/day) (S\$)		1,800.00		
Nett Liability (S\$)		6,800.00		

INSPECTION

Date of Assignment: 08/06/2018
 Date Inspected: 08/06/2018 Inspected At: Soon San Motor Trading (HQ)
 BLK 3006 UBI ROAD 1 #01-390
 Singapore 408700
 Estimated Period of Repair: 14.0 days

Adjuster: MOHD RASUL

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_printprt&caseid=715788&extid=274660&CFID=37540911&C... 1/5

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Bent	907.00 FL	*907.00 FL
2	2		*BOOT LID HINGES	Serviceable	240.00 FL	*- FL
3	1		*BOOT LID AVANTE PLATE	Necessary	35.00 FL	*35.00 FL
4	1		*BOOT LID S PLATE	Necessary	30.00 FL	*30.00 FL
5	1		*BOOT LID EMBLEM	Necessary	24.00 FL	*24.00 FL
6	1		*BOOT LID S PLATE	Necessary	21.00 FL	*21.00 FL
7	1		*BOOT LID REFLECTORS	N/s Scratched/O/s Serviceable	330.00 FL	*165.00 FL
8	1		*BOOT LID TOP SPOILER	Serviceable	550.00 FL	*- FL
9	1		*BOOT LID CENTRE GARNISH	Cracked	210.00 FL	*210.00 FL
10	2		*BOOT LID MEMBER PLATE LAMP	Serviceable	70.00 FL	*- FL
11	1		*BOOT LID REVERSE CAMERA	Serviceable	350.00 FL	*- FL
12	1		*BOOT LID TOP LOCK	Bent	108.30 FL	*108.30 FL
13	1		*BOOT LID LOWER LOCK	Bent	41.60 FL	*41.60 FL
14	1		*BOOT LID RUBBER	Necessary	92.00 FL	*92.00 FL
15	1		*BOOT LID INSULATOR	Serviceable	149.00 FL	*- FL
16	2		*TAIL LAMPS	Cracked	749.20 FL	*749.20 FL
17	2		*TAIL LAMP INNER PANEL	Repair	321.60 FL	*- FL
18	1		*REAR BUMPER	Deformed	446.00 FL	*446.00 FL
19	1		*REAR BUMPER INNER SPONGE	Cracked	119.20 FL	*119.20 FL
20	10		*REAR BUMPER INNER CLIPS	Necessary	40.00 FL	*40.00 FL
21	2		*REAR BUMPER SIDE HOLDER	Necessary	52.00 FL	*52.00 FL
22	2		*REAR BUMPER TOP CLIPS	Necessary	20.00 FL	*20.00 FL
23	1		*REAR BUMPER REINFORCEMENT	Cracked	247.20 FL	*247.20 FL
24	10		*REAR BUMPER LOWER SPOILER CLIPS	Necessary	40.00 FL	*40.00 FL
25	2		*REAR BUMPER REFLECTORS	Missing	80.00 FL	*80.00 FL
26	1		*REAR BUMPER LOWER CENTRE CHROME	Distorted	210.00 FL	*210.00 FL
27	1		*REAR PANEL	Buckled	559.50 FL	*559.50 FL
28	1		*REAR PANEL LOWER LOCK COVER	Serviceable	98.00 FL	*- FL
29	2		*REAR FENDER TRIM COVER	Cut	338.00 FL	*338.00 FL
30	1		*FRONT BUMPER	Deformed	435.00 FL	*435.00 FL
31	1		*FRONT BUMPER INNER SPONGE	Cracked	120.00 FL	*120.00 FL
32	1		*FRONT BUMPER REINFORCEMENT	Bent	254.30 FL	*254.30 FL
33	2		*FRONT BUMPER SIDE HOLDERS	Necessary	61.00 FL	*61.00 FL
34	10		*FRONT BUMPER INNER CLIPS	Necessary	40.00 FL	*40.00 FL
35	2		*FRONT BUMPER TOP CLIPS	Necessary	20.00 FL	*20.00 FL
36	1		*FRONT BUMPER LOWER SPOILER	Serviceable	650.00 FL	*- FL
37	10		*FRONT BUMPER LOWER SPOILER INNER CLIPS	Not Necessary	40.00 FL	*- FL
38	2		*HEAD LAMPS	Cracked	960.00 FL	*960.00 FL
39	1		*FRONT GRILLER	Cracked	366.00 FL	*366.00 FL
40	1		*SUPPORT PANEL	Cracked	791.30 FL	*791.30 FL
41	1		*BONNET	Bent	1,017.00 FL	*1,017.00 FL
42	12		*BONNET INSULATOR INNER CLIPS	Necessary	60.00 FL	*60.00 FL
43	1		*BONNET LOCK	Bent	68.10 FL	*68.10 FL
44	1		*BONNET RUBBER	Necessary	35.00 FL	*35.00 FL
45	2		*BONNET HINGES	Serviceable	170.00 FL	*- FL
46	1		*SET REAR BUMPER REVERSE SENSORS	Necessary	280.00 FS	*220.00 FS
47	1		*REAR BUMPER LOWER SPOILER	Deformed	448.00 FS	*300.00 FS
48	2		*REAR NUMBER PLATE WITH COVER	Bent	200.00 FS	*35.00 FS
49	1		*REAR EXHAUST PIPE	Serviceable	580.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 13,074.30 9,317.70

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 20.00/20.00% (S\$)					2,313.26	1,752.54
Total Parts (S\$)					10,761.04	7,565.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RUSTPROOF FRONT & REAR.	New	300.00	120.00
2	TO FOCUS HEADLAMP & WIRING.	New	100.00	30.00
3	TO DISMANTLE / RENEW REVERSE CAMERA.	New	100.00	60.00
4	TO DISMANTLE / RENEW REVERSE SENSORS.	New	100.00	60.00
5	TO REMOVE / REFIT REAR INTERIOR TO EFFECT REPAIR.	New	100.00	60.00
6	TO DISMANTLE / RENEW BOOT LID TOP SPOILER.	New	100.00	60.00
7	TO DISMANTLE / RENEW REAR BUMPER SPOILER.	New	100.00	60.00
8	TO DISMANTLE / RENEW FRONT BUMPER SPOILER.	New	100.00	60.00
9	TO DISMANTLE / RENEW REAR EXHAUST PIPE.	New	100.00	0.00
10	TO DISMANTLE / RENEW ACCIDENT PORTION.	New	1,800.00	1,400.00
11	TO SPRAY PAINT.	New	1,500.00	1,400.00
Gross Labour Cost (\$\$)			4,400.00	3,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >