

SOON SAN MOTOR TRADING

Blk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

AIG ASIA PACIFIC PTE LTD

78, Shenton Way #09-16

AIG BUILDING

S,pore 079120

Accident date:06/06/18

Date:07/06/18

Estimate cost to repair vel: SJR 6575E (Hyundai Avante) claims under vel:SLD 7687J.

1pce boot lid	\$ 907.00	RT /
2pcs boot lid hinges@\$120	240.00	X
1pce boot lid avante plate	35.00	na /
1pce boot lid s plate	30.00	na /
1pce boot lid emblem	24.00	na /
1pce boot lid s plate	21.00	na /
2pcs boot lid reflectors@ <u>\$165</u>	330.00	LH-SLA / RH-X
1pce boot lid top spoiler	550.00	X
1pce boot lid centre garnish	210.00	CRA /
2pcs boot lid number plate lamp@\$35	70.00	X
1pce boot lid reverse camera	350.00	X
1pce boot lid top lock	108.30	RT /
1pce boot lid lower lock	41.60	RT /
1pce boot lid rubber	92.00	na /
1pce boot lid insulator	149.00	X
2pcs tail lamps@\$374.60	749.20	CRA /
2pcs tail lamp inner panel@ <u>\$160.80</u>	321.60	Repair
1pce rear bumper	446.00	DE /
1pce rear bumper inner sponge	119.20	CRA /
10pcs rear bumper inner clips@\$4	40.00	na /
2pcs rear bumper side holder@\$26	52.00	na /
1set rear bumper reverse sensors	350.00	na / S/N-220
2pcs rear bumper top clips@\$10	20.00	na /
1pce rear bumper reinforcement	247.20	CRA /
1pce rear bumper lower spoiler	560.00	DE / S/N 300
10pcs rear bumper lower spoiler clips@\$4	40.00	na /

SOON SAN MOTOR TRADING

Blk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

AIG ASIA PACIFIC PTE LTD

78, Shenton Way #09-16

AIG BUILDING

S,pore 079120

Accident date:06/06/18

Date:07/06/18

Estimate cost to repair vel: SJR 6575E (Hyundai Avante) claims under vel:SLD 7687J.

2pcs rear bumper reflectors@\$40	\$ 80.00	page 2	MUS /
1pce rear bumper lower centre chrome	210.00		MUS /
1pce rear panel	559.50		RA /
1pce rear panel lower lock cover	98.00		X
2pcs rear fender trim cover@\$169	338.00		cut /
1pce front bumper	435.00	DE /	
1pce front bumper inner sponge	120.00	T. CRA /	
1pce front bumper reinforcement	254.30	T. RA /	
2pcs front bumper side holders@\$31	61.00	re /	
10pcs front bumper inner clips@\$4	40.00	re /	
2pcs front bumper top clips@\$10	20.00	re /	
1pce front bumper lower spoiler	650.00	X	
10pcs front bumper lower spoiler inner clips@\$4	40.00	X	
2pcs head lamps@\$480	960.00	RH - RA / LH - CRA /	
1pce front griller	366.00	CRA /	
1pce support panel	791.30	CRA /	
1pce bonnet	1,017.00	RA /	
12pce bonnet insulator inner clips@\$5	60.00	re /	
1pce bonnet lock	68.10	RA /	
1pce bonnet rubber	35.00	re /	
2pcs bonnet hinges@\$85	170.00	X	
	\$ 12,476.30		
Less 20%	2,495.26		
	\$ 9,981.04		

SOON SAN MOTOR TRADING

Blok.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept

AIG ASIA PACIFIC PTE LTD

78, Shenton Way #09-16

AIG BUILDING

S,pore 079120

Accident date:06/06/18

Date:07/06/18

Estimate cost to repair vel: SJR 6575E (Hyundai Avante) claims under vel:SLD 7687J.

Page 3	\$ 9,981.04
2pcs rear number plate with cover@\$100	200.00 S/N -35
Lobour 1pce rear exhaust pipe	580.00 X
To rustproof front & rear	300.00 120
To focus headlamp & wiring	100.00 70 30
To dismantle/renew reverse camera	100.00 60
To dismantle/renew reverse sensors	100.00 60
To remove/refit rear interior to effect repair	100.00 60
To dismantle/renew boot lid top spoiler	100.00 60
To dismantle/renew rear bumper spoiler	100.00 60
To dismantle/renew front bumper spoiler	100.00 60
To dismantle/renew rear exhaust pipe	100.00 X
To dismantle/renew accident portion	1,800.00 1400
To spray paint	1,500.00 1400
Total:	\$ 15,161.04
	Rasul
	Hr 90010068
	14 days
	48

Rasul
Hp 90010068
14 days
4/3

08/06/18 @ 1120

Ready after repair