

SMRT Accident Vehicle Repair Estimates



Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHF287M
 Ref. No : TAX/06/18/2027
 Reg. Date : 14/12/2017
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS4
 Name of Driver : TOO KIM THOR
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 07/06/2018 12:10:00 PM
 Accident Reported Date / Time : 07/06/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024096481
 Special Instruction to ARC, if any :
 SLB5448G
 Prepared Date : 07/06/2018 04:48:50 PM



Sathya Saw

8/6/2018

sebastianyeang@lkkauto.com

- Part by Part Repair
- Question mark item photo
- Photo before paint.

3 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU503576440

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	1,014.00	0.00
Total Spray Painting Charges :	1,098.00	0.00
Total Material Charges :	5,392.12	5,392.12
Other Charges :	1,476.88	0.00
TOTAL :	8,981.00	0.00
Lum Sum Total :	0.00	0.00
No. of Repair Days :	6.00	0.00 3 days
Prepared / Adjusted By :		
Arc / Surveyor Sign Off Date :	07/06/2018 06:38:09 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 07/06/2018 06:38:09 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH REAR PORTION	1,014.00	0.00 600
Total Labour	1,014.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY FILLER RR BUMPER RH	180.00	0.00 100
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0.00 100
RESPRAY WHEEL CAP	180.00	0.00 100
TO RESPRAY RIM	180.00	0.00 100 X
Total Spray Painting & Panel Beating	1,098.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 40
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 40
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 50
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00 60
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0.00 40
TO REMOVE AND REFIT TYRE	120.00	0.00 40
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00 60
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 X
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 X
TO REMOVE / REFIT SEAT	120.00	0.00 X
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	0.00 296.88 296.88 (net)
Total Other Costs	1,476.88	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
5215947913			COVER, RR BUMPER ASSY ✓ DMG	1	423.90	25.00	317.92	Replace	Replace	No
5202347030			REAR BUMPER REINFORCEMENT ?	1	318.80	25.00	239.10	Replace	Replace	No
5246247030			PAD, RR BUMPER, RH & LH, 1 ?	2	3.80	25.00	5.70	Replace	Replace	No
5246247020			PAD, RR BUMPER, RH & LH, 2 ?	2	3.80	25.00	5.70	Replace	Replace	No
5246247010			PAD, RR BUMPER, RH & LH, 3 ?	2	3.80	25.00	5.70	Replace	Replace	No
5219147030			SEAL, RR BUMPER ARM, RH & LH ?	2	11.00	25.00	16.50	Replace	Replace	No
5257647040			RETAINER, RR BUMPER, LH ?	1	111.50	25.00	83.62	Replace	Replace	No
5257547040			RETAINER, RR BUMPER, RH ?	1	112.70	25.00	84.52	Replace	Replace	No
			SENSOR REVERSE ?	1	180.00	0.00	180.00	Replace	Replace	No
5256547900			FILLER, RR BUMPER, RH ✓ CUT	1	119.90	25.00	89.92	Replace	Replace	No
5216947020			COVER, GUARD RR BUMPER LOWER ✓ CUT	1	14.80	25.00	11.10	Replace	Replace	No
5245347010			GUARD, RR BUMPER, LOWER ?	1	558.30	25.00	418.72	Replace	Replace	No
			PIXEL STICKER ✓ NEC	2	60.00	0.00	120.00	Replace	Replace	No
7680147110A1			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY R	1	891.20	25.00	668.40	Replace	Replace	No
7544147090			NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR ✓ NEC	1	52.30	25.00	39.22	Replace	Replace	No
7544247130			NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR ✓ NEC	1	52.30	25.00	39.22	Replace	Replace	No
7540348010			EMBLEM SUB-ASSY REAR ✓ NEC	1	46.30	25.00	34.72	Replace	Replace	No
	COMMO N		STICKER DECAL 65558888 ✓ NEC	1	21.60	0.00	21.60	Replace	Replace	No
			STICKER SMRT LOGO ✓ NEC	1	7.80	0.00	7.80	Replace	Replace	No
8158147010			LENS & BODY ASSY, RR BUMPER, RH ✓ CRK	1	486.80	10.00	438.12	Replace	Replace	No
8155147281			LENS & BODY, REAR COMBINATION LAMP, RH ?	1	438.10	10.00	394.29	Replace	Replace	No
6160147150			PANEL SUB-ASSY, FENDER REAR RH ?	1	824.80	25.00	618.60	Replace	Replace	No
4260247130			CAP SUB-ASSY, WHEEL ✓ SCR	1	175.80	25.00	131.85	Replace	Replace	No
4261147450			WHEEL, DISC X NN	1	1,555.10	25.00	1,166.32	Replace	Replace	No
			TYRE X NN	1	126.74	0.00	126.74	Replace	Replace	No
TOTAL MATERIALS							5,265.43	5,265.38		
TOTAL MATERIALS(Discounted)							5,392.12	5,392.12		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									