

ASS. REC. BY:

REF:

cs/FCI/8010571/719d3n2

Special Instruction:

Surveyor:

CWS

Taufik

ASSIGNMENT (Office)

From (Person):

Sarene Ler

of

FCI

Date/Time:

9/6/18 @ 12:26pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJT 5792R

Insured:

SHA 77592

at Workshop m/s:

Charm's Customcraft

Tel:

6272 5429

of

Blk 1010, Bkt Merah Lane 3 # 01-105

Policy No:

Claim No:

D18004614MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

06/06/2018

CA / REV / REP. / REV 24 HRS

1up

H.O.D. Endorsement:

Date/Time:

8:15am @ 11/6/18

Person Contacted:

Sharon

Vehicle

IN OUT

Date/Time

Action/Instruction (✓) Estimate

SJT 5792R-X

SHA 77592-CC3/TMI15008304/H/vbd1

DOA: 16/05/2015

12/6/18 @ 3:39pm revised to Sarene Ler by email

16/10/19 @ 3:52pm confirmed with Sharon LS #1500, 15 days.

CRed to 13577.75, 47%

Signature

Taufik

REF:

FCI

ASSIGNMENT

From:

Date:

11/6/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SST 5792R

at Workshop m/s

Charn's Customcraft

of

Blk 1010, Blk Meruh Lane 3# 01-105

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

\$31K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

15

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'DS'

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No.

SST 5792R

Yr Regn:

2009, at

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Wish

c.c.

1777

Colour:

white

A/C:

Insured / Std / NI / NA

Sp. Reading

116879

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

EGE 200024557

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/45R17

R:

1 4

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

11/6/18 @ 1500

Survey held at

Charn's Customcraft

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

* check limit
Repair limit \$15K

RECEIVED 16 OCT 2018

Date/Time: File Pass to?

☐

Preli. Report

1) 16/10 transfer

☐

Final Report

Date/Time: File Return to?

2)

Report Format:

TP

Lump Sum / I.B.T. (\$)

15000

Days Of Repair:

15

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Insp (\$)

☐

Weekend (\$)

Survey Fee:

Transportation

1) S + RS \$1

2) Photo

3) Other

580

08P

17/10/18

18x15: 270

170 + 270

50

157

647



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18010571/T1qd3		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 11-06-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 7759Z	Veh. Inspected	SJT 5792R	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18004614MFSH	Excess (\$)	0.00	
Assign From	CWS (SERENE LER)	Assign Date	11/06/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	06/06/2018	Inspection Date	11/06/2018	
Survey held at	CHARN'S CUSTOMCRAFT BLK 1010 BUKIT MERAH LANE 3 #01-105 SINGAPORE 159724			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18004614MFSH

Date: 12 June 2018

Our Ref: CS/FC118010571/T1qd3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SJT 5792R.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 11/06/2018 at the premises of M/s CHARN'S CUSTOMCRAFT, and have the following to report:-

Workshop Estimate Amount	: S\$ 28,522.25 .
Revised Estimate Amount	: S\$ 15,672.00 .
"Check" Items Amount	: S\$ 4,904.00 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:
The vehicle sustained damages
at the front & rear portion.



Yours faithfully

Taufikh
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	08-06-2018	Our Ref No. D18004614MFSH
Accident Date	06-06-2018	Claim Type. Third Party
Insured Vehicle	SHA7759Z	Third Party Vehicle. SJT5792R
Survey Location	BLK 1010 BUKIT MERAH LANE 3 #01-105	
Contact Person.	SHARON LEE	
Contact No.	62725429/ 0	Fax No. 62736676
Survey Type	DIRECT SETTLEMENT: EST. COR - \$30,518.81	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CHARN'S CUSTOMCRAFT	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/241296)



PRI Documents



Close



PRI Header Details

Claim No	D18004614MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & CHARN'S HUAT]
Workshop Name	CHARN'S CUSTOMCRAFT (Contact Person : SHARON LEE)	Survey Location & Contact Details	BLK 1010 BUKIT MERAH LANE 3 #01-105 Mobile: 0 , Phone: 62725429 , Fax: 62736676 EmailId: CHARN@SINGNET.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT: EST. COR - \$30,518.81		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA7759Z	TP Vehicle No	SJT5792R
PRI Recieved Date	08-06-2018 09:10:52 PM	Surveyor Appointed Date	09-06-2018 12:26:43 PM	Surveyor Accept Date	11-06-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	11-06-2018	Upload Survey Report *:	Choose File
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 12 June 2018 3:39 PM
To: 'Claim Workflow System'; assignments
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18004614MFSH/1
Attachments: CSFCI18010571T1qd3.pdf

Dear Serene,

Enclosed herewith preliminary advice of SJT 5792R.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 11 June 2018 8:15 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18004614MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Saturday, 9 June 2018 12:26 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SERENELER@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18004614MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited



Toyota Wish Price Range Depreciation 2009 Vehicle Type Advanced Search

Home > Used Cars > ValueCars Auto Traders > Toyota Wish 1.8A X

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle



PC SHOW EXCLUSIVE



Toyota Wish 1.8A X

Overview Financial Accessories Similar Research Photos Map

Add to Shortlist Add to Compare Add a Note Report Error

Car Details

Price	\$32,800
Depreciation	\$15,490 /yr View models with similar depreciation
Reg Date	30-Oct-2009 (1yr 4mths 17days COE left)
Manufactured	2009
Mileage	-
Transmission	Auto
Engine Cap	1,797 cc
Road Tax	\$974 /yr
Power	106.0 kW (142 bhp)
Curb Weight	1,340 kg
Features	Powerful And Fuel Efficient Dual VVTi DOHC Engine, CVT Transmission, Digital Climate Aircon, SRS Airbags, ABS, Traction Control, Retractable Side Mirrors.
Accessories	Keyless Entry/ Start/Stop, Sport Mirrors, Solar Film, Factory Fitted Audio System, 2 Tone Upholstery, Leather Seats, Knockdown Rear Seats.

Description
One Of The New Toyota Wish 1.8A With Highest Specification Eg. Keyless Entry And Start Button Yet Down To Earth Japanese MPV! Black Exterior With 2 Tone Leather Seats! Audio Set! Most Fuel Efficiency MPV With Least Maintenance On This Ride! Flexible Loan And Down Payment Available! Come View And We Discuss Further Thanks!

COE	\$19,510	?
OMV	\$22,834	?
ARF	\$22,834	?
Dereg Value	\$15,253 as of today (change)	?
No. of Owners	1	?
Type of Veh	MPV	?
Category	PART Car	?
Availability	Available	?

Add to Shortlist Add to Compare Add a Note

Posted on: 11-Jun-2018 | Last Updated on: 11-Jun-2018

Tags: Toyota Wish, 2009 Toyota Wish, Toyota, Wish, Used Toyota

Upfront Payment more Financial Info

Transfer Fee	\$25	?
Down Payment	\$5,840 (range)	Maximum 70% Loan ?
1st Instalment	\$1,492	?
Total Upfront Payment	\$11,357 (excluding insurance)	?

Estimates based on 70% loan at 2.98% interest rate. Check with seller for exact figure.

Items for Toyota Wish

View All

Magnetic Sun Shade \$110	Reverse Camera \$150
Car Pedals \$108	Leather Upholstery From \$980
Console Box \$110	Bidged Carplate For Sale FOR SALE \$13,800

Showing 6 out of 200 suitable items for Toyota Wish [View All](#)

Hanlip Automobiles Pte Ltd is a specialist workshop for Toyota cars.



Seller Information

Company	ValueCars Auto Traders • dealer's picklist • 49 vehs sold 15 vehs available
Address	61 Ubi Avenue 2 #02-06 Search cars nearby this location
Location	Automobile Megamart
Office No	68410062
Contact Person(s)	Alex 96370341 Audrey 96528622 Richard 88222308

Useful Services

STA SINGAPORE TRADING ASSOCIATION	Afraid of lemons? Request to have this car evaluated professionally. Vehicle Evaluation Find out the market value for your car. Get a free Car Valuation. Free Valuation
--	--

Recommended for you



Don't let your petrol points go to waste



Credit card petrol promotions at Esso



Car Review - Toyota Wish 2.0 Deluxe (A)



Look good and feel beautiful with AFOND Soa



The meaning behind these warning lights



Five technologies for a smarter VW future

Compare

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1307F
Vehicle Details	
Vehicle No.:	SJT5792R
Vehicle to be Exported:	No
Intended De-registration Date:	12 Jun 2018
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8X A
Primary Colour:	White
Manufacturing Year:	2009
Engine No.:	2ZR0469557
Chassis No.:	ZGE200024557
Maximum Power Output:	106.0 kW (142 bhp)
Open Market Value:	\$22,552.00
Original Registration Date:	20 Oct 2009
First Registration Date:	20 Oct 2009
Transfer Count:	1
Actual ARF Paid:	\$22,552.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Oct 2019
PARF Rebate Amount:	\$12,403.00
Intended COE Rebate Details	
COE Expiry Date:	19 Oct 2019
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$19,289.00
COE Rebate Amount:	\$2,608.00
Total Rebate Amount:	\$15,011.00

The information contained herein is correct as at 12 Jun 2018

OK

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	1307F

Vehicle Details

Vehicle No.:	SJT5792R
Vehicle to be Exported:	Yes
Intended De-registration Date:	27 Jun 2018
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8X A
Primary Colour:	White
Manufacturing Year:	2009
Engine No.:	2ZR0469557
Chassis No.:	ZGE200024557
Maximum Power Output:	106.0 kW (142 bhp)
Open Market Value:	\$22,552.00
Original Registration Date:	20 Oct 2009
First Registration Date:	20 Oct 2009
Transfer Count:	1
Actual ARF Paid:	\$22,552.00

Intended PARF Rebate Details


PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Oct 2019
PARF Rebate Amount:	\$12,403.00

Intended COE Rebate Details

COE Expiry Date:	19 Oct 2019
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$19,289.00
COE Rebate Amount:	\$2,525.00
Total Rebate Amount:	\$14,928.00

The information contained herein is correct as at 08 Jun 2018

OK



創 CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

NTUC/FC(SHA7759Z)
DOA: 06/06/2018@1645

MS FIRST CAPITAL INSURANCE PTE LTD

08/06/2018

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM
ESTIMATE COST OF REPAIR FOR VEHICLE NO:
SJT 5792 R - TOYOTA WISH 1.8X A
CHASSIS NO: ZGE20-0024557 (2009)

1 pc	Front bonnet	\$	865.00	bt -
1 pc	Front bonnet hinge LH	\$	55.00	? bt -
1 pc	Front bonnet hinge RH	\$	55.00	? bt -
1 pc	Front bonnet sponge	\$	393.00	ne XH4
6 pcs	Front bonnet sponge clips x \$5.50	\$	33.00	ne -
1 pc	Front bonnet seal	\$	35.00	ne -
1 pc	Front bonnet logo	\$	48.00	ne -
1 pc	Front bonnet lock	\$	95.00	bt -
1 pc	Front grille	\$	185.00	ang -
1 pc	Front headlamp LH	\$	950.00	an -
1 pc	Front headlamp RH	\$	950.00	an -
2 pcs	Front headlamp lower clips @ \$5.50	\$	11.00	ne -
1 pc	Front bumper	\$	552.00	de -
1 pc	Front bumper retainer LH	\$	60.00	an -
1 pc	Front bumper retainer RH	\$	60.00	an -
1 pc	Front bumper under cover	\$	125.00	de -
1 pc	Front bumper grille LH	\$	85.00	de -
1 pc	Front bumper grille RH	\$	85.00	de -
1 pc	Front bumper foglight cover LH	\$	80.00	? de -
1 pc	Front bumper foglight cover RH	\$	80.00	? de -
8 pcs	Front bumper clips x @ \$5.50	\$	44.00	an -
1 pc	Front bumper reinforcement	\$	315.00	bt -
1 pc	Front bumper sponge	\$	105.00	an -
1 pc	Front support panel	\$	1,289.00	bt -
1 pc	Front support panel top garnish	\$	158.00	de -
8 pcs	Front support panel top garnish clips x @ \$5.50	\$	44.00	an -
1 pc	Brace panel	\$	90.00	bt -



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

SJT 5792 R - TOYOTA WISH 1.8X A

1 pc	Horn wire socket	\$	345.00	? CKA
1 pc	A/C condenser	\$	1,507.00	bt
1 pc	Radiator	\$	2,005.00	? bt
6 pcs	Radiator side garnish clips x @ \$5.50	\$	33.00	? Lnn
1 pc	Rear boot	\$	1,400.00	bt
2 pcs	Rear windscreen moulding @ \$45	\$	90.00	ner
1 pc	Rear boot logo	\$	98.00	ner
1 pc	Rear boot chrome moulding	\$	195.00	cut
1 pc	Rear boot lock	\$	425.00	del
1 pc	Rear boot rubber	\$	320.00	twi
1 pc	Rear fender LH	\$	1,210.00	Rx
1 pc	Rear fender RH	\$	1,210.00	Rx
1 pc	Rear fender inner trim board LWR LH	\$	750.00	? de
1 pc	Rear fender inner trim board LWR RH	\$	750.00	x de
1 pc	Rear taillamp LH	\$	288.00	? CKA
1 pc	Rear taillamp RH	\$	288.00	? CKA
1 pc	Rear bumper	\$	595.00	de
1 pc	Rear bumper reflector LH	\$	75.00	? cut
1 pc	Rear bumper reflector RH	\$	75.00	? Lnn
1 pc	Rear bumper retainer LH	\$	95.00	ner
1 pc	Rear bumper retainer RH	\$	95.00	ner
1 pc	Rear bumper side bracket LH	\$	65.00	ner
1 pc	Rear bumper side bracket RH	\$	65.00	ner
1 pc	Rear bumper ctr bracket ROUND LH	\$	30.00	? del
1 pc	Rear bumper ctr bracket ROUND RH	\$	30.00	? del
4 pcs	Rear bumper clips @ \$5.50	\$	22.00	ner
1 pc	Rear end panel (inner)	\$	145.00	bt
1 pc	Rear end panel (outer)	\$	485.00	bt
1 pc	Spare tyre compartment	\$	650.00	buc
1 pc	Spare tyre compartment ctr garnish	\$	400.00	de
1 pc	Spare tyre lock	\$	325.00	? bt
1 pc	Rear chassis LH	\$	987.00	Rx
1 pc	Rear chassis RH	\$	987.00	Rx
1 pc	Rear fender glass moulding LH (c/w glass)	\$	425.00	x n7
1 pc	Rear fender glass moulding RH (c/w glass)	\$	425.00	x n7
1 pc	Exhaust silencer	\$	1,010.00	? bt
1 pc	Exhaust heat shield	\$	155.00	? bt



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

SJT 5792 R - TOYOTA WISH 1.8X A

1 pc	Rear door LH	\$ 1,280.00	Ry
1 pc	Rear door RH	\$ 1,280.00	Ry
1 pc	Rear door glass outer moulding RH	\$ 81.00	x un
		\$ 27,543.00	
	LESS 25%	\$ 6,885.75	
		\$ 20,657.25	
1 pc	Front no.plate (S/NETT)	\$ 35.00	mi3
1 pc	Rear no.plate (S/NETT)	\$ 35.00	cu4
1 set	Reverse sensor (S/Nett)	\$ 200.00	nu
1 pc	Radiator coolant (S/NETT)	\$ 40.00	ne
1 pc	Rear windscreen sealant (S/NETT)	\$ 35.00	✓ nee
2 pcs	Rear quarter glass sealant LH & RH (S/NETT)	\$ 70.00	x un
	Remove and install cushions, seats back rest, inner trim, garnish, roof lining and upholstery to facilitate repair.	\$ 180.00	60.
	Remove, replace a/c assy and refill gas	\$ 100.00	✓
	Check wiring (front)	\$ 40.00	30
	Check wiring (rear)	\$ 40.00	30
	Vehicle on bench	\$ 350.00	250? x un photo.
	Remove and reinstall door glass & fittings rear RH	\$ 60.00	x un
	Remove and reinstall door glass & fittings rear LH	\$ 60.00	x un
	To apply rust-proofing	\$ 120.00	80.
	Remove necessary parts: jacking, panel beating, repair and straighten front inner panel, front support panel, front bonnet, front fenders LH/RH, front bumper and front door LH/RH.	\$ 800.00	600
	Putty and respray front inner panel, front support panel, front bonnet, front fenders LH/RH, front bumper and front doors LH/RH. (PEARL COL)	\$ 1,400.00	1200
	Remove necessary parts: welding, jacking, panel beating, repair and straighten rear inner panel, rear end panel (inner & outer), rear boot, rear fenders LH/RH, rear bumper, rear doors LH/RH and rear chassis LH/RH.	\$ 2,500.00	2000 1600 1400



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

SJT 5792 R - TOYOTA WISH 1.8X A

Putty and resrapy rear inner panel, rear end panel,
rear boot, rear fenders LH/RH, rear bumper, rear
doors LH/RH and rear chassis LH/RH. (PEARL COL)

ADD 7% GST

1600
\$ 1,800.00
\$ 28,522.25
\$1,996.56
\$30,518.81

Note: The above is an estimate only. IF other parts requested
during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT

.....

Page 4 of 4

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97495749
"wp"

11/6/18 @ 1150

Resurvey after repair.

sur @ (Kuantan)

12 days

13/6/18



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

NTUC/FC(SHA7759Z)
DOA: 06/06/2018@1645

MS FIRST CAPITAL INSURANCE PTE LTD

08/06/2018

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM
ESTIMATE COST OF REPAIR FOR VEHICLE NO:
SJT 5792 R - TOYOTA WISH 1.8X A
CHASSIS NO: ZGE20-0024557 (2009)

1 pc	Front bonnet	\$	865.00	bt -
1 pc	Front bonnet hinge LH	\$	55.00	24 -
1 pc	Front bonnet hinge RH	\$	55.00	24 -
1 pc	Front bonnet sponge	\$	7,393.00	600 x 400
6 pcs	Front bonnet sponge clips x \$5.50	\$	33.00	ae -
1 pc	Front bonnet seal	\$	35.00	ae -
1 pc	Front bonnet logo	\$	48.00	ae -
1 pc	Front bonnet lock	\$	95.00	bt -
1 pc	Front grille	\$	185.00	ang -
1 pc	Front headlamp LH	\$	950.00	ae -
1 pc	Front headlamp RH	\$	950.00	ae -
2 pcs	Front headlamp lower clips @ \$5.50	\$	11.00	ae -
1 pc	Front bumper	\$	552.00	de -
1 pc	Front bumper retainer LH	\$	60.00	ae -
1 pc	Front bumper retainer RH	\$	60.00	ae -
1 pc	Front bumper under cover	\$	125.00	de -
1 pc	Front bumper grille LH	\$	85.00	de -
1 pc	Front bumper grille RH	\$	85.00	de -
1 pc	Front bumper foglight cover LH	\$	80.00	24 -
1 pc	Front bumper foglight cover RH	\$	80.00	24 -
8 pcs	Front bumper clips x @ \$5.50	\$	44.00	ae -
1 pc	Front bumper reinforcement	\$	315.00	bt -
1 pc	Front bumper sponge	\$	105.00	ae -
1 pc	Front support panel	\$	1,289.00	bt -
1 pc	Front support panel top garnish	\$	158.00	de -
8 pcs	Front support panel top garnish clips x @ \$5.50	\$	44.00	ae -
1 pc	Brace panel	\$	90.00	bt -



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars

BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

SJT 5792 R - TOYOTA WISH 1.8X A

1 pc	Horn wire socket	\$ 345.00 ? cur ✓
1 pc	A/C condenser	\$ 1,507.00 bt ✓
1 pc	Radiator	\$ 2,005.00 ? bt ✓
6 pcs	Radiator side garnish clips x @ \$5.50	\$ 33.00 ? Xnn
1 pc	Rear boot	\$ 1,400.00 bt ✓
2 pcs	Rear windscreen moulding @ \$45	\$ 90.00 ner ✓
1 pc	Rear boot logo	\$ 98.00 ner ✓
1 pc	Rear boot chrome moulding	\$ 195.00 cur ✓
1 pc	Rear boot lock	\$ 425.00 dd ✓
1 pc	Rear boot rubber	\$ 320.00 twi ✓
1 pc	Rear fender LH	\$ 1,210.00 Rx
1 pc	Rear fender RH	\$ 1,210.00 Rx
1 pc	Rear fender inner trim board LWR LH	\$ 750.00 ? do ✓
1 pc	Rear fender inner trim board LWR RH	\$ 750.00 ? de ✓
1 pc	Rear taillamp LH	\$ 288.00 ? cur ✓
1 pc	Rear taillamp RH	\$ 288.00 ? cur ✓
1 pc	Rear bumper	\$ 595.00 de ✓
1 pc	Rear bumper reflector LH	\$ 75.00 ? out ✓
1 pc	Rear bumper reflector RH	\$ 75.00 ? Xnn
1 pc	Rear bumper retainer LH	\$ 95.00 ner ✓
1 pc	Rear bumper retainer RH	\$ 95.00 ner ✓
1 pc	Rear bumper side bracket LH	\$ 65.00 ner ✓
1 pc	Rear bumper side bracket RH	\$ 65.00 ner ✓
1 pc	Rear bumper ctr bracket ROUND LH	\$ 30.00 ? dd ✓
1 pc	Rear bumper ctr bracket ROUND RH	\$ 30.00 ? dd ✓
4 pcs	Rear bumper clips @ \$5.50	\$ 22.00 ner ✓
1 pc	Rear end panel (inner)	\$ 145.00 bt ✓
1 pc	Rear end panel (outer)	\$ 485.00 bt ✓
1 pc	Spare tyre compartment	\$ 650.00 bre ✓
1 pc	Spare tyre compartment ctr garnish	\$ 400.00 de ✓
1 pc	Spare tyre lock	\$ 325.00 ? bt ✓
1 pc	Rear chassis LH	\$ 987.00 Rx
1 pc	Rear chassis RH	\$ 987.00 Rx
1 pc	Rear fender glass moulding LH (c/w glass)	\$ 425.00 x nn
1 pc	Rear fender glass moulding RH (c/w glass)	\$ 425.00 x nn
1 pc	Exhaust silencer	\$ 1,010.00 ? bt ✓
1 pc	Exhaust heat shield	\$ 155.00 ? bt ✓



CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

SJT 5792 R - TOYOTA WISH 1.8X A

1 pc	Rear door LH	\$ 1,280.00	Ry
1 pc	Rear door RH	\$ 1,280.00	Ry
1 pc	Rear door glass-outer moulding RH	\$ 81.00	x nn
		\$ 27,543.00	
		\$ 6,885.75	
		\$ 20,657.25	
	LESS 25%		
1 pc	Front no.plate (S/NETT)	\$ 35.00	mc3
1 pc	Rear no.plate (S/NETT)	\$ 35.00	cm4
1 set	Reverse sensor (S/Nett)	\$ 200.00	nn
1 pc	Radiator coolant (S/NETT)	\$ 40.00	nr
1 pc	Rear windscreen sealant (S/NETT)	\$ 35.00	rel.
2-pcs	Rear quarter glass sealant LH & RH (S/NETT)	\$ 70.00	x nn
	Remove and install cushions, seats back rest, inner trim, garnish, roof lining and upholstery to facilitate repair.	\$ 180.00	60.
	Remove, replace a/c assy and refill gas	\$ 100.00	✓
	Check wiring (front)	\$ 40.00	30
	Check wiring (rear)	\$ 40.00	30
	Vehicle on bench	\$ 350.00	250 x nn photo
	Remove and reinstall door glass & fittings rear RH	\$ 60.00	x nn
	Remove and reinstall door glass & fittings rear LH	\$ 60.00	x nn
	To apply rust-proofing	\$ 120.00	80.
	Remove necessary parts: jacking, panel beating, repair and straighten front inner panel, front support panel, front bonnet, front fenders LH/RH, front bumper and front door LH/RH.	\$ 800.00	600
	Putty and respray front inner panel, front support panel, front bonnet, front fenders LH/RH, front bumper and front doors LH/RH. (PEARL COL)	\$ 1,400.00	1200
	Remove necessary parts: welding, jacking, panel beating, repair and straighten rear inner panel, rear end panel (inner & outer), rear boot, rear fenders LH/RH, rear bumper, rear doors LH/RH and rear chassis LH/RH.	\$ 2,500.00	2000 1400 1400

5400



創 CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

SJT 5792 R - TOYOTA WISH 1.8X A

Putty and resrapy rear inner panel, rear end panel,
rear boot, rear fenders LH/RH, rear bumper, rear
doors LH/RH and rear chassis LH/RH. (PEARL COL)

ADD 7% GST

1600
\$ 1,800.00
\$ 28,522.25
\$1,996.56
\$30,518.81

Note: The above is an estimate only. IF other parts requested
during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT

.....

Page 4 of 4

Parts - 14428.50
S/N - 345
Lab - 570
20,473.50

less 706 4094.70
16,378.80

C/S - \$16,350/-
1/58 15,000

Tanjin 97495749
'ur'

11/6/18 @ 1150
Resny after repair.
sur @ (Kuantan)

12days 15days
16days +



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref.: CS/FCI18010571/T1qd3n2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date: 19-10-2018



Code: FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 7759Z	Veh. Inspected	SJT 5792R
Policy No.	D-18068936MFSH	Coverage (\$)	0.00
Claim No.	D18004614MFSH	Excess (\$)	0.00
Assign From	SERENE	Assign Date	09/06/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA WISH 1.8X	c.c	1797
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	ZGE200024557	Colour	WHITE
Odometer	116879	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R17	CONTINENTAL	6 mm
L/H Front Tyre	225/45 R17	CONTINENTAL	6 mm
R/H Rear Tyre	225/45 R17	CONTINENTAL	6 mm
L/H Rear Tyre	225/45 R17	CONTINENTAL	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	06/06/2018	Inspection Date	11/06/2018
Survey held at	CHARN'S CUSTOMCRAFT BLK 1010 BUKIT MERAH LANE 3 #01-105 SINGAPORE 159724		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	15 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJT 5792R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BONNET	BENT	865.00	865.00
1	FRONT BONNET HINGE LH	BENT	55.00	55.00
1	FRONT BONNET HINGE RH	BENT	55.00	55.00
1	FRONT BONNET SPONGE	NOT NECESSARY	393.00	-
6	FRONT BONNET SPONGE CLIPS @\$5.50	NECESSARY	33.00	33.00
1	FRONT BONNET SEAL	NECESSARY	35.00	35.00
1	FRONT BONNET LOGO	NECESSARY	48.00	48.00
1	FRONT BONNET LOCK	BENT	95.00	95.00
1	FRONT GRILLE	CRACKED	185.00	185.00
1	FRONT HEADLAMP LH	CRACKED	950.00	950.00
1	FRONT HEADLAMP RH	CRACKED	950.00	950.00
2	FRONT HEADLAMP LOWER CLIPS @\$5.50	NECESSARY	11.00	11.00
1	FRONT BUMPER	DEFORMED	552.00	552.00
1	FRONT BUMPER RETAINER LH	NECESSARY	60.00	60.00
1	FRONT BUMPER RETAINER RH	NECESSARY	60.00	60.00
1	FRONT BUMPER UNDER COVER	DEFORMED	125.00	125.00
1	FRONT BUMPER GRILLE LH	DEFORMED	85.00	85.00
1	FRONT BUMPER GRILLE RH	DEFORMED	85.00	85.00
1	FRONT BUMPER FOGLIGHT COVER LH	DEFORMED	80.00	80.00
1	FRONT BUMPER FOGLIGHT COVER RH	DEFORMED	80.00	80.00
8	FRONT BUMPER CLIPS @\$5.50	NECESSARY	44.00	44.00
1	FRONT BUMPER REINFORCEMENT	BENT	315.00	315.00
1	FRONT BUMPER SPONGE	CRACKED	105.00	105.00
1	FRONT SUPPORT PANEL	BENT	1,289.00	1,289.00
1	FRONT SUPPORT PANEL TOP GARNISH	DEFORMED	158.00	158.00
8	FRONT SUPPORT PANEL TOP GARNISH CLIPS @\$5.50	NECESSARY	44.00	44.00
1	BRACE PANEL	BENT	90.00	90.00
1	HORN WIRE SOCKET	CRACKED	345.00	345.00
1	A/C CONDENSER	BENT	1,507.00	1,507.00
1	RADIATOR	BENT	2,005.00	2,005.00
6	RADIATOR SIDE GARNISH CLIPS @\$5.50	NOT NECESSARY	33.00	-

Report Ref No. CS/FCI18010571/T1qd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BOOT	BENT	1,400.00	1,400.00
2	REAR WINDSCREEN MOULDING @\$45.00	NECESSARY	90.00	90.00
1	REAR BOOT LOGO	NECESSARY	98.00	98.00
1	REAR BOOT CHROME MOULDING	CUT	195.00	195.00
1	REAR BOOT LOCK	DENTED	425.00	425.00
1	REAR BOOT RUBBER	TWISTED	320.00	320.00
1	REAR FENDER LH	TO REPAIR SEE LABOUR	1,210.00	-
1	REAR FENDER RH	TO REPAIR SEE LABOUR	1,210.00	-
1	REAR FENDER INNER TRIM BOARD LWR LH	DEFORMED	750.00	750.00
1	REAR FENDER INNER TRIM BOARD LWR RH	DEFORMED	750.00	750.00
1	REAR TAILLAMP LH	CRACKED	288.00	288.00
1	REAR TAILLAMP RH	CRACKED	288.00	288.00
1	REAR BUMPER	DEFORMED	595.00	595.00
1	REAR BUMPER REFLECTOR LH	CUT	75.00	75.00
1	REAR BUMPER REFLECTOR RH	NOT NECESSARY	75.00	-
1	REAR BUMPER RETAINER LH	NECESSARY	95.00	95.00
1	REAR BUMPER RETAINER RH	NECESSARY	95.00	95.00
1	REAR BUMPER SIDE BRACKET LH	NECESSARY	65.00	65.00
1	REAR BUMPER SIDE BRACKET RH	NECESSARY	65.00	65.00
1	REAR BUMPER CTR BRACKET ROUND LH	DENTED	30.00	30.00
1	REAR BUMPER CTR BRACKET ROUND RH	DENTED	30.00	30.00
4	REAR BUMPER CLIPS @\$5.50	NECESSARY	22.00	22.00
1	REAR END PANEL (INNER)	BENT	145.00	145.00
1	REAR END PANEL (OUTER)	BENT	485.00	485.00
1	SPARE TYRE COMPARTMENT	BUCKLED	650.00	650.00
1	SPARE TYRE COMPARTMENT CTR GARNISH	DEFORMED	400.00	400.00
1	SPARE TYRE LOCK	BENT	325.00	325.00
1	REAR CHASSIS LH	TO REPAIR SEE LABOUR	987.00	-
1	REAR CHASSIS RH	TO REPAIR SEE LABOUR	987.00	-
1	REAR FENDER GLASS MOULDING LH (C/W GLASS)	NOT NECESSARY	425.00	-

Report Ref No. CS/FC118010571/T1qd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR FENDER GLASS MOULDING RH (C/W GLASS)	NOT NECESSARY	425.00	-
1	EXHAUST SILENCER	BENT	1,010.00	1,010.00
1	EXHAUST HEAT SHIELD	BENT	155.00	155.00
1	REAR DOOR LH	TO REPAIR SEE LABOUR	1,280.00	-
1	REAR DOOR RH	TO REPAIR SEE LABOUR	1,280.00	-
1	REAR DOOR GLASS OUTER MOULDING RH	NOT NECESSARY	81.00	-
	LESS 25% DISCOUNT		-6,885.75	-4,789.25
			20,657.25	14,367.75
	SPECIAL NETT ITEMS			
1	FRONT NO PLATE (SN)	MISSING	35.00	35.00
1	REAR NO PLATE (SN)	CRACKED	35.00	35.00
1	SET REVERSE SENSOR (SN)	NOT WORKING	200.00	200.00
1	RADIATOR COOLANT (SN)	NECESSARY	40.00	40.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	35.00	35.00
2	REAR QUARTER GLASS SEALANT LH & RH (SN)	NOT NECESSARY	70.00	-
			415.00	345.00
	LABOUR			
	REMOVE AND INSTALL CUSHIONS,SEATS BACK REST,INNER TRIM,GARNISH,ROOF LINING AND UPHOLSTERY TO FACILITATE REPAIR.		180.00	60.00
	REMOVE,REPLACE A/C ASSY AND REFILL GAS.		100.00	100.00
	CHECK WIRING (FRONT).		40.00	30.00
	CHECK WIRING (REAR).		40.00	30.00
	VEHICLE ON BENCH.	NOT NECESSARY	350.00	-
	REMOVE AND REINSTALL DOOR GLASS & FITTINGS REAR RH.	NOT NECESSARY	60.00	-
	REMOVE AND REINSTALL DOOR GLASS & FITTINGS REAR LH.	NOT NECESSARY	60.00	-
	TO APPLY RUST-PROOFING.		120.00	80.00
	REMOVE NECESSARY PARTS;JACKING,PANEL BEATING,REPAIR AND STRAIGHTEN FRONT INNER PANEL,FRONT SUPPORT PANEL,FRONT BONNET,FRONT FENDERS LH/RH,FRONT BUMPER AND FRONT DOOR LH/RH.		800.00	600.00

Report Ref No. CS/FCI18010571/T1qd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PUTTY AND RESPRAY FRONT INNER PANEL, FRONT SUPPORT PANEL, FRONT BONNET, FRONT FENDERS LH/RH, FRONT BUMPER AND FRONT DOORS LH/RH (PEARL COL).		1,400.00	1,200.00
	REMOVE NECESSARY PARTS; WELDING, JACKING, PANEL BEATING, REPAIR AND STRAIGHTEN REAR INNER PANEL, REAR END PANEL (INNER & OUTER), REAR BOOT, REAR FENDERS LH/RH, REAR BUMPER, REAR DOORS LH/RH AND REAR CHASSIS LH/RH.		2,500.00	2,000.00
	PUTTY AND RESPRAY REAR INNER PANEL, REAR END PANEL, REAR BOOT, REAR FENDERS LH/RH, REAR BUMPER, REAR DOORS LH/RH AND REAR CHASSIS LH/RH (PEARL COL).		1,800.00	1,600.00
			7,450.00	5,700.00
	GRAND TOTAL		28,522.25	20,412.75
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				15,000.00

Report Ref No. CS/FCI18010571/T1qd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.