

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0799/2018
DATE : 08-JUN-2018

FWD SINGAPORE PTE LTD
6 TEMASEK BOULEVARD, #18-01 SUNTEC TOWER 4

S(038986)
TEL : 68208888
FAX :

OWNER'S NAME : LOW YUN XUAN (LIU WENXUAN)
ADDRESS : BLK 308C PUNGGOL WALK
#11-332
S(823308)
TELEPHONE NO : 9745 6703

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1700022063
VEHICLE NO : SLQ1767H
MODEL CODE : SJ5GK7C
MODEL/YEAR : FORESTER 2.0I-L AWD CVT
ENGINE NO : FB20YA28548
CHASSIS NO : JF1SJ5KC5HG092390
MILEAGE : 1 KM
DATE IN : 08/06/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : KUAN WEI LOONG**
ACCIDENT DATE : 05/06/2018

Print Date : 08/06/2018
Print Time : 12:27:36

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLQ1767H

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM) AGAINST SLB6838H - FWD		
2	ZZ/001	CONDUCT TP CLAIM FWD LOCATION:PUNGGOL WAY TO SUMANK LINK DATE:05/06/2018 TIME:1830HRS		
3	ZZ/002	REPAIR/REPLACE REAR BUMPER,FLOOR PAN, TAILGATE AND PANEL	2800.00	2520
4	ZZ/003	RESPRAY REAR BUMPER,FLOOR PAN, TAILGATE AND PANEL	2100.00	1680
5	ZZ/004	DISMENTLE/REFIX UNDERCARRIAGE REAR LHS/RHS/CENTER TO FACILITATE REPAIR	900.00	840
6	ZZ/005	REMOVE/REFIX EXHAUST	150.00	✓
7	ZZ/006	TO CONDUCT WATER SEEPAGE TEST	100.00	50
8	ZZ/007	TRANSFER TAILGATE MECHANISM	150.00	✓
9	ZZ/008	WHEEL ALIGNMENT	200.00	150
10	ZZ/009	REMOVE/REFIX CARPET,SEATS TO FACILITATE REPAIR	400.00	280
11	ZZ/011	REMOVE/INSTALL REAR WINDSCREEN	300.00	250
12	ZZ/012	TO REMOVE/REFIX FUEL TANK	200.00	150
13	ZZ/013	TO CONDUCT REAR LIGHTING TEST	50.00	30
14	ZZ/014	TO CONDUCT REAR ANTI-RUST COATING	580.00	290
15	ZZ/015	TO SUPPLY/INSTALL REVERSE SENSOR-2 EYES	70 300.00	✓
16	ZZ/016	TO SUPPLY/INSTALL REAR TINTED FILM	145.00	✓
17	ZZ/017	SUNDRIES	100.00	50
18	ZZ/10	REMOVE/REFIX REAR BOOT GARNISH & TRIM TO FACILITATE REPAIR	150.00	✓
TOTAL LABOUR CHARGES			8625.00	

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLQ1767H

		DAMAGED PARTS & PRICES			
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT
					S/LIST REMARKS
1	EXH PIPE ASSY R	44200SG011	720.00	7	
2	MUFFLER ASSY RH NA	44300SG010	601.20	7	
3	R EXH CUTTER RH/LH GE3/SH	44370FG002	72.00	7	
4	DUCT COMPL RHD	51121SG0009P	680.40	✓	
5	FLOOR PAN R R CP	52129SG0019P	432.00	✓	
6	TOE BOARD ASSY RHD	52210FJ0219P	576.00	✓	
7	SKIRT COMPL R	52401SG0109P	288.00	✓	
8	BUMPER FACE REAR FORESTER IL	57704SG012	540.00	✓	
9	BRKT SD R RH	(1) 57707SG080	14.40	7	
10	BRKT SD R LH	57707SG090	14.40	7	
11	BEAM COMPL R EU	57711SG0219P	288.00	✓	
12	COVER HOOK R	57731SG010NN	12.60	✓	
13	COVER EXH COMPL RRH	59020FJ002	60.50	7	
14	PANEL CPL R/G NA	60809SG0109P	1072.80	X	
15	LETTER MARK FORESTOR R	93079SG000	39.60	✓	
16	LETTER MK R SUB	93079SG030	64.80	✓	
17	CARGO STEP PANEL S/S	E7710SG000	460.00	✓	
SUB TOTAL			5936.70	0.00	0.00
LESS DISCOUNT (NETT-20 %)			1187.34	0.00	0.00
GRAND TOTAL			4749.36	0.00	0.00
OVERALL TOTAL			4749.36		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLQ1767H

TOTAL LABOUR CHARGES	8625.00
TOTAL SPARE PARTS CHARGES	4749.36

GRAND TOTAL	13374.36 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

*Not Withheld
1-B.1
Resurvey B4 pain
10 days*

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: