

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0799/2018
DATE : 08-JUN-2018

FWD SINGAPORE PTE LTD
6 TEMASEK BOULEVARD, #18-01 SUNTEC TOWER 4

S(038986)
TEL : 68208888
FAX :

OWNER'S NAME : LOW YUN XUAN (LIU WENXUAN)
ADDRESS : BLK 308C PUNGGOL WALK
#11-332
S(823308)
TELEPHONE NO : 9745 6703

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1700022063
VEHICLE NO : SLQ1767H
MODEL CODE : SJ5GK7C
MODEL/YEAR : FORESTER 2.0I-L AWD CVT
ENGINE NO : FB20YA28548
CHASSIS NO : JF1SJS5KC5HG092390
MILEAGE : 1 KM
DATE IN : 08/06/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : KUAN WEI LOONG**
ACCIDENT DATE : 05/06/2018

Print Date : 08/06/2018
Print Time : 12:27:36

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLQ1767H

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM) AGAINST SLB6838H - FWD		
2	ZZ/001	CONDUCT TP CLAIM FWD LOCATION:PUNGGOL WAY TO SUMANK LINK DATE:05/06/2018 TIME:1830HRS		
3	ZZ/002	REPAIR/REPLACE REAR BUMPER,FLOOR PAN,TAILGATE AND PANEL	2800.00	
4	ZZ/003	RESPRAY REAR BUMPER,FLOOR PAN,TAILGATE AND PANEL	2100.00	
5	ZZ/004	DISMENTLE/REFIX UNDERCARRIAGE REAR LHS/RHS/CENTER TO FACILITATE REPAIR	900.00	
6	ZZ/005	REMOVE/REFIX EXHAUST	150.00	
7	ZZ/006	TO CONDUCT WATER SEEPAGE TEST	100.00	
8	ZZ/007	TRANSFER TAILGATE MECHANISM	150.00	
9	ZZ/008	WHEEL ALIGNMENT	200.00	
10	ZZ/009	REMOVE/REFIX CARPET,SEATS TO FACILITATE REPAIR	400.00	
11	ZZ/011	REMOVE/INSTALL REAR WINDSCREEN	300.00	
12	ZZ/012	TO REMOVE/REFIX FUEL TANK	200.00	
13	ZZ/013	TO CONDUCT REAR LIGHTING TEST	50.00	
14	ZZ/014	TO CONDUCT REAR ANTI-RUST COATING	580.00	
15	ZZ/015	TO SUPPLY/INSTALL REVERSE SENSOR-2 EYES	300.00	
16	ZZ/016	TO SUPPLY/INSTALL REAR TINTED FILM	145.00	
17	ZZ/017	SUNDRIES	100.00	
18	ZZ/10	REMOVE/REFIX REAR BOOT GARNISH & TRIM TO FACILITATE REPAIR	150.00	
		TOTAL LABOUR CHARGES	8625.00	

MOTORIMAGE ENTERPRISES PTE. LTD.
 19 LORONG 8, TOA PAYOH
 SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLQ1767H

S/NO PARTS DESCRIPTION		PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
1	EXH PIPE ASSY R	44200SG011	720.00			
2	MUFFLER ASSY RH NA	44300SG010	601.20			
3	R EXH CUTTER RH/LH GE3/SH	44370FG002	72.00			
4	DUCT COMPL RHD	51121SG0009P	680.40			
5	FLOOR PAN R R CP	52129SG0019P	432.00			
6	TOE BOARD ASSY RHD	52210FJ0219P	576.00			
7	SKIRT COMPL R	52401SG0109P	288.00			
8	BUMPER FACE REAR FORESTER IL	57704SG012	540.00			
9	BRKT SD R RH	(1) 57707SG080	14.40			
10	BRKT SD R LH	57707SG090	14.40			
11	BEAM COMPL R EU	57711SG0219P	288.00			
12	COVER HOOK R	57731SG010NN	12.60			
13	COVER EXH COMPL RRH	59020FJ002	60.50			
14	PANEL CPL R/G NA	60809SG0109P	1072.80			
15	LETTER MARK FORESTOR R	93079SG000	39.60			
16	LETTER MK R SUB	93079SG030	64.80			
17	CARGO STEP PANEL S/S	E7710SG000	460.00			
SUB TOTAL			5936.70	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)			1187.34	0.00	0.00	0.00
GRAND TOTAL			4749.36	0.00	0.00	0.00
OVERALL TOTAL			4749.36			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLQ1767H

TOTAL LABOUR CHARGES 8625.00
TOTAL SPARE PARTS CHARGES 4749.36

GRAND TOTAL 13374.36 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00
LIABILITY : 0.00
REMARKS :

PLS NOTE : This estimate is based on visual inspection of the
affected vehicle. Should we require further labour
charges & spare parts in the process of repairs, we
shall inform you accordingly.